WATER QUALITY RESTORATION PLAN AND TOTAL MAXIMUM DAILY LOADS (TMDL) FOR THE BOBTAIL CREEK WATERSHED





Technical Leads:

Heidi Lindgren, Montana Department of Environmental Quality

Bob Anderson, Hydrometrics, Inc.

Contributors:

Montana Department of Environmental Quality Water Quality Planning Bureau

Hydrometrics, Inc.

Brian Sugden, Plum Creek Timber Company

Steve Wegner, USFS, Kootenai National Forest

Bobtail Creek Watershed Group

Confluence Consulting

EXECUTIVE SUMMARY

This document presents a Water Quality Protection Plan and Total Maximum Daily Load (TMDL) for the Bobtail Creek Watershed in Montana. A TMDL is a pollutant budget identifying the maximum amount of a particular pollutant that a waterbody can assimilate without causing applicable water quality standards to be exceeded. Section 303 of the Federal Clean Water Act and the Montana Water Quality Act (Section 75-5-703) require development of TMDLs for impaired waterbodies that do not meet Montana water quality standards. Section 303(d) also requires identification of impaired waterbodies on a list, referred to as the 303(d) list. This 303(d) list is updated every two years and submitted to the U. S. Environmental Protection Agency (EPA) by the Montana Department of Environmental Quality (MDEQ).

Bobtail Creek supports a coldwater fishery that is geographically important to native fish. The development of the water quality plan and TMDL included an in-depth analysis of water quality in Bobtail Creek. The analysis focused on physical parameters linked to excess sediment loading. Results were compared to information from reference streams throughout western Montana and reference literature values to help identify potential aquatic life or cold-water fish limitations. Bobtail Creek was identified as having habitat and fishery limitations linked to excess sediment loading. These limitations were linked to a lack of pools, overly wide channels, excessive eroding banks, and a reduction in the health of the riparian corridor linked to forest and agriculture practices. These limitations were sufficient to justify the impairment determination for Bobtail Creek thus requiring development of a sediment TMDL. Many stakeholders are working toward improved water quality in this watershed and have implemented projects toward water quality improvement.

This plan includes the development of TMDL targets and other beneficial use support indicators that must be satisfied to meet Montana Water Quality Standards. These targets focus on water quality limitations such as pool frequency or width to depth. Targets measuring sediment include Wolman pebble counts and Mc Neil core samples.

Restoration objectives, including TMDL and sediment load allocations are developed to address the sediment sources that are contributing to the impairment conditions. These sources include loads of sediment from rain-on-snow events, mass wasting, and other activities mostly linked to timber harvest, forest and private road erosion, and human induced bank erosion.

This plan also includes strategies for implementation and monitoring. Implementation focuses on a continuation of many the ongoing water quality protection activities in the watershed. The Kootenai National Forest, Plum Creek Timber Company, other private landowners, and other agencies play an important role in effective implementation of this plan and water quality protection and restoration. The monitoring strategy focuses on tracking progress toward meeting TMDL targets and other goals. An important component of the monitoring strategy is to provide for adaptive management to address uncertainties that tend to exist when developing numeric goals and applying them to TMDL targets and load allocations. The monitoring strategy also includes tracking implementation projects and pursuing a better understanding of the water quality and habitat capabilities and limitations in the Bobtail Creek Watershed.

Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area.

Water Body and Pollutants of Concern	Bobtail Creek Pollutants: Siltation and Turbidity - addressed as sediment in the TMDL.				
Impaired Beneficial Uses	Bobtail Creek Impaired Uses: Partially supporting aquatic life and cold-water fishery.				
Pollutant Sources	Sediment (including siltation, turbidity, bank erosion, and other habitat alteration): from silviculture, logging road construction and maintenance, and "other" sources.				
Target Development Strategies	 The current water quality impairment status of each of the waters originally listed on the 2000 and 2002 303(d) list was evaluated using a suite of targets and supplemental indicators. Targets for the Bobtail Creek watershed include threshold values for width-to-depth ratios, pool frequency, riffle stability index, Wolman pebble counts, and McNeil core samples. 				
TMDL	A 95% reduction of total suspended solids during high flow conditions.				
Allocation Strategies	 90% application of road best management practices (BMP) to minimize surface erosion from existing roads. 75% reduction in bank erosion rates. No sediment loading from preventable mass wasting events. No sediment loading from culvert failures where culverts are not up to BMP standards or not maintained. No sediment loading increases (other than potential, minor, predicted, short-term increases associated with full implementation of applicable BMPs) related to future development. No sediment loading increases (other than potential, minor, predicted, short-term increases associated with full implementation of applicable BMPs) related to future timber roads and timber harvest. 				
Restoration Strategies	 Utilize existing restoration programs and plans of the U.S. Forest Service and Plum Creek Timber Company. Encourage additional restoration actives and BMP implementation by private landowners. 				
Margin of Safety	For the Bobtail Creek watershed, a margin of safety is provided by conservative assumptions and proposed additional studies to address uncertainties.				
Seasonal Considerations	Sediment TMDL and targets consider seasonal variations by setting, related habitat targets and biological targets that are affected by year round processes.				

$\underline{D:} \underline{NobtailTMDL} \underline{FinalBobtailCoverDoc.doc}$

Table of Contents

Executive Summary	Error!	Bookmark not defined.
Section 1.0 Introduction		
1.1 Background and Purpose		
1.2 Water Quality Restoration Planning Process		
Section 2.0 Watershed Characterization		
2.1 Location and Regional Description		
2.2 Geological Setting		
2.3 Land Types and Soils		
2.4 Climate		
2.5 Vegetation		
2.6 Land Ownership		
2.7 Land Use		
2.8 Hydrology		
2.8.1 Stream Flow Data		
2.8.2 Equivalent Clear-cut Area Model		
2.9 Fisheries and Aquatic Life		
2.9.1 Fisheries		
2.9.2 Macroinvertebrates		
Section 3.0 Water Quality Impairment Status		
3.1 303(d) List Status		
3.2 Applicable Water Quality Standards		
3.2.1 Classification and Beneficial Uses		
3.2.2 Standards		
3.3 Water Quality Targets and Supplemental Indicators		
3.3.1 Sediment Targets		
3.3.2 Supplemental Indicators		
3.3.3 Uncertainty Associated with Targets and Supplement		
not defined.		
3.4 Current Water Quality Impairment Status for Bobtail Cred	ek	Error! Bookmark not
defined.		
3.4.1 Summary of the 303(d) List	.Error!	Bookmark not defined.
3.4.2 Target and Supplemental Indicator Data		
3.5 Bobtail Creek Water Quality Impairment Status Summary	Error!	Bookmark not defined.
Section 4.0 Source Assessment.		
4.1 USFS Information	.Error!	Bookmark not defined.
4.2 Plum Creek Sediment Delivery Analysis	.Error!	Bookmark not defined.
4.3 Field Review of Residential Reaches – Eroding Banks	.Error!	Bookmark not defined.
4.4 Other Potential Sources		
4.5 Source Assessment Uncertainty	.Error!	Bookmark not defined.
4.6 Source Assessment Summary		
Section 5.0 Total Maximum Daily Load, Allocations, and Uncer		
defined.	•	
5.1 Total Maximum Daily Load	.Error!	Bookmark not defined.
5.1.1 TMDL for Total Suspended Sediment (TSS)	.Error!	Bookmark not defined.
5.2 Load Allocations	.Error!	Bookmark not defined.

5.2.1. Surface Erosion from Performance Based Roads Al	locations Error! Bookmark not
defined.	E. D. D. L. J. C. J. C. J.
5.2.2 Eroding Banks Allocation	
5.2.3 Mass Wasting from Timber Harvest Activities or Ot Bookmark not defined.	ner Development Error!
5.2.4 Culvert Failures	Error! Rookmark not defined
5.2.5 Future Development	
5.2.6 Future Roads and Timber Harvest	
5.2.7 Future Performance-Based Allocations	
5.3 TMDL and Load Allocation Uncertainty	
5.3.1 Margin of Safety	
5.3.2 Seasonality	
Section 6.0 Restoration Strategy	
6.1 USFS Restoration Plans and Responsibilities	
6.2 Plum Creek Timber Company Restoration Plans and Res	sponsibilitiesError! Bookmark
not defined.	
6.3 Other Private Landowner Restoration Plans and Respons	sibilities Error! Bookmark not
defined.	
Section 7.0 Monitoring Strategy	Error! Bookmark not defined.
7.1 Monitoring Plan	Error! Bookmark not defined.
7.2 Trend Monitoring of Target Variables	Error! Bookmark not defined.
7.3 Trend Monitoring of Supplemental Indicators	
7.4 Beneficial Use Linkage Indicators	
7.5 Condition Monitoring	
7.6 Reference Monitoring	
7.7 Data Gaps	
7.8 Adaptive Management Strategy	
Section 8.0 Public Involvement	
References	
References	Error: Bookmark not defined.
Appendices	
Appendix A Streamflow and Total Suspended Solids Data	
Appendix B McNeil Core Data for Bobtail Creek	
Appendix C Total Suspended Solids and Turbidity Data	
Appendix D Severity of Ill Effects Analysis	
Appendix E Bobtail Creek Road Sediment Delivery Analysis	
Appendix F Responses to Public Comments	
List of Figures	
List of Figures Figure 1. 1. Political Creek Wetershod Legation Man	Ennant Dookmank not defined
Figure 1-1. Bobtail Creek Watershed – Location Map	
Figure 2-1. Geology of the Bobtail Creek Watershed.	
Figure 2-2. Land Types of the Bobtail Creek Watershed	
Figure 2-3. Average Precipitation in the Bobtail Creek Watersh	nea Error! Bookmark not
defined.	
Figure 2-4. Vegetation Cover Types in the Bobtail Creek Water	rsned Error! Bookmark not
defined.	

January, 2005 iv

Figure 2-5. Land Ownership in the Bobtail Creek WatershedError! Bookmark not defined.
Figure 2-6. Daily Stream flow and TSS Data from Mouth of Bobtail Creek (Bobtail 1) Water
Years 2001-2003Error! Bookmark not defined.
Figure 3-1. Weight-of-Evidence Approach for Determining Beneficial Use Impairments Error!
Bookmark not defined.
Figure 3-2. Methodology for Determining Compliance with Water Quality Standards Error!
Bookmark not defined.
Figure 3-3. Comparison of Simultaneous Measurements of TSS and Turbidity in Bobtail Creek.
Error! Bookmark not defined.
Figure 3-4. U. S. Forest Service Riparian Management Objectives Sites Error! Bookmark not
defined.
Figure 3-5. Pebble Count Results for Bobtail Creek Watershed Error! Bookmark not defined.
Figure 3-6. Bobtail Creek Watershed Sampling Sites Error! Bookmark not defined.
Figure 3-7. Calculated SEV for Concentrations of TSS Sampled on Bobtail Creek for
Hypothetical Durations Using Model 1 (Adults and Juvenile Salmonids). Error! Bookmark
not defined.
Figure 4-1. TSS Concentrations and Flow on Bobtail Creek During a ROS Event, February 23,
2002Error! Bookmark not defined.
Figure 4-2. TSS and Flow Measured on Tributary Streams in the Bobtail Creek Watershed
During the ROS Event, February 23, 2002Error! Bookmark not defined.
Figure 4-3. Sites Evaluated by Plum Creek Timber Company in the Road Sediment Delivery
Analysis
Figure 4-4. Area of Unstable Stream Reach. Error! Bookmark not defined.
Figure 6-1 Restoration Projects in the Bobtail Creek Watershed. Error! Bookmark not defined.
List of Tables
List of Tables Table F-1 Summary of Required TMDL Elements for the Bohtail Creek TMDL Planning Area
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area.
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined.
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail CreekError! Bookmark not defined.
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail CreekError! Bookmark not defined. Table 1-2. Status of Beneficial Uses from 303(d) ListsError! Bookmark not defined.
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail CreekError! Bookmark not defined. Table 1-2. Status of Beneficial Uses from 303(d) ListsError! Bookmark not defined. Table 2-1. Land Types, Expected Response of the Soil Resource to Different Activities,
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail CreekError! Bookmark not defined. Table 1-2. Status of Beneficial Uses from 303(d) ListsError! Bookmark not defined. Table 2-1. Land Types, Expected Response of the Soil Resource to Different Activities, Resultant Soil Erosion, and Delivery Efficiency to Surface Waters in the Project Area
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek
Table E-1. Summary of Required TMDL Elements for the Bobtail Creek TMDL Planning Area. Error! Bookmark not defined. Table 1-1. Summary of 303(d) Listings for Bobtail Creek

Table 3-4. Applicable Rules for Sediment Related PollutantsError! Bookmark not defined.
Table 3-5 Proposed Sediment Targets and Supplemental Indicators for the Bobtail Creek
Watershed Error! Bookmark not defined.
Table 3-6. Riparian Management Objective for Pool FrequencyError! Bookmark not defined.
Table 3-7. Reference Data for Substrate Fines Error! Bookmark not defined.
Table 3-8. Summary of TSS data used in evaluating TSS and impairment condition of Bobtail
CreekError! Bookmark not defined.
Table 3-9. 303(d) List Status for Bobtail Creek Error! Bookmark not defined.
Table 3-10 Riparian Management Objectives Assessed in the Bobtail Creek Watershed Error!
Bookmark not defined.
Table 3-11. Summary of Percent Fine Sediment in McNeil Core Samples on Bobtail Creek.
Error! Bookmark not defined.
Table 3-12. Summary of 2001 through 2003 Daily TSS Data Collected Near the Mouth of
Bobtail Creek Error! Bookmark not defined.
Table 3-13. Results of February 23, 2003 TSS and Flow Monitoring During Rain –On –Snow for
Main stem Sites
Table 3-14. Models Developed to Predict SEV for Different Life History Stages and Particle
Sizes (Newcombe and Jenson 1996)
Table 3-15. Bank Stability Values in the Bobtail Creek Watershed Error! Bookmark not
defined.
defined. Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined.
Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined.
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and
Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined.
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
 Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
Table 3-16. Bobtail Creek Macroinvertebrate Sampling ResultsError! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data)
Table 3-16. Bobtail Creek Macroinvertebrate Sampling Results. Error! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data). Error! Bookmark not defined. Table 5-1. Allocations for Identified Sediment Loading Sources in Bobtail Creek Watershed. Error! Bookmark not defined. Table 5-2. Road Density Risk Ratings in Miles per Square Mile. Error! Bookmark not defined. Table 5-3. Future Performance-Based Allocations. Error! Bookmark not defined. D:\BobtailTMDL\FinalBobtailSection1.doc D:\BobtailTMDL\FinalBobtailSection2.doc D:\BobtailTMDL\FinalBobtailSection3.doc D:\BobtailTMDL\FinalBobtailSection3.doc
Table 3-16. Bobtail Creek Macroinvertebrate Sampling Results. Error! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data). Error! Bookmark not defined. Table 5-1. Allocations for Identified Sediment Loading Sources in Bobtail Creek Watershed. Error! Bookmark not defined. Table 5-2. Road Density Risk Ratings in Miles per Square Mile. Error! Bookmark not defined. Table 5-3. Future Performance-Based Allocations. Error! Bookmark not defined. D:\BobtailTMDL\FinalBobtailSection1.doc D:\BobtailTMDL\FinalBobtailSection3.doc D:\BobtailTMDL\FinalBobtailSection4.doc D:\BobtailTMDL\FinalBobtailSection5.doc D:\BobtailTMDL\FinalBobtailSection5.doc D:\BobtailTMDL\FinalBobtailSection6.doc D:\BobtailTMDL\FinalBobtailSection6.doc D:\BobtailTMDL\FinalBobtailSection6.doc D:\BobtailTMDL\FinalBobtailSection7.doc
Table 3-16. Bobtail Creek Macroinvertebrate Sampling Results. Error! Bookmark not defined. Table 4-1. Results of Watershed and Fisheries NFMA Screening Process. Error! Bookmark not defined. Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data). Error! Bookmark not defined. Table 5-1. Allocations for Identified Sediment Loading Sources in Bobtail Creek Watershed. Error! Bookmark not defined. Table 5-2. Road Density Risk Ratings in Miles per Square Mile. Error! Bookmark not defined. Table 5-3. Future Performance-Based Allocations. Error! Bookmark not defined. D:\BobtailTMDL\FinalBobtailSection1.doc D:\BobtailTMDL\FinalBobtailSection2.doc D:\BobtailTMDL\FinalBobtailSection3.doc D:\BobtailTMDL\FinalBobtailSection4.doc D:\BobtailTMDL\FinalBobtailSection5.doc D:\BobtailTMDL\FinalBobtailSection5.doc

January, 2005 vi

APPENDICES

Appendix	A Stre	amflow	and	Total	Susi	pended	Solids	Data
1 ippoinain	1 Duc	ullill o vv	ullu	1 Ottai	Dub	penaca	Some	Dutta

Appendix A Streamflow and Total Suspended Solids Data
Appendix B McNeil Core Data for Bobtail Creek
Appendix C Total Suspended Solids and Turbidity Data

Appendix D Severity of Ill Effects Analysis

Appendix E Bobtail Creek Road Sediment Delivery Analysis

Appendix F Responses to Public Comments

SECTION 1.0 INTRODUCTION

This document presents a Water Quality Restoration Plan that includes Total Maximum Daily Loads (TMDL) for the Bobtail Creek Watershed in Montana. The Bobtail Creek Watershed TMDL Planning Area (TPA) drains approximately 22 square miles in northwestern Montana (Figure 1-1). Bobtail Creek is a fourth order tributary to the Kootenai River in northwest Montana. Bobtail Creek is included on Montana's 2000 and 2002 Clean Water Act section 303(d) list, and the listing information is shown in Tables 1-1 and 1-2 (MDEQ, 2000; MDEQ, 2002). The causes of impairment include bank erosion, siltation, turbidity, and other habitat alterations. The Bobtail Creek Watershed (also referred to in this document as the Bobtail TMDL Planning Area, or BTPA) is one of more than 90 TMDL planning areas in the State of Montana in which water quality is currently or was previously listed as impaired or threatened. In each of these TMDL planning areas, the State of Montana is required to develop TMDLs to reduce pollutant loading and eliminate other negative impacts to water quality in impaired and threatened waterbodies.

Table 1-1. Summary of 303(d) Listings for Bobtail Creek.

	Beneficial Uses	Probable		Stream Miles
Year	Not Supported	Causes	Probable Sources	Listed
1996	Not Listed	Not Listed	Not Listed	0
2000	Aquatic life support* Silta 2000 Cold water fishery* habi		Silviculture; Logging road construction/maintenance; Other	10
2002	Aquatic life support* Cold water fishery*	Bank Erosion; Siltation; Turbidity; Other habitat alterations	Silviculture; Logging road construction/maintenance; Other	10

^{*}These uses listed as partially supported

Table 1-2. Status of Beneficial Uses from 303(d) Lists.

Stream	Year	Agriculture	Aquatic	Cold Water	Drinking	Industrial	Primary
	Listed		Life	Fishery –	Water		Contact
			Support	Trout	Supply		(Recreation)
Bobtail	2000	Full	Partial	Partial	Not	Full	Full
Creek					Assessed		
	2002	Full	Partial	Partial	Not	Full	Full
					Assessed		

Impairment Status Definitions for Table 1-2:

Partial = Partial support of Beneficial Use.

Full = Full support of Beneficial Use.

1.1 Background and Purpose

Section 303(d) of the federal Clean Water Act and Section 75-5 of the Montana Water Quality Act provide authority and procedures for monitoring and assessing water quality in Montana's streams and lakes, and for developing restoration plans for those waters not meeting state standards. This document presents a water quality restoration plan for the Bobtail Creek watershed. This plan also defines all necessary Total Maximum Daily Loads (TMDLs) for pollutants of concern in the Bobtail watershed, as specified in the Montana 303(d) List of Impaired and Threatened Waterbodies in Need of Water Quality Restoration. A TMDL is the total amount of pollutant that a stream may receive from all sources without exceeding water quality standards. A TMDL may also be defined as a reduction in pollutant loading that results in meeting water quality standards. The 2000, and 2002 Montana 303(d) lists have included Bobtail Creek, but Bobtail Creek was not listed in 1996. This waterbody was scheduled by the Montana Department of Environmental Quality (MDEQ) for development of a restoration plan and the necessary TMDLs. Water quality impairments affecting Bobtail Creek include sediment pollution and aquatic habitat alterations. The restoration plan outlined in this document establishes quantitative restoration goals for the impaired stream for the offending pollutant. The plan provides recommendations for reducing pollutant loads and improving overall stream health, and establishes a monitoring plan and adaptive management strategy for fine-tuning the restoration plan, thus ensuring its ultimate success in restoring water quality in the Bobtail watershed.

1.2 Water Quality Restoration Planning Process

Development of a TMDL water quality restoration plan follows a series of successive steps, which are described below to provide the reader with a general understanding of the process that was used in developing the Bobtail plan.

The first step in developing a water quality restoration plan is to thoroughly evaluate and describe the water quality problems of concern. This includes understanding the characteristics and function of the watershed, and documenting the location and extent of the water quality impairments and developing water quality targets, or endpoints, that represent the applicable water quality standards. These targets are used to determine whether beneficial uses are fully supported.

The next step is to identify each of the contributing causes and sources of impairment. Pollution source assessments are performed at a watershed scale because all potential sources of water quality problems must be considered when developing the restoration plan.

The total maximum daily load of each pollutant that will meet water quality standards and allow for full support of beneficial uses is then calculated and compared to the total pollutant load derived in the source assessment. If the current load exceeds the total maximum daily load, then a pollutant reduction plan is developed. Pollutant reductions and corresponding restoration measures are allocated across the watershed planning area. This allocation process may be applied on the basis of land use (e.g. forestry, urban, mining, transportation, etc.), land ownership (federal, state, private), sub-watersheds or tributaries, or any combination of these. Specific

allocations are also established for future growth and development in the watershed, and for any natural sources of impairment that may be present.

Lastly, the water quality restoration plan must include a monitoring component designed to evaluate progress in meeting the water quality targets established by the plan, and to ensure that the restoration measures are, in fact, implemented. The monitoring strategy also provides useful information to help strengthen any assumptions made during the initial process. Taken together, the steps in the water quality restoration planning process described above constitute a water quality-based approach to water pollution control, which is also known as the Total Maximum Daily Load process. The end result becomes a "Water Quality Restoration Plan", that if implemented will result in the restoration of water quality and full support of all beneficial uses.




Figure 1-1. Bobtail Creek Watershed - Location Map.

SECTION 2.0 WATERSHED CHARACTERIZATION

This section should provide the reader with a general understanding of the environmental characteristics of the Bobtail Creek watershed that might have relevance to the 303(d)-listed causes of impairments. This section also provides some detail regarding watershed characteristics that might play a significant role in driving pollutant loading (e.g., geographic distribution of soil types, vegetative cover, land use).

2.1 Location and Regional Description

Bobtail Creek is a fourth order stream located within the Kootenai River drainage in Lincoln County, Montana (Upper Kootenai hydrologic unit 17010101) (Figure 1-1). The Bobtail Creek drainage basin encompasses nearly 22 square miles in the Purcell Mountain Range within the northern Rocky Mountain ecoregion. Elevations within the basin range from approximately 4600 feet above mean sea level in the headwaters of Bobtail Creek, to approximately 2400 feet at the confluence of Bobtail Creek and the Kootenai River.

The largest town in Lincoln County, Libby, is located approximately three miles southwest of the Bobtail Creek/Kootenai River confluence. According to the United States Census Bureau (USCB, 2004), the population of Lincoln County in 2000 was 18,837. The reported population of Libby in 2000 was 2,626. These statistics exemplify the rural and sparsely populated nature of the area.

2.2 Geological Setting

Geologic information for the watershed was obtained from the Pipestone draft EIS (USFS, 2002). The Bobtail Creek watershed is underlain by the sporadically distributed carbonate-bearing strata of the Wallace Formation. The lower portions of the stream-bearing valleys are composed of thick layers of glacial deposits (Figure 2-1). During the most recent glaciation, the Purcell Mountains were mostly covered by montane glaciers resulting in the rounded, smooth upland topography characteristic of the drainage.

Valleys and drainage bottoms in the area exhibit moderate relief with relatively stable, moderate side slope gradients. Valley floor slopes are often less than 4% with poorly developed soils derived from the parent glacial till material. Surficial soils in the area are generally comprised of a gravelly silt layer 7 to 14 inches thick, formed in volcanic ash-influenced loess.

2.3 Land Types and Soils

Land type information was obtained from the *Soil Survey of the Kootenai National Forest Area, Montana and Idaho* (Kuennen and Nielsen-Gerhardt, 1995; Figure 2-2). The soil survey identifies a number of land types within Bobtail Creek drainage, and ranks them based on soil response (erosion potential) for various timber management and road construction activities

(Table 2-1). Table 2-2 includes general descriptions of each land type found in Bobtail Creek drainage.

Land type 103, which covers much of the Bobtail Creek drainage bottom (Figure 2-2), is rated as having a moderate to severe soil erosion potential, and a high sediment delivery efficiency (Table 2-1). Sedimentation can result in this land type from changes in the channel and disruption of the soils on or adjacent to stream banks (Kuennen and Nielsen-Gerhardt, 1995). This is consistent with the location of one or more sediment loading sources and habitat alteration areas identified in this plan (Sections 30 and 32, Figure 2-2). These source areas are associated with unstable stream bank and stream channel configurations as discussed throughout this document.

2.4 Climate

The climate of the Bobtail Creek watershed is characterized by long, cool winters and relatively short, temperate summers. Precipitation within the Bobtail Creek watershed varies from an average of 33 inches at the higher elevations to 19 inches in lower elevations (Figure 2-3). Average annual precipitation in the Bobtail Creek watershed is 30.3 inches. Rain-on-snow events do occur within the basin and have been associated with culverts failures and stream channel altering runoff events.

2.5 Vegetation

The Bobtail Creek watershed is largely a forested basin (Figure 2-4). Based on the United States Geologic Survey Gap Analysis Program vegetation database, dominant cover types include mixed mesic forest and mixed broadleaf and conifer forest. For the most part, forested vegetation types cover most upland areas and border most streams in the drainage, although there are areas of converted pasturelands in the lower reaches. Other vegetation types within the drainage include relatively small areas of grasslands located primarily in the drainage bottom, shrubs, and sub alpine meadows. One small area (approximately 80 acres) in the middle reach of the drainage is identified as agricultural lands (Figure 2-4).

2.6 Land Ownership

The Bobtail Creek watershed is under a mixture of federal, state, and private ownership (Figure 2-5). US Forest Service (USFS) holdings comprise the majority of the watershed (73%) with Plum Creek Timber Company (PCTC) the second largest landowner (16%). The State of Montana owns a small percentage of the watershed (0.03%). Other privately owned lands are concentrated along the drainage bottom and constitute 11% of the watershed. Although non-PCTC private ownership is relatively small in the drainage, the significance of these lands in water quality restoration planning is significant since the mainstream of Bobtail Creek is bordered by these privately-held land parcels for approximately half (5 miles) of its entire length.




Figure 2-1. Geology of the Bobtail Creek Watershed.




Figure 2-2. Land Types of the Bobtail Creek Watershed.

Table 2-1. Land Types, Expected Response of the Soil Resource to Different Activities, Resultant Soil Erosion, and

Delivery Efficiency to Surface Waters in the Project Area (Kuennen and Nielsen-Gerhardt, 1995).

	Timber Management and Productivity		Road Construction and Maintenance				bility of the Erosion	Sedimentation
Land Types	Tractor Operation	Sediment Hazard	Maintenance of cut and fill areas	Fill material used for surfacing roads	Sediment hazard on roads	Surface layer	Lower layer	Sediment delivery efficiency
103	Soil damage	Severe	No limitations	Tread erosion	Severe	Moderate	Severe	High
105	Not listed	Not listed	No limitations	No limitations	Moderate	Moderate	Severe	Low
106	Soil damage	Moderate	No limitations	Tread erosion	Moderate	Moderate	Severe	Low
108	Soil damage	Moderate	No limitations	Tread erosion	Severe	Severe	Severe	Low
302	Slope	Moderate	Cut Bank Slough	Tread erosion	Moderate	Moderate	Moderate	Moderate
303	Rock outcrop	Moderate	No limitations	Large stones	Slight	Slight	Slight	Low
322	Soil damage	Moderate	Cut Bank Slough	Rut formation	Severe	Moderate	Severe	Low
323	No limitation	Moderate	Cut Bank Slough	Rut formation	Severe	Severe	Severe	Low
329	Soil damage	Moderate	Cut Bank Slough	Tread erosion	Moderate	Moderate	Moderate	Low
352	Complex slope, Soil damage	Moderate	Cut Bank Slough	Tread erosion	Moderate	Moderate	Moderate	Moderate
355	Rock outcrop	Moderate	No limitations	Large stones	Moderate	Moderate	Moderate	Moderate
357	Slope	Severe	Landslides	Large stones	Severe	Moderate	Moderate	High
381	Slope	Severe	Landslides	Tread erosion	Severe	Moderate	Moderate	High

Table 2-2. Descriptions of Land Types Occurring in the Bobtail Creek Watershed (Kuennen and Nielsen-Gerhardt, 1995).

Land	Landform	Slope (%)	Parent Material	Vegetation		Elevation (Ft.)	Rock	Brief Description*
Types 103	Terraces	0-15	Alluvial deposits	Moist, mixed forest	Aspect Variable	2000-3500	outcrop(%)	Gently undulating alluvial terraces at low elevations
105	Alluvial basins	0-5	Alluvial deposits	Wet meadows	Variable	2000-4000	0	Poorly drained flood plains and wet mountain meadows
106	Terraces	0-15	Glacial outwash deposits	Moist, mixed forest	Variable	2500-4000	0	Glacial outwash terraces
108	Terraces	0-15	Lacustrine deposits and glacial outwash deposits	Moist, mixed forest	Variable	2000-4000	0	Flat to gently undulating terraces at low elevations
302	Glaciated mountain slopes	30-60	Compact glacial till	Dry, mixed forest	Southerly	3000-4200	0	Convex mid-elevation mountain slopes
303	Glaciated mountain ridges	15-35	Material weathered from metasedimentary rocks	Open-grown forest	Southerly	3500-4700	50	Rounded mountain ridge tops and ridge noses
322	Moraines	15-35	Compact glacial till	Moist, mixed forest	Variable	2500-5000	0	Low relief rolling foothills
323	Moraines	15-35	Compact glacial till	Dry, mixed forest	Variable	2500-5000	0	Rolling foothills and drumlins
329	Moraines	15-35	Compact glacial till	Sub alpine forest	Variable	3000-5500	0	Rolling convex ridges
352	Glaciated mountain slopes	20-60	Compact glacial till	Moist, mixed forest	Northerly	2200-5600	0	Rounded valley side slopes
355	Glaciated mountain slopes	20-50	Compact glacial till	Moist, mixed forest	Northerly	3000-5500	20	Convex mountain slopes: Salish Cabinet and Purcell Ranges
357	Dissected glaciated mountain slopes	30-60	Compact glacial till and material weathered from metasedimentary rocks	Moist, mixed forest	Northerly	3500-5500	0	Strongly dissected long straight mountain slopes
381	Dissected glaciated mountain slopes	30-60	Compact glacial till and material weathered from metasedimentary rocks	Dry, mixed forest	Southerly	3000-5000	0	Steep mountain slopes closely spaced drainages

^{*}The brief description is metadata obtained from the Kootenai National Forest website http://www.fs.fed.us/r1/kootenai/maps/gis




Figure 2-3. Average Precipitation in the Bobtail Creek Watershed.




Figure 2-4. Vegetation Cover Types in the Bobtail Creek Watershed.




Figure 2-5. Land Ownership in the Bobtail Creek Watershed.

2.7 Land Use

Human land use activities in the basin include silviculture, residential development, agriculture (primarily grazing and hay harvest), and road development/maintenance (forest roads, county roads and private residential roads). Forestry activities have occurred throughout the basin. Residential and agricultural uses are primarily restricted to the drainage bottom in the lower half of the watershed.

Prior to the arrival of Euro-Americans, disturbance in the Bobtail Creek watershed included both natural and human-induced sources. For example, the natural fire regime resulted in periodic stand-replacing fires in the watershed. In addition, less intensive under story fires were common events. Native Americans probably influenced vegetation through under story burns intended to promote berry production. The Bobtail Creek Watershed has experienced four significant fires between 1917 and 1932, burning approximately 1500 acres. There have been no significant fires since 1932 (USFS, 2002).

Logging and associated road construction and maintenance are currently the primary land-use activities in the basin. Since the 1950s, about 24% of the drainage has been harvested with 56% of the harvest occurring in the past 20 years. There are over 128 miles of road in the drainage, equating to nearly six miles of road per square mile of watershed. An assessment of soil characteristics indicates there are over 10 square miles of sensitive soils in the 22 square mile basin. There are over 44 miles of road and 66 stream crossings on these sensitive soils. Results of a watershed screening analysis performed by the USFS (2002) indicate a severe rating for Bobtail Creek drainage based on the magnitude of landscape change experienced, and the sediment production hazard. The analysis also rated the habitat degradation potential as moderate (USFS, 2002). A logging skid-road constructed by a small-acreage private-land owner built adjacent to Bobtail Creek in the late 1980s captured Bobtail Creek during a rain-on snow events in the early 1990's have led to significant erosion and channel aggredation (Plum Creek Timber Company, 2004).

Agricultural practices have also had an adverse impact on Bobtail Creek. Livestock grazing in the stream corridor has resulted in bank erosion and riparian degradation, primarily in Township 32 N, Range 31 W, Section 32 (see Agricultural Lands in Figure 2-4).

Mining activities have been minimal in the Bobtail Creek watershed. A small amount of gravel and fill development has occurred in the basin. These developments have been located away from surface water resources and are not considered to have an appreciable impact. There have been no hard rock mining activities in the basin.

Considerable residential development has occurred along the lower half of Bobtail Creek. This residential development, and associated private road building and stream encroachment, has resulted in impacts to the Bobtail Creek channel and riparian area. Private road crossings, possibly in conjunction with increased water yield resulting from upstream land use activities, has resulted in significant channel instability and stream bank erosion.

2.8 Hydrology

Existing information on the hydrology of Bobtail Creek has been collected primarily by the US Forest Service (USFS). Hydrologic information includes: periodic stream flow and stream stage data collected near the mouth of Bobtail Creek between 1995 and 2003; daily stream stage data collected from 1996 to present; daily stream flow rates for 2000 through 2003 calculated from stream stage data; and estimates of changes in water yield resulting from silvicultural activities in the basin.

2.8.1 Stream Flow Data

Periodic stream flow and corresponding stream stage data have been collected by the USFS between 1995 and 2003 at an established monitoring station near the mouth of Bobtail Creek (site Bobtail 1: SE ½, SE ½, Section 19). These stream stage/stream flow data were used to develop a stream stage/stream flow-rating curve for site Bobtail 1. The rating curve was used to calculate daily stream flow rates from daily stream stage readings collected from 2001 through 2003. The calculated daily stream flow data for 2001 through 2003 are shown in Figure 2-6 (along with daily total suspended solids measurements). The 1995-2003 manual stream flow/stream stage measurements are included in Table 2-3. Additional stream stage data are included in Appendix A.

Peak flows in Bobtail Creek typically occur in May or June in response to snow melt runoff. The maximum measured stream flow from 1995 to 2003 was 100 cubic feet per second (cfs), recorded on February 21, 1995 (Table 2-3), while the minimum stream flow was 2.9 cfs recorded on August 23 and October 1, 2001. The maximum flow calculated from the daily stream stage data for water years 2001-2003 was 110.7 cfs on April 16, 2002, and the minimum calculated flow was 0.70 cfs on September 30, 2002 (Figure 2-6, Appendix A). The Pipestone Draft EIS (USFS, 2002) also reports that one section of Bobtail Creek, located in T32N, R31W, Section 30 goes dry on an annual basis.

Rain-on-snow (ROS) events occur sporadically in the Bobtail Creek watershed and can result in rapid increases in stream flows. For example, a ROS event in November 1990 caused major stream channel alterations, including a major shift in the channel location and washout of a number of culverts on privately owned lands. This was followed by another ROS event in April 1991. These two events, both of which occurred in Section 30, T32N, R31W (Figure 2-5), coupled with poor practices are believed to be responsible for much of the stream channel instability and excessive in-stream sediment loading responsible for impairment of Bobtail Creek (MDEQ, 1991). Several restoration projects have been completed or are currently scheduled for implementation in this area as discussed in Section 6.0.

2.8.2 Equivalent Clear-cut Area Model

In 2000, the USFS used the equivalent clear-cut area (ECA) model (USFS, 1991) to estimate the percent increase in peakflow month in Bobtail Creek resulting from vegetation removal (primarily timber harvest). TMDL-related consequences of increased water yield, and particularly percent increase in peakflow month, include potential stream bank instability, stream

channel scouring, and culvert failure. All of these consequences have the potential to directly contribute to the sediment-related impairments in Bobtail Creek. The ECA model results indicate that average annual runoff has increased by up to 10% due to land clearing activities in the drainage. The Bobtail percent peakflow increases are discussed further in Section 4.0.

Figure 2-6. Daily Stream flow and TSS Data from Mouth of Bobtail Creek (Bobtail 1) Water Years 2001-2003.




Table 2-3. Measured Stream Flow and Stream Stage Data Pairs at River Road Near Mouth of Bobtail Creek, 1995-2003.

Date	Staff Gage Ht (feet)	Stream Flow (ft ³ /sec)
2/21/95	3.12	100.0
4/21/95	1.27	14.3
5/16/95	1.17	12.1
6/29/95	1.05	7.4
7/7/95	1.00	7.8
8/8/95	0.98	4.8
9/7/95	0.90	5.1
10/23/95	0.98	5.2
12/15/95	1.90	50.0
1/25/96	1.47	23.1
3/14/96	1.60	36.4
6/6/96	0.72	28.4
6/28/96	0.28	17.6
7/23/96	0.60	10.0
7/24/96	0.50	9.2
7/30/96	0.78	7.7
8/6/96	0.80	9.9
8/22/96	0.71	7.3
10/3/96	0.68	6.2
3/18/97	1.50	38.0
6/10/97	1.51	22.7
6/23/97	1.35	21.3
7/16/97	1.90	12.3
8/26/97	2.01	8.6
3/13/98	2.15	11.6
3/26/98	2.85	50.7
5/27/98	2.80	44.3
10/28/98	1.96	4.4
3/22/99	3.15	73.4
11/8/99	2.10	7.0
4/5/00	3.20	90.9
7/17/00	2.15	7.5
5/17/01	2.13	7.2
6/6/01	2.13	5.6
8/23/01	2.03	4.1
8/23/01	1.96	2.9
10/1/01	1.89	2.9
4/8/02	3.02	78.4
6/18/02	1.82	13.6
8/19/02	1.57	5.3
3/19/03	2.08	24.6
5/14/03	- i	
5/14/03	1.79	9.5 7.4
3/29/03	1.70	1.4

All measurements recorded by USFS

2.9 Fisheries and Aquatic Life

2.9.1 Fisheries

Bobtail Creek supports an assemblage of native and introduced species of fish and other vertebrates including the tailed frog (Table 2-4). Native species include westslope cutthroat trout, a Montana species of special concern. Tributaries like Bobtail Creek provide important flow and temperature refugia for subadult bull trout from the Kootenai River. Juvenile bull trout have been recorded in Bobtail Creek but have not been observed in recent years (MFWP, 1999).

Introduced species in the Bobtail Creek watershed include rainbow trout and brook trout. Bobtail Creek supports both resident and adfluvial populations of rainbow trout. Restoring spawning grounds in the lower portions of Bobtail Creek may increase recruitment of rainbow trout to the Kootenai River, a popular recreational fishery.

Electro fishing surveys have indicated a decline in all fish species in Bobtail Creek. Table 2-5 Includes fish population data collected by the Montana Department of Fish, Wildlife and Parks in 1976 and 1997. Although the 1976 and 1997 data are not from the same stream reach, they were performed in areas of similar habitat and thus are considered to be comparable. The data show significant decreases in fish populations in Bobtail Creek in the 21 year period. Of considerable interest is the status of westslope cutthroat trout, a species of special concern, which were absent in the 1997 survey.

The combination of siltation and the presence of nonnative brook trout is a significant threat to the westslope cutthroat trout (Shepard et al., 1998).

Table 2-4. Vertebrate Species in Bobtail Creek and its Tributaries.

Family/Common	Scientific	Introduced/	Status	Stream Use
Name	Name	Native		
Fish				
Salmonidae				
Rainbow trout	Oncorhynchus mykiss	Introduced		Resident and adfluvial spawners
Westslope cutthroat trout	O. clarki lewisii	Native	Species of special concern	Resident
Brook trout	Salvelinus fontanalis	Introduced		Resident
Rainbow X cutthroat trout	O. mykiss x O. clarki			
Bull trout	Salvelinus confluentus	Native	Threatened, species of special concern	Incidental

Family/Common Name	Scientific Name	Introduced/ Native	Status	Stream Use	
Cottidae					
Slimy sculpin ¹	Cottus cognatus	Native		Unknown	
Torrent sculpin ²	Cottus rhotheus	Native	Species of special concern	Unknown	
Amphibians					
Tailed frog	Ascaphus truei	Native		Resident	

Slimy sculpin are present in Pipe Creek. Presence in Bobtail Creek has not been verified.

Table 2-5. Trout Estimates for 1976 and 1997 Electro Fishing Sections in Bobtail Creek.

Species	#/500 ft in 1976	#/mile in 1976	#/500 ft 1997	#/mile in 1997	
Rainbow Trout	123	1303	59	628	
Brook Trout	68	718	10	106	
Westslope Cutthroat Trout	33	349	0	0	
TOTAL	224	2370	69	734	

Data from MFWP, 1999

1976 survey in T32N R31W S20; 1997 survey in T31N R32W S17

2.9.2 Macroinvertebrates

Macroinvertebrate populations demonstrate good biological integrity in Bobtail Creek. Five macroinvertebrate samples collected by PCTC in July 1991 (Table 2-6) showed large proportions of stoneflies and taxa adapted to high flow and colder water conditions (clinger taxa) (Barbour et al., 1999). This indicates substrate free of siltation effects and intact riparian conditions in this section of Bobtail Creek. In should be noted however that these samples were collected immediately upstream (Section 19, T32N, R31W) of the area of significant stream channel damage resulting from the November 1990 ROS event. The samples also were collected prior to the 1997 flood event that caused significant stream channel damage upstream of Section 32. Therefore, these samples may not be representative of current macroinvertebrate populations as affected by these channel altering runoff events.

Macroinvertebrate data collected by the USFS in 2000 and 2001 (Table 2-6) show a decrease in macroinvertebrate population for specialized feeding groups (i.e., shredders and scrapers). The dominant taxa was the subfamily Chironominae. Members of this taxonomic group are typically collector-filterers and collector-gatherers. Collector-filterers and collector-gatherers are generalists, and higher numbers of these taxa are not usually found in healthy streams (Merritt

² Torrent sculpin are present in Quartz Creek. Presence in Bobtail Creek has not been verified.

and Cummins, 1978). A diversity of specialized functional feeding group organisms such as shredders and scrapers are expected in healthy streams.

It should be noted that the Plum Creek samples were taken in a fully forested reach of stream at the lower end of Plum Creek ownership where the channel bed is composed of coarse gravel (80% of bed coarser than 1 in), while the USFS samples were taken in downstream reaches of stream influenced by agriculture, grazing, and residential development where the stream gradient is much lower and the substrate is much finer (Plum Creek Timber Company, 2004).

Table 2-6. Bobtail Creek Macroinvertebrate Sampling Results.

Table 2-0. Dobtan Creek Macrom vertebrate Sampling Results.										
	Metric Guidelines*		Plum Creek Timber Company				US Forest Service			
Location		SE 1	SE 1/4, SE 1/4, SE 1/4, S19, T32N, R31W				SE 1/4, NW 1/4, NE1/4, S5, T31N, R31W			
Date		7/25/1991	7/25/1991	7/25/1991	7/25/1991	7/25/1991	10/3/2000	10/3/2000	10/3/2000	8/30/2001
Replicate/ Sample Number		1	2	3	4	5	114572	114573	114574	118552
Taxa Richness	>28	30	32	29	31	33	33	34	29	28
EPT Richness	>19	25	26	24	23	28	24	22	15	17
Biotic Index	<3	3.69	3.45	2.76	2.89	3	3.2	3.7	5.05	3.07
% Dominant	<25	39.86	38.13	28.8	25.18	31.31	19.8	25.7	31.2	40.1
% Collectors	<60	42.7	40.61	27.87	28.57	30.8	42	22	63	38
% Scrapers + Shredders	>55	47.23	50.32	59.84	55	52.77	37	32	7	7
% EPT	>70	57.73	60.07	71.99	71.25	68.38	80.3	57.5	26.5	19.9
Mountain IBI**		0.76	0.76	0.95	0.90	0.81	0.86	0.76	0.38	0.24

^{*} Mountain region metric guidelines established for Montana wadable streams

^{**} Montana Mountain Macroinvertebrate Index of Biological Integrity

>0.75 indicates full support

^{0.25 - 0.75} indicates partial support

< 0.25 indicates nonsupport

SECTION 3.0 WATER QUALITY IMPAIRMENT STATUS

This section first presents the 303(d) list status of Bobtail Creek. This summary is followed by a list of applicable water quality standards and a translation of those standards into proposed water quality goals or targets. The remainder of the section is devoted to a review of available water quality data and an updated water quality impairment status determination for Bobtail Creek.

3.1 303(d) List Status

A summary of the 303(d) list status and history of listings is provided in Tables 3-1 and 3-2. Bobtail Creek was first placed on the 303(d) list in 2000. The 2000 and 2002 303(d) lists reported that Bobtail Creek is impaired (MDEQ, 2000 and MDEQ, 2002). Listed causes of impairment include bank erosion, siltation, turbidity, and other habitat alterations. The impaired beneficial used are aquatic life support and cold water fishery.

Bank erosion and habitat alterations are considered "pollution," while siltation and turbidity are considered "pollutants." It is the Environmental Protection Agency's position that TMDLs are required only for "pollutants" that are causing or contributing to water quality impairment. However, since the habitat alteration and bank erosion do contribute to the impairment of beneficial uses (cold water fishery and aquatic life support), restoration goals (Section 6.0) are developed in this document for these impairment causes to help ensure that all beneficial uses are ultimately supported in Bobtail Creek.

The inclusion of Bobtail Creek on the 303(d) list is due, partially, to efforts of the Bobtail Watershed Group, a landowner/stakeholder group committed to the restoration of Bobtail Creek. The Watershed Group petitioned the Montana Department of Environmental Quality (MDEQ) for inclusion of Bobtail Creek on the state's 2000 303(d) list. Based on a review of the available information, MDEQ determined that there is sufficient, credible data that indicate two beneficial uses (cold water fishery and aquatic life support) are only partially supported in the entire ten miles of main stem Bobtail Creek. Although no tributaries to Bobtail Creek are listed as impaired, existing data indicate that conditions in some tributaries may contribute to impairment of Bobtail Creek. Therefore, several elements of the Bobtail Creek restoration strategy (Section 6.0) apply throughout the drainage, thereby addressing potential impairment conditions within tributary drainages as well.

Tubic 5 1. Summary of 505(a) Distings for Bobtan Creek.								
	Beneficial Uses			Stream Miles				
Year	Not Supported	Probable Causes	Probable Sources	Listed				
1996	Not Listed	Not Listed	Not Listed	0				
2000	Aquatic life support* Cold water fishery*	Bank Erosion; Siltation; Turbidity; Other habitat alterations	Silviculture; Logging road construction/maintenance; Other	10				
2002	Aquatic life support* Cold water fishery*	Bank Erosion; Siltation; Turbidity; Other habitat alterations	Silviculture; Logging road construction/maintenance; Other	10				

Table 3-1. Summary of 303(d) Listings for Bobtail Creek.

Table 3-2. Status of Beneficial Uses from 303(d) Lists.

Stream	Year	Agriculture	Aquatic	Cold		Industrial	Primary
	Listed		Life	Water	Water		Contact
			Support	Fishery –	Supply		(Recreation)
				Trout			
Bobtail	2000	Full	Partial	Partial	Not	Full	Full
Creek					Assessed		
	2002	Full	Partial	Partial	Not	Full	Full
					Assessed		

Impairment Status Definitions for Table 3-2: Partial = Partial support of Beneficial Use.

Full = Full support of Beneficial Use.

3.2 Applicable Water Quality Standards

Water quality standards include the uses designated for a waterbody, the legally enforceable standards that ensure that the uses are supported, and a non-degradation policy that protects the high quality of a waterbody. The ultimate goal of this water quality restoration plan, once implemented, is to ensure that all designated beneficial uses are fully supported and all standards are met. Water quality standards form the basis for the targets described in Section 3.3. Pollutants addressed in this Water Quality Restoration Plan include siltation and turbidity. This section provides a summary of the applicable water quality standards for each of these pollutants.

3.2.1 Classification and Beneficial Uses

Classification is the assignment (designation) of a single or group of uses to a waterbody based on the potential of the waterbody to support those uses. Designated Uses or Beneficial Uses are simple narrative descriptions of water quality expectations or water quality goals. There are a variety of "uses" of state waters including: growth and propagation of fish and associated aquatic life; drinking water; agriculture; industrial supply; and recreation and wildlife. The Montana Water Quality Act (WQA) directs the Board of Environmental Review (BER, i.e., the state) to establish a classification system for all waters of the state that includes their present (when the Act was originally written) and future most beneficial uses (Administrative Rules of Montana (ARM) 17.30.607-616) and to adopt standards to protect those uses (ARM 17.30.620-670).

^{*}These uses listed as partially supported

Montana, unlike many other states, uses a watershed based classification system with some specific exceptions. As a result, *all* waters of the state are classified and have designated uses and supporting standards. All classifications have multiple uses and in only one case (A-Closed) is a specific use (drinking water) given preference over the other designated uses. Some waters may not actually be used for a specific designated use, for example as a public drinking water supply; however, the quality of that waterbody must be maintained suitable for that designated use. When natural conditions limit or preclude a designated use, permitted point source discharges or non-point source discharges may not make the natural conditions worse.

Modification of classifications or standards that would lower a water's classification or a standard (i.e., B-1 to a B-3), or removal of a designated use because of natural conditions can only occur if the water was originally misclassified. All such modifications must be approved by the BER, and are undertaken via a Use Attainability Analysis (UAA) that must meet EPA requirements (40 CFR 131.10(g), (h) and (j)). The UAA and findings presented to the BER during rulemaking must prove that the modification is correct and all existing uses are supported. An existing use cannot be removed.

Descriptions of Montana's surface water classifications and designated beneficial uses are presented in Table 3-3. All waterbodies within the Bobtail TPA are classified as B-1.

Table 3-3. Montana Surface Water Classifications and Designated Beneficial Uses.

Classification	Designated Uses
A-CLOSED	Waters classified A-Closed are to be maintained suitable for drinking, culinary and food
CLASSIFICATION:	processing purposes after simple disinfection.
A-1 CLASSIFICATION:	Waters classified A-1 are to be maintained suitable for drinking, culinary and food processing purposes after conventional treatment for removal of naturally present impurities.
B-1 CLASSIFICATION:	Waters classified B-1 are to be maintained suitable for drinking, culinary and food processing purposes after conventional treatment; bathing, swimming and recreation; growth and propagation of salmonid fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.
B-2 CLASSIFICATION:	Waters classified B-2 are to be maintained suitable for drinking, culinary and food processing purposes after conventional treatment; bathing, swimming and recreation; growth and marginal propagation of salmonid fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.
B-3 CLASSIFICATION:	Waters classified B-3 are to be maintained suitable for drinking, culinary and food processing purposes after conventional treatment; bathing, swimming and recreation; growth and propagation of non-salmonid fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.
C-1 CLASSIFICATION:	Waters classified C-1 are to be maintained suitable for bathing, swimming and recreation; growth and propagation of salmonid fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.
C-2 CLASSIFICATION:	Waters classified C-2 are to be maintained suitable for bathing, swimming and recreation; growth and marginal propagation of salmonid fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.
C-3 CLASSIFICATION:	Waters classified C-3 are to be maintained suitable for bathing, swimming and recreation; growth and propagation of non-salmonid fishes and associated aquatic life, waterfowl and furbearers. The quality of these waters is naturally marginal for drinking, culinary and food processing purposes, agriculture and industrial water supply.
I CLASSIFICATION:	The goal of the State of Montana is to have these waters fully support the following uses: drinking, culinary and food processing purposes after conventional treatment; bathing, swimming and recreation; growth and propagation of fishes and associated aquatic life, waterfowl and furbearers; and agricultural and industrial water supply.

3.2.2 Standards

In addition to the Use Classifications described above, Montana's water quality standards include numeric and narrative criteria as well as a nondegradation policy.

<u>Numeric</u> surface water quality standards have been developed for many parameters to protect human health and aquatic life. These standards are in the Department Circular WQB-7 (MDEQ, 2004). The numeric human health standards have been developed for parameters determined to be toxic, carcinogenic, or harmful and have been established at levels to be protective of long-term (i.e., life long) exposures as well as through direct contact such as swimming.

The numeric aquatic life standards include chronic and acute values that are based on extensive laboratory studies including a wide variety of potentially affected species, a variety of life stages and durations of exposure. Chronic aquatic life standards are protective of long-term exposure to a parameter. The protection afforded by the chronic standards includes detrimental effects to reproduction, early life stage survival and growth rates. In most cases the chronic standard is more stringent than the corresponding acute standard. Acute aquatic life standards are protective of short-term exposures to a parameter and are not to be exceeded.

High quality waters are afforded an additional level of protection by the <u>nondegradation</u> rules (ARM 17.30.701 et. seq.,) and in statute (75-5-303 MCA). Changes in water quality must be "non-significant" or an authorization to degrade must be granted by the Department. However under no circumstance may standards be exceeded. It is important to note that, waters that meet or are of better quality than a standard are high quality for that parameter, and nondegradation policies apply to new or increased discharges to that the waterbody.

<u>Narrative</u> standards have been developed for substances or conditions for which sufficient information does not exist to develop specific numeric standards. The term "Narrative Standards" commonly refers to the General Prohibitions in ARM 17.30.637 and other descriptive portions of the surface water quality standards. The General Prohibitions are also called the "free from" standards; that is, the surface waters of the state must be free from substances attributable to discharges, including thermal pollution, that impair the beneficial uses of a waterbody. Uses may be impaired by toxic or harmful conditions (from one or a combination of parameters) or conditions that produce undesirable aquatic life. Undesirable aquatic life includes bacteria, fungi and algae.

The standards applicable to the list of pollutants addressed in the Bobtail TPA are summarized below.

3.2.2.1 Sediment

Sediment (i.e., coarse and fine bed sediment) and suspended sediment are addressed via the narrative criteria identified in Table 3-4. The relevant narrative criteria do not allow for harmful or other undesirable conditions related to increases above naturally occurring levels or from discharges to state surface waters. This is interpreted to mean that water quality goals should strive toward a reference condition that reflects a waterbody's greatest potential for water quality

given current and historic land use activities where all reasonable land, soil, and water conservation practices have been applied and resulting conditions are not harmful, detrimental or injurious to beneficial uses (see definitions in Table 3-4).

3.2.2.2 Turbidity

The allowable changes in turbidity (above natural) is a rather small 5 or 10 nephelometric turbidity units (NTU), see Table 3-4. The likely direct effects of increased turbidity are on recreation and aesthetics and drinking water supplies. Indirectly increased turbidity can be linked to an increased pathogen potential, total recoverable metals concentration and increased total suspended sediment. Turbidity cannot be equated with other parameters. Turbidity is a measure of light scatter in water. Suspended or colloidal solids like phytoplankton, metal precipitates or clay may cause the light scatter. In some cases it may be a useful and easily measured surrogate for total suspended solids (TSS) but only after paired flow and seasonal (full hydrograph) turbidity and TSS data have been collected and a statistically significant correlation exists.

Table 3-4. Applicable Rules for Sediment Related Pollutants.

Rule(s)	Standard
17.30.623(2)	No person may violate the following specific water quality standards for waters classified B-1.
17.30.623(2)(f)	No increases are allowed above naturally occurring concentrations of sediment or suspended sediment (except a permitted in 75-5-318, MCA), settleable solids, oils, or floating solids, which will or are likely to create a nuisance or render the waters harmful, detrimental, or injurious to public health, recreation, safety, welfare, livestock, wild animals, birds, fish, or other wildlife.
17.30.637(1)	State surface waters must be free from substances attributable to municipal, industrial, agricultural practices or other discharges that will.
17.30.637(1)(a)	Settle to form objectionable sludge deposits or emulsions beneath the surface of the water or upon adjoining shorelines.
17.30.637(1)(d)	Create concentrations or combinations of materials that are toxic or harmful to human, animal, plant, or aquatic life.
	The maximum allowable increase above naturally occurring turbidity is: 0 NTU for A-closed; 5 NTU for A-1, B-1, and C-1; 10 NTU for B-2, C-2, and C-3).
17.30.602(17)	"Naturally occurring" means conditions or material present from runoff or percolation over which man has no control or from developed land where all reasonable land, soil, and water conservation practices have been applied.
17.30.602(21)	"Reasonable land, soil, and water conservation practices" means methods, measures, or practices that protect present and reasonably anticipated beneficial uses. These practices include but are not limited to structural and nonstructural controls and operation and maintenance procedures. Appropriate practices may be applied before, during, or after pollution-producing activities.

3.3 Water Quality Targets and Supplemental Indicators

To develop a TMDL, it is necessary to establish quantitative water quality goals referred to in this document as targets. TMDL targets must represent the applicable numeric or narrative water quality standards and full support of all associated beneficial uses. For many pollutants with established numeric water quality standards, the water quality standard is used directly as the TMDL target. Where targets are established for pollutants with only narrative standards, the target must be a waterbody-specific, measurable interpretation of the narrative standard.

In this Water Quality Restoration Plan siltation and turbidity are jointly considered, as they are derived from the same sources and jointly preclude full support of beneficial uses. Additionally, there is nothing to be gained by addressing these two causes independently in this specific watershed. For the remainder of this document, unless otherwise specifically stated, siltation and turbidity will be referred to jointly as "sediment".

In the case of the Bobtail TPA, there is no single parameter that can be applied alone to provide a direct measure of beneficial use impairment associated with sediment or nutrients. As a result, a suite of targets and supplemental indicators has been selected to help determine when impairments are present (Tables 3-5). In consideration of the available data for the Bobtail watershed, the targets are the most reliable and robust measures of impairment and beneficial use support available. As described in the one-by-one discussions of individual targets presented in the following paragraphs, there is a documented relationship between the selected target values and beneficial use support, or sufficient reference data are available to establish a threshold value representing "full support of beneficial uses" for this watershed.

In addition to having a documented relationship with the suspected impaired beneficial use, the targets have direct relevance to the pollutant of concern. The targets, therefore, are relied on as threshold values that if exceeded (based on sufficient data), indicate water quality impairment. The targets are also applied as water quality goals by which the ultimate success of implementation of this plan will be measured in the future.

The supplemental indicators provide supporting and/or collaborative information when used in combination with the targets in determining impairment status. In addition, some of the supplemental indicators are necessary to determine whether exceedances of targets are a result of natural versus anthropogenic causes. However, the proposed supplemental indicators are not sufficiently reliable to be used alone as a measure of impairment because (1) the cause-effect relationship between the supplemental indicator(s) and beneficial use impairments is weak or uncertain; (2) the supplemental indicator(s) cannot be used to isolate impairment associated with individual pollutants (e.g., to differentiate between an impairment caused by excessive levels of sediment and an impairment caused by high concentrations of metals); or (3) there is too much uncertainty associated with the supplemental indicator(s) to have a high level of confidence in the result.

Table 3-5 Proposed Sediment Targets and Supplemental Indicators for the Bobtail Creek Watershed.

Target	Threshold				
	Rosgen Stream Type	Width-to-depth ratio			
Width-to-Depth Ratios	В	10 to 28			
	C	10 to 21			
	Bankfull Width (ft)	Pools per mile			
Pool Frequency	<10	96			
1 ooi Frequency	10-20	56			
	20-25	47			
Riffle Stability Index	A range of 45 to 75 in Rosgen B channel types.				
Wolman Pebble Counts	Frequency of less than 20 Percent for sizes < 2 mm				
McNeil Core Percentage of	28 Percent or less				
Subsurface Fine Sediment					
(<6.35 mm)					
Supplemental Indicators	Recommended Values				
Total Suspended Solids	An average value of 5.7 mg/L				
	A maximum value not to excee	d value of 75 mg/L			
Bank Stability	≥80%				
Montana Mountain	> 75 Percent				
Macroinvertebrate Index of This shows full support based on Montana					
Biological Integrity	Department of Environmental Quality protocol.				

Targets and Supplemental Indicators Applied to Beneficial Use Impairment Determinations

The beneficial use impairment determinations presented in Section 3.4 are based a weight-ofevidence approach in combination with the application of best professional judgment. The weight-of-evidence approach outlined in Figure 3-1, is applied as follows. If none of the target values are exceeded, the water is considered to be fully supporting its beneficial uses and a TMDL is not required. This is true even if one or more of the supplemental indicator values are exceeded. On the other hand, if one or more of the target values are exceeded, the circumstances around the exceedance are investigated and the supplemental indicators are used to provide additional information to support a determination of impairment/non-impairment. In this case, the circumstances around the exceedance of a target value are investigated and it is not automatically assumed that the exceedance represents anthropogenic impairment (e.g., Are the data reliable and representative of the entire reach? Is the exceedance a result of natural causes such as floods, drought, fire, or the physical character of the watershed?). This is also the case where the supplemental indicators assist by providing collaborative and supplemental information, and the weight-of-evidence of the complete suite of targets and supplemental indicators is used to make the impairment determination. A conservative approach is used if the supplemental indicators are inconclusive. When the supplemental indicators support neither impairment nor non-impairment, it is assumed that the water is impaired.




Figure 3-1. Weight-of-Evidence Approach for Determining Beneficial Use Impairments.

Targets as Water Quality Goals

In accordance with the Montana Water Quality Act (MCA 75-5-703(7) and (9)), the MDEQ is required to assess the waters for which TMDLs have been completed to determine whether compliance with water quality standards has been attained. This assessment will use the suite of targets specified in Table 3-5 to measure compliance with water quality standards and achievement of full support of all applicable beneficial uses (Figure 3-2). The supplemental indicators will not be used directly as water quality goals to measure the success of this water quality restoration plan. If all of the target threshold values are met, it will be assumed that beneficial uses are fully supported and water quality standards have been achieved. Alternatively, if one or more of the target threshold values are exceeded, it will be assumed that beneficial uses are not fully supported and water quality standards have not been achieved. However, it will not be automatically assumed that implementation of a TMDL was unsuccessful just because one or more of the target threshold values have been exceeded. As noted above, the circumstances around the exceedance will be investigated. Supplemental indicators and/or other potentially useful information will be used to evaluate the specific conditions. For example, might the exceedance be a result of natural causes such as floods, drought, fire, or the physical character of the watershed? In addition, in accordance with MCA 75-5-703(9), an evaluation will be conducted to determine whether:

- The implementation of a new or improved suite of control measures is necessary.
- More time is needed to achieve water quality standards.
- Revisions to components of the TMDL are necessary.

Detailed discussions regarding each of the targets and supplemental indicators are presented below.




Figure 3-2. Methodology for Determining Compliance with Water Quality Standards.

3.3.1 Sediment Targets

The proposed sediment targets include width-to-depth ratios, pool frequency, riffle stability index, Wolman pebble counts, and McNeil core substrate fines.

Width-to-Depth Ratios

Bankfull width/depth ratios describe the cross-sectional shape of stream channels and provide a measure of channel stability. As the width/depth ratio increases, the stream becomes wider and shallower. Accelerated stream bank erosion and an increased sediment supply accompany increases in the width/depth ratio (Rosgen, 1996). Lower width/depth ratios are associated with the presence of deep pools that provide better thermal protection for coldwater fish (Riggers et al., 1998).

The Kootenai National Forest developed a set of reference streams for bankfull width to depth ratios, where the upper end of one standard deviation is a ratio of 28 for B streams with average bankfull widths of 16 feet; and the upper end of one standard deviation is a ratio of 21 for C streams with average bankfull width of 24 feet. Based on recommendations from the U.S. Forest Service (2002) a minimum width to depth ratio of 10 is expected in both B and C streams. Therefore, a width to depth ratio reference range of 10 to 28 in B reaches and 10 to 21 in C reaches of the Bobtail TPA are used for targets.

The proposed width/depth ratio targets would help to address sediment supply issues associated with unstable stream banks, fish habitat issues associated with pool abundance, and thermal problems contributed in part by high surface area to volume ratios. Recovery of width to depth ratios may take decades, and long-term monitoring will be necessary to verify the relationship between this target and full support of designated beneficial uses. Monitoring long-term trends in width/depth ratios should be performed at permanently monumented cross-sections. The cross-sections should be established in riffles of unchannelized reaches. The width-to-depth ratio targets are intended to be applied as appropriate representative cross section ratios averaged over the segment length.

Pool Frequency

Pool frequency (pools/mile) is a critical measure of the availability of rearing and refugia habitat for salmonids in the Bobtail TPA. Pools provide the habitat for where salmonids spend the majority of their lives. They provide resting habitat for adult fish and rearing habitat for juveniles and sub-adults, and are in some way important to nearly all life stages of salmonids (Bjorn and Reiser, 1991). Pools provide hiding cover, thermal and hydraulic refugia, and feeding areas where energy expenditure is low. An abundance of high quality pools is necessary to sustain healthy salmonid populations. The frequency of high quality pool habitat in a stream can be affected by land management activities such as logging, mining, road construction, and grazing (Bilby, 1984, Clifton, 1989; Sedell and Froggaht, 1984). This in turn can affect fish populations (Riggers et al., 1998).

The Pipestone Draft Environmental Impact Statement (USFS, 2002) identifies the Riparian Management Objectives (RMO) from the Inland Native Fish Strategy (USFS, 1995) for pool frequency that apply to streams in the Bobtail TPA. Pool frequency RMOs vary by stream width and are presented in Table 3-6.

Table 3-6. Riparian Management Objective for Pool Frequency.

Bankfull Width (ft)	Pools per mile
<10	96
10-20	56
20-25	47

Riffle Stability Index

The riffle stability index provides an estimate of sediment supply in a watershed. Kappesser (2002) found that riffle stability index values between 40 and 70 in B-channels indicate that a stream's sediment transport capacity is in dynamic equilibrium with its sediment supply. Values between 70 and 85 indicate that sediment supplies are moderately high, while values greater than 85 are suggestive of excessively sediment-loaded streams. Rowe et al. (2003) reviewed the RSI as a potential target variable for sediment TMDLs in Idaho and, based largely on Kappesser's work, recommended an RSI target of < 70. The authors cautioned, however, that this value is most applicable in the belt geology of northern Idaho and would thus likely have to be adjusted in other geologies. In developing sediment TMDLs for the St. Regis River and several of its tributaries, the Montana DEQ conducted an assessment of riffle stability index values, primarily

in C-channels. Riffle stability index values of 75 and greater were documented in managed subwatersheds within the St. Regis River drainage. Watersheds were considered to be "managed" in the study if roads existed above a stream survey site. Other managed and unmanaged sub-watersheds within St. Regis drainage produced riffle stability index values of between 46 and 75. The results indicated that there was more mobile bedload in managed areas of the St. Regis watershed as compared to less developed stream segments. The MDEQ study resulted in a recommended RSI target of 45 – 75. The 45 minimum was included because in some cases, heavily riprapped stream reaches for example, a very low RSI can indicate an unnaturally high sediment transport capacity. Based on Kappesser (2002) and the unpublished St. Regis TMDL, the RSI for the Bobtail TPA will be 45 to 75 on Rosgen B channel types.

Wolman Pebble Counts - Percent Surface Substrate Fines < 2mm

Research by macroinvertebrate specialists (Relyea, personal communication, as cited in EPA, 2004) indicates that surface fines (< 2 mm) need to be elevated to levels between 20 - 40%, based on pebble count data, to result in a decrease in macroinvertebrate richness. Development of this target is one of the important criteria for evaluating whether or not excess sediment loading indicates a "siltation" type of impairment cause. A frequency below 20%, for sizes less than 2 mm in riffles, is the target for Wolman pebble count results.

McNeil Core – Percent Subsurface Substrate Fines < 6.35 mm

McNeil core sampling involves the use of a standard 15.2-centimeter hollow core sampler to collect subsurface sediments in stream bottom substrates (Deleray et al., 1999). Measurements of the size range of subsurface substrate material in the streambed are indicative of salmonid spawning and incubation habitat quality. Substrate fine materials smaller than 6.35 millimeters are commonly used to describe spawning gravel quality, and they include the size range typically generated by land management activities (Weaver and Fraley, 1991). Weaver and Fraley (1991) observed a significant inverse relationship between the percentage of material smaller than 6.35 millimeters and the emergence success of westslope cutthroat trout and bull trout. Further, they demonstrated a linkage between ground-disturbing activities and spawning habitat quality. Streambed sediments < 6.35 mm in size can be detrimental to spawning by smothering eggs or entombing alevins. Based on relationships between percent fines and embryo survival developed for cutthroat trout (Weaver and Fraley, 1991) and rainbow trout (Irving and Bjornn, 1984), the fine sediment concentrations observed in Bobtail Creek equate to an estimated survival to emergence for embryos of between 26% for westslope cutthroat trout and 35% for rainbow trout.

Table 3-7 presents reference data for substrate fines. MDEQ and the Flathead National Forest established McNeil core percent fine reference conditions for the Big Creek TMDL, of less than or equal to 30 percent substrate fines (< 6.35 mm) for a McNeil core sample. Most other TMDL target conditions are based on local reference conditions that show achievable substrate fines values typically in the range of 25 to 35 percent fines less than 6.35 mm.

Results from McNeil Core sampling by the Kootenai National Forest show average percent substrate fines at reference sites monitored from 1997 – 2003 ranged from 17 to 29 percent with similar median values (Table 3-7). The 75th percentile values typically fall below 28 percent.

January, 2005

Therefore, a value of 28 percent substrate fines less than 6.35 mm is proposed as a target for the Bobtail TPA.

Table 3-7. Reference Data for Substrate Fines.

Source	rce Percent Fines						
McNeil Core Substrate Fines (<6.35 mm)							
Big Creek TMDL	30						
Other TMDL targets in Western Montana	25 - 35						
Kootenai Sampling (1997-2003)	Average	Stnd Dev.	75 th Percentile	Median			
Bear Creek	19.0	6.0	22.5	19.5			
Flattail Creek	26.7	7.2	28.3	26.0			
Himes Creek #1	29.1	4.4	28.2	27.5			
Libby	25.4	4.5	27.9	26.0			
West Fork Quartz (Upper)	17.1	3.6	18.0	16.5			
Upper Silver Butte	21.0	4.3	23	21.5			

3.3.2 Supplemental Indicators

As stated previously, the proposed supplemental indicators are not sufficiently robust to be used alone as a measure of sediment impairment in Bobtail Creek. These indicators are used as supplemental information, in combination with the targets, to provide better definition of potential sediment impairments. The supplemental indicators, total suspended solids, bank stability, and macroinvertebrates are discussed below. As previously stated, these indicators will be used in the future, if the targets are not met, in evaluating the circumstances around the exceedance of the target. In the future, other supplemental indicators may also be identified.

Total Suspended Solids

The USFS has conducted frequent TSS monitoring in Bobtail Creek over the past several years including daily TSS sampling near the mouth for water years 2001 through 2003. Total suspended solids (TSS) and turbidity (i.e., one of the listed causes of impairment), are interrelated since TSS is the primary cause of elevated turbidity in Bobtail Creek. Because TSS and turbidity are closely associated in terms of causes, sources, and related impairments, they are linked in this document. Figure 3-3 shows the close correlation between TSS and turbidity based on simultaneous TSS and turbidity measurements obtained from Bobtail Creek.

January, 2005




Figure 3-3. Comparison of Simultaneous Measurements of TSS and Turbidity in Bobtail Creek.

A plan for addressing TSS and turbidity must identify the extent to which these pollutants are impacting beneficial uses, and determine the degree to which the pollutants are elevated over baseline or "natural" levels. To provide for a comparison of the available TSS data from Bobtail Creek and reference or "least impaired" streams, data for other drainages were obtained from the USGS, with the following selection criteria applied:

- 1) Drainages must range from 1 to 45 square miles in area;
- 2) Drainages must be within the Columbia River drainage in Montana; and
- 3) Drainages must meet the criteria of least impaired reference conditions.

A total of 12 drainages meeting the screening criteria were identified in the United States Geologic Survey (USGS) database for which TSS data were available. All 12 drainages are located in western Montana with seven of the sites located in northwest Montana. The reference drainages are listed in Table 3-8 along with their individual drainages areas, number of TSS values available, and the minimum, maximum and mean TSS values from the USGS database. Bobtail Creek TSS data are also summarized in Table 3-8. The complete TSS database for Bobtail Creek and the 12 reference drainages are included in Appendix C.

Overall, TSS values were relatively low in the reference drainages, with reference stream values ranging from 1.0 to 75 mg/L. The average of the 186 reference drainage values was 5.7 mg/L, and the median, or mid value, was 3.0 mg/L (Table 3-8). This trend of relatively low average and

median TSS values and significantly greater maximum values is typical of TSS concentration trends in mountainous streams. The higher TSS concentrations generally occur during high flow events resulting from snowmelt runoff and/or high intensity rainfall events. Although it is normal for TSS concentrations to increase during high flow periods, significant increases during high flow events usually indicate some level of land disturbance in a drainage.

The TSS supplemental indicator value for Bobtail Creek will be an average value of 5.7 mg/L with a maximum not to exceed value of 75 mg/L.

Table 3-8. Summary of TSS data used in evaluating TSS and impairment condition of Bobtail Creek.

	Site		Drainage Area	No. of	Min	Max	Mean	Median
Source	Number	Site Name	(sq mi)	Samples	mg/L	mg/L	mg/L	mg/L
Bobtail Cree	ek Data							
		Bobtail Creek Near Mouth						
USFS		(includes sites Bobtail 1,	22	1131	0.002	14786	125.3	2
USFS		Bobtail 2, and Bobtail Ck at	22	1131	0.002	14/60	123.3	2
		River Road)						
Reference S	tream Data							
USGS	12303400	Ross Creek near Troy MT	24	19	1	4	1.9	2
USGS	12303430	Stanley Creek near Troy MT	13	19	1	3	1.7	1
USGS	12353400	Negro Gulch near Alberton MT	8	9	2	4	3.4	4
USGS	12370900	Teepee Creek near Polson MT	2	15	1	14	6.2	6
USGS	12374250	Mill Cr ab Bassoo Cr near Niarada MT	20	11	1	26	8.6	8
USGS	12375900	South Crow Creek near Ronan MT	8	16	1	26	4.5	2
USGS	12377150	Mission Cr ab Reservoir near St. Ignatius MT	12	22	1	75	8.3	3
USGS	12383500	Big Knife Creek near Arlee MT	7	12	2	38	8.1	4
USGS	12387450	Valley Creek near Arlee MT	15	15	1	24	6.6	4
USGS	12388400	Revais Cr below West Fork near Dixon MT	23	28	1	28	4.8	2
USGS	12388650	Camas Creek near Hot Springs MT	4	16	1	41	10.9	7
USGS	12389450	West Fork Thompson River near Thompson Falls, MT	36	4	1	4	2.5	2.5
Sum	Summary for All Reference Streams Combined			186	1	75	5.7	3

Complete data in Appendix C

Bank Stability

The US Forest Service analyzed several Riparian Management Objectives (RMOs) (Section 3.4.2). From this analysis pool frequency, width-to-depth ratios, and riffle stability index targets were created. Another identified RMO was bank stability. Bank stabilities of less than 80% are considered impaired by the Inland Native Fish Strategy Standards (USFS, 1995). The proposed supplemental indicator value for bank stability is greater than or equal to 80%.

Macroinvertebrates

Macroinvertebrate data help to provide a better understanding of the cumulative and intermittent impacts that might have occurred over time in a stream, and they are a direct measure of the aquatic life beneficial use. Analytical methods used to interpret macroinvertebrate data are constantly evolving, based on new data and information offered from research. With this in mind, the macroinvertebrate supplemental indicator is intended to integrate multiple stressors and pollutants to provide an assessment of the overall aquatic life use condition. The macroinvertebrate targets are also intended to provide information regarding which pollutant(s) might be causing the impairment.

Macroinvertebrate data are typically organized according to a multimetric index of biological integrity (IBI), or a "multimetric index". In Montana the Mountain Index of Biological Integrity (IBI) (MDEQ, 1998) has been developed. Individual metrics (e.g. clinger taxa, percent EPT) are designed to indicate biological response to human-induced stressors. Scores are assigned to individual metrics, summed across several of them, and the total used to compare among samples or sampling sites. Three possible multimetric indices have been developed for Montana: 1) Mountain; 2) Foothill Valley and Plains (MFVP); and 3) Plains. The Mountain IBI was chosen for streams in the Bobtail TPA based on site characteristics, primarily elevation. MDEQ uses a scoring procedure with the maximum possible score is 100 percent. Total scores greater than 75 percent are considered within the range of anticipated natural variability and represent full support of their beneficial use (aquatic life). Additionally, data collected in 1991 (Section 3.4.2) shows that Bobtail Creek has the ability to reach the 75% criteria; therefore, a score representing full support (>75 percent) is proposed as the Mountain IBI target.

3.3.3 Uncertainty Associated with Targets and Supplemental Indicators

The targets and supplemental indicators were developed to represent desired conditions and achievement of water quality standards. However, a shortage of local reference data and the inherent variability in natural conditions in aquatic ecosystems combine to introduce a degree of uncertainty into the targets and indicators. As a result, reference conditions upon which the target thresholds were based may not accurately represent local potential, and thus targets may be difficult to achieve. In response, targets and supplemental indicators will be evaluated at least every five years (Section 7.0). This evaluation will include consideration of target suitability and could result in modification of the targets as more suitable reference data become available. Nevertheless, the target and supplemental indicator thresholds presented in this document are reasonable approximations of reference conditions based on the available data.

January, 2005

3.4 Current Water Quality Impairment Status for Bobtail Creek

The following section summarizes relevant data for Bobtail Creek.

3.4.1 Summary of the 303(d) List

The 2000 and 2002 Montana 303(d) lists reported that aquatic life and cold-water fishery beneficial uses were partially supported in Bobtail Creek due to bank erosion, siltation, turbidity, and other habitat alterations. The probable sources of the problems were listed as silviculture, logging road construction and maintenance, and "other". The 303(d) status of Bobtail Creek is summarized in Table 3-9.

Table 3-9. 303(d) List Status for Bobtail Creek.

Year	Use Support Status	Probable Impaired Uses	Probable Causes of Impairment	Probable Sources of Impairment	Stream Miles Listed
1996	Not Listed	Not Listed	Not Listed	Not Listed	0
2000	Partial Support	Aquatic life support Cold water fishery	Bank Erosion, Siltation, Turbidity, Other habitat alterations	Silviculture, Logging road construction/maintenance, Other	10
2002	Partial Support	Aquatic life support Cold water fishery	Bank Erosion, Siltation, Turbidity, Other habitat alterations	Silviculture, Logging road construction/maintenance, Other	10

3.4.2 Target and Supplemental Indicator Data

As described in Section 3.3, a suite of targets representing applicable narrative water quality standards has been developed for listed streams in the Bobtail TPA. A review of available data for Bobtail Creek is provided below. Targets and supplemental indicators for which current data are available include: width-to-depth ratios, pool frequency, riffle stability index, Wolman pebble counts, McNeil core values, total suspended solids, bank erosion, and macroinvertebrates.

Width-to-Depth Ratios

The U.S. Forest Service measured width-to-depth ratios at eighteen locations (Figure 3-4) in the Bobtail TPA during the Pipestone EIS Riparian Management Objectives (RMO) assessment (USFS 2002). In two Rosgen B reaches the target of a range between 10 and 28 was not met, and in one Rosgen C reach the target of 10 to 21 was not met. The results of the RMO analysis are presented in Table 3-10.

Pool Frequency

The U.S. Forest Service measured pool frequency at eighteen locations (Figure 3-4) in the Bobtail TPA during the Pipestone EIS assessment (USFS, 2002). In stream reaches with a width of less

than ten feet, three reaches did not meet the target of 96 pools per mile. In stream reaches of widths between ten and twenty feet, four reaches did not meet the target of 56 pools per mile. The only stream over twenty feet in width did not meet the target of 47 pools per mile. The results of this RMO analysis are presented in Table 3-9.

Riffle Stability Index

The U.S. Forest Service measured the riffle stability index at several locations (Figure 3-4) in the Bobtail TPA during the Pipestone EIS assessment (USFS, 2002). The indicator range of 45 to 75 RSI, which applies to Rosgen B streams, was not met in five of six reaches. The results of this analysis are presented in Table 3-10.

Table 3-10 Riparian Management Objectives Assessed in the Bobtail Creek Watershed.

Site	Rosgen Type	Bankfull Width (ft)	Pools per mile	LWD per Foot	% Bank Stability	Width/ Depth Ratio	Riffle Stability Index
1- Bobtail Cr.	B4	16.3	72	1/31	100	23	73
2- Bobtail Trb	A4	6.2	117	1/30	100	8.9	79
3- Bobtail Cr.	B4	18.8	88	0/240	100	28	85
4- Bobtail Cr.	B4	19	53	1/39	100	17	83
5- Bobtail Cr.	C4	10.8	64	1/21	92	18.6	90
7- Bobtail Cr.	B4	7.7	52	1/9	100	12	89
8- Terge Cr.	A4a+	2.5	330	1/10	100	8.9	88
9- Bobtail Cr.	B4a	5.5	377	0/50	100	11.2	87
10- Bobtail Cr.	E4b	9.8	79	1/200	74	7.3	
11- Bobtail Cr.	B4c	23.7	30	1/13	97	57	
12- Bobtail Cr.	C4	18.9	45	1/12	78	26	
13- Bobtail Cr.	B4c	10.3	Dry	ı	-	26	
14- Bobtail Cr.	B4	17.0	15	1/26	69	18	
15- Bobtail Cr.	C4	12.0	66	1/120	100	12	
1- Bull Cr.	E6	4.2	176	1/8	05	6.6	
2- Bull Cr.	B4a	8.5	195	1/9	100	10.4	
6- Bull Cr.	B4	7.3	293	1/22	100	5.8	84
6a- Bull Cr.	G4	5.2	0	1/10	17	7.3	94


Shaded values do not meet target or indicator thresholds.

Wolman Pebble Counts - Percent Surface Substrate Fines < 2mm

Pebble counts have been conducted at numerous locations throughout the Bobtail Creek watershed and are used here to identify areas exhibiting excessive deposition of fine sediment. Pebble counts were performed by the USFS in 19 areas of Bobtail Creek in 1994, 1995 and 1997 (Figure 3-5). Reaches with the highest percentages of fine particles include reaches 5, 9, and 10 (Figure 3-5). Reach 5 (lower) and reach 10 do not meet the target of particles < 2 mm having a frequency of less than 20%.

Figure 3-4. U. S. Forest Service Riparian Management Objectives Sites.

Bobtail Creek TMDL Planning Area U.S. Forest Service Riparian Managment Objectives Sites







Figure 3-5. Pebble Count Results for Bobtail Creek Watershed.



McNeil Core Samples

The US Forest Service collected McNeil core samples from one location on Bobtail Creek in 1994, 2000, 2001, 2002 and 2003. The sample site is located approximately 0.6 miles upstream of the confluence with Bull Creek in the SE ¼ of Section 5, T31N, R31W (see stream core sample site, Figure 3-6). The 1994 sampling included three replicate samples from this site, while the 2000, 2001, 2002 and 2003 sampling included 10 replicate samples each. The McNeil core sampling results are summarized in Table 3-11, and the complete dataset is included in Appendix B.

As shown in Table 3-11, a total of 43 core samples were collected between 1994 and 2003. The percentage of fine sediment particles (<6.35 mm in diameter) in these samples range from 15% to 57%. The average percent fines for each year were very consistent, with the annual averages ranging from 32.7% in 2002, to 34.9% in 1994. The average percent fines content for the entire database is 33.8%. This value is above the proposed target of 28%.

Table 3-11. Summary of Percent Fine Sediment in McNeil Core Samples on Bobtail Creek.

	% Fine Sediment (<6.35mm) in Individual Replicate Samples										
Year	Replic ate 1	Replicate 2	Replicate 3	Replicate 4	Replicate 5	Replicate 6	Replicate 7	Replicate 8	Replicate 9	Replicate 10	Average
1994	28.5%	40.7%	35.3%	na	na	na	na	na	na	Na	34.9%
2000	39%	41%	33%	40%	30%	25%	36%	30%	35%	39%	34.8%
2001	38%	30%	31%	34%	25%	33.7%	31%	40.8%	36%	31%	33.1%
2002	28%	40%	39%	25%	37%	24%	31%	28%	43%	32%	32.7%
2003	27%	38%	51%	26%	32%	57%	29%	26%	33%	15%	33.4%
			on 5 T21N D2						Overall	Average	33.8%

All samples collected in NE¼ of Section 5, T31N, R31W (see Figure 3-6)

All samples collected by USFS Complete database included in Appendix B

January, 2005 44




Figure 3-6. Bobtail Creek Watershed Sampling Sites.

Total Suspended Solids

The following evaluation of impairment conditions in Bobtail Creek, relative to TSS, involved numerous steps and multiple lines of evidence including:

- 1) Compilation and review of existing TSS and turbidity data from Bobtail Creek;
- 2) Comparison of Bobtail Creek TSS values to TSS values from other "least impaired" watersheds; and
- 3) Assessment of potential effects of TSS on aquatic life in Bobtail Creek.

Compilation of Existing TSS/Turbidity Data

As discussed in Section 2.0, the majority of hydrologic and water quality data available from Bobtail Creek drainage was collected by the USFS. The USFS has conducted frequent TSS monitoring in Bobtail Creek over the past several years, with daily TSS data collected near the mouth of Bobtail Creek for water years 2001 through 2003 (see data in Figure 2-6). Daily TSS samples were collected at a gauging station located in the SE¹/₄ of Section 19 near the mouth of Bobtail Creek (Figure 3-6).

Table 3-12 provides yearly summaries of the daily TSS data collected near the mouth of Bobtail Creek. Maximum annual TSS values range from 104 mg/L in 2001 to 14,786 mg/L in 2002, while average annual values ranged from 3.9 mg/L in 2001 to 370 mg/L in 2002.

Table 3-12. Summary of 2001 through 2003 Daily TSS Data Collected Near the Mouth of Bobtail Creek.

1120 Will of 2 00 Will of Vill									
Year	No. Samples	Min	Max	Mean	Median				
2001	365	1.3	104	3.9	2.0				
2002	365	1.0	14786	369.8	2.0				
2003	365	1.1	313.7	7.8	2.5				
2001-2003	1,095	1.0	14786	125.3	2.0				

Year refers to water year, 10/01 through 9/30

All concentrations in mg/L

All data included in Appendix C

The extremely high TSS value of 14,786 mg/L occurred on April 11, 2002. This coincides with a period of elevated TSS during spring runoff with daily TSS measurements consistently greater than 1,000 mg/L from March 30 to April 18, 2002 and again from April 22 to April 26, 2002. TSS values decreased rapidly in the following days with TSS measured at 5.3 mg/L on April 30' 2002. As shown in Figure 2-6, this period of extremely high TSS corresponds to a period of higher than normal spring flows. Peak flows during this period exceeded 100 cfs while peak flows in April 2001 and 2003 failed to reach 30 cfs (Figure 2-6).

Results of a comprehensive TSS sampling event conducted by the USFS on February 23, 2002 provide a synopsis of spatial TSS concentration trends during a rain-on snow event (Table 3-13). As shown in Table 3-13, stream flow increased consistently with downstream direction, from 20 cfs to 50 cfs over a distance of approximately six miles (TSS sampling sites shown on Figure 3-

6). TSS concentrations (and loads) actually decreased from the upper site (72 mg/L at Harpers Bridge), to the next downstream site (26 mg/L at Wegners). TSS concentrations then increased steadily downstream from Wegners to a maximum of 74 mg/L at River Road near the mouth of Bobtail Creek. These TSS concentration and loading trends indicate one or more sources of sediment loading to Bobtail Creek are present upstream of Harpers Bridge (Section 30), with instream sediment deposition occurring between the Harpers and Wegner sampling locations. Likely sources include the area of damaged channel located in Section 30 and discussed in Section 4.0. Additional sediment loading sources exist downstream of Wegners as indicated by the steady increase in TSS concentrations and loads between this location and the mouth of Bobtail Creek. Source assessment is discussed more fully in Section 4.0.

Table 3-13. Results of February 23, 2003 TSS and Flow Monitoring During Rain – On –Snow for Main stem Sites.

Site	Location	Flow cfs	TSS mg/L	TSS Load tons/day
BC below Harpers Bridge	SE ¹ / ₄ Sec 30, T32N, R31W	20	72	3.9
BC at Wegner's	SW ¹ / ₄ Sec 32, T32N, R31W	25	26	1.75
BC below Red Rose Ranch	SE ¹ / ₄ Sec 32, T32N, R31W	30	34	2.75
BC at Brebner's	Mid Sec 8, T31N, R31W	45	70	8.5
BC at River Road	SE ¹ / ₄ Sec 19, T31N, R31W	50	74	10

Sites shown in upstream to downstream order

All data collected by USFS

cfs - cubic feet per second

Site locations shown on Figure 3-6

BC – Bobtail Creek

Extensive TSS data has been collected from Bobtail Creek over the last few years. This data indicates multiple sediment loading sources are present within the drainage, with TSS concentrations reaching extremely high concentrations during spring runoff and other high flow conditions. However, average and median TSS concentrations suggest that the elevated TSS concentrations are restricted to high flow events, with TSS concentrations much lower under typical flow conditions.

Comparison to TSS Values from Other "Least Impaired" Drainages

Following compilation and review of available data, the Bobtail Creek TSS data were compared to TSS data from similar drainages in western Montana. The purpose of this comparison was to assess TSS concentrations in Bobtail Creek in relation to other "least impaired" drainages as a measure of TSS-related impairment in Bobtail Creek.

Bobtail Creek differed from the reference streams in terms of the number and magnitude of extreme TSS values. The maximum TSS value recorded in Bobtail Creek, 14,786 mg/L, is

almost 200 times more than the maximum value recorded in the reference drainages (Tables 3-8 and 3-12). Similarly, the average TSS value in Bobtail Creek, 125.3 mg/L, is significantly greater than the 5.7 mg/L average of all reference drainage data. As previously discussed, elevated TSS levels in Bobtail Creek coincide with periods of high flow such as spring runoff (Figure 2-6). These extreme high flow TSS peaks indicate significant sediment loading to the stream from disturbed lands within the drainage. Comparison of Bobtail Creek TSS concentrations to those from the reference streams (125.3 mg/L verses 5.7 mg/L for averages of the two datasets), as well as the shear magnitude of TSS concentrations in Bobtail Creek (up to 14,786 mg/L) provide clear evidence that Bobtail Creek is in fact impaired, at least on a periodic basis, due to TSS (Rowe et al., 2003).

Detailed review of the Bobtail Creek TSS data provides insight into the timing and duration of elevated TSS concentrations. Although the maximum and average TSS values are high, the median value was only 2.0 mg/L (Table 3-12). This means that half of the 1,131 TSS measurements taken from Bobtail Creek are less than 2.0 mg/L. The 75th percentile for the dataset is 6.2 mg/L meaning 75% of the TSS values are less than this. This trend of high TSS values during high flow conditions and relatively low TSS values during the majority of the year is evident in Figure 2-6. This information indicates that TSS may only act as a source of water quality impairment in Bobtail Creek during high flow periods.

The overall higher concentrations of TSS measured in Bobtail Creek compared to the 12 reference streams suggest that sediment loading in this watershed is elevated above least impaired conditions, primarily during spring runoff and other high flow events. While limited in duration, the magnitude of these elevated TSS episodes are believed to negatively impact the fishery and aquatic life in Bobtail Creek.

Assessment of TSS Effects on Biota

The impact of TSS on fish and aquatic life is related to the TSS concentration, the duration of the TSS episode, and the timing of the elevated TSS episode relative to life history stages of the aquatic organism. These relationships have been used to develop models to predict the severity of ill effects (SEV) on fish at different life history stages (Newcombe and Jenson, 1996). The SEV varies from behavioral effects such as avoidance to lethal effects. Based on the documented elevated TSS values in Bobtail Creek, effects of TSS on Bobtail Creek biota were estimated using the SEV. Although physical and biological conditions within Bobtail Creek deviate from certain model assumptions, the model does provide a qualitative assessment of water quality impairment from TSS (and thus turbidity). The SEV model is not intended as a quantitative analysis of TSS-related impairment in Bobtail Creek, but is presented to corroborate other evidence of impairment presented in this report, including the magnitude of periodic elevated TSS concentrations, comparisons to reference stream concentrations, and documented declines in fish populations. The SEV model is briefly summarized below and presented in more detail in Appendix D.

Multiple SEV models have been developed to determine TSS effects on aquatic life (Table 3-14). Because fish are more vulnerable at different periods of their life cycle, these models are typically applied for different portions of the year based on the presence of vulnerable life

history stages. Of the four models, models 1 and 4 were selected for the Bobtail Creek analysis. These two models address a range of life history stages of salmonids (eggs, larvae, juvenile, and adult) and were developed for a relatively wide range of particle sizes. Based on information provided by Plum Creek (Plum Creek Timber Company, 2004) model 4 (for eggs and larvae) may not be valid for the fish found in Bobtail Creek, as the Bobtail fish bury their eggs in redds, and therefore those eggs may not be directly exposed to the effects of TSS.

Table 3-14. Models Developed to Predict SEV for Different Life History Stages and Particle Sizes (Newcombe and Jenson 1996).

Model	Life History Stages and	Model Information
Number	Particle Sizes	
1	Juvenile and adult salmonids; particle sizes 0.5-250 µm	$SEV = 1.064 + 0.6068 \times LN(D) + 0.7384 \times LN(C)$
2	Adult salmonids; particle sizes 0.5-250 µm	$SEV = 1.6814 + 0.4769 \times LN(D) + 0.7565 \times LN(C)$
3	Juvenile salmonids: particle sizes 0.5-75 µm	$SEV = 0.7262+0.7034\times LN(D)+0.7144\times LN(C)$
4	Eggs and larvae of salmonids and non-salmonids	$SEV = 3.7456+1.0946 \times LN(D)+0.3117 \times LN(C)$

D= duration of exposure in days; C=TSS concentration in mg/L

Based on the results of model 1 (Figure 3.7) SEV calculated for juvenile and adult salmonids based on TSS concentrations measured in Bobtail Creek experience sub-lethal but harmful effects within a few days for even low concentrations (5 mg/L) of TSS. Daily monitoring of TSS near the mouth of Bobtail Creek document high TSS values for the March to June period, even in drought years. TSS exceeded 5 mg/L and ranged as high as 14.6 mg/L for up to 18 days. Furthermore, the average TSS concentration occurring during spawning and incubation was greater than 11 mg/L. This concentration can lead to harmful impacts (increased coughing and respiration rate) to juvenile and adult salmonids in only 3 days of exposure (Appendix D). As pointed out by Rowe et al. (2003), discretion should be utilized when applying the SEV analysis and its associated models, as it can be inconsistent with other work.




Figure 3-7. Calculated SEV for Concentrations of TSS Sampled on Bobtail Creek for Hypothetical Durations Using Model 1 (Adults and Juvenile Salmonids).

Because timing of spawning and incubation for spring spawning species such as rainbow trout and westslope cutthroat trout typically coincide with the higher flows occurring during spring runoff, it is probable that a certain degree of para-lethal to lethal stress to eggs and larvae is unavoidable in most drainages, even with minimal development and disturbance. Still, the higher concentrations measured in Bobtail Creek, and the SEV values calculated, indicate an elevated risk for fish in Bobtail Creek during the more vulnerable life history stages.

The potential for TSS to impact early life history stages is further underscored by comparisons of TSS concentrations for various months (Figure 2-6). Most of the higher values occur from March to June, when eggs and larvae are within redds. Bobtail Creek samples demonstrated considerably higher concentrations of TSS than the reference streams combined.

Based on comparisons with regional reference streams, TSS in Bobtail Creek showed markedly higher peak concentrations. These concentrations, in conjunction with the SEV scores for juvenile and adult salmonid life stages, support the inclusion of TSS as a cause of impairment in Bobtail Creek. Based on the strong correlation between TSS and turbidity in Bobtail Creek as shown in Figure 3-3, this information also supports inclusion of turbidity as a source of impairment in Bobtail Creek.

Bank Stability

As described in Section 3.3.2, the supplemental indicator value for bank stability is ≥80 percent. Five of the study reaches do not meet these standards (Table 3-15). Unstable banks are an inchannel source of sediment. Furthermore, laterally migrating banks have the potential to increase width-to-depth ratios, further decreasing sediment transport capabilities. Note that relatively high levels of eroding bank were recorded in stream reaches experiencing channel instability (Section 30 and 32) following the 1997 ROS flood event.

Table 3-15. Bank Stability Values in the Bobtail Creek Watershed.

Site	Rosgen	% Bank		
Site	Type	Bankfull Width (ft)	Stability	
1- Bobtail Cr.	B4	16.3	100	
2- Bobtail Trb	A4	6.2	100	
3- Bobtail Cr.	B4	18.8	100	
4- Bobtail Cr.	B4	19	100	
5- Bobtail Cr.	C4	10.8	92	
7- Bobtail Cr.	B4	7.7	100	
8- Terge Cr.	A4a+	2.5	100	
9- Bobtail Cr.	B4a	5.5	100	
10- Bobtail Cr.	E4b	9.8	74	
11- Bobtail Cr.	B4c	23.7	97	
12- Bobtail Cr.	C4	18.9	78	
13- Bobtail Cr.	B4c	10.3	-	
14- Bobtail Cr.	B4	17.0	69	
15- Bobtail Cr.	C4	12.0	100	
1- Bull Cr.	E6	4.2	05	
2- Bull Cr.	B4a	8.5	100	
6- Bull Cr.	B4	7.3	100	
6a- Bull Cr.	G4	5.2	17	
Current INFS Standards*			>80%	

Shaded values do not meet supplemental indicator thresholds.

Macroinvertebrates

Macroinvertebrates were collected at one site by Plum Creek Timber Company (PCTC) in July 1991 and by the US Forest Service at a different site in October 2000 and August 2001. PCTC collected five replicate macroinvertebrate samples in the upper half of Bobtail Creek (SE¼ of Section 19, T32N, R31W) in July 1991 (Table 3-16). The Montana Mountain Macroinvertebrate Index of Biological Integrity (Mountain IBI) indicates full support of beneficial uses (Table 3-16). In all five samples, these taxa exceeded ecoregion criteria for biological integrity and full support of beneficial uses. These samples were collected above unstable reaches and before the 1997 flood event. These data provide baseline information and an internal reference that can be used in establishing numeric targets in the basin.

The USFS collected macroinvertebrate samples downstream of the PCTC sampling site (NE¼ Section 5, T31N, R31W) in October 2000 and August 2001 (Table 3-16). The USFS data show a greater level of impairment as compared to the 1991 PCTC data. There was a large decrease in the number of macroinvertebrates specialized in eating detrital materials. Detrital (allocthonous) materials include any dead plant material that falls into a stream or waterbody. Macroinvertebrates that specialize in consuming allocthonous materials are usually well represented in healthy streams (Barbour et al., 1999). Allocthonous materials also contribute to habitat diversity that increases the surface area for periphyton and allows other specialized invertebrates to exist in the same stream (Merritt and Cummins, 1978). A healthy well-developed mountain stream typically will retain a complete riparian zone. The riparian zone is the primary source of allocthonous material. A possible reason for the decline of shredder/scraper populations could be a decline in the riparian zone. Another possibility is the sampling technique used. Different sampling techniques will collect different macroinvertebrate populations. A third and more likely possibility is that sampling locations differed between Plum Creek and Forest Service sites, which along with a nine year delay between sampling events contributed to the disparity between samples. As previously noted (Section 2.9.2) the Plum Creek samples were collected in a forested reach of stream where the channel bed is composed of coarse gravel, while the USFS samples were taken downstream of agriculture, grazing, and residential development where the stream gradient is much lower and the substrate is much finer (Plum Creek Timber Company, 2004). One replicate in the USFS October 2000 sampling and the August 2001 sampling do not meet the target of a Mountain IBI of greater than 75 percent.

Table 3-16. Bobtail Creek Macroinvertebrate Sampling Results.

	Metric Guidelines*	Plum Creek Timber Company			US Forest Service					
Location		SE 1	/4, SE 1/4,	SE 1/4, S1	9, T32N, R	31W	SE 1/4, N	W 1/4, NE1	/4, S5, T31	N, R31W
Date		7/25/1991	7/25/1991	7/25/1991	7/25/1991	7/25/1991	10/3/2000	10/3/2000	10/3/2000	8/30/2001
Replicate/ Sample Number		1	2	3	4	5	114572	114573	114574	118552
Taxa Richness	>28	30	32	29	31	33	33	34	29	28
EPT Richness	>19	25	26	24	23	28	24	22	15	17
Biotic Index	<3	3.69	3.45	2.76	2.89	3	3.2	3.7	5.05	3.07
% Dominant	<25	39.86	38.13	28.8	25.18	31.31	19.8	25.7	31.2	40.1
% Collectors	<60	42.7	40.61	27.87	28.57	30.8	42	22	63	38
% Scrapers + Shredders	>55	47.23	50.32	59.84	55	52.77	37	32	7	7
% EPT	>70	57.73	60.07	71.99	71.25	68.38	80.3	57.5	26.5	19.9
Mountain IBI**		0.76	0.76	0.95	0.90	0.81	0.86	0.76	0.38	0.24

^{*} Mountain region metric guidelines established for Montana wadable streams

^{**} Montana Mountain Macroinvertebrate Index of Biological Integrity

>0.75 indicates full support

< 0.24 indicates nonsupport

3.5 Bobtail Creek Water Quality Impairment Status Summary

The listed impairments for Bobtail Creek were summarized in **Tables 3-1 and 3-2.** The available data suggest that the stream, on the 2000 and 2002 303(d) lists, probably does not fully support its beneficial uses as a result of the pollutants that are included on the lists. TMDLs for these impairments are presented later in this document (Section 5.0). The primary pollutants of concern in these TMDLs are siltation and turbidity. For the purposes of this document, sediment is used to refer to a group of sediment-related pollutants including siltation, turbidity, bank erosion, and habitat alteration. Bobtail creek is impaired by sediment.

Based on review of existing information and results of various evaluations, current conditions support the contention that Bobtail Creek is impaired due to elevated turbidity (and total suspended sediment), siltation, and habitat alteration. The turbidity/TSS impairment is restricted primarily to high stream flow conditions associated with spring runoff and periodic rain-on-snow events. Comparison of fine sediment (<6.35mm) content in the Bobtail Creek streambed with that from nearby least impaired streams indicates that percent fine sediment in Bobtail Creek is elevated, and that these levels may inhibit fish propagation and survival during sensitive life stages. Basin-wide assessments conducted by the USFS documenting current watershed characteristics for various riparian management objectives (width-to-depth ratios, pool frequency, etc.) confirm that Bobtail Creek is impaired due to habitat alteration.

SECTION 4.0 SOURCE ASSESSMENT

Assessments and evaluations have been conducted in the Bobtail Creek watershed that provide information on the sources of impairment in Bobtail Creek. A substantial amount of the information used in this document was provided by the U. S. Forest Service (USFS) as part of the Kootenai National Forest Plan, the Inland Native Fish Strategy (INFS), and the Pipestone Environmental Impact Statement (EIS). Plum Creek Timber Company (PCTC) and the Bobtail Creek Watershed Group (BWG) provided additional information and data.

4.1 USFS Information

Management activities, planning, and stream assessments conducted by the USFS constitute the majority of the information available to evaluate sources of impairment in the Bobtail Creek watershed. USFS information was collected in preparation for the Pipestone EIS (USFS, 2002). This includes basin-level screening of potential risks based on land use practices in the basin, and stream assessments and TSS sampling throughout the watershed.

USFS Road Analysis

The Watershed and Fisheries National Forest Management Act (NFMA) Screen Process was developed to provide an estimate of the risk of sediment production and delivery based on characteristics of roads within a basin (USFS, 2002a). Specifically, it involves the calculation of several metrics based on basin-level road density, road density on sensitive land types, and the ratio of road crossings on sensitive land types to the miles of road on those types (Table 4-1). These scores are multiplied and compared to the appropriate criteria for wet areas (average precipitation > 30 inches/year) or dry areas (average precipitation < 30 inches/year). At an annual average of 30.3 inches/year in the Bobtail Creek watershed, Bobtail Creek scores as "nonfunctioning" in terms of road impact factor. This suggests that roads are a significant source of sediment to Bobtail Creek. Furthermore, the Pipestone DEIS (USFS, 2002) states that many roads in upper Bobtail Creek do not meet best management practices (BMPs).

USFS personnel have examined roads on National Forest Lands to determine sediment production and delivery risks (unpublished data). The road sediment delivery analysis (RSDA) included an inventory of Forest Service roads, assessment of the age and development history of the roads, road surface types and maintenance level, road management objectives, current and projected future road use, and degree of connectivity with streams including number an location of stream crossings. The evaluation identified seven road failures in the upper watershed, and two crossings with undersized culverts where water washed across the road and was eroding fill slopes.

Table 4-1. Results of Watershed and Fisheries NFMA Screening Process.

Data Type	Description	Bobtail Score (where applicable)	
• Miles of road/mile ²	This attribute allows a quick analysis of the landscape changing processes that have taken place in the watershed.	5.81 = Severe	
• Miles of road/mile ² on sensitive land types	This attribute allows the analysis of the sediment generating potential of roads constructed in the following land types (322, 323, 357, 108).	4.4 = Severe	
Number of stream crossings on sensitive land types	This attribute will allow the analysis of the water quality and fisheries habitat degradation potential due to road/stream interactions.	1.5 = Moderate	
Road Impact Factor	This attribute attempts to integrate the potential effects the transportation network is having on watershed function. This attribute is produced from the multiplication of the scores received from the above screens.	38.35 = Non Functioning	

November, 2004 **DRAFT** 56

USFS Analysis of Peak Flow and Relation to Eroding Banks

As part of the Pipestone EIS analysis in the Bobtail Creek watershed (USFS, 2002), USFS personnel have employed the equivalent clear-cut acres (ECA) model (USFS, 1991) to assess increases in peak flow due to timber harvest activities in the basin. In 2000, the Bobtail Creek drainage had an ECA of 2281 acres. Based on the model, which projects a 1% increase in peak flow per 215 ECAs, a resulting increase of peak flow of 10.6% is predicted. However, in the Final Pipestone EIS (USFS, 2004) a current peak flow increase of 10.8% was reported. Both of these values, 10.6% and 10.8%, are greater than the values the USFS suggests for stability (stable banks and stream bed). The USFS (2002), based on monitoring information from the adjacent Quartz Creek watershed, suggest that stability would be expected with water yields below the 7% to 9% level. Quartz Creek and Bobtail Creek watersheds are similar in geology so they are expected to function in similar manners. The peak flow increase of 10.6% likely leads to bank instability; therefore, contributes to the sediment source for Bobtail Creek.

USFS TSS Sampling during a Rain-On-Snow (ROS) Event and Related Road Densities and Bank Erosion

TSS sampling conducted by the USFS during a ROS event on February 23, 2002 provides information regarding sources of suspended sediment in the Bobtail Creek basin. TSS samples on the main stem of Bobtail Creek ranged from 26 to 74 mg/L (Table 3-13, Figure 4-1). Flow consistently increased in a downstream direction, TSS did not (see decrease in TSS concentration between "Below Harper's" and "At Wagner's," Figure 4-1). This underscores the concept of multiple sediment sources and the presence of sediment deposition within the Bobtail Creek channel. Sediment transport efficiency between the Harper's property and Wegner's property is likely limited by high width-to-depth-ratios in this wide and unstable reach, resulting in instream sediment deposition and the observed reduction if TSS concentrations (and loads).

There are two major potential sources of fine sediment above the highest sampling site on the main stem of Bobtail Creek. First, relatively high densities of roads and 19 stream crossings on sensitive land type 357 (Figure 2-2) could be a source. Second, this site was located immediately downstream of a highly unstable reach of stream on private land that had undergone channel reconstruction in the summer of 2001 and vegetation may not have recovered sufficiently to reduce sediment inputs. Because of this, concentrations of TSS at this location cannot be assumed to represent conditions in the forested headwaters upstream.

TSS concentrations measured on tributaries in the lower portions of the watershed indicate that Bull Creek is also a significant source of fine sediment to Bobtail Creek (Figure 4-2). The TSS concentration in Bull Creek at Bobtail Road was 47 mg/L, and the concentrations in three separate tributaries entering Bull Creek downstream of this site ranged from 16 to 22 mg/L (Appendix C). Bank erosion near the confluence of Bobtail Creek and Bull Creek may be a contributing source of sediment.

80 70 **TSS** Flow 60 TSS (mg/L) and Flow (cfs) 50 40 30 20 10 0 Below Harper's At Wegner's Below Red At Brebner's At River Road Rose Ranch

Figure 4-1. TSS Concentrations and Flow on Bobtail Creek During a ROS Event, February 23, 2002.

Presented in upstream (left) to downstream (right) order.




Figure 4-2. TSS and Flow Measured on Tributary Streams in the Bobtail Creek Watershed During the ROS Event, February 23, 2002.

Presented in upstream (left) to downstream (right) order.

4.2 Plum Creek Sediment Delivery Analysis

Plum Creek Timber Company conducted a road sediment delivery analysis on their holdings in May 2000 following protocol outlined in the Standards Methods for Conducting Watershed Analyses (Washington Forest Practices Board, 1997). The purpose of the analysis was to assess risks and identify actions to protect water quality on PCTC lands. The analysis results are summarized in Table 4-2 and monitoring sites shown on Figure 4-3.

Based on this analysis, a total of 17.3 tons per year of sediment is delivered to streams in the Bobtail Creek watershed from Plum Creek roads. Sediment loading from road crossings varies from 0 to 3.3 tons per year. Additional information on the PCTC road sediment delivery analysis is provided in Appendix E.

Table 4-2. Bobtail Creek Road Sediment Delivery Analysis on PCTC Property (Sugden and Richeal 2000, Unpublished Data).

Troporty (Surge	Tread	Cut slope	Fill slope	TOTAL
Location	Delivery	Delivery	Delivery	Total
Code	(tons/yr)	(tons/yr)	(tons/yr)	(tons/yr)
6	2.4	0.9	0.0	3.3
15	2.0	0.1	0.0	2.1
24	1.4	0.1	0.0	1.5
10	0.9	0.3	0.0	1.1
13	0.5	0.6	0.0	1.1
22	1.0	0.1	0.0	1.1
21	1.0	0.1	0.0	1.0
5b	0.5	0.4	0.0	0.9
23	0.6	0.2	0.0	0.8
1	0.4	0.3	0.0	0.7
4	0.3	0.3	0.0	0.7
12	0.5	0.0	0.0	0.6
2	0.4	0.1	0.0	0.5
18	0.5	0.0	0.0	0.5
5	0.3	0.1	0.0	0.4
18b	0.3	0.0	0.0	0.4
17	0.1	0.1	0.0	0.2
18d	0.0	0.0	0.0	0.1
10b	0.0	0.0	0.0	0.0
19	0.0	0.0	0.0	0.0
18c	0.0	0.0	0.0	0.0
Watershed	13.2	3.9	0.2	17.3
Totals				

PCTC road analysis methodology and data in Appendix E

Delivery Analysis. Bobtail Creek Road Sediment Delivery Analysis May 15, 2000 B. Sugden and M. Richeal 24 PCT 7 9 USFS USFS 23 22 USFS 13 18 17 USFS 16 12 PCT 10b PCT 19 PCT 21 18 USFS 17 1/5 USFS USFS 5b PCT PCT_Property 28 No Sediment Delivery or Routing Potential USFS Sediment Delivery Inventory Location

Figure 4-3. Sites Evaluated by Plum Creek Timber Company in the Road Sediment

4.3 Field Review of Residential Reaches – Eroding Banks

Bobtail Creek's problems, in part, stem from extreme erosion caused when the stream jumped out of its banks and ran down a skid road that a small-private landowner built adjacent to the stream when logging their property in the late 1980's. The diversion of the stream down this skid road first occurred during severe rain-on-snow events in the fall of 1990 and spring of 1991. MDEQ analyzed this situation in a warning letter submitted to the private landowner. Additional events in February 1996, spring 1997, and more recent floods have continued to erode this unstable reach, leading to extensive channel aggredation downstream (Plum Creek Timber, 2004).

In October 1999, the Bobtail Creek Watershed Group conducted field reviews of private holdings in unstable reaches in sections 29, 30, and 32 (T32N R31W) (Figure 2-4). Steve Wegner, a professional hydrologist with the USFS conducted these evaluations in conjunction with private property owners. These evaluations identified areas of eroding bank and channel instability in these reaches that contribute to sediment loading and reduced transport leading to siltation. Of considerable concern is a section where the stream left its historical channel and scoured an overflow channel 15 feet wide and 3 feet deep (Figure 4-4). This continues to act as a potential source of sediment loading to the stream. Other sources of sediment loading and habitat degradation from private land holdings include livestock grazing, private roads, and stream encroachment.



Figure 4-4. Area of Unstable Stream Reach.

4.4 Other Potential Sources

According to the USFS (2002), there is one known large bedload source area on Bobtail Creek in section T32N, R31W, Sections 30 and 32 (sites 12, 13 on Figure 3-4) on private property (mentioned in Section 4.3). The USFS (2002) also acknowledges that numerous road/stream crossing failures have been documented within this watershed in the past decade. County roads,

pastures, and grazing are all potentially significant impacts in lower watershed and contribute to eroding banks and other sediment loading sources.

4.5 Source Assessment Uncertainty

As described above, an effort was made to identify all significant anthropogenic sources of sediment loading in the Bobtail Creek watershed. Although it is felt that this has resulted in sufficient information to reach the conclusions presented in this report, there are still some uncertainties regarding whether or not all of the significant sources have been identified, and regarding the quantification of sediment loads. The primary uncertainties are as follows:

- Bank erosion has not been thoroughly assessed in the Bobtail Creek watershed.
- The extent to which USFS roads, recognized in the upper drainage as not meeting BMP standard, are actively contributing sediment to the stream network is unknown.
- The extent to which past activities such as harvest and road building have affected Bobtail Creek watershed is unknown.
- The extent to which agriculture and private land development have affected the Bobtail Creek watershed is also unknown.

These uncertainties will be addressed by the proposed activities described in Section 8.0.

4.6 Source Assessment Summary

Based on available information and detailed analyses, primary sources of impairment include sediment yield from roads, and an area of unstable stream banks on private property within the middle portion of the drainage (Section 30). Sediment yield to Bobtail Creek from PCTC roads has been quantified as 17.3 tons/year. Results of Equivalent Clear-Cut Area analyses by the USFS indicate that increased water yield (peak flows) resulting from past timber harvesting in the drainage may contribute to stream channel instability and habitat-related impairment. Current management plans for the watershed should address many of these problem areas in Bobtail Creek drainage.

January, 2005

SECTION 5.0 TOTAL MAXIMUM DAILY LOAD, ALLOCATIONS, AND UNCERTAINTY

5.1 Total Maximum Daily Load

A TMDL is composed of the sum of individual waste load allocations (WLAs) for point sources, and load allocations (LAs) for nonpoint sources and natural background levels. In addition, the TMDL must include a margin of safety (MOS), either implicitly or explicitly, that accounts for the uncertainty in the relationship between the pollutant loads and the quality of the receiving waterbody. Conceptually, this definition is denoted by the equation:

TMDL = WLAs + LAs + MOS

There are no point sources of sediment in the Bobtail Creek watershed; therefore, that variable can be removed from the equation. The primary human-caused sediment sources in the watershed appear to be forest roads and agriculture.

This TMDL definition is difficult to apply in a watershed such as Bobtail Creek where impairments are caused by nonpoint sources. One alternative often used for TMDL development in similar situations is to express the sediment TMDL as a percent reduction in loading. Therefore, the sediment TMDL for Bobtail Creek and its tributaries is expressed as percent reductions in TSS. The TMDL for TSS addresses turbidity as a cause of impairment due to the previously established correlation between TSS and turbidity (Section 3.3.2), and as the primary source of sediment loading to the stream, and also indirectly addresses siltation. The basic premise of this TMDL is that the targets will be achieved by reducing sediment loading (i.e., the TSS load) to the stream.

5.1.1 TMDL for Total Suspended Sediment (TSS)

This TMDL is developed for TSS. The average TSS concentration in Bobtail Creek for the 2000 through 2003 daily samples is 125 mg/L (Table 3-8). This compares to an average TSS value from 12 reference drainages of 5.7 mg/L. As described in Sections 3.3.2 and 3.4.2, the high average TSS concentration is contributed to high TSS values during high flow conditions. This is further exemplified in Figure 2-6, where high TSS values correspond to high flow events. Therefore, the TMDL for TSS is a 95% reduction in average TSS concentrations during high flow conditions.

This TMDL is intended to address the pollutant-related impairment conditions in Bobtail Creek. Allocations designed to meet these reductions are discussed below. The uncertainties with this are further discussed in Section 5.3.

5.2 Load Allocations

This section identifies allocations that support the TMDL developed for Bobtail Creek. The goal is to ensure that the water quality targets (Section 3.3.1) are met and, more importantly, that

beneficial uses are restored and/or protected. The allocations all apply to nonpoint sources and are therefore defined as load allocations.

Waste load allocations are not required since there are no permitted point sources regulated under the National Pollutant Discharge Elimination System. However, NPDES/storm water discharge permits are required for land disturbance activities over one acre in size, often related to construction activities. These sources are addressed in the future development allocation (Section 5.2.5).

Assistance from all landowners will be needed to ensure protection of water quality because many of the allocations are based on voluntary implementation of management practices. If a landowner or set of landowners exceeds an allocation relative to their percentage of land ownership, then the risk of not meeting water quality targets is increased. Under these conditions, an additional burden could be placed on other landowners to compensate for the unexpected increase in impact/loading if Bobtail Creek is to meet water quality standards.

For Bobtail Creek, load allocations have been developed for identified sources of sediment loading, including runoff from roads and eroding banks (Table 5-1). These allocations address the primary sources or source categories, and are expressed as performance based allocations.

Table 5-1. Allocations for Identified Sediment Loading Sources in Bobtail Creek Watershed.

Source	Current Annual Estimated Load	Performance Based Load Allocation	
Surface Erosion from Existing USFS Roads	50-70 tons/year	90% application of road best management practices.	
Surface Erosion from Existing Plum Creek Timber Company Roads	17 tons/year	90% application of road best management practices.	
Surface Erosion from Existing County and Other (non-PCTC) Roads	>2 tons/year	90% application of road best management practices.	
Eroding Banks linked to Human Activities	Eroding banks documented as significant sediment loading source in Section 30, T 32N, R31W and other locations	75% reduction of bank erosion due to human causes such as grazing, agriculture, road crossings, hydraulic modifications on private and public lands.	

January, 2005

Table 5-1. Allocations for Identified Sediment Loading Sources in Bobtail Creek Watershed.

Source	Current Annual Estimated	Performance Based
Source	Load	Load Allocation
Mass Wasting from	Not quantified	No loading from preventable mass
Timber Harvest or	_	wasting events.
Other Activities		
Culverts	Not quantified	No loading from culvert failures where
		culverts are not up to best management
		practice standards or not maintained.
Future Development	Not quantified	No sediment loading increases other
_	-	than potential minor predicted short-
		term increases associated with full
		implementation of applicable BMP
		standards.
Future Roads and	Not quantified	No sediment loading increases other
Timber Harvest	_	than potential minor predicted short-
		term increases associated with full
		implementation of applicable BMP
		standards.

5.2.1. Surface Erosion from Performance Based Roads Allocations

The allocation for surface erosion from roads applies to timber harvest roads as well as other forest roads, county roads, and private roads (Table 5-1). The 90% application of BMPs is used in recognition of achievable reductions from this source category and as a component of the margin of safety. The use of a 90% application of road BMPs is also important for the protection of tributary streams to avoid impairments in these streams. This road sediment allocation is also applied to individual landowners.

Both Plum Creek Timber Company (PCTC) and the U.S. Forest Service (USFS) have committed to decrease sediment delivery from roads on their respective properties in the Bobtail Creek watershed. Through their Native Fish Habitat Conservation Plan (PCTC, 2000), PCTC will implement a basin-wide program including road decommissioning, upgrading and maintenance of BMPs on logging roads on their property (Section 6.0). These activities are expected to significantly reduce sediment loading from PCTC roads in the next several years.

5.2.2 Eroding Banks Allocation

The allocation for sediment loading associated with eroding banks is expressed as a reduction in bank erosion in the lower reaches of Bobtail Creek and on Bull Creek or any stream where bank erosion can be controlled by using BMPs or reasonable land, soil and water conservation practices. During the INFS screening process, 5 reaches were identified with excessive percentages of eroding bank (Table 3-10). Unfortunately, the source assessment did not provide a good link between bank erosion and land use causes, although land use in these areas and funded restoration projects suggest a linkage between preventable bank erosion, riparian health, and grazing and other human activities. Where such linkages exist, it is assumed that the bank

erosion can be reduced by as much as 75% via BMP implementation and the application of reasonable land, soil and water conservation practices. This 75% is consistent with the bank erosion allocation for similar sources in the Blackfoot Headwaters and Ninemile TMDL allocations (MDEQ, 2004a; MDEQ 2004b).

Although BMPs such as grazing management should be a primary focus, active channel restoration may be a desirable approach where passive restoration may require excessively long stream recovery times even with BMP implementation. BMP implementation and the application of reasonable land, soil, and water conservation practices will need to focus on grazing and other human impacts that are contributing to unstable bank conditions. Reasonable land, soil, and water conservation practices should include upstream reductions in peak flows and other contributing factors to downstream bank erosion. As mentioned in Section 4.0, the USFS recommends peak flow increases of <7-9% and the watershed is currently experiencing peak flow increases of 10.8%. Reducing peak flow increases will also help reach the eroding bank allocation. Peak flows are discussed further in Section 5.2.7.

5.2.3 Mass Wasting from Timber Harvest Activities or Other Development

Timber harvest activities and other development, including road building, have the potential to significantly contribute sediment to streams within the Bobtail Creek Watershed if measures are not taken to prevent this loading. An example includes avoiding certain types of timber harvest practices, including road building, in areas of sensitive land types. This allocation is set such that there should be no increase in loading where such loading is preventable via application of BMPs or other practices to prevent mass wasting.

5.2.4 Culvert Failures

The allocation for culvert failures is set at no loading from culverts that are not up to forestry BMP standards, which generally require passage of a 25-year storm event. This BMP standard is applied to all culverts, including existing culverts, culverts on private or county property, and any new culverts. The goal of this allocation is to ensure minimal preventable excess sediment loading from culvert failures under high flow conditions. The PCTC Native Fish Habitat Conservation Plan requires a higher storm event passage in some situations for new or upgraded crossings. INFS generally requires that the USFS use a 100-year flood design for culverts. To be consistent with the goals of this allocation, drainages with a high road density should be designed to meet higher standards such as a 50 or 100-year event to avoid a very large culvert failure loading risk when 25-year events occur. The Bobtail Creek watershed road density is 4.3 miles per square mile and is considered to be at high risk for water quality impairment (Table 5-2). Proper culvert size, placement and maintenance will help to alleviate problems from the high road densities. Culvert maintenance to ensure flow passage is also an important consideration, since a properly designed, but poorly maintained culvert, could fail during lower flow conditions.

5.2.5 Future Development

It is not reasonable to assume that there will be no future development in the Bobtail Creek watershed. An allocation is therefore required to account for potential future sediment loading.

This allocation proposes no sediment loading increases associated with future development other than potential minor, short-term increases that may be predicted and associated with full implementation of the applicable riparian best management practice (BMP) standards. Additionally, storm water permits should address no increase above natural conditions, except for temporary exceedances. Future development is further addressed in Section 5.2.7 and Table 5-3.

5.2.6 Future Roads and Timber Harvest

It is not reasonable to assume that there will be no future silviculture activities in the Bobtail Creek watershed. An allocation is therefore required to account for potential future sediment loading. This allocation proposes no future sediment loading increases associated with harvest and/or forest roads other than potential minor, short-term increases that may be predicted and associated with full implementation of applicable best management practice (BMP) standards. Future timber road development and future timber harvest are further addressed in Section 5.2.7 and Table 5-3.

5.2.7 Future Performance-Based Allocations

Future development and future roads and harvest can result in higher levels of bank instability. Bank instability is likely to result in higher sediment loads in the Bobtail Creek watershed. It is important to address these future activities and decrease the related bank erosion and resulting sediment loading.

Future development and future timber roads and harvest can result in riparian disturbance and reduced bank stability. Complete application and proper use of BMPs will help to minimize the potential sediment loading. It is recommended that there is full application of appropriate BMP standards related to development.

Bank erosion from future timber road development and timber harvest can also be the result of increased peak flows. It is recommended that there is a peak flow increase of no greater than 7-9% in the Bobtail Creek watershed (Section 5.2.2). Compliance with this indicator will help maintain a stable stream channel configuration and natural sediment transport. The ECA model and other land management tools can be used to evaluate future conditions within the watershed in meeting this indicator condition.

Culverts associated with timber roads and harvest also may contribute to future bank erosion. As specified in the Pipestone EIS (USFS, 2004), current plans call for removal of 30 stream crossings, 21 of which are located on sensitive land types. Culvert removal is intended to restore the Bobtail Creek flow regime to a more natural condition and reduce sediment accumulation upstream of culverts, and streambed scouring downstream of culverts due to increased flow velocities. Culvert removal will also address fish migration barrier problems that may be associated with the culverts.

Road decommissioning and the resulting decrease in road density may also decrease future bank erosion. The Bobtail Creek watershed has an existing road density of 4.3 miles per square mile

(USFS, 2004). This density is considered to be a high risk for water quality impairment. Table 5-2 provides a range of risk guidelines regarding road density (Johnson, as cited in EPA, 2004). The Pipestone EIS calls for decommissioning of 18 miles of roads, 11 miles of which occur on sensitive land types. According to the EIS, PCTC has also agreed to remove 1.5 miles of road. This will result in an estimated road density of 3.2 miles per square mile (USFS 2004). It is proposed that road densities move toward a decreased value with a goal of <1.5 miles per square mile in the Bobtail Creek watershed.

Table 5-2. Road Density Risk Ratings in Miles per Square Mile.

Risk	Kootenai National Forest ^a	Idaho Panhandle National Forest	Multi-Agency Bull Trout Screen	Columbia River Basin Final EIS ^b
Low	< 1.5	< 1.7	< 1.5	< 2.0 (proper function)
Moderate	1.5–3.5	1.7-4.7	1.5–3.0	2.0–3.0 (functioning at risk)
High	> 3.5	> 4.7	> 3.0	> 3.0 (non proper function)

^aThe values reported for the Kootenai National Forest represent the range of values for areas with mean annual precipitation of 20 to 40 inches (similar to the FTPA; see Section 2.1.1).

January, 2005

^bThe Columbia River Basin Final Environmental Impact Statement (CRB FEIS) reports low, moderate, and high in terms of proper functioning condition.

Table 5-3. Future Performance-Based Allocations.

		Action	Rationale	Responsible Party
	Guture Development	No sediment loading increases other than potential minor predicted short-term increases associated with full implementation of applicable BMP standards.	Bank erosion from riparian disturbance will result in sediment loading. This can be minimized with the proper utilization of BMPs.	Private Landowners
ar	Guture Roads nd Timber Harvest	No sediment loading increases other than potential minor predicted short-term increases associated with full implementation of applicable BMP standards. Manage basin vegetation to result in an ECA leading to an estimated increase in peak flows of <7-9% Culvert Removal.	Bank erosion from riparian disturbance will result in sediment loading. This can be minimized with the proper utilization of BMPs. Increased water yield and peak flows increase the risks of channel instability and can increase pollutants of concern. Stream crossings promote sediment delivery and can limit fish movement. Roads in the watershed have been identified as	USFS, Plum Creek Timber Company, private landowners USFS, Plum Creek Timber Company, private landowners USFS, Plum Creek Timber Company, private landowners USFS, Plum Creek Timber Company, private landowners USFS, Plum Creek Timber Company,

5.3 TMDL and Load Allocation Uncertainty

The analysis presented in this document assumes that the load reductions proposed for Bobtail Creek will enable it to meet target condition, and further assumes that meeting target conditions will ensure full support of all beneficial uses. To validate this assumption, implementation monitoring has been proposed in the monitoring plan in Section 7.0. This monitoring is intended to track progress toward meeting targets. If it looks like greater reductions in loading or improved performance is necessary to meet targets, then a new TMDL and/or allocations will be developed based on achievable reductions through application of reasonable land, soil, and water conservations practices. The linkage between meeting targets and supporting beneficial uses will also be monitored through the supplemental indicators described in Section 3.0, including TSS, bank erosion, and macroinvertebrates.

January, 2005

5.3.1 Margin of Safety

Applying a margin of safety is a required component of TMDL development. The margin of safety (MOS) accounts for the uncertainty about the pollutant loads and the quality of the receiving water and is intended to protect beneficial uses in the face of this uncertainty. The MOS may be applied implicitly by using conservative assumptions in the TMDL development process or explicitly by setting aside a portion of the allowable loading (USEPA, 1999). This plan addresses MOS in several ways:

- Multiple targets addressing physical channel conditions are developed to address excess fines and other impairments.
- The suite of proposed supplemental indicators, including biological indicators, used to help verify beneficial use support determinations.
- The proposed supplemental indicators may also provide an early warning method to identify pollutant-loading threats that may not otherwise be identified, if targets are not met.
- The WQRP presented in this document go beyond what is required by the EPA for TMDL development by including restoration and monitoring for non-pollutants such as habitat alteration. By doing so, the WQRP provides a holistic approach to water quality restoration and thus an additional MOS for beneficial use support.
- A large amount of data and assessment information were considered prior to finalizing any impairment determinations. Impairment determination were based on conservative assumptions that error on the side of keeping streams listed and developing TMDLs unless overwhelming evidence of use support was available.
- To be protective and proactive, TMDLs and subsequent restoration and monitoring were developed as part of this WQRP even though they were not required in all cases.
- Consideration of seasonality.
- The adaptive management approach evaluates target attainment and allows for refinement of load allocation, targets, and restoration strategies to ensure restoration of beneficial uses.
- The monitoring plan calls for evaluation of tributaries not on the 303(d) list that may contribute sediment to the Bobtail Creek Watershed.

5.3.2 Seasonality

Addressing seasonal variations is an important and required component of TMDL development. Throughout this plan, seasonality is an integral factor. Water quality and habitat parameters such as fine sediment, suspended sediment, turbidity, and macroinvertebrates are all recognized to have seasonal cycles.

Specific examples of how seasonality has been addressed include:

• Source assessment of sediment loading inherently incorporates runoff flows when erosion is greatest.

- Targets were developed with seasonality in mind: the % <6 fine sediment target data is collected in the summer, after flushing flows have passed; macroinvertebrate and supplemental indicator data is collected during the summer months when these biological communities most accurately reflect stream conditions.
- Throughout this document, the data reviewed cover a range of years, seasons, and geographic area within the Bobtail TPA.

SECTION 6.0 RESTORATION STRATEGY

It is important to note that elements of the following implementation strategy are strictly voluntary in nature. The only requirements are that MDEQ formally reevaluate this WQRP/TMDL in 5 years following implementation of this plan. Any data collected by stakeholders will serve to help make impairment decisions in the future.

Based on the current impairment conditions and impairment sources identified for Bobtail Creek drainage, a restoration strategy has been developed to guide restoration in the drainage and facilitate water quality improvement. Restoration requirements for Bobtail Creek are primarily associated with sediment loading from roads and unstable stream banks, and habitat impairment related to channel instability and poorly functioning culverts. Extensive restoration programs and obligations are already in place in the drainage, many of which address sediment loading from roads, poorly functioning culverts and aquatic habitat enhancement, through USFS and Plum Creek Timber Company land management programs. Therefore, this restoration strategy relies on these existing programs and obligations that are expected to result in attainment of restoration targets in the coming years. Additional restoration strategies are proposed for non-PCTC private lands to address potential problems related to roads, culverts and unstable stream channels on these lands. Several restoration activities and projects have already been completed (Figure 6-1).

6.1 USFS Restoration Plans and Responsibilities


Restoration and management plans by the USFS constitute a significant component of the restoration strategy in Bobtail Creek. The following is a list of actions or management approach planned for this basin:

- The USFS plans on decommissioning several miles of existing forest roads in the drainage. Current plans include decommissioning 18 miles of road (USFS, 2004). Approximately 11 miles of these roads are located on sensitive land types, and therefore should decease sediment loading to Bobtail Creek and its tributaries.
- The USFS will oversee the removal of thirty stream crossings, 21 of which are on sensitive land types (USFS, 2004). Stream crossing and associated culvert removal will help restore the Bobtail Creek flow regime to a more natural condition, and reduce sediment accumulation upstream of culverts, and streambed scouring downstream of culverts due to increased flow velocities. Culvert removal will also address fish migration barrier problems that may be associated with the culverts.
- The USFS will continue their extensive monitoring program in Bobtail Creek drainage (Section 7.0). USFS monitoring will include geomorphic surveys at 18 locations, continuous stream flow and TSS monitoring, McNeil core sampling, and biological monitoring. These monitoring activities are scheduled to continue for at least 10 more years.

Additionally, it is recommended that the USFS manage timber harvesting on National Forest lands to limit water yield increases to less than 7-9% off of National Forest managed lands.

Figure 6-1 Restoration Projects in the Bobtail Creek Watershed.

Bobtail Creek TMDL Planning Area Restoration Locations



6.2 Plum Creek Timber Company Restoration Plans and Responsibilities

Plum Creek Timber Company is responsible for implementation of a number of water quality and habitat restoration activities in Bobtail Creek drainage under their Native Fish Habitat Conservation Plan (NFHCP). Specific requirements of the NFHCP are as follows:

- Under the NFHCP, Plum Creek will be fully implementing Montana's Forestry Best Management Practices on their properties;
- Bobtail Creek is designated in the NFHCP as a High Priority Watershed. With this designation, Plum Creek will upgrade all roads to meet state BMP standards (with some specific enhancements) by the end of 2010. This work will include improving general road drainage, reducing the length of road draining to streams, and adding supplemental filtration (e.g., slash filter windrows, silt fences, etc.) where drainage feature outfalls discharge too close to streams for effective filtration;
- Where fish passage barriers exist, they will be corrected prior to 2010. This deadline may be extended if necessary to fully work out details with cost-share partners (e.g., USFS);
- New stream culvert installations will be designed to accommodate at a minimum the 50-year peak flow;
- Roads that Plum Creek does not require for forest management will be abandoned (reclaimed) by the end of 2010;
- All roads will be re-inspected for BMP condition every 5 years;
- Any new roads will be constructed to specific enhanced standards, such as gravel surfacing
 of the road running surface over stream crossings in highly erodible soils. Should
 potentially unstable landforms be identified on proposed roads, a geotechnical review will
 be conducted to ensure potential risk is minimized; and
- In addition to standard state Streamside Management Zone regulations, Plum Creek will be providing extra riparian protection along streams that contain channel migration zones. Riparian buffers must also be enhanced with additional leave trees when streamside roads inhibit recruitment on the opposite side of the stream.

Additionally, it is recommended that Plum Creek manage timber harvesting on their lands to limit water yield increases to less than 7-9% off of Plum Creek-owned lands.

6.3 Other Private Landowner Restoration Plans and Responsibilities

Many restoration activities have occurred on private lands within the Bobtail Creek watershed. Restoration activities along the privately owned reaches in the lower portions of the watershed will be the responsibility of private landowners; however, much of this will likely be accomplished with both financial and technical assistance from agencies and the Bobtail Creek Watershed Group. For example, the Natural Resource and Conservation Service is available to provide both technical assistance and grants for implementation of grazing management practices. Similarly, grants through the Montana MDEQ have been used to restore reaches of channel and are likely to be a source of these funds in the future. Finally, the Bobtail Creek Watershed Group has been effective in organizing landowners to cooperatively plant riparian vegetation and build fences.

The following are the specific tasks that may be completed by private landowners in conjunction with government agencies and the Bobtail Creek Watershed Group. It should be noted that most, if not all of these tasks would be undertaken on a voluntary basis.

- Implement riparian BMPs to restore riparian structure and function where impacted by private roads or stream encroachment.
- Restore channel stability in unstable stream reaches in sections 29, 30 and 32, T32N, R31W (see Section 2.8.1, 4.3). Of particular concern is restoration and stabilization of the stream segment where the stream recently overtopped its banks and cut a new 15-foot wide channel. Use of hard channel armoring, such as rock riprap should be avoided in these stream restoration efforts.
- Replace undersized or improperly functioning culverts.
- Assist in monitoring of water quality parameters.

Implementation of riparian BMPs and monitoring will be ongoing activities. Channel restoration will be largely contingent on acquisition of grant funds but should be completed within 5 years.

SECTION 7.0 MONITORING STRATEGY

It is important to note that elements of the following monitoring strategy are strictly voluntary in nature. The only requirements are that MDEQ formally reevaluate this WQRP/TMDL in 5 years following implementation of this plan. Any data collected by stakeholders will serve to help make impairment decisions in the future.

Water quality monitoring will be critical for evaluating future water quality trends in Bobtail Creek drainage and is a required component of TMDL development. Montana law (MCA 75-5-703(7)) states "Once the control measures... have been implemented... the Department shall develop a monitoring program to assess the waters that are subject to the TMDL to determine whether compliance with water quality standards has been attained..." TMDL-related monitoring is also necessary to provide information for determining if modifications of restoration targets, load allocations, or restoration strategies. This section outlines a monitoring strategy designed to provide the information necessary to meet these requirements. Much of the information and data requirements for TMDL implementation will be made available through ongoing USFS and Montana Department of Fish, Wildlife and Parks monitoring activities. Plum Creek Timber Company, the Bobtail Watershed Group, MDEQ, or other public and private entities may provide other sources of data and information.

7.1 Monitoring Plan

As part of the overall implementation strategy for this water quality protection plan, a water quality monitoring plan for the Bobtail Creek watershed is included to help meet the following six objectives:

- 1. Document water quality trends associated with future implementation efforts.
- 2. Monitor progress toward meeting water quality targets.
- 3. Fill existing data gaps throughout the watershed.
- 4. Conduct an adaptive management strategy to fulfill requirements of this WQRP.
- 5. Conduct a phased hydrologic study to fulfill the requirements of this WQRP.
- 6. Address all assumptions and uncertainties identified in this WQRP.

This monitoring plan will address the need to evaluate the progress toward meeting or protecting water quality standards and associated beneficial uses (Montana State Law (75-5-703(7) and (9)). The monitoring will also address the tracking of specific implementation efforts. It is anticipated that the stakeholders will help develop monitoring details and help pursue funding for monitoring and data evaluation. The Bobtail Creek Watershed Water Quality Protection Monitoring Plan includes the following:

- Continue the collection of data for targets and indicators.
- Conduct road sediment assessments and determine sediment loading from road erosion for the Bobtail Creek watershed.

- Conduct more in-depth bank erosion assessments and determine sediment loading from bank erosion within the Bobtail Creek watershed.
- Monitor the implementation of restoration actions. Monitoring activities should include tracking the effectiveness of BMPs on forest roads in meeting targets, and summarizing the length of road upgrades to BMP standards, length of decommissioned roads, and fish passage barriers corrected. Additionally riparian BMPs should also be tracked and analyzed for effectiveness.
- Monitor redds and/or populations of native salmonid species in Bobtail Creek.
- Collect new biological (macroinvertebrate and periphyton) data every year.
- Conduct RMO assessments at sites established by the Kootenai National Forest every 5 years.

7.2 Trend Monitoring of Target Variables

MDEQ is required by state law to monitor success of this TMDL and WQRP five years after implementation of control measures through the monitoring of target values. Many of these targets are scheduled to be monitored by the USFS. MDEQ acknowledges that schedules may change and the cost associated with this monitoring; therefore, it is suggested that that all stakeholders and land managers within the watershed work together to develop a effective monitoring program for the Bobtail watershed.

Width-to-Depth Ratios, Pool Frequency, and Riffle Stability Index

Stream channel geomorphic and fish habitat assessments should be continued at the established USFS sites to assess riparian management objectives (RMOs) defined in the Inland Native Fish Strategy (USFS, 1995). The surveys should be performed at the 18 RMO and Channel Cross-Section sites shown in Figure 3-4 and listed in Table 3-10, and include measurement of the following RMOs:

- Pools frequency;
- Large woody debris per foot;
- Percent bank stability;
- Width to depth ratio; and
- Riffle stability index.

Stream channel geomorphic analyses should occur at least once every five years.

Wolman Pebble Counts

Wolman Pebble Count sampling should occur on a five-year basis, as part of the stream channel geomorphic analysis at USFS established sites in the watershed. This data will aid in evaluation of future trends in particles < 2mm for comparison to the 20% or less target. Other sites on non-USFS lands should be considered.

McNeil Core Sampling

McNeil core sampling should occur on an annual basis at one site in NE¼ of Section 5, T31N, R31W (Figure 2-2). This data will aid in evaluation of future trends in fine sediment content (<6.35mm) in the streambed for comparison to the 28% or less target. Streambed sediment data will be required from multiple locations throughout the drainage to assess future compliance with the percent fines target. The USFS monitoring activities include annual McNeil core sampling at one location in lower Bobtail Creek. At least four additional McNeil core sampling locations should be added to the monitoring program, including one near the mouth of Bobtail Creek, two in upper Bobtail Creek, and one in Bull Creek drainage. The exact monitoring locations should coincide with areas of potential fish spawning habitat to ensure the intent of this restoration target (protection of salmonids during critical life stages) is met.

7.3 Trend Monitoring of Supplemental Indicators

Stream flow and TSS Monitoring

Daily stream flow and TSS data from site Bobtail 1 near the mouth of Bobtail Creek (Section 30, T31N, R31W) should continue to be collected. This information will be used for evaluating the hydrologic response to various natural and human influences in the drainage, as well as future trends in TSS levels.

Stream flow is calculated on a daily basis from continuous stream stage data and a stream stage/flow-rating curve. Actual flow measurements are recorded six to eight times per year to update the rating curve. TSS is measured daily with an ISCO automated sampler.

Bank Stability

As mentioned above, stream channel geomorphic analysis should be continued at established USFS sites to assess riparian management objectives (RMOs) defined in the Inland Native Fish Strategy (USFS, 1995). The surveys will be performed at the 18 RMO and Channel Cross-Section sites shown in Figure 3-4 and listed in Table 3-10, and include measurement of the following RMOs:

- Pools frequency;
- Large woody debris per foot;
- Percent bank stability;
- Width to depth ratio; and
- Riffle stability index.

Stream channel geomorphic analyses should occur at least once every five years.

Macroinvertebrates

The macroinvertebrate sampling should occur annually at one site in the NE¼ of Section 5, T31N, R31W (same location as stream core sampling site, Figure 2-2). Sample analyses will

include the metrics shown in Table 3-16. Macroinvertebrate sampling should be performed at up to four additional sites corresponding to the McNeil core sampling sites recommended above to provide adequate coverage for assessing the watershed health and beneficial use attainment in the future.

7.4 Beneficial Use Linkage Indicators

Fish Population Monitoring

Montana Fish, Wildlife, and Parks is currently scheduled complete fish population surveys every two to three years. Fish populations will be monitored by two methods. First, redd counts will be conducted in the lower reaches of Bobtail Creek to evaluate the response of rainbow trout to decreased siltation of these spawning grounds. Second, resident fish will be sampled to assess fish population trends following implementation of restoration activities.

7.5 Condition Monitoring

For a stream channel to again become stable, it needs to be able to properly distribute its flow and sediment supply in order to maintain its dimension, pattern and profile without degrading or aggrading. Adjustments occur partially as a result of a change in the stream flow magnitude and/or timing, sediment supply and/or size, direct channel disturbance, and riparian vegetation changes (Rosgen, 1996). Management strategies and additional mitigations outlined in the restoration plan portion of this document would assist in the geomorphic recovery of these segments. It is important to note that "recovery" is defined as "potential for recovery" based on the reference conditions. Once this recovery is met, sediment loads are expected to reach their expected norm due to efficiency of the system. Putting a time limit on geomorphic recovery can be rather difficult. However, routine measurements of pool frequency, bank stability, and width/depth ratios can show trends over time. These trends can be used to make inferences towards the expected and desired evolutionary stage of the stream channel.

7.6 Reference Monitoring

As discussed in Sections 7.2 and 7.3, continued monitoring surrounding the water quality targets and supplemental indicators outlined in Section 3.3 is needed to further verify impairment status and achievement of full beneficial use support. In addition to monitoring and data collection of the target/indicator parameters outlined in Section 3.3, continued monitoring of those same parameters in reference streams is needed to help increase confidence that the targets and supplemental indicator values chosen best represent the narrative water quality standards.

MDEQ uses the reference condition to determine if narrative water quality standards are being achieved. The term "reference condition" is defined as the condition of a waterbody capable of supporting its present and future beneficial uses when all reasonable land, soil, and water conservation practices have been applied. In other words, reference condition reflects a waterbody's greatest potential for water quality given historic land use activities.

MDEQ applies the reference condition approach for making beneficial use-support determinations for certain pollutants (such as sediment) that have specific narrative standards. All classes of waters are subject to the provision that there can be no increase above naturally occurring concentrations of sediment and settleable solids, oils, or floating solids sufficient to create a nuisance or render the water harmful, detrimental or injurious. These levels depend on site-specific factors, so the reference conditions approach is used.

Also, Montana water quality standards do not contain specific provisions addressing nutrients (nitrogen and phosphorous), or detrimental modifications of habitat or flow. However, these factors are known to adversely affect beneficial uses under certain conditions or combination of conditions. The reference conditions approach is used to determine if beneficial uses are supported when nutrients, flow or habitat modifications are present.

Waterbodies used to determine reference condition are not necessarily pristine or perfectly suited to giving the best possible support to all possible beneficial uses. Reference condition also does not reflect an effort to turn the clock back to conditions that may have existed before human settlement, but is intended to accommodate natural variations in biological communities, water chemistry, etc. due to climate, bedrock, soils, hydrology and other natural physiochemical differences. The intention is to differentiate between natural conditions and widespread or significant alterations of biology, chemistry or hydrogeomorphology due to human activity. Therefore, reference conditions should reflect minimum impacts from human activities. It attempts to identify the potential condition that could be attained (given historical land use) by the application of reasonable land, soil and water conservation practices. MDEQ realizes that presettlement water quality conditions usually are not attainable.

Comparison of conditions in a waterbody to reference waterbody conditions must be made during similar season and/or hydrologic conditions for both waters. For example, the TSS of a stream at base flow during the summer should not be compared to the TSS of reference condition that would occur during a runoff event in the spring. In addition, a comparison should not be made to the lowest or highest TSS values of a reference site, which represent the outer boundaries of reference conditions.

The following methods may be used to determine reference conditions:

Primary Approach

- Comparing conditions in a waterbody to baseline data from minimally impaired waterbodies that are in a nearby watershed or in the same region having similar geology, hydrology, morphology, and/or riparian habitat.
- Evaluating historical data relating to condition of the waterbody in the past.
- Comparing conditions in a waterbody to conditions in another portion of the same waterbody, such as an unimpaired segment of the same stream.

Secondary Approach

- Reviewing literature and studies (e.g. a review of studies of fish populations, etc.) that were conducted on similar waterbodies that are least impaired.
- Seeking expert opinion (e.g. expert opinion from a regional fisheries biologist who has a good understanding of the waterbody's fisheries health or potential).
- Applying quantitative modeling (e.g. applying sediment transport models to determine how much sediment is entering a stream based on land use information, etc.).

MDEQ uses the primary approach for determining reference condition if adequate regional reference data are available and uses the secondary approach to estimate reference condition when there are no regional data. MDEQ often uses more than one approach to determine reference condition, especially when regional reference condition data are sparse or nonexistent.

7.7 Data Gaps

The following data gaps have been identified during the TMDL development process and will be addressed by the Implementation Team:

- Macroinvertebrate Data: Macroinvertebrate data should be collected in additional reaches within the Bobtail Creek watershed. It is important to have a representation of the entire watershed.
- Surface erosion for existing roads in the Bobtail Creek watershed should be further assessed.
- Bank erosion in the Bobtail Creek watershed should be further assessed.

7.8 Adaptive Management Strategy

As monitoring data is obtained and evaluated, MDEQ in partnership with the stakeholders will adjust load allocations as necessary to meet targets, especially those targets associated with instream conditions. Additionally, targets could also be adjusted. These adjustments would take into account new technologies and information as they arise.

At the end of 5 years, an evaluation of BMP implementation, target compliance and beneficial use determinations will be made. At this time, recommendations would be made by MDEQ to ensure that the goals of this restoration plan are being met. If, at that time, any one goal or target is not being met, an evaluation would be made that would determine one or more of the following:

- Adjustments to land-use activities;
- Make changes to original targets; and
- Collect additional data and reevaluate next cycle.

To ensure reasonable and equitable decisions are made regarding future target and/or management adjustments, MDEQ would evaluate and compare both reference and TPA stream data collected under this WQRP with the data collected prior to the development of this plan.

Additionally, if at the 5-year evaluation period it is found that any or all of the streams within the Bobtail Creek TPA are fully supporting beneficial uses, steps would be taken to ensure that management practices and mitigation measures outlined in this WQRP would continue. While favorable management practices would be expected to continue, the level of monitoring outlined in this WQRP could be revised. At this time, the monitoring strategy could be scaled back in both the frequency and intensity. While reducing the monitoring program could take place under these circumstances, enough monitoring should continue to occur to ensure that full beneficial use support remains in place.

SECTION 8.0 PUBLIC INVOLVEMENT

The Bobtail Creek Watershed Group, Kootenai National Forest, the Lincoln Conservation District, Plum Creek Timber Company and other agencies and stakeholders contributed to the development of this plan.

Early in this project, the Bobtail Creek Watershed Group played an important role in water quality restoration planning in the Bobtail Creek watershed. In 2001, the Bobtail Creek Watershed Group worked in conjunction with Montana Watershed, Inc. for a Bobtail Creek watershed project utilizing Section 319 funding. This project included restoration work, funding for education programs, and early TMDL development work. A draft of a TMDL was completed in June 2002. In November 2003 a two-week stakeholder review and an internal MDEQ review were held on the first draft of the TMDL. It was determined that additional information was available and more work needed to be done to make this an acceptable TMDL.

This version of the TMDL and water quality restoration plan has a one-month public comment period from November 29, 2004 through December 27, 2004. A formal public meeting was held on December 8, 2004 at the Forest Service Office in Libby, Montana.

This final document reflects modifications made in response to the written and verbal comments received throughout the public comment period. The written comments and respective responses to those comments are provided in Appendix F.

Any future significant revisions to this plan or identification of water quality impairment conditions on future 303(d) lists will also undergo public review.

January, 2005

APPENDIX A - Streamflow and Total Suspended Solids Data

Provided by the U.S. Forest Service

<u>Water</u>	<u>Gage</u>				
<u>Year</u>	Height	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
2001	2.11	1	10/1/00	7.651898734	2
	2.11	2	10/2/00	7.651898734	2
	2.11	3	10/3/00	7.651898734	2
	2.12	4	10/4/00	8.284810127	2
	2.12	5	10/5/00	8.284810127	2
	2.13	6	10/6/00	8.917721519	2
	2.13	7	10/7/00	8.917721519	2
	2.13	8	10/8/00	8.917721519	2
	2.14	9	10/9/00	9.550632911	2
	2.14	10	10/10/00	9.550632911	2
	2.14	11	10/11/00	9.550632911	2
	2.15	12	10/12/00	10.1835443	2
	2.15	13	10/13/00	10.1835443	2
	2.16	14	10/14/00	10.8164557	2
	2.16	15	10/15/00	10.8164557	2
	2.17	16	10/16/00	11.44936709	2
	2.18	17	10/17/00	12.08227848	2
	2.19	18	10/18/00	12.71518987	2
	2.2	19	10/19/00	13.34810127	2
	2.2	20	10/20/00	13.34810127	2
	2.21	21	10/21/00	13.98101266	2
	2.21	22	10/22/00	13.98101266	2
	2.21	23	10/23/00	13.98101266	2
	2.21	24	10/24/00	13.98101266	2
	2.22	25	10/25/00	14.61392405	2
	2.22	26	10/26/00	14.61392405	2
	2.22	27	10/27/00	14.61392405	2
	2.25	28	10/28/00	16.51265823	2
	2.23	29	10/29/00	15.24683544	2
	2.23	30	10/30/00	15.24683544	2
	2.23	31	10/31/00	15.24683544	2
	2.23	32	11/1/00	15.24683544	2
	2.23	33	11/2/00	15.24683544	2
	2.23	34	11/3/00	15.24683544	2
	2.23	35	11/4/00	15.24683544	2
	2.23	36	11/5/00	15.24683544	2
	2.23	37	11/6/00	15.24683544	2

January, 2005 A-1

Water	Gage				
<u>Year</u>	<u>Height</u>	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	2.23	38	11/7/00	15.24683544	2
	2.23	39	11/8/00	15.24683544	2
	2.23	40	11/9/00	15.24683544	2
	2.23	41	11/10/00	15.24683544	2
	2.22	42	11/11/00	14.61392405	2
	2.22	43	11/12/00	14.61392405	2
	2.22	44	11/13/00	14.61392405	2
	2.22	45	11/14/00	14.61392405	2
	2.22	46	11/15/00	14.61392405	2
	2.22	47	11/16/00	14.61392405	2
	2.22	48	11/17/00	14.61392405	2
	2.21	49	11/18/00	13.98101266	2
	2.21	50	11/19/00	13.98101266	2
	2.21	51	11/20/00	13.98101266	2
	2.21	52	11/21/00	13.98101266	2
	2.2	53	11/22/00	13.34810127	2
	2.2	54	11/23/00	13.34810127	2
	2.19	55	11/24/00	12.71518987	2
	2.19	56	11/25/00	12.71518987	2
	2.18	57	11/26/00	12.08227848	2
	2.18	58	11/27/00	12.08227848	2
	2.18	59	11/28/00	12.08227848	2
	2.17	60	11/29/00	11.44936709	2
	2.17	61	11/30/00	11.44936709	2
	2.17	62	12/1/00	11.44936709	2
	2.17	63	12/2/00	11.44936709	2
	2.17	64	12/3/00	11.44936709	2
	2.17	65	12/4/00	11.44936709	2
	2.17	66	12/5/00	11.44936709	2
	2.17	67	12/6/00	11.44936709	2
	2.17	68	12/7/00	11.44936709	2
	2.17	69	12/8/00	11.44936709	2
	2.16	70	12/9/00	10.8164557	2
	2.16	71	12/10/00	10.8164557	2
	2.16	72	12/11/00	10.8164557	2
	2.16	73	12/12/00	10.8164557	2
	2.16	74	12/13/00	10.8164557	2
	2.15	75	12/14/00	10.1835443	2
	2.15	76	12/15/00	10.1835443	2
	2.15	77	12/16/00	10.1835443	2

January, 2005 A-2

<u>Water</u>	Gage	D 4 T/	D (CEC	
<u>Year</u>	<u>Height</u>	<u>DAY</u>	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.15	78 - 3	12/17/00	10.1835443	2
	2.15	79	12/18/00	10.1835443	2
	2.15	80	12/19/00	10.1835443	2
	2.16	81	12/20/00	10.8164557	2
	2.16	82	12/21/00	10.8164557	2
	2.16	83	12/22/00	10.8164557	2
	2.16	84	12/23/00	10.8164557	2
	2.16	85	12/24/00	10.8164557	2
	2.16	86	12/25/00	10.8164557	2
	2.16	87	12/26/00	10.8164557	2
	2.16	88	12/27/00	10.8164557	2
	2.16	89	12/28/00	10.8164557	2
	2.16	90	12/29/00	10.8164557	2
	2.17	91	12/30/00	11.44936709	2
	2.17	92	12/31/00	11.44936709	2
	2.17	93	1/1/01	11.44936709	2
	2.18	94	1/2/01	12.08227848	2
	2.18	95	1/3/01	12.08227848	2
	2.19	96	1/4/01	12.71518987	2
	2.19	97	1/5/01	12.71518987	2
	2.2	98	1/6/01	13.34810127	2
	2.2	99	1/7/01	13.34810127	2
	2.21	100	1/8/01	13.98101266	2
	2.2	101	1/9/01	13.34810127	2
	2.19	102	1/10/01	12.71518987	2
	2.19	103	1/11/01	12.71518987	2
	2.2	104	1/12/01	13.34810127	2
	2.2	105	1/13/01	13.34810127	2
	2.2	106	1/14/01	13.34810127	2
	2.2	107	1/15/01	13.34810127	2
	2.2	108	1/16/01	13.34810127	2
	2.2	109	1/17/01	13.34810127	2
	2.2	110	1/18/01	13.34810127	2
	2.19	111	1/19/01	12.71518987	2
	2.19	112	1/20/01	12.71518987	2
	2.19	113	1/21/01	12.71518987	2
	2.19	114	1/22/01	12.71518987	2
	2.19	115	1/23/01	12.71518987	2
	2.19	116	1/24/01	12.71518987	2
	2.19	117	1/25/01	12.71518987	2

January, 2005 A-3

Water	Gage		_		
<u>Year</u>	<u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.18	118	1/26/01	12.08227848	2
	2.18	119	1/27/01	12.08227848	2
	2.18	120	1/28/01	12.08227848	2
	2.18	121	1/29/01	12.08227848	2
	2.18	122	1/30/01	12.08227848	2
	2.18	123	1/31/01	12.08227848	2
	2.18	124	2/1/01	12.08227848	2
	2.18	125	2/2/01	12.08227848	2
	2.18	126	2/3/01	12.08227848	2
	2.19	127	2/4/01	12.71518987	2
	2.19	128	2/5/01	12.71518987	2
	2.19	129	2/6/01	12.71518987	2
	2.19	130	2/7/01	12.71518987	2
	2.19	131	2/8/01	12.71518987	2
	2.19	132	2/9/01	12.71518987	2
	2.19	133	2/10/01	12.71518987	2
	2.19	134	2/11/01	12.71518987	2
	2.19	135	2/12/01	12.71518987	2
	2.19	136	2/13/01	12.71518987	2
	2.19	137	2/14/01	12.71518987	2
	2.19	138	2/15/01	12.71518987	2
	2.19	139	2/16/01	12.71518987	2
	2.19	140	2/17/01	12.71518987	2
	2.19	141	2/18/01	12.71518987	2
	2.19	142	2/19/01	12.71518987	2
	2.18	143	2/20/01	12.08227848	2
	2.18	144	2/21/01	12.08227848	2
	2.18	145	2/22/01	12.08227848	2
	2.18	146	2/23/01	12.08227848	2
	2.18	147	2/24/01	12.08227848	2
	2.18	148	2/25/01	12.08227848	2
	2.18	149	2/26/01	12.08227848	2
	2.18	150	2/27/01	12.08227848	2
	2.18	151	2/28/01	12.08227848	2
	2.18	152	3/1/01	12.08227848	2
	2.18	153	3/2/01	12.08227848	2
	2.19	154	3/3/01	12.71518987	2
	2.19	155	3/4/01	12.71518987	2
	2.2	156	3/5/01	13.34810127	2
	2.2	157	3/6/01	13.34810127	2

<u>Water</u> Year	<u>Gage</u> Height	DAY	Doto	CFS	TSS (Mg/L)
<u>1 ear</u>	2.2	158	<u>Date</u> 3/7/01		
	2.2	158		13.34810127	2
	2.2		3/8/01	13.34810127	2
		160	3/9/01	13.34810127	2
	2.2	161	3/10/01	13.34810127	2
	2.2	162	3/11/01	13.34810127	2
	2.2	163	3/12/01	13.34810127	2
	2.2	164	3/13/01	13.34810127	2
	2.2	165	3/14/01	13.34810127	2
	2.2	166	3/15/01	13.34810127	2
	2.2	167	3/16/01	13.34810127	2
	2.22	168	3/17/01	14.61392405	2
	2.22	169	3/18/01	14.61392405	2
	2.22	170	3/19/01	14.61392405	2
	2.22	171	3/20/01	14.61392405	2
	2.22	172	3/21/01	14.61392405	2
	2.21	173	3/22/01	13.98101266	2
	2.21	174	3/23/01	13.98101266	2
	2.2	175	3/24/01	13.34810127	2
	2.21	176	3/25/01	13.98101266	2
	2.22	177	3/26/01	14.61392405	2
	2.22	178	3/27/01	14.61392405	2
	2.23	179	3/28/01	15.24683544	2
	2.25	180	3/29/01	16.51265823	2
	2.25	181	3/30/01	16.51265823	2
	2.25	182	3/31/01	16.51265823	2
	2.25	183	4/1/01	16.51265823	2
	2.26	184	4/2/01	17.14556962	2
	2.27	185	4/3/01	17.77848101	2
	2.28	186	4/4/01	18.41139241	2
	2.29	187	4/5/01	19.0443038	2
	2.31	188	4/6/01	20.31012658	2
	2.3	189	4/7/01	19.67721519	2
	2.3	190	4/8/01	19.67721519	2
	2.3	191	4/9/01	19.67721519	2
	2.29	192	4/10/01	19.0443038	2
	2.3	193	4/11/01	19.67721519	2
	2.3	194	4/12/01	19.67721519	2
	2.3	195	4/13/01	19.67721519	2
	2.3	196	4/14/01	19.67721519	2
	2.3	197	4/15/01	19.67721519	2

Year Height DAY Date CFS TSS (Mg/L) 2.3 198 4/16/01 19.67721519 2 2.31 199 4/17/01 20.31012658 3 2.31 200 4/18/01 20.31012658 5 2.37 202 4/20/01 24.10759494 9 2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90566329 14.6 2.44 209 4/27/01 28.5379468 9.3 2.48 210 4/28/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 <t< th=""><th>Water</th><th>Gage</th><th></th><th>_</th><th></th><th></th></t<>	Water	Gage		_		
2.31 199 4/17/01 20.31012658 3 2.31 200 4/18/01 20.31012658 5 2.35 201 4/19/01 22.84177215 8 2.37 202 4/20/01 24.10759494 9 2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 12 2.39 206 4/25/01 26.63924051 14.6 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3	<u>Year</u>	<u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
2.31 200 4/18/01 20.31012658 5 2.35 201 4/19/01 22.84177215 8 2.37 202 4/20/01 24.10759494 9 2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 <					19.67721519	2
2.35 201 4/19/01 22.84177215 8 2.37 202 4/20/01 24.10759494 9 2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.47 214 5/2/01 30.43670886 5.3					20.31012658	3
2.37 202 4/20/01 24.10759494 9 2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 10.6 2.51 212 4/30/01 32.9683543 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.43 215 5/5/01 26.00632911 5.3 <th></th> <th></th> <th></th> <th>4/18/01</th> <th>20.31012658</th> <th>5</th>				4/18/01	20.31012658	5
2.37 203 4/21/01 24.10759494 10 2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.45 215 5/5/01 26.00632911 5.3		2.35	201	4/19/01	22.84177215	8
2.38 204 4/22/01 24.74050633 11 2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.38 218 5/6/01 24.74050633 4 </th <th></th> <th>2.37</th> <th>202</th> <th>4/20/01</th> <th>24.10759494</th> <th>9</th>		2.37	202	4/20/01	24.10759494	9
2.39 205 4/23/01 25.37341772 12 2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.3 218 5/6/01 24.74050633 4 <th></th> <th>2.37</th> <th>203</th> <th>4/21/01</th> <th>24.10759494</th> <th>10</th>		2.37	203	4/21/01	24.10759494	10
2.39 206 4/24/01 25.37341772 13.7 2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.3 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.34 222 5/10/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8		2.38	204	4/22/01	24.74050633	11
2.41 207 4/25/01 26.63924051 14.6 2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3		2.39	205	4/23/01	25.37341772	12
2.43 208 4/26/01 27.90506329 14.6 2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.49 214 5/2/01 30.43670886 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6		2.39	206	4/24/01	25.37341772	13.7
2.44 209 4/27/01 28.53797468 9.3 2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.42 217 5/5/01 26.06632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.0886076 8 <t< th=""><th></th><th>2.41</th><th>207</th><th>4/25/01</th><th>26.63924051</th><th>14.6</th></t<>		2.41	207	4/25/01	26.63924051	14.6
2.48 210 4/28/01 31.06962025 13.3 2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.45 216 5/4/01 27.2721519 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.28 225 5/13/01 18.41139241 4 <td< th=""><th></th><th>2.43</th><th>208</th><th>4/26/01</th><th>27.90506329</th><th>14.6</th></td<>		2.43	208	4/26/01	27.90506329	14.6
2.48 211 4/29/01 31.06962025 10.6 2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.23 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 <t< th=""><th></th><th>2.44</th><th>209</th><th>4/27/01</th><th>28.53797468</th><th>9.3</th></t<>		2.44	209	4/27/01	28.53797468	9.3
2.51 212 4/30/01 32.96835443 5.3 2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.177848101 4 2		2.48	210	4/28/01	31.06962025	13.3
2.49 213 5/1/01 31.70253165 5.3 2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.32 223 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.175848101 4 2.26 228 5/16/01 17.14556962 64 2		2.48	211	4/29/01	31.06962025	10.6
2.47 214 5/2/01 30.43670886 5.3 2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.32 223 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 5.340425532 33.3 2.04<		2.51	212	4/30/01	32.96835443	5.3
2.45 215 5/3/01 29.17088608 5.3 2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 5.340425532 33.3 2.04 <th></th> <th>2.49</th> <th>213</th> <th>5/1/01</th> <th>31.70253165</th> <th>5.3</th>		2.49	213	5/1/01	31.70253165	5.3
2.42 216 5/4/01 27.2721519 5.3 2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 <th></th> <th>2.47</th> <th>214</th> <th>5/2/01</th> <th>30.43670886</th> <th>5.3</th>		2.47	214	5/2/01	30.43670886	5.3
2.4 217 5/5/01 26.00632911 5.3 2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.587628866 8 2.05 <th></th> <th>2.45</th> <th>215</th> <th>5/3/01</th> <th>29.17088608</th> <th>5.3</th>		2.45	215	5/3/01	29.17088608	5.3
2.38 218 5/6/01 24.74050633 4 2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.87628866 8 2.05 233 5/21/01 5.587628866 8 2.08 <th></th> <th>2.42</th> <th>216</th> <th>5/4/01</th> <th>27.2721519</th> <th>5.3</th>		2.42	216	5/4/01	27.2721519	5.3
2.37 219 5/7/01 24.10759494 6.6 2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.587628866 8 2.05 233 5/21/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13		2.4	217	5/5/01	26.00632911	5.3
2.36 220 5/8/01 23.47468354 90.6 2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13		2.38	218	5/6/01	24.74050633	4
2.35 221 5/9/01 22.84177215 6.6 2.34 222 5/10/01 22.20886076 8 2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.37	219	5/7/01	24.10759494	6.6
2.34 222 5/10/01 22,20886076 8 2.32 223 5/11/01 20,94303797 1.3 2.3 224 5/12/01 19,67721519 1.3 2.28 225 5/13/01 18,41139241 4 2.27 226 5/14/01 17,77848101 2.6 2.27 227 5/15/01 17,77848101 4 2.26 228 5/16/01 17,14556962 64 2.18 229 5/17/01 7,17 104 2.09 230 5/18/01 6,17062635 2.6 2.03 231 5/19/01 5,340425532 33.3 2.04 232 5/20/01 5,4375 8 2.05 233 5/21/01 5,587628866 8 2.08 234 5/22/01 5,954643629 9.3 2.11 235 5/23/01 7,651898734 4 2.13 236 5/24/01 8,917721519 28		2.36	220	5/8/01	23.47468354	90.6
2.32 223 5/11/01 20.94303797 1.3 2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.35	221	5/9/01	22.84177215	6.6
2.3 224 5/12/01 19.67721519 1.3 2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.34	222	5/10/01	22.20886076	8
2.28 225 5/13/01 18.41139241 4 2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.32	223	5/11/01	20.94303797	1.3
2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.3	224	5/12/01	19.67721519	1.3
2.27 226 5/14/01 17.77848101 2.6 2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.28	225	5/13/01	18.41139241	4
2.27 227 5/15/01 17.77848101 4 2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28				5/14/01	17.77848101	2.6
2.26 228 5/16/01 17.14556962 64 2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.27			17.77848101	
2.18 229 5/17/01 7.17 104 2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.26		5/16/01	17.14556962	64
2.09 230 5/18/01 6.17062635 2.6 2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28				5/17/01		
2.03 231 5/19/01 5.340425532 33.3 2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28		2.09	230	5/18/01	6.17062635	2.6
2.04 232 5/20/01 5.4375 8 2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28			231			
2.05 233 5/21/01 5.587628866 8 2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28						
2.08 234 5/22/01 5.954643629 9.3 2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28						
2.11 235 5/23/01 7.651898734 4 2.13 236 5/24/01 8.917721519 28						
2.13 236 5/24/01 8.917721519 28						

Water Year	Gage Height	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.18	238	5/26/01	12.08227848	5.3
	2.17	239	5/27/01	11.44936709	30.6
	2.16	240	5/28/01	10.8164557	2.6
	2.16	241	5/29/01	10.8164557	2.6
	2.16	242	5/30/01	10.8164557	2.6
	2.17	243	5/31/01	11.44936709	4
	2.17	244	6/1/01	11.44936709	5.3
	2.16	245	6/2/01	10.8164557	3.9
	2.17	246	6/3/01	11.44936709	2.6
	2.17	247	6/4/01	11.44936709	2.6
	2.16	248	6/5/01	10.8164557	4
	2.16	249	6/6/01	10.8164557	2.6
	2.16	250	6/7/01	10.8164557	22.6
	2.16	251	6/8/01	10.8164557	2.6
	2.16	252	6/9/01	10.8164557	2.6
	2.16	253	6/10/01	10.8164557	2.6
	2.16	254	6/11/01	10.816456	5.3
	2.17	255	6/12/01	11.44936709	5.3
	2.17	256	6/13/01	11.44936709	14.6
	2.17	257	6/14/01	11.44936709	9.3
	2.17	258	6/15/01	11.44936709	34.6
	2.18	259	6/16/01	12.08227848	4
	2.18	260	6/17/01	12.08227848	12
	2.17	261	6/18/01	11.44936709	6.6
	2.18	262	6/19/01	12.08227848	6.6
	2.18	263	6/20/01	12.08227848	6.6
	2.18	264	6/21/01	12.08227848	8
	2.18	265	6/22/01	12.08227848	6.7
	2.17	266	6/23/01	11.44936709	5.3
	2.17	267	6/24/01	11.44936709	5.6
	2.17	268	6/25/01	11.44936709	9.3
	2.17	269	6/26/01	11.44936709	6.6
	2.16	270	6/27/01	10.8164557	5.4
	2.16	271	6/28/01	10.8164557	6.7
	2.15	272	6/29/01	10.1835443	6.6
	2.14	273	6/30/01	9.550632911	2.7
	2.14	274	7/1/01	9.550632911	4
	2.15	275	7/2/01	10.1835443	4
	2.12	276	7/3/01	8.284810127	4
	2.12	277	7/4/01	8.284810127	4

<u>Water</u> Year	<u>Gage</u> <u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
1001	2.11	278	7/5/01	7.651898734	4
	2.11	279	7/6/01	7.651898734	3
	2.1	280	7/7/01	7.018987342	2.6
	2.09	281	7/8/01	6.386075949	2.6
	2.07	282	7/9/01	5.738660907	4.1
	2.05	283	7/10/01	5.587628866	2.7
	2.04	284	7/11/01	5,4375	4.2
	2.03	285	7/12/01	5.340425532	2.6
	2.03	286	7/13/01	5.340425532	1.4
	2.03	287	7/14/01	5.340425532	8
	2.04	288	7/15/01	5.4375	2.6
	2.04	289	7/16/01	5.4375	2.6
	2.04	290	7/17/01	5.4375	2.6
	2.04	291	7/18/01	5.4375	2.6
	2.03	292	7/19/01	5.340425532	1.3
	2.03	293	7/20/01	5.340425532	1.3
	2.03	294	7/21/01	5.340425532	1.3
	2.03	295	7/22/01	5.340425532	2.8
	2.03	296	7/23/01	5.340425532	2.6
	2.04	297	7/24/01	5.4375	2.6
	2.04	298	7/25/01	5.4375	1.3
	2.03	299	7/26/01	5.340425532	1.3
	2.02	300	7/27/01	5.127659574	1.3
	2.02	301	7/28/01	5.127659574	1.3
	2.02	302	7/29/01	5.127659574	1.3
	2.02	303	7/30/01	4.07	1.3
	2.03	304	7/31/01	5.340425532	1.3
	2.03	305	8/1/01	5.340425532	1.3
	2.03	306	8/2/01	5.340425532	1.8
	2.02	307	8/3/01	5.127659574	2.8
	2.01	308	8/4/01	4.914893617	4.2
	2	309	8/5/01	4.70212766	1.3
	1.99	310	8/6/01	4.508547009	1.4
	1.97	311	8/7/01	4.081196581	2.8
	1.95	312	8/8/01	3.717391304	1.4
	1.93	313	8/9/01	3.431818182	1.4
	1.91	314	8/10/01	3.119047619	1.5
	1.92	315	8/11/01	3.279069767	1.4
	1.91	316	8/12/01	3.119047619	1.5
	1.91	317	8/13/01	3.119047619	1.4

Water Year	Gage	DAV	Doto	CES	TSS (Ma/I)
<u>1 ear</u>	<u>Height</u> 1.93	<u>DAY</u> 318	<u>Date</u> 8/14/01	<u>CFS</u>	TSS (Mg/L)
	1.95	318	8/14/01 8/15/01	3.431818182 3.717391304	1.3
	1.93	320	8/16/01	3.577777778	1.3 1.5
	1.94	320	8/17/01	3.717391304	3.3
	1.95	321	8/18/01	3.717391304	3.3 1.6
	1.96	323	8/19/01	3.867521368	1.4
	1.95	324	8/20/01	3.717391304	1.4
	1.95	325	8/21/01	3.717391304	4.2
	1.95	326	8/22/01	3.717391304	4
	1.95	327	8/23/01	3.717391304	3.2
	1.94	328	8/24/01	3.577777778	2.7
	1.95	329	8/25/01	3.717391304	1.4
	1.94	330	8/26/01	3.577777778	1.3
	1.94	331	8/27/01	3.577777778	2.6
	1.94	332	8/28/01	3.577777778	2.8
	1.93	333	8/29/01	3.431818182	2.8
	1.93	334	8/30/01	3.431818182	1.3
	1.93	335	8/31/01	3.431818182	1.3
	1.93	336	9/1/01	3.431818182	1.4
	1.93	337	9/2/01	3.431818182	1.3
	1.93	338	9/3/01	3.431818182	1.3
	1.93	339	9/4/01	3.431818182	1.5
	1.93	340	9/5/01	3.431818182	1.4
	1.93	341	9/6/01	3.431818182	1.3
	1.93	342	9/7/01	3.431818182	1.3
	1.93	343	9/8/01	3.431818182	1.3
	1.93	344	9/9/01	3.431818182	1.3
	1.93	345	9/10/01	3.431818182	1.3
	1.92	346	9/11/01	3.279069767	1.3
	1.92	347	9/12/01	3.279069767	1.3
	1.92	348	9/13/01	3.279069767	1.3
	1.92	349	9/14/01	3.279069767	1.3
	1.92	350	9/15/01	3.279069767	1.4
	1.92	351	9/16/01	3.279069767	1.3
	1.91	352	9/17/01	3.119047619	1.3
	1.91	353	9/18/01	3.119047619	1.3
	1.91	354	9/19/01	3.119047619	1.3
	1.91	355	9/20/01	3.119047619	1.3
	1.91	356	9/21/01	3.119047619	1.3
	1.9	357	9/22/01	2.951219512	1.3

<u>Water</u>	Gage				
<u>Year</u>	Height	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	1.9	358	9/23/01	2.951219512	1.3
	1.9	359	9/24/01	2.951219512	1.3
	1.9	360	9/25/01	2.951219512	1.3
	1.9	361	9/26/01	2.951219512	2
	1.9	362	9/27/01	2.951219512	3
	1.89	363	9/28/01	2.775	2.6
	1.89	364	9/29/01	2.775	1.3
	1.89	365	9/30/01	2.93	1.3
2002	1.89	1	10/1/01	2.775	1.3
	1.89	2	10/2/01	2.775	1.3
	1.89	3	10/3/01	2.775	1.3
	1.9	4	10/4/01	2.951219512	4.1
	1.9	5	10/5/01	2.951219512	9
	1.91	6	10/6/01	3.119047619	1.3
	1.92	7	10/7/01	3.279069767	1.2
	1.93	8	10/8/01	3.431818182	1.2
	1.93	9	10/9/01	3.431818182	1.2
	2	10	10/10/01	4.70212766	2.5
	2.03	11	10/11/01	5.340425532	5.3
	2.03	12	10/12/01	5.340425532	1.3
	2.03	13	10/13/01	5.340425532	1.3
	2.03	14	10/14/01	5.340425532	1.3
	2.03	15	10/15/01	5.340425532	1.3
	2.03	16	10/16/01	5.340425532	1.3
	2.04	17	10/17/01	5.4375	1.3
	2.04	18	10/18/01	5.4375	1.3
	2.04	19	10/19/01	5.4375	1.3
	2.04	20	10/20/01	5.4375	1.3
	2.04	21	10/21/01	5.4375	1.3
	2.1	22	10/22/01	7.018987342	1.3
	2.11	23	10/23/01	7.651898734	1.3
	2.11	24	10/24/01	7.651898734	1.3
	2.1	25	10/25/01	7.018987342	1.3
	2.1	26	10/26/01	7.018987342	1.3
	2.1	27	10/27/01	7.018987342	1.3
	2.1	28	10/28/01	7.018987342	1.3
	2.1	29	10/29/01	7.018987342	1.3
	2.1	30	10/30/01	7.018987342	1.3
	2.1	31	10/31/01	7.018987342	1.3
	2.1	32	11/1/01	7.018987342	1.3

<u>Water</u>	Gage			C T C	mag 25 F)
<u>Year</u>	<u>Height</u>	<u>DAY</u>	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.1	33	11/2/01	7.018987342	1.3
	2.1	34	11/3/01	7.018987342	1.3
	2.1	35	11/4/01	7.018987342	1.3
	2.1	36	11/5/01	7.018987342	1.3
	2.1	37	11/6/01	7.018987342	1.3
	2.1	38	11/7/01	7.018987342	1.3
	2.11	39	11/8/01	7.651898734	1.3
	2.11	40	11/9/01	7.651898734	1.3
	2.11	41	11/10/01	7.651898734	1.3
	2.11	42	11/11/01	7.651898734	1.3
	2.1	43	11/12/01	7.018987342	1.3
	2.1	44	11/13/01	7.018987342	1.3
	2.1	45	11/14/01	7.018987342	1.3
	2.1	46	11/15/01	7.018987342	1.3
	2.1	47	11/16/01	7.018987342	1.3
	2.1	48	11/17/01	7.018987342	1.3
	2.1	49	11/18/01	7.018987342	1.3
	2.1	50	11/19/01	7.018987342	1.3
	2.09	51	11/20/01	6.386075949	1.3
	2.09	52	11/21/01	6.386075949	1.3
	2.08	53	11/22/01	5.954643629	1.3
	2.08	54	11/23/01	5.954643629	1.3
	2.07	55	11/24/01	5.738660907	1.3
	2.07	56	11/25/01	5.738660907	1.7
	2.07	57	11/26/01	5.738660907	1.3
	2.07	58	11/27/01	5.738660907	1.3
	2.07	59	11/28/01	5.738660907	1.3
	2.07	60	11/29/01	5.738660907	1.3
	2.07	61	11/30/01	5.738660907	1.3
	2.07	62	12/1/01	5.738660907	1.3
	2.07	63	12/2/01	5.738660907	1.3
	2.06	64	12/3/01	5.522678186	1.3
	2.06	65	12/4/01	5.522678186	1.3
	2.07	66	12/5/01	5.738660907	1.3
	2.07	67	12/6/01	5.738660907	1.3
	2.07	68	12/7/01	5.738660907	1.3
	2.07	69	12/8/01	5.738660907	1.3
	2.07	70	12/9/01	5.738660907	1.3
	2.08	71	12/10/01	5.954643629	1.3
	2.08	72	12/11/01	5.954643629	1.3

Water	Gage				
Year	<u>Height</u>	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	2.08	73	12/12/01	5.954643629	1.3
	2.08	74	12/13/01	5.954643629	1.3
	2.08	75	12/14/01	5.954643629	1.3
	2.09	76	12/15/01	6.386075949	1.3
	2.09	77	12/16/01	6.386075949	1.3
	2.09	78	12/17/01	6.386075949	1.3
	2.09	79	12/18/01	6.386075949	1.3
	2.1	80	12/19/01	7.018987342	1.3
	2.1	81	12/20/01	7.018987342	1.3
	2.1	82	12/21/01	7.018987342	1.3
	2.1	83	12/22/01	7.018987342	1.3
	2.11	84	12/23/01	7.651898734	1.3
	2.11	85	12/24/01	7.651898734	1.3
	2.11	86	12/25/01	7.651898734	1.3
	2.11	87	12/26/01	7.651898734	1.3
	2.12	88	12/27/01	8.284810127	1.3
	2.12	89	12/28/01	8.284810127	1.3
	2.12	90	12/29/01	8.284810127	1.3
	2.12	91	12/30/01	8.284810127	1.3
	2.12	92	12/31/01	8.284810127	1.3
	2.12	93	1/1/02	8.284810127	1.3
	2.11	94	1/2/02	7.651898734	1.3
	2.11	95	1/3/02	7.651898734	1.3
	2.11	96	1/4/02	7.651898734	1.3
	2.12	97	1/5/02	8.284810127	1.3
	2.12	98	1/6/02	8.284810127	1.3
	2.12	99	1/7/02	8.284810127	1.3
	2.15	100	1/8/02	10.1835443	1.3
	2.34	101	1/9/02	22.20886076	1.3
	2.32	102	1/10/02	20.94303797	1.3
	2.3	103	1/11/02	19.67721519	1.3
	2.18	104	1/12/02	12.08227848	1.3
	2.18	105	1/13/02	12.08227848	1.3
	2.17	106	1/14/02	11.44936709	1.3
	2.15	107	1/15/02	10.1835443	1.3
	2.12	108	1/16/02	8.284810127	1.3
	2.11	109	1/17/02	7.651898734	1.3
	2.11	110	1/18/02	7.651898734	1.3
	2.11	111	1/19/02	7.651898734	1.3
	2.11	112	1/20/02	7.651898734	1.3

Water Vace	<u>Gage</u>	DAV	Data	CEC	TCC (Madi)
<u>Year</u>	<u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.11	113	1/21/02	7.651898734	1.3
	2.12	114	1/22/02	8.284810127	1.3
	2.12	115	1/23/02	8.284810127	1.3
	2.12	116	1/24/02	8.284810127	1.3
	2.12	117	1/25/02	8.284810127	1.3
	2.11	118	1/26/02	7.651898734	1.3
	2.11	119	1/27/02	7.651898734	1.3
	2.11	120	1/28/02	7.651898734	1.3
	2.11	121	1/29/02	7.651898734	1.3
	2.12	122	1/30/02	8.284810127	1.3
	2.12	123	1/31/02	8.284810127	1.3
	2.12	124	2/1/02	8.284810127	1.4
	2.12	125	2/2/02	8.284810127	1.5
	2.11	126	2/3/02	7.651898734	1.6
	2.11	127	2/4/02	7.651898734	1.7
	2.11	128	2/5/02	7.651898734	1.8
	2.12	129	2/6/02	8.284810127	1.9
	2.12	130	2/7/02	8.284810127	2
	2.12	131	2/8/02	8.284810127	2
	2.11	132	2/9/02	7.651898734	2
	2.11	133	2/10/02	7.651898734	2
	2.11	134	2/11/02	7.651898734	2
	2.11	135	2/12/02	7.651898734	2
	2.1	136	2/13/02	7.018987342	2
	2.1	137	2/14/02	7.018987342	2
	2.1	138	2/15/02	7.018987342	2
	2.11	139	2/16/02	7.651898734	2
	2.11	140	2/17/02	7.651898734	2
	2.12	141	2/18/02	8.284810127	2
	2.13	142	2/19/02	8.917721519	2
	2.12	143	2/20/02	8.284810127	2
	2.12	144	2/21/02	8.284810127	2
	2.13	145	2/22/02	8.917721519	2
	2.13	146	2/23/02	8.917721519	2
	2.8	147	2/24/02	51.32278481	200
	2.7	148	2/25/02	44.99367089	200
	2.65	149	2/26/02	41.82911392	200
	2.6	150	2/27/02	38.66455696	200
	2.55	151	2/28/02	35.5	300
	2.5	152	3/1/02	32.33544304	300

Water	Gage				
<u>Year</u>	Height	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	2.45	153	3/2/02	29.17088608	200
	2.4	154	3/3/02	26.00632911	200
	2.3	155	3/4/02	19.67721519	100
	2.25	156	3/5/02	16.51265823	50
	2.2	157	3/6/02	13.34810127	50
	2.2	158	3/7/02	13.34810127	30
	2.19	159	3/8/02	12.71518987	20
	2.18	160	3/9/02	12.08227848	2
	2.18	161	3/10/02	12.08227848	2
	2.19	162	3/11/02	12.71518987	2
	2.3	163	3/12/02	19.67721519	2
	2.37	164	3/13/02	24.10759494	2
	2.52	165	3/14/02	33.60126582	2
	2.52	166	3/15/02	33.60126582	2
	2.5	167	3/16/02	32.33544304	2
	2.46	168	3/17/02	29.80379747	2
	2.46	169	3/18/02	29.80379747	2
	2.41	170	3/19/02	26.63924051	2
	2.41	171	3/20/02	26.63924051	2
	2.41	172	3/21/02	26.63924051	2
	2.41	173	3/22/02	26.63924051	2
	2.4	174	3/23/02	26.00632911	2
	2.4	175	3/24/02	26.00632911	2
	2.4	176	3/25/02	26.00632911	2
	2.39	177	3/26/02	25.37341772	20
	2.39	178	3/27/02	25.37341772	70
	2.4	179	3/28/02	26.00632911	100
	2.5	180	3/29/02	32.33544304	500
	2.5	181	3/30/02	32.33544304	1000
	2.63	182	3/31/02	40.56329114	2000
	2.68	183	4/1/02	43.7278481	7000
	2.81	184	4/2/02	67.40932642	8000
	3.03	185	4/3/02	78.80829016	9000
	2.9	186	4/4/02	72.07253886	5000
	2.87	187	4/5/02	70.51813472	5000
	2.85	188	4/6/02	69.48186528	6000
	2.82	189	4/7/02	67.92746114	6000
	2.88	190	4/8/02	78.41	6000
	2.9	191	4/9/02	72.07253886	7084
	3.08	192	4/10/02	81.39896373	9094

<u>Water</u>	<u>Gage</u>	DAW	D . (CEC	
<u>Year</u>	<u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	3.1	193	4/11/02	82.43523316	14786
	3.13	194	4/12/02	83.98963731	14015
	3.2	195	4/13/02	87.61658031	8794
	3.35	196	4/14/02	95.38860104	2142
	3.45	197	4/15/02	100.5699482	2437
	3.75	198	4/16/02	116.1139896	3175
	3.5	199	4/17/02	103.1606218	2212
	3	200	4/18/02	77.25388601	1202
	2.55	201	4/19/02	53.93782383	48.6
	2.53	202	4/20/02	52.9015544	38.7
	2.5	203	4/21/02	51.34715026	52.7
	2.48	204	4/22/02	50.31088083	2554
	2.46	205	4/23/02	49.2746114	2500
	2.45	206	4/24/02	48.75647668	2500
	2.38	207	4/25/02	45.12953368	1500
	2.36	208	4/26/02	44.09326425	1000
	2.32	209	4/27/02	42.02072539	500
	2.28	210	4/28/02	39.94818653	100
	2.22	211	4/29/02	36.83937824	10.6
	2.2	212	4/30/02	35.80310881	5.3
	2.2	213	5/1/02	35.80310881	5.3
	2.19	214	5/2/02	35.28497409	5.3
	2.21	215	5/3/02	36.32124352	17.5
	2.28	216	5/4/02	39.94818653	17.5
	2.22	217	5/5/02	36.83937824	8.7
	2.21	218	5/6/02	36.32124352	13.7
	2.2	219	5/7/02	35.80310881	13.7
	2.2	220	5/8/02	35.80310881	10
	2.15	221	5/9/02	33.21243523	10
	2.09	222	5/10/02	30.10362694	7.7
	2.04	223	5/11/02	27.51295337	8
	2.02	224	5/12/02	26.47668394	6
	2	225	5/13/02	25,44041451	5.3
	1.98	226	5/14/02	24.40414508	7.5
	2.05	227	5/15/02	28.03108808	6.2
	2.09	228	5/16/02	30.10362694	5
	2.13	229	5/17/02	32.1761658	1.2
	2.13	230	5/18/02	32.1761658	1.2
	2.12	231	5/19/02	31.65803109	1.2
	2.13	232	5/20/02	32.1761658	6.2
	4.13	434	3120102	32.1701030	0.2

Water	Gage				
<u>Year</u>	<u>Height</u>	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	2.13	233	5/21/02	32.1761658	55
	2.18	234	5/22/02	34.76683938	155
	2.38	235	5/23/02	45.12953368	122.5
	2.55	236	5/24/02	53.93782383	66.2
	2.35	237	5/25/02	43.57512953	35
	2.19	238	5/26/02	35.28497409	30.4
	2.18	239	5/27/02	34.76683938	30.6
	2.17	240	5/28/02	34.24870466	25
	2.16	241	5/29/02	33.73056995	24
	2.15	242	5/30/02	33.21243523	21.2
	2.14	243	5/31/02	32.69430052	18.7
	2.13	244	6/1/02	32.1761658	18.7
	2.12	245	6/2/02	31.65803109	15
	2.1	246	6/3/02	30.62176166	14.5
	2.08	247	6/4/02	29.58549223	12
	2.06	248	6/5/02	28.5492228	10
	2.04	249	6/6/02	27.51295337	8
	2.02	250	6/7/02	26.47668394	6
	2	251	6/8/02	25.44041451	2.6
	1.98	252	6/9/02	24.40414508	2.6
	1.96	253	6/10/02	23.36787565	2.6
	1.93	254	6/11/02	21.8134715	5.3
	1.9	255	6/12/02	20.25906736	5.3
	1.89	256	6/13/02	19.74093264	14.6
	1.87	257	6/14/02	18.70466321	9.3
	1.86	258	6/15/02	18.1865285	34.6
	1.86	259	6/16/02	18.1865285	4
	1.85	260	6/17/02	17.66839378	12
	1.84	261	6/18/02	17.15025907	6.6
	1.83	262	6/19/02	16.63212435	6.6
	1.82	263	6/20/02	16.11398964	6.6
	1.82	264	6/21/02	16.11398964	8
	1.8	265	6/22/02	15.07772021	6.7
	1.8	266	6/23/02	15.07772021	5.3
	1.79	267	6/24/02	14.55958549	5.6
	1.77	268	6/25/02	13.52331606	9.3
	1.77	269	6/26/02	13.52331606	6.6
	1.76	270	6/27/02	13.00518135	5.4
	1.75	271	6/28/02	12.48704663	6.7
	1.75	272	6/29/02	12.48704663	6.6

Water Voor	Gage	DAV	Doto	CES	TSS (Mg/I)
<u>Year</u>	Height	<u>DAY</u>	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	1.74	273	6/30/02	11.96891192	2.7
	1.74	274	7/1/02	11.96891192	4
	1.74	275	7/2/02	11.96891192	4
	1.73	276	7/3/02	11.4507772	4
	1.72	277	7/4/02	10.93264249	4
	1.72	278	7/5/02	10.93264249	4
	1.71	279	7/6/02	10.41450777	3
	1.71	280	7/7/02	10.41450777	2.6
	1.7	281	7/8/02	9.896373057	2.6
	1.7	282	7/9/02	9.896373057	4.1
	1.69	283	7/10/02	9.378238342	2.7
	1.69	284	7/11/02	9.378238342	2.7
	1.68	285	7/12/02	8.860103627	2.7
	1.68	286	7/13/02	8.860103627	2.7
	1.68	287	7/14/02	8.860103627	2
	1.67	288	7/15/02	8.341968912	1
	1.67	289	7/16/02	8.341968912	3.7
	1.67	290	7/17/02	8.341968912	1.2
	1.67	291	7/18/02	8.341968912	2.5
	1.66	292	7/19/02	7.823834197	2.5
	1.66	293	7/20/02	7.823834197	2.5
	1.67	294	7/21/02	8.341968912	1.2
	1.66	295	7/22/02	7.823834197	1.2
	1.66	296	7/23/02	7.823834197	3.7
	1.66	297	7/24/02	7.823834197	2.5
	1.66	298	7/25/02	7.823834197	3.7
	1.66	299	7/26/02	7.823834197	4.9
	1.66	300	7/27/02	7.823834197	3.8
	1.65	301	7/28/02	7.305699482	8.8
	1.65	302	7/29/02	7.305699482	2.3
	1.65	303	7/30/02	7.305699482	2.8
	1.64	304	7/31/02	6.787564767	1.6
	1.64	305	8/1/02	6.787564767	6.1
	1.64	306	8/2/02	6.787564767	2.5
	1.63	307	8/3/02	6.269430052	11.2
	1.63	308	8/4/02	6.269430052	4
	1.62	309	8/5/02	5.751295337	2.7
	1.62	310	8/6/02	5.751295337	2.6
	1.61	310	8/7/02	5.233160622	2.5
	1.61	312	8/8/02	5.233160622	2.5

Water Voor	<u>Gage</u>	DAV	Doto	CES	TSS (Ma/I)
<u>Year</u>	Height	<u>DAY</u>	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	1.61 1.61	313	8/9/02	5.233160622	2.4
	1.61	314	8/10/02 8/11/02	5.233160622	2.3
	1.61	315 316	8/11/02	5.233160622	2
	1.61	317	8/13/02	5.233160622 5.233160622	2 2
	1.61	317	8/13/02	5.233160622	
	1.61	319	8/15/02	5.233160622	2 2
	1.61	320	8/15/02	5.233160622	2
	1.6	321	8/17/02	<i>4.715025907</i>	2
	1.61	321	8/18/02	5.233160622	1.6
	1.6	323	8/19/02	5.33	1.4
	1.61	324	8/20/02	5.233160622	1.4
	1.6	325	8/21/02	<i>4.715025907</i>	4.2
	1.6	326	8/22/02	4.715025907	4.2
	1.6	327	8/23/02	4.715025907	3.2
	1.6	328	8/24/02	4.715025907	2.7
	1.6	329	8/25/02	4.715025907	1.4
	1.6	330	8/26/02	4.715025907	1.4
	1.6	331	8/27/02	4.715025907	2.6
	1.6	332	8/28/02	4.715025907	2.8
	1.6	333	8/29/02	4.715025907	2.8
	1.6	334	8/30/02	4.715025907	1.3
	1.6	335	8/31/02	4.715025907	1.3
	1.59	336	9/1/02	4.713023907	1.3
	1.59	337	9/2/02	4.196891192	1.4
	1.59	338	9/3/02	4.196891192	1.3
	1.59	339	9/4/02	4.196891192	1.5
	1.59	340	9/5/02	4.196891192	1.4
	1.59	341	9/6/02	4.196891192	1.3
	1.59	342	9/7/02	4.196891192	1.3
	1.59	343	9/8/02	4.196891192	1.3
	1.58	344	9/9/02	3.678756477	1.3
	1.58	345	9/10/02	3.678756477	1.3
	1.58	346	9/11/02	3.678756477	1.3
	1.58	347	9/12/02	3.678756477	1.3
	1.58	348	9/13/02	3.678756477	1.3
	1.58	349	9/14/02	3.678756477	1.3
	1.57	350	9/15/02	3.160621762	1.4
	1.57	351	9/16/02	3.160621762	1.3
	1.57	352	9/17/02	3.160621762	1.3
	1.57	JJ2	1111104	3.100021/02	1.3

<u>Water</u> Year	<u>Gage</u> Height	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
<u>1 cur</u>	1.57	353	9/18/02	3.160621762	1.3
	1.57	354	9/19/02	3.160621762	1.3
	1.57	355	9/20/02	3.160621762	1.3
	1.57	356	9/21/02	3.160621762	1.3
	1.57	357	9/22/02	3.160621762	1.3
	1.56	358	9/23/02	2.642487047	1.3
	1.56	359	9/24/02	2.642487047	1.3
	1.56	360	9/25/02	2.642487047	1.3
	1.56	361	9/26/02	2.642487047	2
	1.56	362	9/27/02	2.642487047	3
	1.56	363	9/28/02	2.642487047	2.6
	1.56	364	9/29/02	2.642487047	1.3
	1.56	365	9/30/02	2.642487047	1.3
2003	1.54	1	10/1/02	1.606217617	1.2
	1.54	2	10/2/02	1.606217617	1.2
	1.54	3	10/3/02	1.606217617	1.1
	1.54	4	10/4/02	1.606217617	1.1
	1.54	5	10/5/02	1.606217617	1.2
	1.54	6	10/6/02	1.606217617	1.2
	1.54	7	10/7/02	1.606217617	1.2
	1.54	8	10/8/02	1.606217617	1.2
	1.54	9	10/9/02	1.606217617	1.2
	1.54	10	10/10/02	1.606217617	1.2
	1.54	11	10/11/02	1.606217617	1.8
	1.54	12	10/12/02	1.606217617	1.6
	1.54	13	10/13/02	1.606217617	1.2
	1.54	14	10/14/02	1.606217617	1.2
	1.54	15	10/15/02	1.606217617	1.2
	1.54	16	10/16/02	1.606217617	1.2
	1.54	17	10/17/02	1.606217617	1.2
	1.54	18	10/18/02	1.606217617	1.2
	1.55	19	10/19/02	2.124352332	1.2
	1.55	20	10/20/02	2.124352332	1.2
	1.56	21	10/21/02	2.642487047	1.2
	1.56	22	10/22/02	2.642487047	1.2
	1.56	23	10/23/02	2.642487047	2.5
	1.56	24	10/24/02	2.642487047	5
	1.56	25	10/25/02	2.642487047	5
	1.56	26	10/26/02	2.642487047	1.2
	1.56	27	10/27/02	2.642487047	1.2

Water Voor	Gage	DAV	Doto	CES	тее (Ма/Г)
<u>Year</u>	<u>Height</u>	DAY	<u>Date</u> 10/28/02	<u>CFS</u>	TSS (Mg/L)
	1.56 1.56	28 29	10/28/02	2.642487047	1.3 1.3
			10/29/02	2.642487047 2.642487047	
	1.56 1.56	30 31	10/30/02		1.3 1.3
	1.56	32	11/1/02	2.642487047 2.642487047	1.3 1.2
	1.56	33	11/1/02	2.642487047	1.2
	1.50 1.57	33 34	11/2/02	3.160621762	1.2
	1.57 1.57	3 4 35	11/3/02	3.160621762	1.2
	1.57 1.57	36	11/4/02	3.160621762	1.2
	1.57 1.57	30 37	11/6/02	3.160621762	1.2
	1.57 1.57	38	11/0/02	3.160621762	1.2
	1.57 1.57	39	11/7/02	3.160621762	1.2
	1.57 1.57	40	11/9/02	3.160621762	1.2
	1.57	41	11/10/02	3.160621762	1.2
	1.57	42	11/11/02	3.160621762	1.2
	1.57	43	11/11/02	3.160621762	1.2
	1.57	44	11/13/02	3.160621762	1.2
	1.57	45	11/13/02	3.160621762	1.2
	1.57	46	11/15/02	3.160621762	1.2
	1.57	47	11/16/02	3.160621762	1.2
	1.57	48	11/17/02	3.160621762	1.2
	1.57	49	11/18/02	3.160621762	1.2
	1.57	50	11/19/02	3.160621762	1.2
	1.57	51	11/20/02	3.160621762	1.2
	1.57	52	11/21/02	3.160621762	1.2
	1.57	53	11/22/02	3.160621762	1.2
	1.57	5 <i>4</i>	11/23/02	3.160621762	1.2
	1.57	55	11/24/02	3.160621762	1.2
	1.57	56	11/25/02	3.160621762	1.2
	1.57	57	11/26/02	3.160621762	1.2
	1.58	58	11/27/02	3.678756477	1.3
	1.58	59	11/28/02	3.678756477	1.3
	1.58	60	11/29/02	3.678756477	1.3
	1.58	61	11/30/02	3.678756477	1.3
	1.58	62	12/1/02	3.678756477	1.3
	1.58	63	12/2/02	3.678756477	1.3
	1.58	64	12/3/02	3.678756477	1.3
	1.58	65	12/4/02	3.678756477	1.3
	1.58	66	12/5/02	3.678756477	1.3
	1.58	67	12/6/02	3.678756477	1.3

Water	Gage				
<u>Year</u>	<u>Height</u>	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	1.58	68	12/7/02	3.678756477	1.3
	1.58	69	12/8/02	3.678756477	1.3
	1.58	70	12/9/02	3.678756477	1.3
	1.58	71	12/10/02	3.678756477	1.3
	1.58	72	12/11/02	3.678756477	1.3
	1.58	73	12/12/02	3.678756477	1.3
	1.58	74	12/13/02	3.678756477	1.3
	1.58	75	12/14/02	3.678756477	1.3
	1.58	76	12/15/02	3.678756477	1.3
	1.57	77	12/16/02	3.160621762	1.2
	1.57	78	12/17/02	3.160621762	1.2
	1.57	79	12/18/02	3.160621762	1.2
	1.57	80	12/19/02	3.160621762	1.2
	1.57	81	12/20/02	3.160621762	1.2
	1.57	82	12/21/02	3.160621762	1.2
	1.57	83	12/22/02	3.160621762	1.2
	1.57	84	12/23/02	3.160621762	1.2
	1.57	85	12/24/02	3.160621762	1.2
	1.57	86	12/25/02	3.160621762	1.2
	1.57	87	12/26/02	3.160621762	1.2
	1.57	88	12/27/02	3.160621762	1.2
	1.57	89	12/28/02	3.160621762	1.2
	1.57	90	12/29/02	3.160621762	1.2
	1.57	91	12/30/02	3.160621762	1.2
	1.57	92	12/31/02	3.160621762	1.2
	1.56	93	1/1/03	2.642487047	1.1
	1.56	94	1/2/03	2.642487047	1.1
	1.56	95	1/3/03	2.642487047	1.1
	1.57	96	1/4/03	3.160621762	1.1
	1.57	97	1/5/03	3.160621762	1.1
	1.57	98	1/6/03	3.160621762	1.1
	1.57	99	1/7/03	3.160621762	1.1
	1.57	100	1/8/03	3.160621762	1.1
	1.57	101	1/9/03	3.160621762	1.1
	1.57	102	1/10/03	3.160621762	1.1
	1.57	103	1/11/03	3.160621762	1.1
	1.57	104	1/12/03	3.160621762	1.2
	1.57	105	1/13/03	3.160621762	1.2
	1.58	106	1/14/03	3.678756477	1.2
	1.58	107	1/15/03	3.678756477	1.2

Water	<u>Gage</u>				
<u>Year</u>	Height	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	1.58	108	1/16/03	3.678756477	1.2
	1.58	109	1/17/03	3.678756477	1.2
	1.58	110	1/18/03	3.678756477	1.2
	1.58	111	1/19/03	3.678756477	1.2
	1.59	112	1/20/03	4.196891192	1.2
	1.59	113	1/21/03	4.196891192	1.8
	1.59	114	1/22/03	4.196891192	1.8
	1.59	115	1/23/03	4.196891192	1.8
	1.59	116	1/24/03	4.196891192	2.2
	1.59	117	1/25/03	4.196891192	2.2
	1.59	118	1/26/03	4.196891192	2.2
	1.6	119	1/27/03	4.333333333	2.2
	1.63	120	1/28/03	4.653846154	4
	1.65	121	1/29/03	4.711229947	4
	1.66	122	1/30/03	5.245989305	5
	1.67	123	1/31/03	5.780748663	5
	1.67	124	2/1/03	5.780748663	5
	1.67	125	2/2/03	5.780748663	5
	1.68	126	2/3/03	6.315508021	5
	1.68	127	2/4/03	6.315508021	5
	1.69	128	2/5/03	6.85026738	5
	1.7	129	2/6/03	7.385026738	6.5
	1.71	130	2/7/03	7.919786096	6.6
	1.73	131	2/8/03	8.989304813	6
	1.71	132	2/9/03	7.919786096	6
	1.7	133	2/10/03	7.385026738	6
	1.69	134	2/11/03	6.85026738	6.2
	1.69	135	2/12/03	6.85026738	6.2
	1.69	136	2/13/03	6.85026738	6.2
	1.68	137	2/14/03	6.315508021	6.2
	1.68	138	2/15/03	6.315508021	6.2
	1.67	139	2/16/03	5.780748663	6.2
	1.67	140	2/17/03	5.780748663	6.2
	1.67	141	2/18/03	5.780748663	6.2
	1.67	142	2/19/03	5.780748663	6.2
	1.66	143	2/20/03	5.245989305	6.2
	1.66	144	2/21/03	5.245989305	6.2
	1.66	145	2/22/03	5.245989305	6.2
	1.66	146	2/23/03	5.245989305	6.2
	1.67	147	2/24/03	5.780748663	6.2

Water Year	<u>Gage</u> <u>Height</u>	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	1.67	148	2/25/03	5.780748663	6.2
	1.67	149	2/26/03	5.780748663	6.2
	1.67	150	2/27/03	5.780748663	6.2
	1.66	151	2/28/03	5.245989305	6.2
	1.66	152	3/1/03	5.245989305	6.2
	1.66	153	3/2/03	5.245989305	6.2
	1.66	154	3/3/03	5.245989305	6.2
	1.67	155	3/4/03	5.780748663	6.2
	1.67	156	3/5/03	5.780748663	6.2
	1.67	157	3/6/03	5.780748663	6.2
	1.67	158	3/7/03	5.780748663	6.2
	1.68	159	3/8/03	6.315508021	5
	1.68	160	3/9/03	6.315508021	5
	1.68	161	3/10/03	6.315508021	5
	1.67	162	3/11/03	5.780748663	5
	1.67	163	3/12/03	5.780748663	5
	1.69	164	3/13/03	6.85026738	4
	1.7	165	3/14/03	7.385026738	4
	1.71	166	3/15/03	7.919786096	5
	1.91	167	3/16/03	18.61497326	7
	1.95	168	3/17/03	20.7540107	8
	1.99	169	3/18/03	22.89304813	7
	2.1	170	3/19/03	28.77540107	7
	2.08	171	3/20/03	24.6	18.7
	2.1	172	3/21/03	28.77540107	7.7
	2.12	173	3/22/03	29.84491979	26.2
	2.45	174	3/23/03	47.49197861	298.7
	2.6	175	3/24/03	55.51336898	313.7
	2.45	176	3/25/03	47.49197861	67.5
	2.37	177	3/26/03	43.21390374	37.5
	2.27	178	3/27/03	37.86631016	23.7
	2.21	179	3/28/03	34.65775401	20
	2.18	180	3/29/03	33.05347594	10
	2.18	181	3/30/03	33.05347594	13.3
	2.21	182	3/31/03	34.65775401	11.2
	2.26	183	4/1/03	37.3315508	60
	2.51	184	4/2/03	50.70053476	73.7
	2.41	185	4/3/03	45.35294118	40
	2.3	186	4/4/03	39.47058824	73.7
	2.27	187	4/5/03	37.86631016	22.5

Water	<u>Gage</u>				
<u>Year</u>	<u>Height</u>	<u>DAY</u>	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	2.23	188	4/6/03	35.72727273	10.3
	2.19	189	4/7/03	33.58823529	10.3
	2.17	190	4/8/03	32.51871658	10
	2.15	191	4/9/03	31.44919786	16.6
	2.12	192	4/10/03	29.84491979	7.5
	2.13	193	4/11/03	30.37967914	7.5
	2.14	194	4/12/03	30.9144385	10
	2.13	195	4/13/03	30.37967914	20
	2.13	196	4/14/03	30.37967914	23.7
	2.12	197	4/15/03	29.84491979	21.2
	2.12	198	4/16/03	29.84491979	20
	2.11	199	4/17/03	29.31016043	20
	2.09	200	4/18/03	28.24064171	20
	2.08	201	4/19/03	27.70588235	20
	2.06	202	4/20/03	26.63636364	30
	2.04	203	4/21/03	25.56684492	17.5
	2.02	204	4/22/03	24.4973262	20
	2	205	4/23/03	23.42780749	22.5
	1.98	206	4/24/03	22.35828877	17.5
	1.96	207	4/25/03	21.28877005	17.5
	1.94	208	4/26/03	20.21925134	18.7
	1.92	209	4/27/03	19.14973262	52
	1.91	210	4/28/03	18.61497326	18.7
	1.9	211	4/29/03	18.0802139	12
	1.9	212	4/30/03	18.0802139	11.2
	1.9	213	5/1/03	18.0802139	9.3
	1.89	214	5/2/03	17.54545455	12
	1.89	215	5/3/03	17.54545455	17.5
	1.88	216	5/4/03	17.01069519	10
	1.88	217	5/5/03	17.01069519	10
	1.87	218	5/6/03	16.47593583	6.2
	1.86	219	5/7/03	15.94117647	1.3
	1.84	220	5/8/03	14.87165775	1.2
	1.83	221	5/9/03	14.3368984	1.2
	1.81	222	5/10/03	13.26737968	2.5
	1.8	223	5/11/03	12.73262032	1.2
	1.79	224	5/12/03	12.19786096	1.2
	1.79	225	5/13/03	12.19786096	2.5
	1.79	226	5/14/03	9.45	<i>3.7</i>
	1.79	227	5/15/03	12.19786096	1.2

Water Year	<u>Gage</u> Height	DAY	<u>Date</u>	<u>CFS</u>	TSS (Mg/L)
	1.79	228	5/16/03	12.19786096	1.2
	1.78	229	5/17/03	11.6631016	2.5
	1.78	230	5/18/03	11.6631016	2.5
	1.78	231	5/19/03	11.6631016	1.2
	1.77	232	5/20/03	11.12834225	1.2
	1.76	233	5/21/03	10.59358289	1.2
	1.76	234	5/22/03	10.59358289	1.2
	1.75	235	5/23/03	10.05882353	1.2
	1.75	236	5/24/03	10.05882353	1.2
	1.74	237	5/25/03	9.524064171	1.2
	1.74	238	5/26/03	9.524064171	1.2
	1.73	239	5/27/03	8.989304813	1.2
	1.72	240	5/28/03	8.454545455	1.2
	1.71	241	5/29/03	7.43	1.2
	1.7	242	5/30/03	7.385026738	3.7
	1.7	243	5/31/03	7.385026738	1.2
	1.69	244	6/1/03	6.85026738	2.5
	1.69	245	6/2/03	6.85026738	6
	1.69	246	6/3/03	6.85026738	8
	1.69	247	6/4/03	6.85026738	20
	1.68	248	6/5/03	6.315508021	6.2
	1.68	249	6/6/03	6.315508021	6.2
	1.67	250	6/7/03	5.780748663	6.2
	1.67	251	6/8/03	5.780748663	61.2
	1.67	252	6/9/03	5.780748663	30
	1.66	253	6/10/03	5.245989305	10
	1.66	254	6/11/03	5.245989305	10
	1.66	255	6/12/03	5.245989305	7.5
	1.65	256	6/13/03	4.711229947	8.7
	1.65	257	6/14/03	4.711229947	6
	1.65	258	6/15/03	4.711229947	8.7
	1.64	259	6/16/03	4.695340502	13.7
	1.64	260	6/17/03	4.695340502	6.2
	1.64	261	6/18/03	4.695340502	7.5
	1.63	262	6/19/03	4.653846154	10
	1.63	263	6/20/03	4.653846154	10
	1.63	264	6/21/03	4.653846154	11.2
	1.62	265	6/22/03	4.58677686	10
	1.62	266	6/23/03	4.58677686	3.7
	1.62	267	6/24/03	4.58677686	9

Water	<u>Gage</u>				
Year	Height	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	1.61	268	6/25/03	4.410480349	2.5
	1.61	269	6/26/03	4.410480349	3.7
	1.61	270	6/27/03	4.410480349	1.2
	1.6	271	6/28/03	4.333333333	3.7
	1.6	272	6/29/03	4.333333333	3.7
	1.59	273	6/30/03	4.196891192	6.6
	1.59	274	7/1/03	4.196891192	6.6
	1.58	275	7/2/03	3.678756477	6.5
	1.58	276	7/3/03	3.678756477	6.5
	1.58	277	7/4/03	3.678756477	6.5
	1.58	278	7/5/03	3.678756477	6.5
	1.57	279	7/6/03	3.160621762	6.5
	1.57	280	7/7/03	3.160621762	6.5
	1.57	281	7/8/03	3.160621762	6.5
	1.57	282	7/9/03	3.160621762	6.4
	1.57	283	7/10/03	3.160621762	6.4
	1.57	284	7/11/03	3.160621762	6.4
	1.56	285	7/12/03	2.642487047	6.4
	1.56	286	7/13/03	2.642487047	6.4
	1.56	287	7/14/03	2.642487047	6.4
	1.56	288	7/15/03	2.642487047	7.1
	1.56	289	7/16/03	2.642487047	6.2
	1.55	290	7/17/03	2.124352332	6.2
	1.55	291	7/18/03	2.124352332	8.7
	1.55	292	7/19/03	2.124352332	7.5
	1.55	293	7/20/03	2.124352332	7.5
	1.55	294	7/21/03	2.124352332	10
	1.54	295	7/22/03	1.606217617	6.2
	1.54	296	7/23/03	1.606217617	6.2
	1.54	297	7/24/03	1.606217617	7.7
	1.53	298	7/25/03	1.088082902	7.5
	1.52	299	7/26/03	1.015553522	1.2
	1.52	300	7/27/03	1.015553522	1.2
	1.52	301	7/28/03	1.015553522	1.2
	1.51	302	7/29/03	0.924062214	4
	1.51	303	7/30/03	0.924062214	5
	1.5	304	7/31/03	0.832570906	10
	1.49	305	8/1/03	0.741079597	7.5
	1.49	306	8/2/03	0.741079597	5
	1.48	307	8/3/03	0.649588289	7.5

Water	<u>Gage</u>				
<u>Year</u>	Height	DAY	Date	<u>CFS</u>	TSS (Mg/L)
	1.48	308	8/4/03	0.649588289	8.7
	1.48	309	8/5/03	0.649588289	7.5
	1.47	310	8/6/03	0.558096981	7.5
	1.47	311	8/7/03	0.558096981	8
	1.47	312	8/8/03	0.558096981	11.2
	1.47	313	8/9/03	0.558096981	5
	1.47	314	8/10/03	0.558096981	18.7
	1.47	315	8/11/03	0.558096981	11.2
	1.47	316	8/12/03	0.558096981	7.5
	1.47	317	8/13/03	0.558096981	7.5
	1.47	318	8/14/03	0.558096981	7.5
	1.47	319	8/15/03	0.558096981	7.5
	1.46	320	8/16/03	0.466605672	7.5
	1.46	321	8/17/03	0.466605672	8.7
	1.46	322	8/18/03	0.466605672	5
	1.46	323	8/19/03	0.466605672	6.2
	1.46	324	8/20/03	0.466605672	6.2
	1.46	325	8/21/03	0.466605672	16
	1.46	326	8/22/03	0.466605672	5.3
	1.46	327	8/23/03	0.466605672	1.4
	1.45	328	8/24/03	0.375114364	1.4
	1.45	329	8/25/03	0.375114364	1.4
	1.45	330	8/26/03	0.375114364	1.3
	1.45	331	8/27/03	0.375114364	1.3
	1.45	332	8/28/03	0.375114364	1.3
	1.45	333	8/29/03	0.375114364	1.3
	1.45	334	8/30/03	0.375114364	1.3
	1.45	335	8/31/03	0.375114364	1.3
	1.45	336	9/1/03	0.375114364	1.3
	1.44	337	9/2/03	0.283623056	1.3
	1.44	338	9/3/03	0.283623056	1.3
	1.44	339	9/4/03	0.283623056	1.3
	1.44	340	9/5/03	0.283623056	1.3
	1.44	341	9/6/03	0.283623056	1.3
	1.44	342	9/7/03	0.283623056	1.3
	1.44	343	9/8/03	0.283623056	1.3
	1.44	344	9/9/03	0.283623056	1.3
	1.44	345	9/10/03	0.283623056	1.3
	1.44	346	9/11/03	0.283623056	1.3
	1.44	347	9/12/03	0.283623056	1.3

Gage				
Height	DAY	Date	CFS	TSS (Mg/L)
1.44	<i>348</i>	9/13/03	0.283623056	1.3
1.45	349	9/14/03	0.375114364	1.3
1.45	350	9/15/03	0.375114364	1.3
1.45	351	9/16/03	0.375114364	1.3
1.45	352	9/17/03	0.375114364	1.3
1.45	353	9/18/03	0.375114364	1.3
1.46	354	9/19/03	0.466605672	1.4
1.46	355	9/20/03	0.466605672	1.4
1.46	356	9/21/03	0.466605672	1.4
1.47	357	9/22/03	0.558096981	1.4
1.47	358	9/23/03	0.558096981	1.4
1.47	359	9/24/03	0.558096981	1.4
1.48	360	9/25/03	0.649588289	1.5
1.48	361	9/26/03	0.649588289	1.5
1.48	362	9/27/03	0.649588289	1.5
1.49	363	9/28/03	0.741079597	1.5
1.49	364	9/29/03	0.741079597	1.5
1.49	365	9/30/03	0.741079597	1.5
	Height 1.44 1.45 1.45 1.45 1.45 1.45 1.45 1.46 1.46 1.47 1.47 1.47 1.48 1.48 1.48 1.49 1.49	Height DAY 1.44 348 1.45 349 1.45 350 1.45 351 1.45 352 1.45 353 1.46 354 1.46 355 1.46 356 1.47 357 1.47 358 1.47 359 1.48 360 1.48 361 1.48 362 1.49 363 1.49 364	Height DAY Date 1.44 348 9/13/03 1.45 349 9/14/03 1.45 350 9/15/03 1.45 351 9/16/03 1.45 352 9/17/03 1.45 353 9/18/03 1.46 354 9/19/03 1.46 355 9/20/03 1.46 356 9/21/03 1.47 357 9/22/03 1.47 358 9/23/03 1.48 360 9/25/03 1.48 361 9/26/03 1.48 362 9/27/03 1.49 363 9/28/03 1.49 364 9/29/03	Height DAY Date CFS 1.44 348 9/13/03 0.283623056 1.45 349 9/14/03 0.375114364 1.45 350 9/15/03 0.375114364 1.45 351 9/16/03 0.375114364 1.45 352 9/17/03 0.375114364 1.45 353 9/18/03 0.375114364 1.46 354 9/19/03 0.466605672 1.46 355 9/20/03 0.466605672 1.47 357 9/22/03 0.558096981 1.47 358 9/23/03 0.558096981 1.48 360 9/25/03 0.649588289 1.48 361 9/26/03 0.649588289 1.48 362 9/27/03 0.649588289 1.49 363 9/28/03 0.741079597 1.49 364 9/29/03 0.741079597

<u>low</u>

28.53

25

25

24

15

APPENDIX B - McNeil Core Data for Bobtail Creek

ALL DATA SUMMARIZED

]	Percent Passing <		Average Percent <
Year		<u>ld ID #</u>	<u>6.35 mm</u>	<u>Year</u>	<u>6.35mm</u>
	1994	1	28.53	1994	34.9
		2	40.75	2000	
		3	35.31	2001	33.1
Average			34.86	2002	
				2003	33.4
	2000	1	39		
		2	41		
		3	33		
		4	40		
		5	30		
		6	25		
		7	36		
		8	30		
		9	35		
		10	39		
Average			34.8		
	2004		20		
	2001	1	38		
		2	30		
		3	31		
		4	34 25		
		5 6	33.7		
		7	33.7		
		8	40.8		
		9	36		
		10	31		
Average		10	33.05		
	2002	1	28		
		2	40		
		3	39		
		4	25		
		5	37		
		6	24		
		7	31		
		8	28		
		9	43		
		10	32		
Average			32.7		

2003	1	27
	2	38
	3	51
	4	26
	5	32
	6	57
	7	29
	8	26
	9	33
	10	15
Average		33.4

YEAR 2000 DATA

			Sieve	
Project Name Date	Field ID Number		Size(mm)	%Passing
Bobtail	2000	1	76.2	100
Bobtail	2000	1	50.8	97
Bobtail	2000	1	38.1	85
Bobtail	2000	1	25.4	71
Bobtail	2000	1	19.05	59
Bobtail	2000	1	9.525	51
Bobtail	2000	1	12.7	46
Bobtail	2000	1	6.35	39
Bobtail	2000	1	2.36	25.69
Bobtail	2000	1	2	23.73
Bobtail	2000	1	1.18	18.2
Bobtail	2000	1	0.6	10.22
Bobtail	2000	1	0.425	7.19
Bobtail	2000	1	0.3	4.99
Bobtail	2000	1	0.15	3.08
Bobtail	2000	1	0.075	2.31
Bobtail	2000	2	76.2	100
Bobtail	2000	2	50.8	96
Bobtail	2000	2	38.1	91
Bobtail	2000	2	25.4	75
Bobtail	2000	2	19.05	69
Bobtail	2000	2	9.525	59
Bobtail	2000	2	12.7	51
Bobtail	2000	2	6.35	41
Bobtail	2000	2	2.36	22.79
Bobtail	2000	2	2	20.11
Bobtail	2000	2	1.18	13.38
Bobtail	2000	2	0.6	7.22
Bobtail	2000	2	0.425	5.53
Bobtail	2000	2	0.3	4.06
Bobtail	2000	2	0.15	2.36

		_		
Bobtail	2000	2	0.075	1.55
Bobtail	2000	3	76.2	100
Bobtail	2000	3	50.8	100
Bobtail	2000	3	38.1	92
Bobtail	2000	3	25.4	79
Bobtail	2000	3	19.05	66
Bobtail	2000	3	9.525	53
Bobtail	2000	3	12.7	42
Bobtail	2000	3	6.35	33
Bobtail	2000	3	2.36	20.77
Bobtail	2000	3	2	18.92
Bobtail	2000	3	1.18	13.71
Bobtail	2000	3	0.6	7.14
Bobtail	2000	3	0.425	4.89
Bobtail	2000	3	0.3	3.25
Bobtail	2000	3	0.15	1.84
Bobtail	2000	3	0.075	0.74
Bobtail	2000	4	76.2	100
Bobtail	2000	4	50.8	100
Bobtail	2000	4	38.1	87
Bobtail	2000	4	25.4	69
Bobtail	2000	4	19.05	61
Bobtail	2000	4	9.525	52
Bobtail	2000	4	12.7	47
Bobtail	2000	4	6.35	40
Bobtail	2000	4	2.36	24.4
Bobtail	2000	4	2	21.73
Bobtail	2000	4	1.18	15.37
Bobtail	2000	4	0.6	10.48
Bobtail	2000	4	0.425	9.01
Bobtail	2000	4	0.3	7.61
Bobtail	2000	4	0.15	5.88
Bobtail	2000	4	0.075	5.07
Bobtail	2000	5	76.2	100
Bobtail	2000	5	50.8	96
Bobtail	2000	5	38.1	93
Bobtail	2000	5	25.4	70
Bobtail	2000	5	19.05	62
Bobtail	2000	5	9.525	46
Bobtail	2000	5	12.7	38
Bobtail	2000	5	6.35	30
Bobtail	2000	5 5 5	2.36	14.13
Bobtail	2000	5	2	15.85
Bobtail	2000	5	1.18	10.77
Bobtail	2000	5	0.6	7.46
Bobtail	2000	5	0.425	5.26
Bobtail	2000	5	0.423	3.61
Bobtail	2000	5	0.15	3.01
Bobtail	2000	5	0.13	1.67
Bobtail	2000	6	76.2	100
Bobtail	2000	6	50.8	95
Bobtail		6		
םטטנמוו	2000	O	38.1	85

D 1 . 11	2000		25.4	
Bobtail	2000	6	25.4	65
Bobtail	2000	6	19.05	57
Bobtail	2000	6	9.525	41
Bobtail	2000	6	12.7	34
Bobtail	2000	6	6.35	26
Bobtail	2000	6	2.36	13.49
Bobtail	2000	6	2	11.9
Bobtail	2000	6	1.18	7.94
Bobtail	2000	6	0.6	4.71
Bobtail	2000	6	0.425	3.84
Bobtail	2000	6	0.3	3.13
Bobtail	2000	6	0.15	2.4
Bobtail	2000	6	0.075	2.15
Bobtail	2000	7	76.2	100
Bobtail	2000	7	50.8	93
Bobtail	2000	7	38.1	82
Bobtail	2000	7	25.4	58
Bobtail	2000	7	19.05	59
Bobtail	2000	7	9.525	50
Bobtail	2000	7	12.7	43
Bobtail	2000	7	6.35	36
Bobtail	2000	7	2.36	20.74
Bobtail	2000	7	2	18.49
Bobtail	2000	7	1.18	12.42
Bobtail	2000	7	0.6	6.68
Bobtail	2000	7	0.425	5.15
Bobtail	2000	7	0.123	3.82
Bobtail	2000	7	0.15	2.21
Bobtail	2000	7	0.075	1.59
Bobtail	2000	8	76.2	100
Bobtail	2000	8	50.8	100
Bobtail	2000	8	38.1	88
Bobtail	2000	8	25.4	67
Bobtail	2000	8	19.05	56
Bobtail	2000	8	9.525	46
Bobtail	2000	8	12.7	36
		8		
Bobtail Bobtail	2000 2000	8	6.35 2.36	28
				14.63
Bobtail	2000	8	1 19	12.8
Bobtail	2000		1.18	7.82
Bobtail	2000	8	0.6	3.59
Bobtail	2000	8	0.425	2.66
Bobtail	2000	8	0.3	1.48
Bobtail	2000	8	0.15	1.3
Bobtail	2000	8	0.075	1.03
Bobtail	2000	9	76.2	100
Bobtail	2000	9	50.8	100
Bobtail	2000	9	38.1	94
Bobtail	2000	9	25.4	76
Bobtail	2000	9	19.05	67
Bobtail	2000	9	9.525	55
Bobtail	2000	9	12.7	46

Bobtail	2000	9	6.35	35
Bobtail	2000	9	2.36	19.79
Bobtail	2000	9	2	17.82
Bobtail	2000	9	1.18	12.78
Bobtail	2000	9	0.6	8.11
Bobtail	2000	9	0.425	6.48
Bobtail	2000	9	0.3	5.05
Bobtail	2000	9	0.15	3.65
Bobtail	2000	9	0.075	3.14
Bobtail	2000	10	76.2	100
Bobtail	2000	10	50.8	100
Bobtail	2000	10	38.1	98
Bobtail	2000	10	25.4	89
Bobtail	2000	10	19.05	72
Bobtail	2000	10	9.525	57
Bobtail	2000	10	12.7	49
Bobtail	2000	10	6.35	39
Bobtail	2000	10	2.36	22.59
Bobtail	2000	10	2	20.33
Bobtail	2000	10	1.18	14.54
Bobtail	2000	10	0.6	9.13
Bobtail	2000	10	0.425	7.29
Bobtail	2000	10	0.3	5.82
Bobtail	2000	10	0.15	4.68
Bobtail	2000	10	0.075	4.4

YEAR 2001 DATA

			Sieve	
Project Name Date	Field ID Number		Size(mm)	% Passing
Bobtail	2001	1	76.2	100
Bobtail	2001	1	50.8	100
Bobtail	2001	1	38.1	96
Bobtail	2001	1	25.4	77
Bobtail	2001	1	19.05	67
Bobtail	2001	1	9.525	55
Bobtail	2001	1	12.7	48
Bobtail	2001	1	6.35	39
Bobtail	2001	1	2.36	23.63
Bobtail	2001	1	2	21.47
Bobtail	2001	1	1.18	15.72
Bobtail	2001	1	0.6	8.79
Bobtail	2001	1	0.425	6.12
Bobtail	2001	1	0.3	4.09
Bobtail	2001	1	0.15	2.49
Bobtail	2001	1	0.075	1.9
Bobtail	2001	2	76.2	100
Bobtail	2001	2	50.8	100
Bobtail	2001	2	38.1	86
Bobtail	2001	2	25.4	69
Bobtail	2001	2	19.05	56

Bobtail	2001	2	9.525	43
Bobtail	2001	2	12.7	37
Bobtail	2001	2	6.35	31
Bobtail	2001	2	2.36	16.39
Bobtail	2001	2	2	14.79
Bobtail	2001	2	1.18	11.06
Bobtail	2001	2	0.6	8.18
Bobtail	2001	2	0.425	7.02
Bobtail	2001	2	0.3	5.77
Bobtail	2001	2	0.15	4.25
Bobtail	2001	2	0.075	3.64
Bobtail	2001	3	76.2	100
Bobtail	2001	3	50.8	94
Bobtail	2001	3	38.1	81
Bobtail	2001	3	25.4	71
Bobtail	2001	3	19.05	60
Bobtail	2001	3	9.525	47
Bobtail	2001	3	12.7	39
Bobtail	2001	3	6.35	31
Bobtail	2001	3	2.36	18.91
Bobtail	2001	3	2	16.71
Bobtail	2001	3	1.18	12.64
Bobtail	2001	3	0.6	9.33
Bobtail	2001	3	0.425	8.06
Bobtail	2001	3	0.3	6.51
Bobtail	2001	3	0.15	4.41
Bobtail	2001	3	0.075	2.66
Bobtail	2001	4	76.2	100
Bobtail	2001	4	50.8	100
Bobtail	2001	4	38.1	89
Bobtail	2001	4	25.4	73
Bobtail	2001	4	19.05	63
Bobtail	2001	4	9.525	51
Bobtail	2001	4	12.7	42
Bobtail	2001	4	6.35	34
Bobtail	2001	4	2.36	21.77
Bobtail	2001	4	2.30	19.76
Bobtail	2001	4	1.18	13.82
Bobtail	2001	4	0.6	6.32
Bobtail	2001	4	0.425	4.01
Bobtail	2001	4	0.3	2.39
Bobtail	2001	4	0.15	1.04
Bobtail	2001	4	0.075	0.54
Bobtail	2001	5	76.2	100
Bobtail	2001	5	50.8	94
Bobtail	2001	5	38.1	90
Bobtail	2001	5	25.4	80
Bobtail	2001	5	19.05	67
Bobtail		5		50
Bobtail	2001	5	9.525	38
Bobtail	2001	5	12.7	
	2001	5	6.35	26 10.88
Bobtail	2001	3	2.36	10.88

		_		
Bobtail	2001	5	2	9.56
Bobtail	2001	5	1.18	6.24
Bobtail	2001	5	0.6	3.02
Bobtail	2001	5	0.425	1.95
Bobtail	2001	5	0.3	1.21
Bobtail	2001	5	0.15	0.74
Bobtail	2001	5	0.075	0.67
Bobtail	2001	6	76.2	100
Bobtail	2001	6	50.8	97
Bobtail	2001	6	38.1	97
Bobtail	2001	6	25.4	81
Bobtail	2001	6	19.05	67
Bobtail	2001	6	9.525	54
Bobtail	2001	6	12.7	45
Bobtail	2001	6	6.35	37
Bobtail	2001	6	2.36	23.97
Bobtail	2001	6	2.30	22.13
Bobtail	2001	6	1.18	16.97
Bobtail	2001	6	0.6	11.48
Bobtail	2001	6	0.425	9.88
Bobtail	2001	6	0.423	8.67
Bobtail	2001	6	0.15	7.44
	2001	6	0.13	6.92
Bobtail		7		
Bobtail	2001		76.2	100
Bobtail	2001	7	50.8	94
Bobtail	2001	7	38.1	78
Bobtail	2001	7	25.4	70
Bobtail	2001	7	19.05	60
Bobtail	2001	7	9.525	47
Bobtail	2001	7	12.7	40
Bobtail	2001	7	6.35	32
Bobtail	2001	7	2.36	17.82
Bobtail	2001	7	2	16.2
Bobtail	2001	7	1.18	11.85
Bobtail	2001	7	0.6	6.26
Bobtail	2001	7	0.425	3.69
Bobtail	2001	7	0.3	1.94
Bobtail	2001	7	0.15	0.83
Bobtail	2001	7	0.075	0.74
Bobtail	2001	8	76.2	100
Bobtail	2001	8	50.8	100
Bobtail	2001	8	38.1	98
Bobtail	2001	8	25.4	85
Bobtail	2001	8	19.05	73
Bobtail	2001	8	9.525	58
Bobtail	2001	8	12.7	49
Bobtail	2001	8	6.35	41
Bobtail	2001	8	2.36	27.72
Bobtail	2001	8	2	25.71
Bobtail	2001	8	1.18	19.2
Bobtail	2001	8	0.6	10.62
Bobtail	2001	8	0.425	8.06
Doomi	2001	o	UT2J	0.00

Bobtail	2001	8	0.3	6.27
Bobtail	2001	8	0.15	4.92
Bobtail	2001	8	0.075	4.46
Bobtail	2001	9	76.2	100
Bobtail	2001	9	50.8	100
Bobtail	2001	9	38.1	85
Bobtail	2001	9	25.4	73
Bobtail	2001	9	19.05	63
Bobtail	2001	9	9.525	51
Bobtail	2001	9	12.7	44
Bobtail	2001	9	6.35	37
Bobtail	2001	9	2.36	21.94
Bobtail	2001	9	2	20.06
Bobtail	2001	9	1.18	15.06
Bobtail	2001	9	0.6	8.57
Bobtail	2001	9	0.425	6.15
Bobtail	2001	9	0.3	4.1
Bobtail	2001	9	0.15	2.29
Bobtail	2001	9	0.075	1.18
Bobtail	2001	10	76.2	100
Bobtail	2001	10	50.8	100
Bobtail	2001	10	38.1	93
Bobtail	2001	10	25.4	75
Bobtail	2001	10	19.05	62
Bobtail	2001	10	9.525	52
Bobtail	2001	10	12.7	39
Bobtail	2001	10	6.35	22
Bobtail	2001	10	2.36	9.81
Bobtail	2001	10	2	8.17
Bobtail	2001	10	1.18	3.38
Bobtail	2001	10	0.6	-1.63
Bobtail	2001	10	0.425	-3.62
Bobtail	2001	10	0.3	-5.28
Bobtail	2001	10	0.15	-6.48
Bobtail	2001	10	0.075	-6.82

YEAR 2002 DATA

			Sieve	
Project Name Date	Field ID Number		Size(mm)	% Passing
Bobtail	2002	1	76.2	100
Bobtail	2002	1	50.8	98
Bobtail	2002	1	38.1	95
Bobtail	2002	1	25.4	74
Bobtail	2002	1	19.05	54
Bobtail	2002	1	9.525	47
Bobtail	2002	1	12.7	39
Bobtail	2002	1	6.35	28
Bobtail	2002	2	76.2	100
Bobtail	2002	2	50.8	100
Bobtail	2002	2	38.1	97

		_		
Bobtail	2002	2	25.4	82
Bobtail	2002	2	19.05	67
Bobtail	2002	2	9.525	61
Bobtail	2002	2	12.7	52
Bobtail	2002	2	6.35	41
Bobtail	2002	3	76.2	100
Bobtail	2002	3	50.8	100
Bobtail	2002	3	38.1	95
Bobtail	2002	3	25.4	81
Bobtail	2002	3	19.05	63
Bobtail	2002	3	9.525	55
Bobtail	2002	3	12.7	48
Bobtail	2002	3	6.35	39
Bobtail	2002	4	76.2	100
Bobtail	2002	4	50.8	100
Bobtail	2002	4	38.1	88
Bobtail	2002	4	25.4	64
Bobtail	2002	4	19.05	47
Bobtail	2002	4	9.525	41
Bobtail	2002	4	12.7	34
Bobtail	2002	4	6.35	25
Bobtail	2002	5	76.2	100
Bobtail	2002	5	50.8	100
		5		
Bobtail	2002	5	38.1	92 76
Bobtail	2002		25.4	76
Bobtail	2002	5	19.05	63
Bobtail	2002	5	9.525	55
Bobtail	2002	5	12.7	47
Bobtail	2002	5	6.35	37
Bobtail	2002	6	76.2	100
Bobtail	2002	6	50.8	92
Bobtail	2002	6	38.1	77
Bobtail	2002	6	25.4	60
Bobtail	2002	6	19.05	45
Bobtail	2002	6	9.525	38
Bobtail	2002	6	12.7	32
Bobtail	2002	6	6.35	24
Bobtail	2002	7	76.2	100
Bobtail	2002	7	50.8	100
Bobtail	2002	7	38.1	98
Bobtail	2002	7	25.4	75
Bobtail	2002	7	19.05	56
Bobtail	2002	7	9.525	48
Bobtail	2002	7	12.7	39
Bobtail	2002	7	6.35	31
Bobtail	2002	8	76.2	100
Bobtail	2002	8	50.8	93
Bobtail	2002	8	38.1	85
Bobtail	2002	8	25.4	66
Bobtail	2002	8	19.05	49
Bobtail	2002	8	9.525	43
Bobtail	2002	8	12.7	36
Doomii	2002	U	14.1	50

Bobtail	2002	8	6.35	29
Bobtail	2002	9	76.2	100
Bobtail	2002	9	50.8	93
Bobtail	2002	9	38.1	91
Bobtail	2002	9	25.4	75
Bobtail	2002	9	19.05	57
Bobtail	2002	9	9.525	54
Bobtail	2002	9	12.7	50
Bobtail	2002	9	6.35	43
Bobtail	2002	10	76.2	100
Bobtail	2002	10	50.8	100
Bobtail	2002	10	38.1	87
Bobtail	2002	10	25.4	66
Bobtail	2002	10	19.05	56
Bobtail	2002	10	9.525	50
Bobtail	2002	10	12.7	42
Bobtail	2002	10	6.35	32

YEAR 2003 DATA

			Sieve	
Project Name Date	Field ID Number		Size(mm)	% Passing
Bobtail	2003	1	76.2	100
Bobtail	2003	1	50.8	100
Bobtail	2003	1	38.1	98
Bobtail	2003	1	25.4	73
Bobtail	2003	1	19.05	52
Bobtail	2003	1	9.525	44
Bobtail	2003	1	12.7	37
Bobtail	2003	1	6.35	29
Bobtail	2003	2	76.2	100
Bobtail	2003	2	50.8	98
Bobtail	2003	2	38.1	93
Bobtail	2003	2	25.4	82
Bobtail	2003	2	19.05	66
Bobtail	2003	2	9.525	58
Bobtail	2003	2	12.7	48
Bobtail	2003	2	6.35	36
Bobtail	2003	3	76.2	100
Bobtail	2003	3	50.8	98
Bobtail	2003	3	38.1	91
Bobtail	2003	3	25.4	83
Bobtail	2003	3	19.05	73
Bobtail	2003	3	9.525	69
Bobtail	2003	3	12.7	65
Bobtail	2003	3	6.35	61
Bobtail	2003	4	76.2	100
Bobtail	2003	4	50.8	100
Bobtail	2003	4	38.1	97
Bobtail	2003	4	25.4	81
Bobtail	2003	4	19.05	57

Bobtail	2003	4	9.525	47
Bobtail	2003	4	12.7	37
Bobtail	2003	4	6.35	27
Bobtail	2003	5	76.2	100
Bobtail	2003	5	50.8	95
Bobtail	2003	5	38.1	87
Bobtail	2003	5	25.4	63
Bobtail	2003	5	19.05	49
Bobtail	2003	5	9.525	42
Bobtail	2003	5	12.7	35
Bobtail	2003	5	6.35	27
Bobtail	2003	6	76.2	100
Bobtail	2003	6	50.8	100
Bobtail	2003	6	38.1	100
Bobtail	2003	6	25.4	95
Bobtail	2003	6	19.05	86
Bobtail	2003	6	9.525	81
Bobtail	2003	6	12.7	72
Bobtail	2003	6	6.35	58
Bobtail	2003	7	76.2	100
Bobtail	2003	7	50.8	100
Bobtail	2003	7	38.1	93
Bobtail	2003	7	25.4	65
Bobtail	2003	7	19.05	49
Bobtail	2003	7	9.525	42
Bobtail	2003	7	12.7	34
Bobtail	2003	7	6.35	25
Bobtail	2003	8	76.2	100
Bobtail	2003	8	50.8	94
Bobtail	2003	8	38.1	84
Bobtail	2003	8	25.4	60
Bobtail	2003	8	19.05	37
Bobtail	2003	8	9.525	31
Bobtail	2003	8	12.7	26
Bobtail	2003	8	6.35	21
Bobtail	2003	9	76.2	100
Bobtail	2003	9	50.8	95
Bobtail	2003	9	38.1	87
Bobtail	2003	9	25.4	72
Bobtail	2003	9	19.05	55
Bobtail	2003	9	9.525	50
	2003	9		42
Bobtail		9	12.7	
Bobtail	2003		6.35	34
Bobtail	2003	10	76.2	100
Bobtail	2003	10	50.8	96
Bobtail	2003	10	38.1	78 67
Bobtail	2003	10	25.4	67
Bobtail	2003	10	19.05	36
Bobtail	2003	10	9.525	27
Bobtail	2003	10	12.7	19
Bobtail	2003	10	6.35	11

APPENDIX C - Total Suspended Solids and Turbidity Da

Provided by the U.S. Forest Service

STATION	DATE/TIME STA	AGE	DISCHARGE	PREV.CR.	TURBIDITY	<u>TSS</u>
BOBTAIL 1	605901130	0.24	1.6	0.31	2.4	2
BOBTAIL 1	605901530				1.5	2
BOBTAIL 1	605901930				1.9	2
BOBTAIL 1	605902330				1.5	2
BOBTAIL 1	606900330				1.5	2
BOBTAIL 1	606900730				1.6	2
BOBTAIL 1	606901130				1.1	2
BOBTAIL 1	606901530				1.4	2
BOBTAIL 1	606901930				1.3	2
BOBTAIL 1	606902330				1.4	2
BOBTAIL 1	607900330				1.2	2
BOBTAIL 1	607900730				1.1	2
BOBTAIL 1	607901130				1.4	2
BOBTAIL 1	607901530				1.4	2
BOBTAIL 1	607901930				1.7	2
BOBTAIL 1	607902330				1.6	2
BOBTAIL 1	608900330				1.3	2
BOBTAIL 1	608900730				1.6	2
BOBTAIL 1	608901130				1.5	2
BOBTAIL 1	608901530				1.7	2
BOBTAIL 1	608901930				1.1	2
BOBTAIL 1	608902330				1.6	2
BOBTAIL 1	609900330				1.5	2
BOBTAIL 1	609900730				1.6	2
BOBTAIL 1	609901130				1	2
BOBTAIL 1	609901530				1.4	2
BOBTAIL 1	609901930				1	2
BOBTAIL 1	609902330				1	2
BOBTAIL 1	918901100		1.8		1.6	3
BOBTAIL 1	918901500				1.4	3
BOBTAIL 1	918901900				1.1	3
BOBTAIL 1	918902300				1.4	3
BOBTAIL 1	919900300				1	3
BOBTAIL 1	919900700				0.9	3
BOBTAIL 1	919901100				1.5	3
BOBTAIL 1	919901500				0	0
BOBTAIL 1	919901900				1.6	3
BOBTAIL 1	919902300				1.5	3
BOBTAIL 1	920900300				1.5	3
BOBTAIL 1	920900700				1.1	3
BOBTAIL 1	920901100				1.7	3
BOBTAIL 1	920901500				1.4	3
BOBTAIL 1	920901900				0.9	
BOBTAIL 1	920902300				0.7	3
BOBTAIL 1	921900300				0.8	
BOBTAIL 1	921900700				1.3	3
BOBTAIL 1	921901100				1	3
BOBTAIL 1	921901500				0.8	3

STATION	DATE/TIME STA	GE	DISCHARGE	PREV.CR.	TURBIDITY	<u>TSS</u>
BOBTAIL 1	921901900				0.5	3
BOBTAIL 1	921902300				0.7	3
BOBTAIL 1	922900300				0.8	330
BOBTAIL 1	922900700				4.2	60
BOBTAIL 1	1019901800	0.24	1.5	0.31	1	2
BOBTAIL 1	1019902000				0	0
BOBTAIL 1	1019902200				0.5	2
BOBTAIL 1	1019902400				0.5	2
BOBTAIL 1	1020900200				0.6	2
BOBTAIL 1	1020900400				0.5	2
BOBTAIL 1	1020900600				0.5	2
BOBTAIL 1	1020900800				0.3	2
BOBTAIL 1	1020901000				0.2	2
BOBTAIL 1	1020901200				0.5	2
BOBTAIL 1	1020901400				0.4	2
BOBTAIL 1	1020901600				0	0
BOBTAIL 1	1020901800				0.5	2
BOBTAIL 1	1020902000				0	0
BOBTAIL 1	1020902200				0.8	2
BOBTAIL 1	1020902400				0.7	2
BOBTAIL 1	1021900200				0.5	2
BOBTAIL 1	1021900400				0.6	2
BOBTAIL 1	1021900600				1	2
BOBTAIL 1	1021900800				0.5	2
BOBTAIL 1	1021901000				0.5	2
BOBTAIL 1	1021901200				0	0
BOBTAIL 1	1021901400				0.5	2
BOBTAIL 1	1021901600				0.5	2
BOBTAIL 1	1021901800				0.8	2
BOBTAIL 1	1021902000				0	0
BOBTAIL 1	1021902200				0.5	2
BOBTAIL 1	1021902400				0.9	2
BOBTAIL 1	528911030	0.52		0.52	0.5	2
BOBTAIL 1	528911230				1.6	2
BOBTAIL 1	528911430				1.7	2
BOBTAIL 1	528911630				1.4	2
BOBTAIL 1	528911830				1.8	2
BOBTAIL 1	528912030				1.6	2
BOBTAIL 1	528912230				2.3	2
BOBTAIL 1	529910030				1.9	2
BOBTAIL 1	529910230				1.6	2
BOBTAIL 1	529910430				1.5	2
BOBTAIL 1	529910630				1.5	2
BOBTAIL 1	529910830				1.3	2
BOBTAIL 1	529911030				1.7	2
BOBTAIL 1	529911230				1.5	2
BOBTAIL 1	529911430				1.4	2
BOBTAIL 1	529911630				1.4	2
BOBTAIL 1	529911830				1.5	2
BOBTAIL 1	529912030				1.3	2
BOBTAIL 1	529912230				1.1	2

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR	TURBIDITY TSS	
BOBTAIL 1	530910030			1.6	2
BOBTAIL 1	530910230			1.7	2
BOBTAIL 1	530910430			1.9	2
BOBTAIL 1	530910630			1.6	2
BOBTAIL 1	530910830			1.6	2
BOBTAIL 1	530911030			1.5	2
BOBTAIL 1	530911230			1.4	2
BOBTAIL 1	530911420			1.8	2
BOBTAIL 1	530911630			1.5	2
BOBTAIL 1	909911630			2.2	2
BOBTAIL 1	909912030			1.2	2
BOBTAIL 1	910910030			1	2
BOBTAIL 1	910910430			1.3	2
BOBTAIL 1	910910830			1	2
BOBTAIL 1	910911230			1.1	2
BOBTAIL 1	910911630			1	2
BOBTAIL 1	910912030			1	2
BOBTAIL 1	911910030			1	2
BOBTAIL 1	911910430			1	2
BOBTAIL 1	911910830			1.3	2
BOBTAIL 1	911911230			1	2
BOBTAIL 1	911911630			1	2
BOBTAIL 1	911912030			1	2
BOBTAIL 1	912910030			1	2
BOBTAIL 1	912910430			1	2
BOBTAIL 1	912910830			1	2
BOBTAIL 1	912911230			1.1	2
BOBTAIL 1	912911630			1.3	2
BOBTAIL 1	912912030			1	2
BOBTAIL 1	913910030			1	2
BOBTAIL 1	913910430			1	2
BOBTAIL 1	913910830			1.3	2
BOBTAIL 1	913911230			1.1	2
BOBTAIL 1	415921230	2	0.8	1 1.3	2
BOBTAIL 1	415921230			1.2	2
BOBTAIL 1	415921630			1.1	2
BOBTAIL 1	415922030			1.6	2
BOBTAIL 1	416920030			1.2	2
BOBTAIL 1	416920430			1.4	2
BOBTAIL 1	416920830			1.4	2
BOBTAIL 1	416921230			1.7	2
BOBTAIL 1	416921630			1.6	2
BOBTAIL 1	416922030			1.6	2
BOBTAIL 1	417920030			1.6	2
BOBTAIL 1	417920430			3.9	16
BOBTAIL 1	417920830			0.9	2
BOBTAIL 1	417921230			1.3	2
BOBTAIL 1	417921630			1.7	2
BOBTAIL 1	417922030			1	2
BOBTAIL 1	418920030			1.3	2
BOBTAIL 1	418920430			1.4	2
					-

STATION	DATE/TIME STAGE	DISCHARGE PREV.CR.	TURBIDITY TSS	
BOBTAIL 1	418920830		1.6	2
BOBTAIL 1	418921230		1.3	2
BOBTAIL 1	418921630		1.5	2
BOBTAIL 1	418922030		1.4	2
BOBTAIL 1	419920030		1.4	2
BOBTAIL 1	419920430		0.9	2
BOBTAIL 1	419920830		1.4	2
BOBTAIL 1	424921330	0.55	1	2
BOBTAIL 1	424921730		1	2
BOBTAIL 1	424922130		1	2
BOBTAIL 1	425920130		1.3	2
BOBTAIL 1	425920530		1	2
BOBTAIL 1	425920930		1.1	2
BOBTAIL 1	425921330		1	2
BOBTAIL 1	425921730		1	2
BOBTAIL 1	425922130		1	2
BOBTAIL 1	426920130		1	2
BOBTAIL 1	426920530		1	2
BOBTAIL 1	426920930		1	2
BOBTAIL 1	426921330		1	2
BOBTAIL 1	426921730		1	2
BOBTAIL 1	426922130		1	2
BOBTAIL 1	427920130		1	2
BOBTAIL 1	427920530		1	2
BOBTAIL 1	427920930		1	2
BOBTAIL 1	427921330		1.4	2
BOBTAIL 1	427921730		1	2
BOBTAIL 1	427922130		1	2
BOBTAIL 1	428920130		1	2
BOBTAIL 1	428920530		1	2
BOBTAIL 1	428920930		1.3	2
BOBTAIL 1	429921300		1.7	2
BOBTAIL 1	429921700		1.2	2
BOBTAIL 1	429922100		1	2
BOBTAIL 1	430920100		1	2
BOBTAIL 1	430920500		2.2	2
BOBTAIL 1	430920900		2	2
BOBTAIL 1	430921300		2.3	2
BOBTAIL 1	430921700		1.5	2
BOBTAIL 1	430922100		1.5	2
BOBTAIL 1	501920100		1.3	2
BOBTAIL 1	501920500		1	2
BOBTAIL 1	501920900		1	2
BOBTAIL 1	501921300		1.2	2
BOBTAIL 1	501921700		0.9	2
BOBTAIL 1	501922100		1.3	2
BOBTAIL 1	502920100		1	2
BOBTAIL 1	502920500		1	2
BOBTAIL 1	502920900		0.9	2
BOBTAIL 1	502921300		0.9	2
BOBTAIL 1	502921700		1	2

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY TSS	
BOBTAIL 1	502922100			1.3	2
BOBTAIL 1	503920100			1.1	2
BOBTAIL 1	503920500			1.2	2
BOBTAIL 1	503920900			1.3	2
BOBTAIL 1	506921215			2.1	2
BOBTAIL 1	506922015			2.6	2
BOBTAIL 1	507920415			1.7	2
BOBTAIL 1	507921215			3.6	6
BOBTAIL 1	507922015			1.6	2
BOBTAIL 1	508920415			1.4	2
BOBTAIL 1	408921215			2	2
BOBTAIL 1	508922015			1.6	2
BOBTAIL 1	509920415			1.3	2
BOBTAIL 1	509921215			1.4	2
BOBTAIL 1	509922015			1.3	2
BOBTAIL 1	510920415			1.5	2
BOBTAIL 1	510921215			1.4	2
BOBTAIL 1	510922015			2.1	2
BOBTAIL 1	511920415			1.1	2
BOBTAIL 1	512921350		0.57	2.4	4
BOBTAIL 1	512921750			1.8	4
BOBTAIL 1	512922150			1.7	4
BOBTAIL 1	513920150			1.7	4
BOBTAIL 1	513920550			1.3	4
BOBTAIL 1	513920950			1.6	4
BOBTAIL 1	513921350			2.3	4
BOBTAIL 1	513921750			1.6	4
BOBTAIL 1	513922150			1.6	4
BOBTAIL 1	514920150			2.3	4
BOBTAIL 1	514920550			1.8	4
BOBTAIL 1	514920950			1.8	4
BOBTAIL 1	514921350			2.2	4
BOBTAIL 1	514921750			1.8	4
BOBTAIL 1	514922150			1.9	4
BOBTAIL 1	515920150			2.7	8
BOBTAIL 1	515920550			2	4
BOBTAIL 1	515920950			1.8	4
BOBTAIL 1	515921350			1.5	4
BOBTAIL 1	515921750			2	4
BOBTAIL 1	515922150			1.4	4
BOBTAIL 1	516920150			1.3	4
BOBTAIL 1	516920550			1.5	4
BOBTAIL 1	516920950			3.6	8
BOBTAIL 1	520921150	1.8	0.35		2.2
BOBTAIL 1	520921350			2.9	2
BOBTAIL 1	520921750			1.2	2
BOBTAIL 1	520922150			1.2	2
BOBTAIL 1	521920150			1.3	2
BOBTAIL 1	521920550			1.3	2
BOBTAIL 1	521920950			1.8	2
BOBTAIL 1	521921350			1.3	2

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY TSS	
BOBTAIL 1	521921750			1.6	2
BOBTAIL 1	521922150			1.1	2
BOBTAIL 1	522920150			1.7	2
BOBTAIL 1	522920550			1.2	2
BOBTAIL 1	522920950			1.5	2
BOBTAIL 1	522921350			1.4	2
BOBTAIL 1	522921750			1.6	2
BOBTAIL 1	522922150			1.2	2
BOBTAIL 1	523920150			2.2	2
BOBTAIL 1	523920550			1.5	2
BOBTAIL 1	523920950			1.3	2
BOBTAIL 1	523921350			2.1	2
BOBTAIL 1	523921750			1.7	2
BOBTAIL 1	523922150			1.5	2
BOBTAIL 1	524920150			1.4	2
BOBTAIL 1	524920550			1.1	2
BOBTAIL 1	524920950			2.8	2
BOBTAIL 1	602921730	1	0.48	1.6	2
BOBTAIL 1	602922130			1.8	2
BOBTAIL 1	603920130			1.4	2
BOBTAIL 1	603920530			3.8	8
BOBTAIL 1	603920930			1.3	2
BOBTAIL 1	603921330			1	2
BOBTAIL 1	603921730			1.2	2
BOBTAIL 1	603922130			1.1	2
BOBTAIL 1	604920130			1	2
BOBTAIL 1	604920530			1.2	2
BOBTAIL 1	604920930			1.3	2
BOBTAIL 1	604921330			0.9	2
BOBTAIL 1	604921730			1.1	2
BOBTAIL 1	604922130			1	2
BOBTAIL 1	605920130			1.2	2
BOBTAIL 1	605920530			1.3	2
BOBTAIL 1	605920930			1.1	2
BOBTAIL 1	605921330			1.3	2
BOBTAIL 1	605921730			1	2
BOBTAIL 1	605922130			1.3	2
BOBTAIL 1	606920130			1.2	2
BOBTAIL 1	606920530			1.3	2
BOBTAIL 1	606920930			1	2
BOBTAIL 1	606921330			1.2	2
BOBTAIL 1	602921530	1	0.48		2
BOBTAIL 1	420931430 0.6		0.10	1.9	2
BOBTAIL 1	420931430 0.6			2.4	2
BOBTAIL 1	420931830	,		1.5	2
BOBTAIL 1	420932230			1.5	2
BOBTAIL 1	420932230			1.6	2
BOBTAIL 1	421930230			1.4	2
BOBTAIL 1	421931030			2.1	2
BOBTAIL 1	421931030			1.4	2
BOBTAIL 1	421931430			1.5	2
DODIAIL I	741731030			1.3	2

STATION	DATE/TIME STAG	E	DISCHARGE	PREV.CR.		
BOBTAIL 1	421932230				1.3	
BOBTAIL 1	422930230				1.4	
BOBTAIL 1	422930630				1.5	
BOBTAIL 1	422931030				1.5	2
BOBTAIL 1	422931430				1.5	2
BOBTAIL 1	422931830				1.7	2
BOBTAIL 1	422932230				1.5	2
BOBTAIL 1	423930230				1.5	2
BOBTAIL 1	423930630				2.1	2
BOBTAIL 1	423931030				1.5	2
BOBTAIL 1	423931430				1.4	2
BOBTAIL 1	423931830				1.5	2
BOBTAIL 1	423932230				1.5	2
BOBTAIL 1	424930230				1.5	
BOBTAIL 1	424930630				1.4	
BOBTAIL 1	424931030				1.3	
BOBTAIL 1		0.38		0.5		
BOBTAIL 1	429941156				2	
BOBTAIL 1	429941556				1.8	
BOBTAIL 1	429941956				2.5	
BOBTAIL 1	429942356				1.8	
BOBTAIL 1	430940356				2.2	
BOBTAIL 1	430940756				1.9	
BOBTAIL 1	430941156				1.6	
BOBTAIL 1	430941556				1.6	
BOBTAIL 1	430941956				1.9	
BOBTAIL 1	430942356				1.6	
BOBTAIL 1	501940356				1.6	
BOBTAIL 1	501940756				1.7	
BOBTAIL 1	501941156				1.9	
BOBTAIL 1	501941556				1.8	
BOBTAIL 1	501941956				1.6	
BOBTAIL 1	501942356				1.5	
BOBTAIL 1	502940356				1.5	
BOBTAIL 1	502940756				1.6	
BOBTAIL 1	502941156				1.8	
BOBTAIL 1	502941556				2.1	
BOBTAIL 1	502941956				1.5	
BOBTAIL 1	502942356				1.8	
BOBTAIL 1	503940356				1.2	
BOBTAIL 1	503940756				1.4	
BOBTAIL 1		0.46		0.75		
BOBTAIL 1	503941007				2	
BOBTAIL 1	503941407				2	
BOBTAIL 1	503941807				1.8	
BOBTAIL 1	503942207				1.7	
BOBTAIL 1	504940207				1.6	
BOBTAIL 1	504940607				1.6	
BOBTAIL 1	504941007				1.8	
BOBTAIL 1	504941407				1.8	
BOBTAIL 1	504941807				1.7	

BOBTAIL I 504942207 1.6 2.22 BOBTAIL I 505940207 1.8 2.22 BOBTAIL I 505940607 1.8 2.22 BOBTAIL I 505941007 1.9 2.22 BOBTAIL I 505941407 1.9 2.22 BOBTAIL I 505942207 1.9 2.22 BOBTAIL I 506940207 1.7 2.22 BOBTAIL I 506940607 1.7 2.22 BOBTAIL I 506940607 1.7 2.22 BOBTAIL I 506941007 1.7 2.22 BOBTAIL I 506941807 1.5 2.22 BOBTAIL I 506941807 1.7 2.22 BOBTAIL I 506942207 1.7 2.22 BOBTAIL I 507940207 1.8 2.22 BOBTAIL I 507940607 1.8 2.22 BOBTAIL 2 420931400 1.8 5.6 BOBTAIL 2 420931400 1.7 5.6 BOBTAIL 2 421930200 <td< th=""><th>STATION</th><th>DATE/TIME STAGE</th><th>DISCHARGE</th><th>PREV.CR.</th><th>TURBIDITY</th><th>TSS</th></td<>	STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	TSS
BOBTAIL 1 505940607 1.8 2.22 BOBTAIL 1 505941407 1.9 2.22 BOBTAIL 1 505941807 1.7 2.22 BOBTAIL 1 505941807 1.7 2.22 BOBTAIL 1 505942207 1.9 2.22 BOBTAIL 1 506940607 1.7 2.22 BOBTAIL 1 506940607 1.7 2.22 BOBTAIL 1 506941007 1.7 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 1.8 5.6 BOBTAIL 2 420931400 1.8 5.6 BOBTAIL 2 421930200 9.7 2.6 BOBTAIL 2 42193000 9.1 2.6 BOBTAIL 2 421931400 9.1	BOBTAIL 1	504942207			1.6	2.22
BOBTAIL 1 505941007 1.8 2.22 BOBTAIL 1 505941407 1.9 2.22 BOBTAIL 1 505941807 1.9 2.22 BOBTAIL 1 505942207 1.9 2.22 BOBTAIL 1 506940607 1.7 2.22 BOBTAIL 1 506941007 1.7 2.22 BOBTAIL 1 506941007 1.6 2.22 BOBTAIL 1 506941007 1.7 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 421930200 9.2 26 BOBTAIL 2 42193000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931800 8.7	BOBTAIL 1	505940207			1.8	2.22
BOBTAIL 1 505941407 1.9 2.22 BOBTAIL 1 505941807 1.7 2.22 BOBTAIL 1 505942207 1.9 2.22 BOBTAIL 1 506940207 1.7 2.22 BOBTAIL 1 506940607 1.7 2.22 BOBTAIL 1 506941007 1.6 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506941807 1.7 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 1.2 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 421930000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3	BOBTAIL 1	505940607			1.8	2.22
BOBTAIL 1 505941807 1.7 2.22 BOBTAIL 1 505942207 1.9 2.22 BOBTAIL 1 505940207 1.7 2.22 BOBTAIL 1 50694007 1.7 2.22 BOBTAIL 1 506941007 1.7 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506941807 1.7 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.2 BOBTAIL 2 42093 9.1 1.2 BOBTAIL 2 420931800 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 42193000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 42293000 8.4 2	BOBTAIL 1	505941007			1.8	2.22
BOBTAIL 1 505942207 1.9 2.22 BOBTAIL 1 506940207 1.7 2.22 BOBTAIL 1 50694007 1.7 2.22 BOBTAIL 1 506941007 1.6 2.22 BOBTAIL 1 506941407 1.6 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940207 1.7 2.22 BOBTAIL 1 507940207 1.8 2.2 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 42193000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931200 9.7 26<	BOBTAIL 1	505941407			1.9	2.22
BOBTAIL I 506940607 1.7 2.22 BOBTAIL I 506940607 1.7 2.22 BOBTAIL I 506941007 1.6 2.22 BOBTAIL I 506941807 1.5 2.22 BOBTAIL I 506941807 1.7 2.22 BOBTAIL I 507940207 1.7 2.22 BOBTAIL I 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420931800 9.7 26 BOBTAIL 2 421930200 9.2 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 42293100 9.7 26 BOBTAIL 2 42293100 8.9 22 </td <td>BOBTAIL 1</td> <td>505941807</td> <td></td> <td></td> <td>1.7</td> <td>2.22</td>	BOBTAIL 1	505941807			1.7	2.22
BOBTAIL 1 506940607 1.7 2.22 BOBTAIL 1 506941007 1.6 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930600 9.7 26 BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 42293000 8.4 22 BOBTAIL 2 422931400 8.7 26	BOBTAIL 1	505942207			1.9	2.22
BOBTAIL 1 506941007 1.7 2.22 BOBTAIL 1 506941407 1.6 2.22 BOBTAIL 1 50694207 1.7 2.22 BOBTAIL 1 507940207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931200 8.4 22 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422931000 8.9 22 BOBTAIL 2 422931400 8.7 22	BOBTAIL 1	506940207			1.7	2.22
BOBTAIL 1 506941407 1.6 2.22 BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 222 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931200 9.2 26 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931200 8.7 26 BOBTAIL 2 422930000 8.4 22 BOBTAIL 2 422931000 8.7 22 BOBTAIL 2 42293100 9.3 28 BOBTAIL 2 422931800 8.7 22	BOBTAIL 1	506940607			1.7	2.22
BOBTAIL 1 506941807 1.5 2.22 BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940207 1.7 2.22 BOBTAIL 2 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.1 26 BOBTAIL 2 421930000 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 8.7 26 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931000 8.7 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931400 8.3 22 BOBTAIL 2 42393000 8.3 28	BOBTAIL 1	506941007			1.7	2.22
BOBTAIL 1 506942207 1.7 2.22 BOBTAIL 1 507940207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930200 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421932000 9.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930600 8.4 22 BOBTAIL 2 42293000 8.9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931400 8.3 22 BOBTAIL 2 422933000 9.3 28	BOBTAIL 1	506941407			1.6	2.22
BOBTAIL 1 507940207 1.7 2.22 BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 420932200 9.7 26 BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422931000 9.2 2 BOBTAIL 2 422931000 8.7 26 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 42293200 9.3 28 BOBTAIL 2 42393100 18 60 <td>BOBTAIL 1</td> <td>506941807</td> <td></td> <td></td> <td>1.5</td> <td>2.22</td>	BOBTAIL 1	506941807			1.5	2.22
BOBTAIL 1 507940607 1.8 2.22 BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 42193200 9.7 26 BOBTAIL 2 42193200 9.7 26 BOBTAIL 2 422930000 8.4 22 BOBTAIL 2 422930000 8.9 22 BOBTAIL 2 422931000 8.7 22 BOBTAIL 2 422931800 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 18 60	BOBTAIL 1	506942207			1.7	2.22
BOBTAIL 2 42093 9.1 22 BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 9.7 26 BOBTAIL 2 421931800 9.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 42293200 9.3 28 BOBTAIL 2 42393000 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 16 60	BOBTAIL 1	507940207			1.7	2.22
BOBTAIL 2 420931400 18 56 BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421931200 8.4 22 BOBTAIL 2 421932200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422931200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 424930200 9.7 54 </td <td>BOBTAIL 1</td> <td>507940607</td> <td></td> <td></td> <td>1.8</td> <td>2.22</td>	BOBTAIL 1	507940607			1.8	2.22
BOBTAIL 2 420931800 17 56 BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931400 9 22 BOBTAIL 2 422931800 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 42293293200 9.3 28 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 42393000 9.3 28 BOBTAIL 2 423931400 18 60 BOBTAIL 2 423931400 16 60 BOBTAIL 2 423931400 16 60 <td>BOBTAIL 2</td> <td>42093</td> <td></td> <td></td> <td>9.1</td> <td>22</td>	BOBTAIL 2	42093			9.1	22
BOBTAIL 2 420932200 9.2 26 BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931000 9.9 22 BOBTAIL 2 422931800 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 42293200 9.3 28 BOBTAIL 2 422931000 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 42493100 9.7 54 BOBTAIL 2 424930600 16 60 <td>BOBTAIL 2</td> <td>420931400</td> <td></td> <td></td> <td>18</td> <td>56</td>	BOBTAIL 2	420931400			18	56
BOBTAIL 2 421930200 9.7 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422931000 8.9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 4229331800 8.3 22 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 18 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 424931000 6 4 BOBTAIL 2	BOBTAIL 2	420931800			17	56
BOBTAIL 2 421930600 9.1 26 BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 9.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422931800 9.3 28 BOBTAIL 2 42293200 9.3 28 BOBTAIL 2 423930000 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931800 18 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424930600 16 60 BOBTAIL 2 42493100 20 60	BOBTAIL 2	420932200			9.2	26
BOBTAIL 2 421931000 9.1 26 BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930600 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 </td <td>BOBTAIL 2</td> <td>421930200</td> <td></td> <td></td> <td>9.7</td> <td>26</td>	BOBTAIL 2	421930200			9.7	26
BOBTAIL 2 421931400 9.3 26 BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 6 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2	BOBTAIL 2	421930600			9.1	26
BOBTAIL 2 421931800 8.7 26 BOBTAIL 2 421932200 9.7 26 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931400 9 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 42493100 20 60 BOBTAIL 2 42493100 7.3 8 BOBTAIL 2 42493100 6.1 4 BOBTAIL 2 42493100 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2	BOBTAIL 2	421931000			9.1	26
BOBTAIL 2 421932200 8.4 22 BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 18 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 42493000 9.7 54 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424931300 6.1 4 BOBTAIL 2 424931300 6.5 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 424932100 5.8 4 BOBTAIL 2	BOBTAIL 2	421931400			9.3	26
BOBTAIL 2 422930200 8.4 22 BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 424931300 7.3 8 BOBTAIL 2 424932100 6.5 4 BOBTAIL 2 424933100 6 4 BOBTAIL 2 424932100 5.8 4 BOBTAIL 2 424932100 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2	BOBTAIL 2	421931800			8.7	26
BOBTAIL 2 422930600 8.9 22 BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 424931300 7.3 8 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 6.5 4 BOBTAIL 2 424931300 5.8 4 BOBTAIL 2 425931300 5.8 4 BOBTAIL 2 425931300 5.4 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2	BOBTAIL 2	421932200			9.7	26
BOBTAIL 2 422931000 9 22 BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424931000 20 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 424931300 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 425931300 5.8 4 BOBTAIL 2 425931300 5.4 2 BOBTAIL 2 425931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2	BOBTAIL 2	422930200			8.4	22
BOBTAIL 2 422931400 8.7 22 BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2	BOBTAIL 2	422930600			8.9	22
BOBTAIL 2 422931800 8.3 22 BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2	BOBTAIL 2	422931000			9	22
BOBTAIL 2 422932200 9.3 28 BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 42493100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2	BOBTAIL 2	422931400			8.7	22
BOBTAIL 2 423930200 9.3 28 BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	422931800			8.3	22
BOBTAIL 2 423930600 18 60 BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424931300 5.8 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 42693100 7.2 4	BOBTAIL 2	422932200			9.3	28
BOBTAIL 2 423931000 18 60 BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 424930500 6.1 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 42693100 7.2 4	BOBTAIL 2	423930200			9.3	28
BOBTAIL 2 423931400 14 60 BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423930600			18	60
BOBTAIL 2 423931800 16 60 BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423931000			18	60
BOBTAIL 2 424930200 9.7 54 BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423931400				
BOBTAIL 2 424930600 16 60 BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423931800			16	60
BOBTAIL 2 424931000 20 60 BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 425930500 6 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426931300 7.2 4	BOBTAIL 2	424930200			9.7	54
BOBTAIL 2 423931300 7.3 8 BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	424930600			16	60
BOBTAIL 2 423932100 6.1 4 BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	424931000			20	60
BOBTAIL 2 424930500 6.5 4 BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423931300			7.3	8
BOBTAIL 2 424931300 7 4 BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	423932100			6.1	4
BOBTAIL 2 424932100 6 4 BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	424930500			6.5	4
BOBTAIL 2 425930500 5.8 4 BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	424931300			7	4
BOBTAIL 2 425931300 5.7 2 BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	424932100			6	4
BOBTAIL 2 425932100 5.4 2 BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	425930500			5.8	4
BOBTAIL 2 426930500 5.4 2 BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4						
BOBTAIL 2 426931300 5.4 2 BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	425932100				
BOBTAIL 2 426932100 7.2 4	BOBTAIL 2	426930500			5.4	
	BOBTAIL 2	426931300				
BOBTAIL 2 427930500 5.5 2		426932100				
	BOBTAIL 2	427930500			5.5	2

STATION	DATE/TIME STAGE	DISCHARGE PREV.CR.	TURBIDITY 7	ΓSS
BOBTAIL 2	427931300		5.3	2
BOBTAIL 2	427932100		5.4	2
BOBTAIL 2	428930500		5.7	2
BOBTAIL 2	428931300		5.4	2
BOBTAIL 2	428932100		5.3	2
BOBTAIL 2	429930500		4.9	2
BOBTAIL 2	429931300		6.4	2
BOBTAIL 2	504931430		4.2	4.4
BOBTAIL 2	504931830		4.6	4.4
BOBTAIL 2	504932230		5	4.4
BOBTAIL 2	505930230		3.7	2.2
BOBTAIL 2	505930630		4.4	2.2
BOBTAIL 2	505931030		4.4	2.2
BOBTAIL 2	505931430		4.2	2.2
BOBTAIL 2	505931830		4.7	2.9
BOBTAIL 2	505932230		4.5	5.2
BOBTAIL 2	506930230		4.7	6.7
BOBTAIL 2	506930630		5.4	8
BOBTAIL 2	506931030		5.1	8
BOBTAIL 2	506931430		5.6	8
BOBTAIL 2	506931830		4.6	8
BOBTAIL 2	506932230		3.6	2.9
BOBTAIL 2	507930230		3.7	2.5
BOBTAIL 2	507930630		3.3	2.2
BOBTAIL 2	507931030		3.7	2.2
BOBTAIL 2	507931430		3	2
BOBTAIL 2	507931830	1	3.7	3.3
BOBTAIL 2	918901000		7	25
BOBTAIL 2	918901400		5.7	18
BOBTAIL 2	918901800		4.7	15
BOBTAIL 2	918902200		4.1	13
BOBTAIL 2	919900200		3.6	13
BOBTAIL 2	919900600		4.4	15
BOBTAIL 2	919901000		3.3	13
BOBTAIL 2	919901400		3.5	13
BOBTAIL 2	919901800		3.7	13
BOBTAIL 2	919902200		3.2	13
BOBTAIL 2	920900200		4.4	15
BOBTAIL 2	921900600		3.6	13
BOBTAIL 2	920901000		2.5	5
BOBTAIL 2	920901400		3.4	13
BOBTAIL 2	920901800		3.7	15
BOBTAIL 2	920902200		3	8
BOBTAIL 2	921900200		4.7	15
BOBTAIL 2	921900600		3.3	13
BOBTAIL 2	921901000		2.3	5
BOBTAIL 2	921901400		2.4	5
BOBTAIL 2	921901800		3.1	10
BOBTAIL 2	921902200		3.6	15
BOBTAIL 2	922900200		6.4	23
BOBTAIL 2	922900600	1	6.9	23

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	TSS
BOBTAIL 2	1005901100	1.1		67	883
BOBTAIL 2	1005901500			56	788
BOBTAIL 2	1005901900			30	463
BOBTAIL 2	1005902300			33	468
BOBTAIL 2	1006900300			10	133
BOBTAIL 2	1006900700			18	208
BOBTAIL 2	1006901100			24	305
BOBTAIL 2	1006901500			31	468
BOBTAIL 2	1006901900			54	778
BOBTAIL 2	1006902300			40	480
BOBTAIL 2	1007900300			34	468
BOBTAIL 2	1019901730 0.5	2		38	872
BOBTAIL 2	1019901930			24	540
BOBTAIL 2	1019902130			24	516
BOBTAIL 2	1019902330			22	504
BOBTAIL 2	1019900130			16	263
BOBTAIL 2	1019900330			18	470
BOBTAIL 2	1019900530			11	183
BOBTAIL 2	1019900730			9.6	125
BOBTAIL 2	1019900930			9.8	149
BOBTAIL 2	1019901130			8.2	117
BOBTAIL 2	1019901330			8.7	123
BOBTAIL 2	1019901530			9.1	126
BOBTAIL 2	1019901730			10	174
BOBTAIL 2	1019901930			8	111
BOBTAIL 2	1019902130			7.6	109
BOBTAIL 2	1019902330			9.1	117
BOBTAIL 2	1020900130			7.2	91
BOBTAIL 2	1020900330			14	234
BOBTAIL 2	1020900530			14	237
BOBTAIL 2	1020900730			19	303
BOBTAIL 2	1020900930			13	185
BOBTAIL 2	1020901130			9.3	103
BOBTAIL 2	1020901330			8.7	105
BOBTAIL 2	1020901530			8.7	108
BOBTAIL 2	1020901730			9.8	158
BOBTAIL 2	1020901930			15	233
BOBTAIL 2	1020902130			11	148
BOBTAIL 2	1020902330			10	135
BOBTAIL 2	407912000			152	1,620.00
BOBTAIL 2	510911445 1.4	2		6.2	26
BOBTAIL 2	510911845			6.8	42
BOBTAIL 2	510912245			6.2	34
BOBTAIL 2	511910245			6	30
BOBTAIL 2	511910645			5.5	22
BOBTAIL 2	511911045			5.9	26
BOBTAIL 2	511911445			6.4	34
BOBTAIL 2	511911845			6	28
BOBTAIL 2	511912245			6.5	38
BOBTAIL 2	512910245			6.9	42
BOBTAIL 2	512910645			5.9	26

BOBTAIL 2 512911445 5 24 BOBTAIL 2 512911845 5 18 BOBTAIL 2 512911845 5 18 BOBTAIL 2 513910245 5.6 28 BOBTAIL 2 51391045 0.82 0.82 5.2 BOBTAIL 2 51391045 0.82 0.82 4.9 BOBTAIL 2 51391045 0.82 0.82 4.9 BOBTAIL 2 514911230 0.82 0.82 4.9 BOBTAIL 2 51491630 4.4 4.4 BOBTAIL 2 51491230 4.5 50 BOBTAIL 2 51591030 4.5 50 BOBTAIL 2 51591030 4.3 4.3 BOBTAIL 2 51591030 4.3 4.3 BOBTAIL 2 51591030 4.4 3 50 BOBTAIL 2 51591030 4.4 4.4 BOBTAIL 2 51591030 4.4 5 BOBTAIL 2 51591030 4.4 5 BOBTAIL 2 51591030 4.5 50 BOBTAIL 2 51591030 4.8 60 BOBTAIL 2 51691030 4.5 52 BOBTAIL 2 51691030 4.5 52 BOBTAIL 2 51691030 4.6 54 BOBTAIL 2 51691030 4.6 54 BOBTAIL 2 51691030 4.1 54 BOBTAIL 2 51791030 5.3 78 BOBTAIL 2 51791030 5.3 78 BOBTAIL 2 51891030 5.3 78 BOBTAIL 2 528911000 5.3 78 BOBTAIL 2 529911000 5.3	STATION	DATE/TIME STAG	E	DISCHARGE	PREV.CR.	TURBIDITY	<u>TSS</u>
BOBTAIL 2 512911845 5 18 BOBTAIL 2 512912245 4.8 14 14	BOBTAIL 2	512911045				5	24
BOBTAIL 2 512912245	BOBTAIL 2	512911445				5	24
BOBTAIL 2	BOBTAIL 2	512911845				5	18
BOBTAIL 2	BOBTAIL 2	512912245				4.8	14
BOBTAIL 2 513911045 0.82 0.82 4.9 155 BOBTAIL 2 514911230 0.82 0.82 4.9 155 BOBTAIL 2 514911630 4.3 46 46 BOBTAIL 2 515910030 4.5 50 50 BOBTAIL 2 515910430 4.3 48 50	BOBTAIL 2	513910245				5.6	28
BOBTAIL 2 514911230 0.82 4.9 155 BOBTAIL 2 514911630 4.3 46 BOBTAIL 2 514912030 4.4 48 BOBTAIL 2 515910030 4.3 50 BOBTAIL 2 515910830 4.3 48 BOBTAIL 2 515911230 4.4 50 BOBTAIL 2 515911630 4.3 50 BOBTAIL 2 515911630 4.3 50 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516910430 4.1 54 BOBTAIL 2 51691030 4.1 54 BOBTAIL 2 51791030 4.3 40 BOBTAIL 2 51791030 4.3	BOBTAIL 2	513910645				5.4	26
BOBTAIL 2 514911630	BOBTAIL 2	513911045	0.82		0.82	5.2	22
BOBTAIL 2 514912030	BOBTAIL 2	514911230	0.82		0.82	4.9	155
BOBTAIL 2 515910030	BOBTAIL 2	514911630				4.3	46
BOBTAIL 2 515910430 4.3 48 BOBTAIL 2 515910830 4.4 50 BOBTAIL 2 515911630 4.4 50 BOBTAIL 2 515911630 4.8 60 BOBTAIL 2 515912030 4.8 60 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910430 4.6 54 BOBTAIL 2 516910830 5.6 62 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5.5 62 BOBTAIL 2 516911230 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911630 5.1 7191230 7.1 7.3 4 BOBTAIL 2 517911630 7.2 24 BOBTAIL 2 517911630 7.2 24 BOBTAIL 2 517912030 7.1 7.3 4 BOBTAIL 2 518910430 7.1 7.3 4 BOBTAIL 2 528912000 7.1 7.3 7.1 4 BOBTAIL 2 52891200 7.1 7.1 86 BOBTAIL 2 529912000 7.1 7.1 86	BOBTAIL 2	514912030				4.4	48
BOBTAIL 2 515910830	BOBTAIL 2	515910030				4.5	50
BOBTAIL 2 515911230 4.4 50 BOBTAIL 2 515911630 4.3 50 BOBTAIL 2 515912030 4.8 60 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911230 12 24 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911000 3.3 10 <tr< td=""><td>BOBTAIL 2</td><td>515910430</td><td></td><td></td><td></td><td>4.3</td><td>50</td></tr<>	BOBTAIL 2	515910430				4.3	50
BOBTAIL 2 515911630 4.3 50 BOBTAIL 2 515912030 4.8 60 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911230 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517911230 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529911000 3.8 8 BOBTAIL 2 529911000 3.8 </td <td>BOBTAIL 2</td> <td>515910830</td> <td></td> <td></td> <td></td> <td>4.3</td> <td>48</td>	BOBTAIL 2	515910830				4.3	48
BOBTAIL 2 515912030 4.8 60 BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910430 4.7 54 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517912030 17 34 BOBTAIL 2 51891030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911200 3.3 10 BOBTAIL 2 529910400 4.5 24 BOBTAIL 2 529910400 3.3 <td>BOBTAIL 2</td> <td>515911230</td> <td></td> <td></td> <td></td> <td>4.4</td> <td>50</td>	BOBTAIL 2	515911230				4.4	50
BOBTAIL 2 516910030 4.5 52 BOBTAIL 2 516910430 4.7 54 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911230 17 34 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911600 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.8 8 BOBTAIL 2 529912000 3.8 <td>BOBTAIL 2</td> <td>515911630</td> <td></td> <td></td> <td></td> <td>4.3</td> <td>50</td>	BOBTAIL 2	515911630				4.3	50
BOBTAIL 2 516910430 4.7 54 BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 529910800 17 186 BOBTAIL 2 52991200 3.3 24 BOBTAIL 2 52991200 3.8 <td>BOBTAIL 2</td> <td>515912030</td> <td></td> <td></td> <td></td> <td>4.8</td> <td>60</td>	BOBTAIL 2	515912030				4.8	60
BOBTAIL 2 516910830 4.6 54 BOBTAIL 2 516911230 5 62 BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 3 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912000 3.8 <td>BOBTAIL 2</td> <td>516910030</td> <td></td> <td></td> <td></td> <td>4.5</td> <td>52</td>	BOBTAIL 2	516910030				4.5	52
BOBTAIL 2 516911230 5 62 BOBTAIL 2 516912030 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 21 42 BOBTAIL 2 518910430 21 42 BOBTAIL 2 518910430 31 44 BOBTAIL 2 528911200 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912000 3.3 3 3 3 8 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910400 3.8 8 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911200 3.3 3 8 BOBTAIL 2 529912400 3.8 8	BOBTAIL 2	516910430				4.7	54
BOBTAIL 2 516911630 5.3 78 BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 3.3 10 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 529912400 3.6 <td>BOBTAIL 2</td> <td>516910830</td> <td></td> <td></td> <td></td> <td>4.6</td> <td>54</td>	BOBTAIL 2	516910830				4.6	54
BOBTAIL 2 516912030 4.1 54 BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 529912400 3.6 <td>BOBTAIL 2</td> <td>516911230</td> <td></td> <td></td> <td></td> <td>5</td> <td>62</td>	BOBTAIL 2	516911230				5	62
BOBTAIL 2 517910030 4.3 46 BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 518910030 17 34 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 0.98 4 4 BOBTAIL 2 <	BOBTAIL 2	516911630				5.3	78
BOBTAIL 2 517910430 4.9 70 BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3.6 8 BOBTAIL 2 530910400 3 0.98 4 4 BOBTAIL 2 <t< td=""><td>BOBTAIL 2</td><td>516912030</td><td></td><td></td><td></td><td>4.1</td><td>54</td></t<>	BOBTAIL 2	516912030				4.1	54
BOBTAIL 2 517910830 4.5 62 BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529912000 3.3 28 BOBTAIL 2 529912000 3.3 8 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 0.98 4 4 BOBTAIL 2 415921100 3 0.98 4 4 4	BOBTAIL 2	517910030				4.3	46
BOBTAIL 2 517911230 12 24 BOBTAIL 2 517911630 22 40 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 530910400 3 0.98 4 4 BOBTAIL 2 415921100 3 0.98 4 4	BOBTAIL 2	517910430				4.9	70
BOBTAIL 2 517911630 22 40 BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 530910400 3 0.98 4 48 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	517910830				4.5	62
BOBTAIL 2 517912030 17 34 BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911200 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 0.98 4 48 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	517911230				12	24
BOBTAIL 2 518910030 21 42 BOBTAIL 2 518910430 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	517911630				22	40
BOBTAIL 2 518910430 0.8 23 44 BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	517912030				17	34
BOBTAIL 2 518910830 0.8 0.82 25 48 BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 0.98 4 48 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	518910030				21	42
BOBTAIL 2 528911200 0.74 4.2 20 BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	518910430				23	44
BOBTAIL 2 528911600 3.7 14 BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	518910830	0.8		0.82	25	48
BOBTAIL 2 528912000 3.3 10 BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	528911200			0.74	4.2	20
BOBTAIL 2 528912400 4.5 24 BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	528911600				3.7	14
BOBTAIL 2 529910400 3.8 24 BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	528912000				3.3	10
BOBTAIL 2 529910800 17 186 BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	528912400				4.5	24
BOBTAIL 2 529911200 3.3 28 BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529910400				3.8	24
BOBTAIL 2 529911600 4.1 10 BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529910800				17	186
BOBTAIL 2 529912000 3.8 8 BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529911200				3.3	28
BOBTAIL 2 529912400 3.6 8 BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529911600				4.1	10
BOBTAIL 2 530910400 3 8 BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529912000				3.8	8
BOBTAIL 2 415921100 3 0.98 4 48	BOBTAIL 2	529912400				3.6	8
	BOBTAIL 2	530910400				3	8
DODTAIL 2 415021100 CO 70	BOBTAIL 2	415921100		3	0.98	4	48
DUDTAIL 2 413921100 6.9 /8	BOBTAIL 2	415921100				6.9	78
BOBTAIL 2 415921500 4.1 56	BOBTAIL 2	415921500				4.1	56
BOBTAIL 2 415921900 3.6 48	BOBTAIL 2	415921900				3.6	48
BOBTAIL 2 415922300 3.5 44	BOBTAIL 2	415922300				3.5	44
BOBTAIL 2 416920300 3.1 40	BOBTAIL 2	416920300				3.1	40
BOBTAIL 2 416920700 4.7 60	BOBTAIL 2	416920700				4.7	60
BOBTAIL 2 406921100 3.4 56	BOBTAIL 2	406921100				3.4	56
BOBTAIL 2 416921500 3.6 56	BOBTAIL 2	416921500				3.6	56

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.		<u>TSS</u>
BOBTAIL 2	416921900			3.8	60
BOBTAIL 2	416922300			8.7	104
BOBTAIL 2	417920300			4.4	82
BOBTAIL 2	417920700			18	234
BOBTAIL 2	417921100			15	206
BOBTAIL 2	417921500			8.2	182
BOBTAIL 2	417921900			7	164
BOBTAIL 2	417922300			6.1	96
BOBTAIL 2	418920300			4.9	80
BOBTAIL 2	418920700			5.3	80
BOBTAIL 2	418921100			5.4	76
BOBTAIL 2	418921500			5.3	76
BOBTAIL 2	418919300			4.7	72
BOBTAIL 2	418922300			4	56
BOBTAIL 2	419920300			4.7	66
BOBTAIL 2	419920700			4.9	68
BOBTAIL 2	419921100			5	84
BOBTAIL 2	419921500			4.8	80
BOBTAIL 2	419921900			4.1	64
BOBTAIL 2	419922300			4.3	64
BOBTAIL 2	429921045			3.9	22
BOBTAIL 2	429921445			3.8	22
BOBTAIL 2	429921845			3.6	20
BOBTAIL 2	429922245			3.5	20
BOBTAIL 2	430920245			3.8	20
BOBTAIL 2	430920645			3.3	8
BOBTAIL 2	430921045			3.5	8
BOBTAIL 2	430921445			4.3	26
BOBTAIL 2	430921845			3.9	24
BOBTAIL 2	430922245			3.6	14
BOBTAIL 2	501920245			4.2	24
BOBTAIL 2	501920645			3.4	8
BOBTAIL 2	501921045			3.3	8
BOBTAIL 2	501921445			3.5	8
BOBTAIL 2	501921845			3.7	8
BOBTAIL 2	501922245			3	4
BOBTAIL 2	502920245			3.3	4
BOBTAIL 2	502920645			3.8	12
BOBTAIL 2	502921045			3.6	8
BOBTAIL 2	502921445			2.8	4
BOBTAIL 2	502921845			3	4
BOBTAIL 2	502922245			3.3	4
BOBTAIL 2	503920245			3.4	4
BOBTAIL 2	503920645			3.1	4
BOBTAIL 2	503921045			3.3	4
BOBTAIL 2	503921445			3.4	4
BOBTAIL 2	503921845			3.1	4
BOBTAIL 2	503922245			3.7	8
BOBTAIL 2	520921420 0.8	3 1.5	1.05		2
BOBTAIL 2	520921820			2.4	2
BOBTAIL 2	520922220			2.3	2

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	<u>TSS</u>
BOBTAIL 2	521920220			2.4	2
BOBTAIL 2	521920620			2.3	2
BOBTAIL 2	521921020			2.6	2
BOBTAIL 2	521921420			2.4	2
BOBTAIL 2	521921820			2	2
BOBTAIL 2	521922220			2.5	2
BOBTAIL 2	522920220			2.4	2
BOBTAIL 2	522920620			2.6	2
BOBTAIL 2	522921020			2.3	2
BOBTAIL 2	522921420			2.2	2
BOBTAIL 2	522921820			2.6	2
BOBTAIL 2	522922220			3	2
BOBTAIL 2	523920220			2.6	2
BOBTAIL 2	523920620			2.5	2
BOBTAIL 2	523921020			2.1	2
BOBTAIL 2	523921420			2.5	2
BOBTAIL 2	523921820			2.4	2
BOBTAIL 2	523922220			2.7	2
BOBTAIL 2	524920220			2.6	2
BOBTAIL 2	524920620			2.7	2
BOBTAIL 2	524921020			2.5	2
BOBTAIL 2	520921220 0.8	3 1.5	1.05		2.2
BOBTAIL 2	602921430	1.2			2
BOBTAIL 2	602921630	1.2			2
BOBTAIL 2	602922030	1,2	0.02	1.5	2
BOBTAIL 2	603920030			1.4	2
BOBTAIL 2	603920430			1.4	2
BOBTAIL 2	603920830			1.3	2
BOBTAIL 2	603921230			1.5	2
BOBTAIL 2	603921630			2.4	2
BOBTAIL 2	603922030			1.2	2
BOBTAIL 2	604920030			1.4	2
BOBTAIL 2	604920430			1.6	2
BOBTAIL 2	604920830			1.6	2
BOBTAIL 2	604921230			1.2	2
BOBTAIL 2	604921630			1.3	2
BOBTAIL 2	604922030			1.3	2
BOBTAIL 2	605920030			1.5	2
BOBTAIL 2	605920430			1.6	2
BOBTAIL 2	605920830			1.3	2
BOBTAIL 2	605921230			1.5	2
BOBTAIL 2	429941030			4.6	2.22
BOBTAIL 2	429941100			4.9	2.85
BOBTAIL 2	429941500			4.5	2.85
BOBTAIL 2	429941900			5	2.85
BOBTAIL 2	429942300			5.4	2.85
BOBTAIL 2	430940300			6.9	2.85
BOBTAIL 2	430940700			5.7	2.85
BOBTAIL 2	430941100			5.3	2.85
BOBTAIL 2	430941100			5.4	2.85
BOBTAIL 2	430941900			5.3	2.85
DOD I AIL 2	4 307 4 1700			3.3	2.03

STATION	DATE/TIME STAG	<u>E</u>	DISCHARGE	PREV.CR.		<u>TSS</u>
BOBTAIL 2	430942300				4.7	2.85
BOBTAIL 2	501940300				5.2	2.85
BOBTAIL 2	501940700				5.4	2.5
BOBTAIL 2	501941100				5.8	2.5
BOBTAIL 2	501941500				5.8	2.5
BOBTAIL 2	501941900				5.8	2.5
BOBTAIL 2	501942300				7	2.5
BOBTAIL 2	502940300				5.4	2.5
BOBTAIL 2	502940700				5	2.5
BOBTAIL 2	502941100				5.4	5
BOBTAIL 2	502941500				5.6	2.5
BOBTAIL 2	502941900				5.9	2.5
BOBTAIL 2	502942300				5.3	2.5
BOBTAIL 2	503940300				5.1	2.5
BOBTAIL 2	503940700				5.8	5
BOBTAIL 2	503940907).75		0.75		2
BOBTAIL 2	503940910				4.6	2.5
BOBTAIL 2	503941310				8.2	2.5
BOBTAIL 2	503941710				6.6	5
BOBTAIL 2	503942110				5.8	5
BOBTAIL 2	504940110				5.4	5
BOBTAIL 2	504940510				5.6	5
BOBTAIL 2	504940910				5.2	5
BOBTAIL 2	504941310				5.8	5
BOBTAIL 2	504941710				5.6	5
BOBTAIL 2	504942110				5.6	5
BOBTAIL 2	505940110				5.4	5
BOBTAIL 2	505940510				6.2	5
BOBTAIL 2	505940910				6.8	5
BOBTAIL 2	505941310				6	5
BOBTAIL 2	505941710				5.7	5
BOBTAIL 2	505942110				5.6	5
BOBTAIL 2	506940110				4.7	5
BOBTAIL 2	506940510				5.1	5
BOBTAIL 2	506940910				5.5	5
BOBTAIL 2	506941310				6.1	5
BOBTAIL 2	506941710				5.3	5
BOBTAIL 2	506942110				5.4	5
BOBTAIL 2	507940110				5.6	5
BOBTAIL 2	507940510				5.7	5
BOBTAIL 2).58		0.58		2.27
BOBTAIL 2	509940900			0.50	9.1	18.75
BOBTAIL 2	509941300				5.5	2
BOBTAIL 2	509941700				5.5	16.27
BOBTAIL 2	509942100				5	14.28
BOBTAIL 2	510940100				4.8	14.28
BOBTAIL 2	510940100				5.2	14.28
BOBTAIL 2	510940900				5.5	14.28
BOBTAIL 2	510940900				5.1	14 14
BOBTAIL 2	510941700				5.1	14 14
BOBTAIL 2	510941700				4.4	10
DODIAIL 2	J10742100				4.4	10

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY 1	<u> SS</u>
BOBTAIL 2	511940100			5.6	10
BOBTAIL 2	511940500			5.8	10
BOBTAIL 2	511940900			5.6	10
BOBTAIL 2	511941300			6	10
BOBTAIL 2	511941700			5.5	10
BOBTAIL 2	511942100			5.4	14
BOBTAIL 2	512940100			6	14
BOBTAIL 2	512940500			5.6	12
BOBTAIL 2	512940900			5	12
BOBTAIL 2	512941300			5.6	12
BOBTAIL 2	512941700			5	12
BOBTAIL 2	512942100			5.2	12
BOBTAIL 2	513940100			6	12
BOBTAIL 2	513940500			5.5	12
BOBTAIL 2	514941230			2.5	2
BOBTAIL 2	514941230			4.2	12
BOBTAIL 2	514942030			4	12
BOBTAIL 2	515940430			6.4	26
BOBTAIL 2	515941230			5.2	14
BOBTAIL 2	515942030			5	14
BOBTAIL 2	516940430			4	8
BOBTAIL 2	516941230			5	14
BOBTAIL 2	516942030			4.5	10
BOBTAIL 2	517940430			6.5	10
BOBTAIL 2	517941230			4.7	28
BOBTAIL 2	517942030			5.1	12
BOBTAIL 2	518940430			4.5	12
BOBTAIL 2	518941230			3.5	10
BOBTAIL 2	518942030			4.1	6
BOBTAIL 2	519940430			4.4	6
BOBTAIL 2	519941230			5	8
BOBTAIL 2	519942030			3.1	8
BOBTAIL 2	520940430			3.7	8
BOBTAIL 2	520941230			5.5	8
BOBTAIL 2	520942030			4	8
BOBTAIL 2	521940430			4.3	8
BOBTAIL 2	521941230			5	8
BOBTAIL 2	521942030			4.3	8
BOBTAIL 2	522940430			5	2
BOBTAIL 3	420931210			1	2
BOBTAIL 3	423931130			2.5	2
BOBTAIL 3	423931930			1.9	2
BOBTAIL 3	424930330			1.6	2
BOBTAIL 3	424931130			2.2	2
BOBTAIL 3	424931930			1.5	2
BOBTAIL 3	425930330			1.8	2
BOBTAIL 3	425931130			1.9	2
BOBTAIL 3	425931930			2.7	2
BOBTAIL 3	426930330			3	2
BOBTAIL 3	426931130			2	2
BOBTAIL 3	426931930			2.3	2
					_

BOBTAIL 3 427930330 2.3 2 BOBTAIL 3 427931130 2.3 2 BOBTAIL 3 428930330 1.9 2 BOBTAIL 3 428931130 2 2 BOBTAIL 3 428931930 1.9 2 BOBTAIL 3 428931930 1.9 2 BOBTAIL 3 42993130 1.5 2 2 BOBTAIL 3 429931930 1.7 2 2 BOBTAIL 3 43093130 1.7 2 2 BOBTAIL 3 43093130 1.7 2 2 BOBTAIL 3 43093130 1.7 2 2 BOBTAIL 3 50393140 1.9 2 2 BOBTAIL 3 50393140 0.9 2 2 BOBTAIL 3 50393240 1 2 2 BOBTAIL 3 504930340 1 2 2 BOBTAIL 3 50493140 0.8 2 2 BOBTAIL 3 50493140 <th>STATION</th> <th>DATE/TIME STAGE</th> <th>DISCHARGE P</th> <th>PREV.CR.</th> <th>TURBIDITY TSS</th> <th></th>	STATION	DATE/TIME STAGE	DISCHARGE P	PREV.CR.	TURBIDITY TSS	
BOBTAIL 3 427931130 2 2 BOBTAIL 3 428930330 1.9 2 BOBTAIL 3 428930130 2 2 BOBTAIL 3 428931130 2 2 BOBTAIL 3 429930330 1.9 2 BOBTAIL 3 429930330 1.5 2 BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 43093130 1.7 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504931440 0.8 2 BOBTAIL 3 504931440 0.7 2	BOBTAIL 3	427930330			2.3	2
BOBTAIL 3 427931930 2 2 BOBTAIL 3 428931130 1.9 2 BOBTAIL 3 428931930 1.9 2 BOBTAIL 3 429931930 1.9 2 BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 429931930 1.7 2 BOBTAIL 3 430931330 1.7 2 BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 50393240 0.9 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 50493140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 50493240 0.7 2 <t< td=""><td>BOBTAIL 3</td><td>427931130</td><td></td><td></td><td>2.3</td><td></td></t<>	BOBTAIL 3	427931130			2.3	
BOBTAIL 3 428931130 2 2 BOBTAIL 3 428930330 1.9 2 BOBTAIL 3 429930330 1.5 2 BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 501930330 1.8 2 BOBTAIL 3 501930330 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 50493140 0.7 2 BOBTAIL 3 50493140 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 50593140 1.2 2	BOBTAIL 3	427931930			2	2
BOBTAIL 3 428931130 2 2 BOBTAIL 3 428930330 1.9 2 BOBTAIL 3 429930330 1.5 2 BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430930330 1.8 2 BOBTAIL 3 430930330 1.8 2 BOBTAIL 3 501930330 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 50493140 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931940 1 2	BOBTAIL 3	428930330			1.9	2
BOBTAIL 3 428931930 1.9 2 BOBTAIL 3 429930330 2 2 BOBTAIL 3 429931130 1.7 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430931930 1.7 2 BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930340 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 505930340 0.9 2 BOBTAIL 3 505930340 1 2 <	BOBTAIL 3					
BOBTAIL 3 429930330 2 2 BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 429931930 1.7 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930340 1.1 2 BOBTAIL 3 504931540 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931540 1 2 B	BOBTAIL 3	428931930			1.9	2
BOBTAIL 3 429931130 1.5 2 BOBTAIL 3 429931930 1.7 2 BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503931940 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931340 0.7 2 BOBTAIL 3 504931340 0.7 2 BOBTAIL 3 505930340 0.9 2 BOBTAIL 3 50593140 1.2 2 BOBTAIL 3 505931540 0.9 2 BOBTAIL 3 506930340 0.9 2						
BOBTAIL 3 429931930 1.7 2 BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930340 1.1 2 BOBTAIL 3 504931540 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 506930340 0.9 2 B						
BOBTAIL 3 430930330 1.7 2 BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 501930330 1.8 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931140 0.7 2 BOBTAIL 3 504931140 0.7 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 50693140 0.9 2						
BOBTAIL 3 430931130 1.7 2 BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506931940 0.9 2 B						
BOBTAIL 3 430931930 1.8 2 BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 0.9 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504931940 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931940 0.9 2 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
BOBTAIL 3 501930330 1.9 2 BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930340 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505931540 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506931940 0.9 2 BOBTAIL 3 506931940 1.2 2 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
BOBTAIL 3 503931540 1.2 2 BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930340 1.1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506931940 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 B						
BOBTAIL 3 503931940 0.9 2 BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 0.9 2 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
BOBTAIL 3 503932340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 507930740 1.2 2 B						
BOBTAIL 3 504930340 1 2 BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505930340 0.9 2 BOBTAIL 3 505930340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 507930340 0.9 2 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
BOBTAIL 3 504930740 1.1 2 BOBTAIL 3 504931140 0.8 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931940 1 4 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.9 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930340 0.9 2 BOB						
BOBTAIL 3 504931140 0.7 2 BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931140 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931540 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507931140 1 2 BOB						
BOBTAIL 3 504931540 0.7 2 BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505930340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931540 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 507930740 1.2 2 BOBTAIL 3 507930740 1.2 2 BOBTAIL 3 509130940 1 2 BOBTAIL 3 510911300 3 3 BOB						
BOBTAIL 3 504931940 0.7 2 BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506932340 0.9 2 BOBTAIL 3 507930740 1.2 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 3 BOBTAIL 3 510911700 2.8 18 BOBTAIL 3 511910500 2.8 15 <						
BOBTAIL 3 504932340 0.9 2 BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911300 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 <						
BOBTAIL 3 505930340 1 2 BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 15 BOBTAIL 3 51191000 2.5 13 <						
BOBTAIL 3 505930740 1 2 BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910500 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 51						
BOBTAIL 3 505931140 1.2 2 BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931940 0.9 2 BOBTAIL 3 506933340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 511910100 2.8 18 BOBTAIL 3 51191000 2.8 15 BOBTAIL 3 511911300 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3						
BOBTAIL 3 505931540 1 2 BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 0.7 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911300 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 <						
BOBTAIL 3 505931940 1 2 BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 507930340 0.7 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 511910100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.6 15 BOBTAIL 3 51191100 2.5 13 BOBTAIL 3 51191100 2.5 13 BOBTAIL 3 51191100 2.5 13 BOBTAIL 3 512910500 2.5 13 BOBTAIL 3 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td></t<>						
BOBTAIL 3 505932340 0.9 2 BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 511910100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.6 15 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3						
BOBTAIL 3 506930340 0.9 2 BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 51191000 2.5 13 BOBTAIL 3 51291000 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3						
BOBTAIL 3 506930740 0.9 2 BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910500 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910500 1.6 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3						
BOBTAIL 3 506931140 1 4 BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910500 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910500 1.6 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3						
BOBTAIL 3 506931540 0.9 2 BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510912100 2.3 8 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910500 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 506931940 1.2 2 BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 506932340 0.7 2 BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 511910100 2.8 18 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 507930340 0.9 2 BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 507930740 1.3 2 BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 507931140 1 2 BOBTAIL 3 510911300 3 30 BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511911300 2.6 15 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 510911300 3 30 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 2.5 13 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 510911700 2.3 8 BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 510912100 2.8 18 BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511910100 2.5 13 BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511910500 2.8 15 BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511910900 2.6 15 BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511911300 2.4 13 BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511911700 2.5 13 BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 511912100 2.5 13 BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 512910100 1.9 3 BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 512910500 2.2 3 BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 512910900 1.6 3 BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 512911300 3.3 45						
BOBTAIL 3 512911700 2.6 30						45
	BOBTAIL 3	512911700			2.6	30

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	<u>TSS</u>
BOBTAIL 3	512912100			2.5	18
BOBTAIL 3	513910100			2.2	8
BOBTAIL 3	513910500			2.7	23
BOBTAIL 3	513910900			2	3
BOBTAIL 3	513911300			2.1	3
BOBTAIL 3	513911700			2.5	13
BOBTAIL 3	513912100			2.3	8
BOBTAIL 3	514910100			3.4	45
BOBTAIL 3	514910500			3.5	53
BOBTAIL 3	514910900			3.8	60
BOBTAIL 3	514911300			3.3	15
BOBTAIL 3	514911700			3.4	15
BOBTAIL 3	514912100			3.5	15
BOBTAIL 3	515910100			4	27
BOBTAIL 3	515910500			3.8	23
BOBTAIL 3	515910900			4.2	31
BOBTAIL 3	515911300			4.3	46
BOBTAIL 3	515911700			3.5	27
BOBTAIL 3	515912100			3	15
BOBTAIL 3	516910100			1.8	4
BOBTAIL 3	516910500			3.1	12
BOBTAIL 3	516910900			3	12
BOBTAIL 3	516911300			3.2	12
BOBTAIL 3	516911700			2.1	8
BOBTAIL 3	516912100			2.6	8
BOBTAIL 3	517910100			2.5	8
BOBTAIL 3	517910500			2.8	8
BOBTAIL 3	517910900			3	8
BOBTAIL 3	517911300			3	8
BOBTAIL 3	517911700			2.7	8
BOBTAIL 3	517912100			2.9	8
BOBTAIL 3	518910100			2.8	8
BOBTAIL 3	518910500			2	8
BOBTAIL 3	518910900			2.6	8
BOBTAIL 3	528911130			1.5	3
BOBTAIL 3	528911530			2.2	3
BOBTAIL 3	528911930			2.4	3
BOBTAIL 3	528912330			2.4	3
BOBTAIL 3	529910330			3.2	8
BOBTAIL 3	529910730			1.8	3
BOBTAIL 3	529911130			1.7	3
BOBTAIL 3	529911530			1.9	3
BOBTAIL 3	529911930			2	3
BOBTAIL 3	529912330			2.8	5
BOBTAIL 3	909911600			1.4	2
BOBTAIL 3	909912000			1.6	3
BOBTAIL 3	909912400			1.3	3
BOBTAIL 3	910910400			1.1	3
BOBTAIL 3	910910800			1.3	3
BOBTAIL 3	910911200			1	3
BOBTAIL 3	910911600			1.6	3

BOBTAIL 3 910912000 1.2 3 3 3 3 3 3 3 3 3	STATION	DATE/TIME STAGE	DISCHARGE PREV.CR.	TURBIDITY TSS	<u> </u>
BOBTAIL 3 91910400 2.2 3 BOBTAIL 3 911911200 1.8 3 BOBTAIL 3 911911200 1.3 3 BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 911912400 1.1 3 BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911000 2.8 6 BOBTAIL 3 1008911000 1.5 3 BOBTAIL 3 1008911000 1.5 3 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 100991400 1.5 3 BOBTAIL 3 100991400 1.5 3 <tr< td=""><td></td><td></td><td></td><td></td><td>_</td></tr<>					_
BOBTAIL 3 91910000 1.9 3 BOBTAIL 3 919111000 1.8 3 BOBTAIL 3 911911600 1.3 3 BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 91291000 1.2 3 BOBTAIL 3 91291100 1.2 3 BOBTAIL 3 912911000 1.2 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 100891100 2.8 6 BOBTAIL 3 100891100 1.5 3 BOBTAIL 3 100891100 1.5 3 BOBTAIL 3 100991000 1.5 3 BOBTAIL 3 100991000 1.5 3 BOBTAIL 3 100991000 1.5 3	BOBTAIL 3	910912400		1.7	
BOBTAIL 3 911911200 1.8 3 BOBTAIL 3 911911600 1.3 3 BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 911912400 1.1 3 BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.4 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 912912400 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911000 1.5 3 BOBTAIL 3 1008911000 1.5 3 BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 100991000 1.7 3 <t< td=""><td>BOBTAIL 3</td><td>911910400</td><td></td><td>2.2</td><td>3</td></t<>	BOBTAIL 3	911910400		2.2	3
BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 911912400 1 3 BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911600 1.4 3 BOBTAIL 3 912912400 1.2 3 BOBTAIL 3 912912400 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 100891200 1.5 3 BOBTAIL 3 100891200 1.5 3 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1009910800 1.7 3 BOBTAIL 3 100991000 1.7 3 <t< td=""><td>BOBTAIL 3</td><td>911910800</td><td></td><td>1.9</td><td>3</td></t<>	BOBTAIL 3	911910800		1.9	3
BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 911912400 1 3 BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.4 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1008912000 1.7 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 100991200 1.5 3 BOBTAIL 3 100991200 1.7 3 BOBTAIL 3 101091400 2 3	BOBTAIL 3	911911200		1.8	3
BOBTAIL 3 911912000 1.4 3 BOBTAIL 3 911912400 1 3 BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.4 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 100991000 1.5 3 BOBTAIL 3 100991000 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 100991200 1.7 3 BOBTAIL 3 100991200 1.7 3 BOBTAIL 3 10109100 1.5 3	BOBTAIL 3	911911600		1.3	3
BOBTAIL 3 911912400 1.1 3 BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911600 2.8 6 BOBTAIL 3 1008911600 1.5 3 BOBTAIL 3 1008911600 1.5 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911600 1.5 3 BOBTAIL 3 100991200 1.7 3 BOBTAIL 3 100991200 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910400 2 3 <tr< td=""><td>BOBTAIL 3</td><td>911912000</td><td></td><td>1.4</td><td></td></tr<>	BOBTAIL 3	911912000		1.4	
BOBTAIL 3 912910400 1.1 3 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911600 1.4 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912400 1.5 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911200 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 <td>BOBTAIL 3</td> <td>911912400</td> <td></td> <td>1</td> <td></td>	BOBTAIL 3	911912400		1	
BOBTAIL 3 912910800 2.7 5 BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912912000 1.4 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008911600 1.5 3 BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911600 2.3 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 101091200 1.5 3 <t< td=""><td>BOBTAIL 3</td><td>912910400</td><td></td><td>1.1</td><td></td></t<>	BOBTAIL 3	912910400		1.1	
BOBTAIL 3 912911200 1.2 3 BOBTAIL 3 912911600 1.4 3 BOBTAIL 3 912912400 1.2 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008911600 1.5 3 BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910400 1.5 3 BOBTAIL 3 1009911000 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010910800 1.5 3 BOBTAIL 3 1010910800 1.5 3 BOBTAIL 3 101091000 1.5 3	BOBTAIL 3	912910800		2.7	
BOBTAIL 3 912911600 1.4 3 BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912400 1.5 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1008912400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911600 2.3 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 10109110400 2 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 101091200 1.9 3	BOBTAIL 3	912911200		1.2	
BOBTAIL 3 912912000 1.2 3 BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1008912000 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 101091200 1.5 3 BOBTAIL 3 101091200 1.5 3 BOBTAIL 3 101091400 1.5 3	BOBTAIL 3	912911600		1.4	
BOBTAIL 3 912912400 1.4 3 BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010911800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 101091200 1.5 3 BOBTAIL 3 1011910400 4.6 29 </td <td>BOBTAIL 3</td> <td>912912000</td> <td></td> <td>1.2</td> <td></td>	BOBTAIL 3	912912000		1.2	
BOBTAIL 3 913910400 1.2 3 BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008912000 1.5 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910800 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 1.5 3 <td>BOBTAIL 3</td> <td>912912400</td> <td></td> <td>1.4</td> <td></td>	BOBTAIL 3	912912400		1.4	
BOBTAIL 3 1008911200 2.8 6 BOBTAIL 3 1008911600 1.5 3 BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912400 1.5 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 1.5 3	BOBTAIL 3	913910400		1.2	
BOBTAIL 3 1008912000 1.3 3 BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 100991200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 101091200 1.5 3 BOBTAIL 3 101091200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 101191200 1.7 3	BOBTAIL 3	1008911200		2.8	6
BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1011910400 1.9 3 BOBTAIL 3 1011910400 2 3 BOBTAIL 3 101191200 1.5 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 101191200 2 3 BOBTAIL 3 101191200 1.7 3	BOBTAIL 3	1008911600		1.5	3
BOBTAIL 3 1008912400 1.7 3 BOBTAIL 3 1009910400 2 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1011910400 1.9 3 BOBTAIL 3 1011910400 2 3 BOBTAIL 3 101191200 1.5 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 101191200 2 3 BOBTAIL 3 101191200 1.7 3	BOBTAIL 3	1008912000		1.3	
BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 101191200 1.5 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1011912400 1.7 3 </td <td>BOBTAIL 3</td> <td>1008912400</td> <td></td> <td>1.7</td> <td></td>	BOBTAIL 3	1008912400		1.7	
BOBTAIL 3 1009910800 1.5 3 BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 101191200 1.5 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 101191200 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1011912400 1.7 3 </td <td>BOBTAIL 3</td> <td>1009910400</td> <td></td> <td>2</td> <td>3</td>	BOBTAIL 3	1009910400		2	3
BOBTAIL 3 1009911200 1.5 3 BOBTAIL 3 1009911600 2.3 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1011912400 1.9 3 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011912000 1.7 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912000 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 415921500 1.1 2	BOBTAIL 3	1009910800			
BOBTAIL 3 1009911600 2.3 3 BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 <					
BOBTAIL 3 1009912000 1.7 3 BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911600 1.4 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3	BOBTAIL 3	1009911600		2.3	
BOBTAIL 3 1009912400 1.7 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010911600 1.4 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011911200 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911200 1.7 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 <td>BOBTAIL 3</td> <td>1009912000</td> <td></td> <td>1.7</td> <td></td>	BOBTAIL 3	1009912000		1.7	
BOBTAIL 3 1010910400 2 3 BOBTAIL 3 1010910800 2.6 3 BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011912400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011912000 1.7 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 41692100 1.7 14 BOBTAIL 3 41692100 1 2 BOBTAIL 3	BOBTAIL 3	1009912400		1.7	
BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911600 1.7 3 BOBTAIL 3 1011912400 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 41692100 1.7 14 BOBTAIL 3 416921900 1 2 BOBTAIL 3	BOBTAIL 3	1010910400		2	3
BOBTAIL 3 1010911200 1.5 3 BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911600 1.7 3 BOBTAIL 3 1011912400 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 41692100 1.7 14 BOBTAIL 3 416921900 1 2 BOBTAIL 3	BOBTAIL 3	1010910800		2.6	
BOBTAIL 3 1010912000 1.5 3 BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415922300 1.1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 416921500 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3	BOBTAIL 3	1010911200			
BOBTAIL 3 1010912400 1.9 3 BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911600 1.7 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921500 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 41692300	BOBTAIL 3	1010911600		1.4	3
BOBTAIL 3 1011910400 4.6 29 BOBTAIL 3 10119110800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 41692300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 41692	BOBTAIL 3	1010912000		1.5	
BOBTAIL 3 1011910800 2 3 BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2	BOBTAIL 3	1010912400		1.9	3
BOBTAIL 3 1011911200 1.5 3 BOBTAIL 3 1011911600 1.7 3 BOBTAIL 3 1011912400 2 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 41692300 1 2 BOBTAIL 3 41692	BOBTAIL 3	1011910400		4.6	29
BOBTAIL 3 1011911600 1.7 3 BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 41692300 1 2	BOBTAIL 3	1011910800		2	3
BOBTAIL 3 1011912000 2 3 BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1011911200		1.5	3
BOBTAIL 3 1011912400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1011911600		1.7	3
BOBTAIL 3 1012910400 1.7 3 BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1011912000		2	3
BOBTAIL 3 1012910800 2 3 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 41692100 6.3 36 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1011912400		1.7	3
BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1012910400		1.7	3
BOBTAIL 3 415921500 1.1 2 BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	1012910800		2	3
BOBTAIL 3 415921900 1.1 2 BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	415921500		1.1	2
BOBTAIL 3 415922300 1 2 BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	415921500		1.1	2
BOBTAIL 3 416920300 1 2 BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	415921900		1.1	2
BOBTAIL 3 416920700 6.3 36 BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	415922300		1	2
BOBTAIL 3 416921100 1.7 14 BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	416920300		1	2
BOBTAIL 3 416921500 1 2 BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	416920700		6.3	36
BOBTAIL 3 416921900 1 2 BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	416921100		1.7	14
BOBTAIL 3 416922300 1 2 BOBTAIL 3 417920300 1 2	BOBTAIL 3	416921500		1	2
BOBTAIL 3 417920300 1 2	BOBTAIL 3	416921900		1	
	BOBTAIL 3	416922300		1	2
BOBTAIL 3 417920700 1.4 2	BOBTAIL 3	417920300		1	2
	BOBTAIL 3	417920700		1.4	2

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	TSS
BOBTAIL 3	417921100			1	2
BOBTAIL 3	417921500			1.1	2
BOBTAIL 3	417921900			1.6	2
BOBTAIL 3	417922300			1.2	2
BOBTAIL 3	418920300			1.6	2
BOBTAIL 3	418920700			3.8	20
BOBTAIL 3	418921100			1.7	2
BOBTAIL 3	418921500			1.8	2
BOBTAIL 3	418921900			1.9	2
BOBTAIL 3	418922300			1.4	2
BOBTAIL 3	419920300			1.5	2
BOBTAIL 3	419920700			1.4	2
BOBTAIL 3	419921100			1	2
BOBTAIL 3	509941145			1.7	4
BOBTAIL 3	509941143			1.7	2.12
BOBTAIL 3	509941543			1.8	2.22
BOBTAIL 3	509941943			1.6	2.27
BOBTAIL 3	509942343			1.8	6.81
BOBTAIL 3	510940343			2.1	5.97
BOBTAIL 3	510940743			1.8	8.88
BOBTAIL 3	510941143			1.7	11.11
BOBTAIL 3	510941543			2	8.88
BOBTAIL 3	510941943			1.5	11.11
BOBTAIL 3	510942343			1.9	20
BOBTAIL 3	511940343			2	13.04
BOBTAIL 3	511940743			1.9	12.5
BOBTAIL 3	511941143			2	13.04
BOBTAIL 3	511941543			2.2	10.86
BOBTAIL 3	511941943			1.8	11.11
BOBTAIL 3	511942343			1.6	12.76
BOBTAIL 3	512940343			2	12.5
BOBTAIL 3	512940743			1.7	10
BOBTAIL 3	512941143			1.5	12
BOBTAIL 3	512941543			1.7	15.21
BOBTAIL 3	512941943			1.7	14
BOBTAIL 3	512942343			1.6	14.58
BOBTAIL 3	513940343			1.7	14.28
BOBTAIL 3	513940743			1.8	16
BOBTAIL 3	514941310			1.8	2.22
BOBTAIL 3	514941317			1.7	2.22
BOBTAIL 3	514942117			2.4	2.22
BOBTAIL 3	515940517			1.8	2.22
BOBTAIL 3	515941317			2.5	2
BOBTAIL 3	515942117			2	2
BOBTAIL 3	516940517			1.5	2.85
BOBTAIL 3	516941317			1.7	2
BOBTAIL 3	516942117			1.8	2
BOBTAIL 3	517940517			1.6	2
BOBTAIL 3	517941317			1.5	2
BOBTAIL 3	517942117			2.1	2
BOBTAIL 3	518940517			2	2

STATION	DATE/TIME STAGE	DISCHARGE PREV.CR.	TURBIDITY TSS	
BOBTAIL 3	518941317		1.5	2
BOBTAIL 3	518942117		1.8	2
BOBTAIL 3	519940517		1.5	2
BOBTAIL 3	519941317		1.8	2
BOBTAIL 3	519942117		2.2	2
BOBTAIL 3	520940517		2.3	2
BOBTAIL 3	520941317		2	2
BOBTAIL 3	520942117		2.3	2
BOBTAIL 3	521940517		1.8	2
BOBTAIL 3	521941317		2	2
BOBTAIL 3	521942117		2.5	2
BOBTAIL 3	522940517		2	2
BOBTAIL 3 DN	429921200		4.3	6
BOBTAIL 3 DN	429921600		1.9	2
BOBTAIL 3 DN	429922000		1.7	2
BOBTAIL 3 DN	430922400		2.1	2
BOBTAIL 3 DN	430920400		2	2
BOBTAIL 3 DN	430920800		1.8	2
BOBTAIL 3 DN	430921200		1.7	2
BOBTAIL 3 DN	430921600		1.6	2
BOBTAIL 3 DN	430922000		1.9	2
BOBTAIL 3 DN	501922400		2	2
BOBTAIL 3 DN	501920400		2	2
BOBTAIL 3 DN	501920800		2.4	2
BOBTAIL 3 DN	501921200		1.7	2
BOBTAIL 3 DN	501921600		1.9	2
BOBTAIL 3 DN	501922000		2.3	4
BOBTAIL 3 DN	502922400		1.7	2
BOBTAIL 3 DN	502920400		1.7	2
BOBTAIL 3 DN	502920800		2.3	2
BOBTAIL 3 DN	502921200		1.8	2
BOBTAIL 3 DN	502921600		0	0
BOBTAIL 3 DN	502922000		0	0
BOBTAIL 3 DN	503922400		0	0
BOBTAIL 3 DN	503920400		0	0
BOBTAIL 3 DN	503920800		0	0
BOBTAIL 3 DN	505922030		2	2
BOBTAIL 3 DN	506920430		1.9	2
BOBTAIL 3 DN	506921230		1.3	2
BOBTAIL 3 DN	506922030		2.5	6
BOBTAIL 3 DN	507920430		2.7	6
BOBTAIL 3 DN	507921230		13	124
BOBTAIL 3 DN	507922030		2.5	22
BOBTAIL 3 DN	508920430		2.1	6
BOBTAIL 3 DN	508921230		1.7	2
BOBTAIL 3 DN	508922030		1.9	2
BOBTAIL 3 DN	509920430		1.9	2
BOBTAIL 3 DN	509921230		2.7	6
BOBTAIL 3 DN	509922030		1.5	2
BOBTAIL 3 DN	510920430		3	6
BOBTAIL 3 DN	510921230		1.3	2
DOD THIL J DIN	310721230		1.J	4

STATION	DATE/TIME STAGE	DISCHARGE PREV.CR.	TURBIDITY TSS	<u>S</u>
BOBTAIL 3 DN	510922030		2.2	2
BOBTAIL 3 DN	511920430		2.4	2
BOBTAIL 3 DN	511921230		1.5	2
BOBTAIL 3 UP	429921130		2.2	2
BOBTAIL 3 UP	429921530		1.5	2
BOBTAIL 3 UP	429921930		1.2	2
BOBTAIL 3 UP	429922330		1.3	2
BOBTAIL 3 UP	430920330		1.1	2
BOBTAIL 3 UP	430920730		1	2
BOBTAIL 3 UP	430921130		1.3	2
BOBTAIL 3 UP	430921530		2	2
BOBTAIL 3 UP	430921930		1.3	2
BOBTAIL 3 UP	430922330		1.3	2
BOBTAIL 3 UP	501920330		1.5	2
BOBTAIL 3 UP	501920730		1.5	2
BOBTAIL 3 UP	501921130		1.4	2
BOBTAIL 3 UP	501921530		1.5	2
BOBTAIL 3 UP	501921930		1.3	2
BOBTAIL 3 UP	501922330		1	2
BOBTAIL 3 UP	502920330		6.9	8
BOBTAIL 3 UP	502920730		1.4	2
BOBTAIL 3 UP	502921130		2	2
BOBTAIL 3 UP	502921530		3	2
BOBTAIL 3 UP	502921930		1.8	2
BOBTAIL 3 UP	502922300		1	2
BOBTAIL 3 UP	503920330		0	0
BOBTAIL 3 UP	503920730		0	0
BOBTAIL 4	420931140		1.4	2
BOBTAIL 4	423931230		5.3	6
BOBTAIL 4	423931630		4.4	4
BOBTAIL 4	423932030		3.3	2
BOBTAIL 4	424930030		3.2	2
BOBTAIL 4	424930430		3	2
BOBTAIL 4	424930830		3.7	2
BOBTAIL 4	424931230		3.7	2
BOBTAIL 4	424931630		3.7	2
BOBTAIL 4	424932030		4.6	6
BOBTAIL 4	425930030		3.9	4
BOBTAIL 4	425930430		3.7	2
BOBTAIL 4	425930830		3.4	2
BOBTAIL 4	503931445		2.3	2.9
BOBTAIL 4	503931845		2.7	2.9
BOBTAIL 4	503932245		3	2.9
BOBTAIL 4	504930245		2.7	2.9
BOBTAIL 4	504930645		2.6	2.9
BOBTAIL 4	504931045		2.7	2.9
BOBTAIL 4	504931445		2.5	2.9
BOBTAIL 4	504931845		2.3	2.9
BOBTAIL 4	504932245		2.7	2.9
BOBTAIL 4	505930245		1.9	2.9
BOBTAIL 4	505930645		3	2.9

STATION	DATE/TIME STAGE	DISCHARGE	PREV.CR.	TURBIDITY	TSS
BOBTAIL 4	505931045			2.2	2.9
BOBTAIL 4	505931445			2.3	2.9
BOBTAIL 4	505931845			4.1	2.9
BOBTAIL 4	505932245			2.3	2.9
BOBTAIL 4	506930245			2.4	2.9
BOBTAIL 4	506930645			2.4	2.9
BOBTAIL 4	506931045			2.3	2.9
BOBTAIL 4	506931445			2.3	2.9
BOBTAIL 4	506931845			2.4	2.9
BOBTAIL 4	506932245			2	2.9
BOBTAIL 4	507930245			2.2	2.9
BOBTAIL 4	507930645			2.3	2.9
BOBTAIL 4	507931045			2.3	2.9
BOBTAIL 4	507931445			2.6	2.9
BOBTAIL 4	507931845			2.3	2.9
BOBTAIL 4	507932245			2.3	2.9
BOBTAIL 4	508930245			2.3	2.9

<u>ıta</u>

REMARKS ISCO **ISCO** ISCO **ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO** ISCO

ISCO

ISCO

ISCO

ISCO

ISCO,SILT

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO, ORGNICS

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

REMARKS ISCO ISCO **ISCO ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO** ISCO ISCO, ORGNICS **ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO** ISCO ISCO **ISCO** ISCO, ORGNICS ISCO **ISCO ISCO ISCO ISCO ISCO ISCO**

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO,SAND,SILT

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO **ISCO**

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

DH-48

DH-48

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO **ISCO**

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

REMARKS ISCO ISCO **ISCO ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO** ISCO SILTS, ORGANIC THRU SAMPLING **ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO** ISCO **ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO ISCO**

ISCO ISCO

ISCO

SILT, SAND

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO,SILT

ISCO,SILT

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

GRAB,MT FWP

ISCO,SILTS

ISCO,SILTS

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

REMARKS ISCO **ISCO ISCO ISCO ISCO ISCO ISCO** ISCO,SILT,SAND ISCO,SILT,SAND ISCO **ISCO ISCO ISCO** ANIMAL PARTS SEEDS, **INTESTINES ISCO ISCO INTESTINES ISCO ISCO ISCO ISCO ISCO** ISCO,SILTS ISCO,SILTS ISCO **ISCO** ISCO,SEEDS ISCO,NEEDLES DH-48 ISCO, SILTS ISCO, SILTS ISCO, SILTS ISCO, SILTS ISCO, SILTS

ISCO, SILTS ISCO, SILTS ISCO, SILTS

- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
- ISCO, SILTS
 - **ISCO**
 - **ISCO ISCO**
 - **ISCO**
 - ISCO

 - **ISCO**
 - **ISCO ISCO**
 - **ISCO**
 - **ISCO**
 - **ISCO**
 - **ISCO**

 - **ISCO**
 - **ISCO**
 - **ISCO ISCO**
 - **ISCO**
 - **ISCO**
 - 0
 - **ISCO**
 - **ISCO**
 - **ISCO**

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

DH-48

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

1000

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

1500

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

1500

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO,NEEDLES

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO,SILT,ORG.

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

DH-48

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

REMARKS ISCO **ISCO ISCO ISCO** ISCO **ISCO**

ISCO ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO MISSING

ISCO MISSING

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO ISCO

ISCO

ISCO

ISCO

ISCO

ISCO

APPENDIX D SEVERITY OF ILL EFFECTS ANALYSIS

The impact of total suspended solids (TSS) on fish and aquatic life is related to the concentration of TSS, the duration of the TSS episode, and the life history stage of the organism. These relationships have been used to develop models to predict the severity of ill effects (SEV) on different life history stages (Newcombe and Jenson, 1996). The SEV varies from behavioral effects such as avoidance to lethal effects (Table D-1).

Selected models were applied to observed levels of TSS to determine the potential negative effects on aquatic life. Because fish are more vulnerable at different periods of their life cycle, we have proposed applying different models at different times of the year depending on the presence of vulnerable life history stages (Table D-2). Of the four models available, models 1 and 4 were chosen because they address a range of life history stages of salmonids (eggs, larvae, juvenile, and adult) and were developed for a relatively wide range of particle sizes. Since timing of spawning for resident westslope cutthroat trout has not been investigated in the Bobtail Creek watershed. Data from rainbow trout investigations were substituted to determine the period for model 4. Trapping studies conducted by Montana Fish, Wildlife & Parks indicate that adfluvial rainbow trout migrate into Bobtail Creek from March through May (Mike Hensler, MFWP, personal communication). Allowing for emergence, model 2 should be applied from March through June (Bell, 1986). Model 1 is appropriate for the rest of the year.

Using these models, SEV was calculated for ranges of TSS observed on Bobtail Creek at hypothetical durations of exposure. Based on curves developed using Model 1, TSS concentrations are unlikely to reach levels that lead to para-lethal or lethal stress in adult or juvenile salmonids (Figure D-1). Even the maximum concentration from the Bobtail 1 data set (573 mg/L) must be maintained for eight days to result in an SEV of 9 or greater, an unlikely scenario. In contrast, SEV calculated for eggs and larvae for these concentrations indicate unacceptable levels of stress within a few days for even the lowest concentrations of TSS (Figure D-2). The minimum concentration of 2 mg/L and the 25th percentile of 5 mg/L need to be maintained for only four days to reach a SEV of 9. Daily monitoring of TSS near the mouth of Bobtail Creek indicates that this is a likely scenario, even in drought years. TSS exceeded 5 mg/L and ranged as high as 14.6 mg/L for up to 18 days. Furthermore, the average TSS concentration occurring during spawning and incubation was greater than 11 mg/L. This concentration can lead to para-lethal to lethal stress for eggs and larvae in only 3 days of exposure.

Note, however, that SEV curves for hypothetical durations of TSS for the reference streams show that the lower concentrations can result in para-lethal stress to eggs and larvae within as little as five days of exposure. Because timing of spawning and incubation for spring spawning species such as rainbow trout and westslope cutthroat trout naturally coincide with higher flows during spring run off, it is probable that a certain degree of para-lethal to lethal stress to eggs and larvae is unavoidable. Still, the overall higher concentrations measured on Bobtail Creek warrant concern for these vulnerable life history stages.

The potential for TSS to impact early life history stages is further underscored by comparisons of TSS concentration among months and among Bobtail data sets and reference sites. Most of the higher values occurred from March to June, when eggs and larvae are within redds. Bobtail Creek samples demonstrated considerably higher concentrations of TSS than the reference streams combined.

It has been pointed out (Plum Creek, 2004; Appendix F) that the model for eggs and larvae (model 4) has some problems with direct applicability to the fish that inhabit Bobtail Creek. The problems include: eggs not being directly exposed to abrasion associated with total suspended solids; upwelling water in the redds may be free of sediments that could entomb eggs and larvae; the model does not consider the porosity or permiablity of the gravel redds; and the lack of distinction between effects from deposited versus suspended sediments in the research. These problems increase the variability in severity of ill effects on eggs and larvae, but do not invalidate the observed effects on these life stages.

Table D-1. Scale of Severity of Ill Effects on Fish (SEV) Associated with Suspended Solids (Newcombe and Jenson, 1996).


SEV	Description of effects on fish
	Nil effect
0	No behavioral effects
	Behavioral Effects
1	Alarm reaction
2	Abandonment of cover
3	Avoidance response
	Sublethal Effects
4	Short-term reduction in feeding rates
5	Minor physiological stress; increase coughing rate; increased respiration rate
6	Moderate physiological stress
7	Moderate habitat degradation; impaired homing
8	Indications of major physiological stress; long term reduction in feeding rate;
	long-term reduction in feeding success; poor condition
	Lethal and para-lethal effects
9	Reduced growth rate; delayed hatching
10	0-20% mortality; increased predation; moderate to severe habitat degradation
11	> 20-40% mortality
12	>40-60% mortality
13	>60-80% mortality
14	> 80-100% mortality

January, 2005

Table D-2. Models Developed to Predict SEV for Different Life History States and Particles Sizes (Newcombe and Jenson, 1996).

(.	· · · · · · · · · · · · · · · · · · ·	
Model	Life History Stages and	Model
	Particle Sizes	
1	Juvenile and adult	$SEV = 1.064 + 0.6068 \times LN(D) + 0.7384 \times LN(C)1$
	salmonids; particle sizes	
	0.5-250 μm	
2	Adult salmonids; particle	$SEV = 1.6814 + 0.4769 \times LN(D) + 0.7565 \times LN(C)$
	sizes 0.5-250 µm	
3	Juvenile salmonids:	$SEV = 0.7262 + 0.7034 \times LN(D) + 0.7144 \times LN(C)$
	particle sizes 0.5-75 µm	
4	Eggs and larvae of	$SEV = 3.7456+1.0946 \times LN(D)+0.3117 \times LN(C)$
	salmonids and non-	
	salmonids	


Figure D-1. Calculated SEV for Concentrations of TSS Sampled on Bobtail Creek for Hypothetical Durations Using Model 1 (Adults and Juvenile Salmonids).



1 D= duration of exposure in hours, C = concentration of TSS (mg/L)

Figure D-2. Calculated SEV for Concentrations of TSS Measured on Bobtail Creek for Hypothetical Durations of Exposure Using Model 4 (Eggs and Larvae).

Model 4: Eggs and larvae of salmonids and non-salmonids; Particle sizes 0.5-75 μm



APPENDIX E

Bobtail Creek Road Sediment Delivery Analysis Brian Sugden and Mitch Richeal May 2000

Sediment delivery from forest roads on Plum Creek ownership in the Bobtail Creek watershed was collected in May 2000 following protocol outlined in the *Standard Methodology for Conducting Watershed Analysis* (Washington Forest Practices Board, 1997). The assessment was completed by Plum Creek's hydrologist (Brian Sugden) and local forester (Mitch Richeal).

This analysis involved a field assessment of all stream-adjacent forest road segments in the watershed and followed the methodology outlined by Washington Forest Practices Board (1997). Stream adjacent road segments are typically locations where roads either cross or parallel streams.

During the field assessment, data were collected on a variety of variables that affect road erosion and sediment delivery processes, including:

- Inherent soil erodibility (a function of geologic parent material)
- Traffic rates (heavy, moderate, or low traffic)
- Surfacing materials (native surfacing, heavy gravel, light gravel)
- Road dimensions (e.g., tread width/length, cutslope lengths, fillslope lengths)
- Drainage design (e.g., amount of road draining to streams)
- Vegetative cover (e.g., cutslope and fillslope vegetation)

The standard methodology calls for sampling selected road segments and extrapolating the results to the entire road system in the watershed. However, for the Bobtail Creek watershed, road erosion was evaluated at every potential delivery site on Plum Creek property as determined by examination of topographic maps and field site inspections. This improvement over standard procedures was important because for purposes of watershed plan development, Plum Creek wanted to be able to directly identify the location and relative importance of all sites that deliver sediment to streams (i.e., a census). The intent of this effort was to conduct field site inspections at 100% of potential sediment delivery locations in the watershed.

In a deviation from the standard methodology, the traffic factor was adjusted to account for seasonal snow cover on the road tread based on discussions with foresters familiar with the study area. In the Bobtail Creek watershed, snow cover was assumed for three and a half months each year.

Base erosion rates were assumed to be 20 tons/acre of road per year for glacial tills and 10 tons/ac/yr for metasedimentary rocks.

Results

A total of 21 locations on Plum Creek property were identified and included in the Road Sediment Delivery Analysis (RSDA). These 21 sites were estimated to contribute a total of 17.3 tons per year to the Bobtail stream network on a land area of 2240 acres (3.5 square miles).

Natural background erosion in these landtypes is approximately 12 tons per square mile per year (Sirucek et al., 1991). So in Plum Creek's 3.5 square mile analysis area, natural loading is estimated to be about 42 tons. Therefore, the contribution from forest roads is estimated to be about 40 percent in excess of background.

Discussion

This analysis assumed that the base erosion rate of forest roads in the Bobtail Creek watershed was 20 tons per acre per year. However, recent road erosion plot data by Plum Creek indicates that actual road erosion rates measured in glacial till soils are less than 1 ton/ac/yr. If the base erosion rates were adjusted to closer to the actual value, the contribution from roads as a percentage of background would be less than 5%.

References

Sirucek, D., L. Kuennen, S. Barndt, K. Lamotte, B. Putnam, V. Ciliberti, and J. Collins. 1991. Process documentation, landtype correlation factors and sediment curves for R1-Watsed model, western Montana zone.

Washington Forest Practices Board. 1997. Standard methodology for conducting watershed analysis. Version 4.0. Washington State Department of Natural Resources, Olympia, Washington.

January, 2005

read Tread h (ft) Width (000 14 15 15 13 10 14 10 15 10 15 10 15 15 15 15 15 15 15 15 15 15 15 15 15	(ft) Tread 0.51 0.22 0.10 0.08 0.08 0.07	d Grade (% 7	Base Ero. Rate (t/ac/yr) 20 20 20 20 20 20 20	Gravel Factor 1.0 1.0 1.0 1.0 1.0 1.0	Traffic Factor 0.7 0.7 0.7 0.7 0.7 0.7	Cover % 20 20 0 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Cover Factor 0.66 0.66 1.00 0.82 1.00	% Delivery 0.5 1.0 1.0 1.0 0.5	Tread Delivery (tons/yr) 2.4 2.0 1.4 0.9 0.5	Contrib. Cutslope Length (ft) 1400 725 250 120	Average Cutslope Width (ft) 10 3 6	Acres Cutslope 0.32 0.05 0.03	Base Ero. Rate (t/ac/yr) 20 20 20 20 20	Cover % 50 70 80 25	Cover Factor 0.29 0.15 0.10 0.58	% Delivery 0.5 1.0 1.0	Cutslope Delivery (tons/yr) 0.9 0.1 0.1 0.3	Contrib. Fillslope Length (ft) 15 30	Average Fillslope Width (ft) 8 8 10	Acres Fillslope 0.000 0.003 0.006	Base Ero. Rate (t/ac/yr) 20 20 20 20	Cover % 80 50	Cover Factor 1.00 0.10 0.29	% Delivery 1.0 1.0 0.5	Fillslope Delivery (tons/yr) 0.0 0.0 0.0 0.0	TOTAL Total (tons/yr) 3.3 2.1 1.5	COMMENTS Major gully erosion, no culverts in draw. Priorty BMP problem area Check PC access on this road. Lock gate at Harper property line? This stream was debris-flowed in 1994 - initiation point on FS road at top of stream. The current 24 inch pipe at this location needs to be increased to a 36 inc pipe. Inlet headwall needs heavy rip-rap installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct deliver over fill at present
h (ft) Width (coo 14 15 13 13 10 14 14 10 15 15 15 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	(ft) Tread 0.51 0.22 0.10 0.08 0.08 0.07	d Grade (% 7	20 20 20 20 20	1.0 1.0 1.0 1.0 1.0	0.7 0.7 0.7 0.7 0.7	% 20 20 0	0.66 0.66 1.00 0.82	0.5 1.0 1.0 1.0	(tons/yr) 2.4 2.0 1.4 0.9	Length (ft) 1400 725 250 120	Width (ft) 10 3 6	Cutslope 0.32 0.05 0.03 0.02	20 20 20 20	% 50 70 80	0.29 0.15 0.10 0.58	0.5	(tons/yr) 0.9 0.1 0.1 0.3	15 30	Width (ft)	0.000 0.003 0.006	(t/ac/yr) 20 20 20	% 80 50	Factor 1.00 0.10 0.29	1.0 1.0	(tons/yr) 0.0 0.0 0.0	(tons/yr) 3.3 2.1 1.5	Major gully erosion, no culverts in draw Priorty BMP problem area Check PC access on this road. Lock gat at Harper property line? This stream was debris-flowed in 1994 initiation point on FS road at top of stream. The current 24 inch pipe at this location needs to be increased to a 36 in pipe. Inlet headwall needs heavy rip-raj installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct delive
000 14 15 13 100 15 100 14 100 14 100 15	0.51 0.22 0.10 0.08 0.08	7 7 2 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	20 20 20 20 20 20	1.0	0.7 0.7 0.7 0.7	20 20 0	0.66 0.66 1.00 0.82	0.5 1.0 1.0 1.0	2.4 2.0 1.4	1400 725 250	10 3 6	0.32 0.05 0.03	20 20 20 20	50 70 80	0.29 0.15 0.10	0.5	0.9	15 30	8	0.000 0.003 0.006	20 20 20	80	1.00 0.10 0.29	1.0	0.0	3.3	Major gully erosion, no culverts in draw Priorty BMP problem area Check PC access on this road. Lock gat at Harper property line? This stream was debris-flowed in 1994 initiation point on FS road at top of stream. The current 24 inch pipe at this location needs to be increased to a 36 in pipe. Inlet headwall needs heavy rip-raj installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct delive
13 13 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	0.22 0.10 0.08 0.08	2. 6 0 6 3 4 7 8	20 20 20 20 20	1.0	0.7 0.7 0.7 0.7	20 0 10 0	0.66 1.00 0.82	1.0	2.0	725 250 120	3 6	0.05	20 20 20	70 80	0.15	1.0	0.1	30	8 8	0.003	20 20	50	0.10	1.0	0.0	2.1	Priorty BMP problem area Check PC access on this road. Lock gat at Harper property line? This stream was debris-flowed in 1994 - initiation point on FS road at top of stream. The current 24 inch pipe at this location needs to be increased to a 36 in pipe. Inlet headwall needs heavy rip-rap installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct deliver
00 15 00 14 00 14 00 15	0.10 0.08 0.08 0.07	6 6 8 4 7 8	20 20 20	1.0	0.7	10	0.82	1.0	0.9	250	8	0.03	20	80	0.10	1.0	0.1	30	8 8	0.006	20	50	0.29	1.0	0.0	1.5	at Harper property line? This stream was debris-flowed in 1994 initiation point on FS road at top of stream. The current 24 inch pipe at this location needs to be increased to a 36 ir pipe. Inlet headwall needs heavy rip-ra installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct delivered.
0 14 0 14 0 15	0.08 0.08 0.07	3 6 3 4 7 8	20	1.0	0.7	10	0.82	0.5	0.9	120	8	0.02	20	25	0.58	1.0	0.3		10								initiation point on FS road at top of stream. The current 24 inch pipe at thi location needs to be increased to a 36 i pipe. Inlet headwall needs heavy rip-ra installed. Dip needs to be constructed closer to crossing Not much to do at this crossing except SFW the fill - some sign of direct deliv
0 15	0.08	8 4	20	1.0	0.7	0	1.00	0.5										30	10	0.007	20	75	0.12	0.5	0.0	1.1	SFW the fill - some sign of direct deliver
0 15	0.07	7 8							0.5	180	12	0.05	20	25	0.58	1.0	1 06						1 '	1 '	1	1	
			20	1.0	0.7	0	1.00			1 1	ĺ		1			1.0	0.6	30	12	0.008	10	90	0.08	1.0	0.0	1.1	Coarse rock on fillslope provides significant filtration benefits
00 15	0.07		1		, !		1.00	1.0	1.0	100	10	0.02	20	70	0.15	1.0	0.1			0.000	20		1.00		0.0	1.1	Ditch relief pipe catch basin needs to be cleaned out.
	0.07	5	20	1.0	0.7	0	1.00	1.0	1.0	100	6	0.01	20	50	0.29	1.0	0.1			0.000	20		1.00		0.0	1.0	Ford of Bobtail Creek. Talk to adjacent landowner about bridge.
00 16	0.11	. 4	20	1.0	0.7	20	0.66	0.5	0.5	200	12	0.06	20	20	0.66	0.5	0.4	50	15	0.017	20	80	0.10	1.0	0.0	0.9	Not much of a stream
15	0.08	6	10	1.0	0.7	0	1.00	1.0	0.6	180	10	0.04	20	50	0.29	1.0	0.2			0.000	20		1.00		0.0	0.8	Add dip on far side of stream. Clean or catch basin at relief pipe inlet
30 15			20	1.0	0.7	30	0.51	1.0	0.4	150	10	0.03	20	40	0.39	1.0	0.3	40	12	0.011	20	75	0.12	1.0	0.0	0.7	Signs of old erosion gullies on fill.
50 15			20	1.0	0.7	50	0.29	0.5	0.3	350	15	0.12	20	50	0.29	0.5	0.3	40	12	0.011	20	70	0.15	1.0	0.0	0.7	
.0 15			20	1.0	0.7	0	1.00	1.0	0.5	90	6	0.01	20	80	0.10	1.0	0.0	30	8	0.006	20	90	0.08	1.0	0.0	0.6	
00 15	0.19		20	1.0	0.7	50 30	0.29	0.5 1.0	0.4	450 200	6	0.08	20	70 80	0.15 0.10	0.5	0.1	20	8	0.007	20 20	75 90	0.12 0.08	1.0	0.0	0.5	Log in pipe outlet. Clean out. Need to double check these measurements some time.
30 16	0.07	4	20	1.0	0.7	20	0.66	0.5	0.3	120	10	0.03	20	40	0.39	0.5	0.1	50	8	0.009	20	80	0.10	1.0	0.0	0.4	some time.
				1.0	0.7		0.66	0.5	0.3		5	0.03	20	80		0.5	0.0		8	0.003		90	0.08	1.0	0.0	0.4	+
20 14			20	1.0	0.7	80	0.10	0.5	0.1	220	10	0.05	20	70	0.15	0.8	0.1	15	8	0.003	20	90	0.08	1.0	0.0	0.2	+
20 13	0.04	3	20	1.0	0.7	90	0.08	0.5	0.0	120	10	0.03	20	90	0.08	1.0	0.0	15	8	0.003	20	90	0.08	1.0	0.0	0.1	
0 12			20	1.0	0.7	90	0.08	1.0	0.0	60	3	0.00	20	70	0.15	1.0	0.0	20	8	0.004	20	90	0.08	1.0	0.0	0.0	
0 13	0.01	. 2	20	1.0	0.7	80	0.10	1.0	0.0	50	8	0.01	20	90	0.08	1.0	0.0	20	10	0.005	20	90	0.08	1.0	0.0	0.0	
13	0.07	5	20	1.0	0.7	80	0.10	0.2	0.0	240	6	0.03	20	90	0.08	0.2	0.0	15	8	0.003	20	90	0.08	1.0	0.0	0.0	Most runoff passes over the stream crossing. Need dip however to reduce r
				-					12.2								2.0	+							0.2	17.2	
0 20 20 0 0	13 14 13 12 13	13 0.07 14 0.07 13 0.04 12 0.02 13 0.01	13 0.07 4 14 0.07 6 13 0.04 3 12 0.02 4 13 0.01 2	13 0.07 4 20 14 0.07 6 20 13 0.04 3 20 12 0.02 4 20 13 0.01 2 20	13 0.07 4 20 1.0 14 0.07 6 20 1.0 13 0.04 3 20 1.0 12 0.02 4 20 1.0 13 0.01 2 20 1.0	13 0.07 4 20 1.0 0.7 14 0.07 6 20 1.0 0.7 13 0.04 3 20 1.0 0.7 12 0.02 4 20 1.0 0.7 13 0.01 2 20 1.0 0.7	13 0.07 4 20 1.0 0.7 20 14 0.07 6 20 1.0 0.7 80 13 0.04 3 20 1.0 0.7 90 12 0.02 4 20 1.0 0.7 90 13 0.01 2 20 1.0 0.7 80	13 0.07 4 20 1.0 0.7 20 0.66 14 0.07 6 20 1.0 0.7 80 0.10 13 0.04 3 20 1.0 0.7 90 0.08 12 0.02 4 20 1.0 0.7 90 0.08 13 0.01 2 20 1.0 0.7 80 0.10	13 0.07 4 20 1.0 0.7 20 0.66 0.5 14 0.07 6 20 1.0 0.7 80 0.10 0.5 13 0.04 3 20 1.0 0.7 90 0.08 0.5 12 0.02 4 20 1.0 0.7 90 0.08 1.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 13 0.07 5 20 1.0 0.7 80 0.10 0.2 0.0 240	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 13 0.07 5 20 1.0 0.7 80 0.10 1.0 0.0 240 6	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 13 0.07 5 20 1.0 0.7 80 0.10 0.2 0.0 240 6 0.03	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 13 0.07 5 20 1.0 0.7 80 0.10 0.2 0.0 240 6 0.03 20	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 13 0.07 5 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 13 0.07 5 20 1.0 0.7 80 0.10 0.2 0.0 240 6 0.03 20 </td <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 13 0.07 5 20 1.0 0.7 80 0.10 0.2</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 120 10 0.03 20 90 0.08 1.0 0.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 0.0 13 0.07 5</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 0.0 20 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 0.0 15</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 12 0.02 4 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 15 8 0.003 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 <td< td=""><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 0.0 20 8 0.004 20 13 0.01 2 20 1.0 0.7 80<</td><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 3 0.0 15 8 0.003 20 90 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 13 0.01 2 20</td></td<><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 20 90 0.08 1.0 0.0 90 0.08 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 50 8 0.01 20 70 0.15 1.0 0.0 20 8 0.004 20 90 0.08</td><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 <</td><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 11 15 8 0.003 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 15</td><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 0.4 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 0.2 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 90 0.08 1.0 0.0 90 0.08 1.0 0.0 1.0 0.0 0.0 1.0 0.0 1.0 0.0 0.0 1.0 0.0 0.0 0.0 1.0 0.0 0.0 0.0</td></td>	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 13 0.07 5 20 1.0 0.7 80 0.10 0.2	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 120 10 0.03 20 90 0.08 1.0 0.0 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 0.0 13 0.07 5	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 0.0 20 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90 0.08 1.0 0.0 15	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 12 0.02 4 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 20 90	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 15 8 0.003 13 0.01 2 20 1.0 0.7 80 0.10 1.0 0.0 50 8 0.01 <td< td=""><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 0.0 20 8 0.004 20 13 0.01 2 20 1.0 0.7 80<</td><td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 3 0.0 15 8 0.003 20 90 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 13 0.01 2 20</td></td<> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 20 90 0.08 1.0 0.0 90 0.08 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 50 8 0.01 20 70 0.15 1.0 0.0 20 8 0.004 20 90 0.08</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 <</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 11 15 8 0.003 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 15</td> <td>13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 0.4 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 0.2 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 90 0.08 1.0 0.0 90 0.08 1.0 0.0 1.0 0.0 0.0 1.0 0.0 1.0 0.0 0.0 1.0 0.0 0.0 0.0 1.0 0.0 0.0 0.0</td>	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 60 3 0.00 20 70 0.15 1.0 0.0 20 8 0.004 20 13 0.01 2 20 1.0 0.7 80<	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 3 0.0 15 8 0.003 20 90 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 13 0.01 2 20	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 20 90 0.08 1.0 0.0 90 0.08 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 50 8 0.01 20 70 0.15 1.0 0.0 20 8 0.004 20 90 0.08	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 12 0.02 4 20 1.0 0.7 90 0.08 1.0 0.0 20 70 0.15 1.0 0.0 20 8 0.004 20 90 <	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 11 15 8 0.003 20 90 0.08 1.0 0.0 15 8 0.003 20 90 0.08 1.0 0.0 15	13 0.07 4 20 1.0 0.7 20 0.66 0.5 0.3 240 5 0.03 20 80 0.10 0.5 0.0 15 8 0.003 20 90 0.08 1.0 0.0 0.4 14 0.07 6 20 1.0 0.7 80 0.10 0.5 0.1 220 10 0.05 20 70 0.15 0.8 0.1 15 8 0.003 20 90 0.08 1.0 0.0 0.2 13 0.04 3 20 1.0 0.7 90 0.08 0.5 0.0 120 10 0.03 20 90 0.08 1.0 0.0 90 0.08 1.0 0.0 90 0.08 1.0 0.0 1.0 0.0 0.0 1.0 0.0 1.0 0.0 0.0 1.0 0.0 0.0 0.0 1.0 0.0 0.0 0.0

APPENDIX F RESPONSES TO PUBLIC COMMENTS

As described in Section 8.0, the formal public comment period for the Water Quality Restoration Plan and Total Maximum Daily Loads (TMDL) for the Bobtail Creek Watershed extended from November 29 to December 27, 2004. Two sets of submitted formal written comments were received by MDEQ. The comments are listed below. Responses prepared by MDEQ follow each of the individual comments. The original comment letters are located in the project files at MDEQ and may be reviewed upon request.

<u>Comment 1:</u> Page 15 -section 2.8.2. The USFS used the ECA model to estimate the percent increase in the peak flow month in Bobtail Creek, not the average annual water yield.

Response: The comment is noted and the text has been changed to reflect this comment.

<u>Comment 2:</u> Page 16 -section 2.8.2. Once again it is the peak flow month increase not the average annual water yield. Also there is no "target" in the 1987 KNF Forest Plan that limits basins to "no greater than 8%" water yield increases.

Response: The comment is noted and the paragraph has been revised to reflect this comment.

<u>Comment 3:</u> Page 19 -section 2.9.2. Libby District would like to have the matrix you use in a spreadsheet so we can run our other macroinvertebrate data through the screen.

Response: The Montana Department of Environmental Quality's macroinvertebrate standard operating procedures, which includes the method for macroinvertebrate analysis, was sent to Steve Wegner, Libby Ranger District Hydrologist on December 13, 2004. It is available on MDEQ's internet site at:

http://www.deq.state.mt.us/wqinfo/monitoring/SOP/pdf/12-1-3.pdf

Comment 4: Page 31 -section 3.3.1. Concerning the McNeil Core sample target- Is the referenced 28 percent target the average, median or the 75th percentile value for substrate fines less than 6.35mm? I realize that getting to this "reference" level for substrate fines would be great for the system but is it reachable considering that Bobtail Creek is a managed watershed with the majority of mainstem landownership in small private blocks? I would think that the target should be set knowing that there is a huge possibility that we will never see a level of substrate fines that resembles the unmanaged streams used as a reference.

Response: The text on page 31 has been changed to clarify the target value of 28 percent. The value of 28 percent comes the 75th percentile in reference drainages.

MDEQ realizes that pre-settlement water quality conditions usually are not attainable. MDEQ is not setting targets to achieve unmanaged conditions, but conditions that support Montana's water quality standards. For sediment that standard is "No increases are allowed above naturally occurring concentrations of sediment or suspended solids...

which render the waters harmful, detrimental, or injurious ... to fish or other wildlife."(ARM 17.30.260-629). "Naturally occurring" refers to conditions or materials present over which man has no control, or from developed land where all reasonable land, soil and water conservation practices have been applied. BMPs do not equate to all reasonable land, soil, and water practices until such time it is demonstrated that they can achieve water quality standards. MDEQ uses reference conditions to determine if water quality standards are being met. Reference conditions are not necessarily pristine, but attempts to define the potential condition that could be attained (given historical land use) by the application of reasonable land soil, and water conservation practices.

Additionally, MDEQ acknowledges the need to verify the appropriateness of the selected targets. Section 3.3 describes the approach for determining if the beneficial uses are being supported and the State's standards are being met. This includes an evaluation of the selected targets, in addition to analysis of circumstances surrounding the exceedance of targets (including the use of the supplemental indicators), if targets are exceeded. In Sections 7.6 - 7.9, recommendations are made to address questions regarding uncertainly associated with the selection of targets.

<u>Comment 5:</u> Page 31 -section 3.3.2. It is hard to tell from the description exactly how the supplemental indicators will affect the measurement of success. For example, what happens if one of the supplemental indicators does not meet its target, what would that trigger?

Response: Supplemental indicators will not be used directly as water quality targets to measure the success of this Water Quality Restoration Plan, but may be used if targets are not met, in examining the circumstances surrounding non-attainment of the targets. These, and/or other potentially more appropriate, supplemental indicators could be useful in determining the underlying causes and sources preventing attainment of the targets. Additional language has been added in Section 3.3 and 3.3.2 to clarify the use of supplemental indicators.

Comment 6: Page 33 -section 3.3.2. It seems that all the TSS data in Bobtail (1,131 samples) is being used to set an unreasonably low TSS target value. Based on 186 samples from the 12 reference streams (an average of only 16 samples per stream) it seems unrealistic to pick an average value target of 5.7 mg/L TSS for Bobtail Creek. How can you make a "managed" watershed meet the outputs from a "least managed or "natural" watershed? Especially since you acknowledge that timber management will continue on private timberlands. I would think there should be more of a range per year with the target value dropping as time goes by and restoration efforts have the time to take hold and reduce sediment.

Response: Our use of the weight of evidence approach as described in Section 3.3 of the document is predictated upon the fact that there is no single parameter that can be applied alone to provide a direct measure of beneficial use impairments associated with sediment. The TSS supplemental indicator was selected specifically to provide one measure of potential sediment impairment associated with the cold-water fisheries beneficial use. The information provided by this parameter was then used in combination with the

information provided by all of the other targets and supplemental indicators to reach conclusions about water quality impairment.

In the upcoming years, the adaptive management strategy (Section 7.8) allows for flexibility in the targets based on monitoring efforts.

TSS is identified as a supplemental indicator, not a target. If the targets for width-to-depth ratios, pool frequency, riffle stability index, Wolman pebble counts, and McNeil Core fine sediments are met in Bobtail Creek, TSS, bank stability, and macroinvertebrate indices will not need to be considered. The supplemental indicators are to be used only if the targets are not met.

The watersheds selected as reference were "least impacted" watersheds. Targets need to represent attainment of standards, including "no increases above naturally occurring" at harmful levels, where naturally occurring refers to conditions or materials present over which man has no control, or where all reasonable land, soil, and water conservations practices have been applied. Reference conditions should reflect minimum impacts from human activities and attempts to identify the potential conditions that could be attained (given historical land use) by the application of reasonable land, soil and water conservation practices.

Comment 7: Page 47 -section 3.4.2. Your analysis of the SEV model leaves me a bit confused. Based on the results of model 4 even at the low end of the TSS concentrations (2-5 mg/L) the model says that we will reach paralethal or lethal effects on eggs and larvae in only 4 days. Using this information how can you set the TSS target level to an average of 5.7 mg/L? This target would result in the termination of any spawning success in the basin. I would remove this section since it seems to invalidate your choice of a target level and make it seem that no matter what happens to improve the water quality in Bobtail Creek it will never be good enough to support a spawning population of fish.

Response: Although MDEQ has chosen not to use TSS as a target, the SEV model provides information derived from laboratory tests that provide useful context for discussing impacts of TSS on fish. This information documents the potential for TSS to impact the fishery, and provides justification for the use of TSS as a supplemental indicator. It is true that the model predicts impacts to eggs and larvae even at low TSS concentrations for relatively short duration exposures. In other words, the model predicts a certain degree of stress to the organisms even with minimal development and disturbance. Please see the previous response with respect to development of targets.

Data not used for targets or supplemental indicators are used to assist in providing context for the reader. MDEQ feels that providing context assists the public in better understanding the both the specific situation and how it relates to the larger picture. As previously stated, targets are site-specific interpretation of the standard, and are set using reference conditions (see response to comment 5).

<u>Comment 8:</u> Page 49 -section 3.4.2. At the bottom of Table 3-15 you state that the bank stability value from INFS has been changed by the KNF to meet site-specific conditions. This is not true and no change has been made to this date.

Response: Table 3-15 has been changed to reflect this comment.

<u>Comment 9:</u> Page 51 -section 3.4.2. Libby Ranger District has macroinvertebrate data for numerous years at 6 "reference" watersheds that could be used to help determine how the Mountain IBI reflects conditions on the Kootenai NF.

Response: MDEQ would appreciate receiving the above-referenced macroinvertebrate data. MDEQ requests all readily available data every two years in preparing it's 305(b) report and 303(d) list. Additionally, when MDEQ starts developing Water Quality Restoration Plans/ TMDLs, MDEQ requests any appropriate information be provided so that this information can be used in developing the Plan. MDEQ regrets that the Forest Service did not previously provide this information.

Comment 10: Page 66 -section 5.2.7. I find it interesting that the private timberlands seem to be getting to walk away from any responsibility in this TMDL. You state that the existing road density is considered a high risk for water quality impairment and then discuss that the FS road decommissioning work will result in lowering the density to 3.2 miles per square mile and further that you propose to have the road density lowered to less than 1.5 miles per square mile this is all well and fine but there is no mention that PCTC is at the present time constructing over 5 miles of road in the upper watershed and has plans to harvest and has already begun harvest on over 600 acres of their lands. It seems like the TMDL is being written to make the USFS try to bring the entire watershed back to health with no quantifiable help from any other landowner.

Response: MDEQ has no legal or enforcement authority to require implementation of voluntary reasonable land, soil, and water conservation practices. This is very clear under state law (MCA 75-5-703). Each TMDL must be established at a level that will achieve compliance with applicable water quality standards. However, "The Department shall support a voluntary program of reasonable land, soil, and water conservation practices to achieve compliance with water quality standards for nonpoint source activities for water bodies that are subject to a TMDL developed and implemented pursuant to this section" (MCA 75-5-703 (8)). MDEQ encourages all appropriate land managers to implement the recommendations contained in the Water Quality Restoration Plan, in order to meet state standards and restore the appropriate beneficial uses.

<u>Comment 11:</u> Page 71 -section 6.1. Concerning the USFS responsibilities. How is it that you expect the forest service to manage timber harvesting on NFS lands to limit water yields to less than 7-9%? Water yields are measured at the mouth of the watershed which includes the actions of ALL landowners. Once again this wording puts all of the restoration squarely on the shoulders of the USFS. This allocation of restoration efforts does not seem proportional to the amount of activities that have caused the problems in Bobtail Creek and continue to press the watershed. For example since the completion of the Pipestone EIS the watershed has had some time to recover ECAs which would have dropped the water yield increase to 8.5% in 2005. With PCTC's

recent road building and timber harvest the water yield will ramp back up to 10.4% no matter what the USFS does in the basin (which for the past 6 years has been only restoration activities).

Response: MDEQ appreciates the National Forest's concerns regarding undue burden on a single land manager. MDEQ, in Section 6.1 has identified commitments that the Forest Service has made in other documents. The first two bullets are identified in the Forest Service's Pipestone Final Environmental Impact Statement (2004, as cited in the draft document). The other and final bullet in this section discusses monitoring activities that the Forest has indicated that they are willing to support. The final statement regarding water yield has been modified so that this recommendation is clearly limited to those lands over which the Nation Forest has management authority. Section 6.2 has been modified to include similar recommendations for limiting peak water yield increases to 7 – 9% on Plum Creek lands.

<u>Comment 12:</u> Page 72 -figure 6-1. Some of the heading in the boxes have changed due to funding shortfalls. The boxes with 2003 decommissioning should be changed to note that some of the work will not be completed till 2005. Approximately 11 miles of the road decommissioning work was completed in 2004.

Response: Figure 6.1 has been modified to reflect this comment.

<u>Comment 13:</u> Page 75 -section 7.0. Concerning the monitoring. I could never find a good description of who will be responsible for writing the monitoring report. Are we to just send data to DEQ and you write the report or are we supposed to write the report?

Response: MDEQ has the legal responsibility for reviewing the water quality monitoring data, but encourages a collaborative effort in implementing recommendations in the Water Quality Restoration Plans. This collaboration can take many forms. This plan does not articulate who is responsible for writing the monitoring report because this has not been determined. What has been determined is that a number of groups have monitoring resources and that coordination of these resources is appropriate.

Under State law (MCA 75-5-703(7)), after control measures have been implemented (incorporation of waste load allocations into discharge permits and application of reasonable land, soil, and water conservation practices), the Department of Environmental Quality is responsible for determining if State water quality standards are being met. This determination is a part of the State's 305(b) Report/303(d) list, which MDEQ produces on a biennial basis. Again, MDEQ is interested in a voluntary collaborative and cooperative approach and encourages land management agencies and private property owners to work with MDEQ in future implementation and monitoring activities.

<u>Comment 14:</u> Page 75 -section 7.0. You state that it is anticipated that the stakeholders will pursue funding for monitoring data and evaluation and you also list quite a lot of additional work you would like to see completed such as road sediment assessment, bank erosion assessments, monitoring of restoration activities including BMPs of road and riparian activities. Considering

that the Bobtail Group has been inactive for 2 years since the majority of the in-channel work on private lands has been completed I am afraid that the majority of this additional work would fall on to the Forest Service. What happens if this work is not completed? The report also states that 4 additional macroinvertebrate sites are recommended, this is an additional cost of nearly \$1,000 per year that the USFS will not be able to pick up. In fact, the current budget does not allow us to complete the single site on Bobtail this fiscal year. Due to the timing of this document, there is little chance of getting a grant to cover the monitoring costs for 2005. There needs to be some flexibility built into this document that allows for some of this monitoring to slide if funding is not available. I also see that periphyton has been added as a monitoring set. This has not been collected before and I have not seen the rational to add it now as a required monitoring item. What is the sampling protocol and analysis cost for this item?

Response: MDEQ does not have the authority to require other entities or persons to monitor or assess data for nonpoint source impacts outside of permitted discharges (point sources). Both Sections 6.0 and 7.0 (Restoration Strategy and Monitoring Strategy) are required elements of the Plan for EPA approval, but do not contain specific nonpoint source actions or recommendations that are legally enforceable.

Comment 15: Page 76 -section 7.2. This section includes the use of the riffle stability index. Since the data for Bobtail was originally collected (1999 and 2000) the use of the riffle stability index has been discontinued as a valid monitoring parameter because of its limited acceptability to specific channel types. I would suggest that you drop this monitoring item requirement off your list. Also on this page the Wolman pebble counts are only completed in conjunction with the stream geomorphology data set and are thus completed only when those variables are sampled (every 5 years). I would hope that this variable could be looked at every 5 years rather than every year.

Response: The MDEQ feels that the Riffle Stability Index (RSI) is an appropriate target for Rosgen type "B" channels in the Bobtail watershed. MDEQ has dropped the recommendation that this target be applied to "C"-type channels in Table 3-5 and Section 3.4.2.

MDEQ does not have the authority to require other entities or persons to monitor or assess data for nonpoint source impacts outside of permitted discharges (point sources). Both Sections 6.0 and 7.0 (Restoration Strategy and Monitoring Strategy) are required elements of the Plan for EPA approval, but do not contain specific nonpoint source actions or recommendations that are legally enforceable.

<u>Comment 16:</u> Page 77 -section 7.3. Once again the discussion of using the riffle stability index comes up in this section. Please see the last comment. In the macroinvertebrate discussion you use the word "should"...does this mean the item of adding 4 more sampling sites is not required?

Response: As the MDEQ feels that a Riffle Stability Index range of 45 – 75 is an appropriate target for Bobtail type-B channels, it is appropriate to recommend monitoring for this target parameter. As previously stated, MDEQ does not have the authority to

require other entities or persons to monitor for nonpoint source impacts outside of permitted discharges (point sources). Four additional monitoring sites are suggested for better assessing watershed health and beneficial use attainment.

Comment 17: Page 79 -section 7 .6. The discussion about reference monitoring and the primary approach leads me to ask the question about the 6 locations where we have macroinvertebrate data on reference locations. It seems that this information should also be used to help judge the improvement (fluctuation) in index scores rather than just state that the index score for Bobtail needs to be above a certain value. What if the index score for a reference stream does not meet the value? Will it somehow then be listed as not meeting water quality criteria? -I don't think it would so it seems to me that there should be some flexibility built into all these target values to somehow adjust depending on what reference values are doing during the same time period.

Response: MDEQ has previously requested data that the Forest has collected and did not receive the data requested. MDEQ agrees that the Forest Service reference site macroinvertebrate data is likely to be useful. As stated in response to a previous comment, the macroinvertebrate data is identified as a supplemental indicator and not as a primary target for determination of use support. If all the targets are met, the question of supplemental indicators being met is moot. If the targets are not met, then supplemental indicators, including the macroinvertebrate metrics, can be used to assist in assessing the circumstances surrounding not meeting targets. The Water Quality Restoration Plan/TMDL also has an adaptive management strategy that allows for flexibility with respect to both targets and load allocations (see subsection 7.8 "Adaptive Management Strategy").

Additionally, the purpose of monitoring reference and impaired streams simultaneously is to help account for natural variability.

<u>Comment 18:</u> Page 80 -section 7.7. In the data gap discussion you once again use the word "should" in every item. This leads me to wonder if the item is required or not.

Response: As previously stated, MDEQ does not have the authority to require other entities or persons to monitor or assess data for nonpoint source impacts outside of permitted discharges (point sources). Both Sections 6.0 and 7.0 (Restoration Strategy and Monitoring Strategy) are required elements of the Plan for EPA approval, but do not contain specific nonpoint source actions or recommendations that are legally enforceable.

<u>Comment 19:</u> Page 80 -section 7.8. The first sentence states "As monitoring data is obtained and evaluated..." There needs to be a much better discussion as to who will be responsible for this data collection and evaluation and what happens if it does not occur.

Response: MDEQ encourages a cooperative collaborative approach to implementation of Water Quality Restoration/TMDL Plans. Developing this approach will take discussion, time and resources. MDEQ is interested in cooperating/participating in such activities. As previously stated, without other assistance, MDEQ has primary responsibility for evaluation of implementation activities as they relate to meeting State water quality

standards. MDEQ agrees that a much better discussion needs to occur in order to establish an efficient monitoring program in Bobtail Creek. MDEQ hopes to initiate such a discussion in the future if a local group does not take the initiative.

<u>Comment 20:</u> Page 20 -Bottom table item should probably be "<.025" to be consistent with the other Mountain IBI asterisk-text.

Response: The table has been changed to reflect this comment.

<u>Comment 21:</u> Page 25- Turbidity section, first sentence talks about "see table above." -What table is this referring to? Table 3-4 *THAT FOLLOWS* in the text lists the 5-10 NTU detail.

Response: The sentence has been changed to reflect this comment.

<u>Comment 22:</u> Page 36 & 49- Bank stability is an INFS-parameter that is only to be applied to non-forested systems. Why is it used here for what is clearly a forested-system??

Response: The Pipestone Draft EIS (which includes Forest Lands in the Bobtail watershed) utilizes the Riparian Management Objectives (RMO), which are part of the INFS decision, as "indicators of aquatic ecosystem health" (USFS 2002, Chapter 3, page 21). Montana Department of Environmental Quality believes that stream channel stability, as described in the Pipestone Draft EIS (Chapter 3, page 22), is equivalent to bank stability. The RMO of bank stability is an indicator of watershed health and provides a proper supplemental indicator for this watershed.

<u>Comment 23:</u> Page 47- Given your SEV values, and known current SS values over a range of flow conditions, how can there still be trout spawning in Bobtail Creek. It makes us question the SEV threshold values.

Response: As stated in the document, The SEV model is not intended as a quantitative analysis of TSS-related impairment in Bobtail Creek, but is presented to corroborate other evidence of impairment presented in this document to show that there is a total suspended solids problem. It is one of three lines of evidence used. The three lines include:

- 1) TSS and turbidity data from Bobtail Compilation and review of existing Creek;
- 2) Comparison of Bobtail Creek TSS values to TSS values from other "least impaired" watersheds; and
- 3) Assessment of potential effects of TSS on aquatic life in Bobtail Creek.

The SEV values are not values set by MDEQ, but data gathered and evaluated by Newcomb and Jenson (1996) from 80 published and adequately documented reports on fish responses to sediment in streams and estuaries.

<u>Comment 24:</u> Page 53- *USDA*, 2002A. What is this reference? It is not included in your list of references...

Response: The reference should be USFS, 2002A. The text has been changed to reflect this comment.

Comment 25: Page 55 - Your analysis of the Peak flow/Eroding bank-conditions concludes that the existing 10.6 to 10.8% increase violates some USFS requirements. This is not correct- The Final Pipestone EIS concluded, based on all of the information used so heavily in this document, that beneficial uses would be protected; meaning that level of flow increase was acceptable. Your reference to a supposed Quartz Creek "threshold" of 7 -9% ignores the fact that the KNF cumulative effects analysis process and conclusions are based on the channel and watershed conditions of the system being evaluated, not on conditions in close or adjacent watersheds. A compromised system like Quartz Creek would have a lower allowable peak flow threshold than a stable system.

Response: MDEQ does not allege any violation on the part of the USFS. MDEQ's analysis of existing conditions concludes that the existing peak flow increases of 10.6-10.8 % contribute to bank instability and sediment impairments in the Bobtail Creek Watershed. Furthermore, Chapter 4, page 32 of the Pipestone Draft EIS (USFS, 2002) states "... this level of peak flows would likely maintain the current sources of instability in the Bobtail watershed. This determination is supported by stream stability and water quality studies conducted by the Libby Ranger District (see District files) in the adjacent Quartz Creek watershed. Monitoring information suggests that stability (stable banks and stream bed) would be expected with water yields below the 7% to 9% level. Because Bobtail and Quartz are similar in geology, it is expected that they will function in a similar manner. Maintaining water yields in the 10.6 to 10.8 % range is expected to delay recovery in this watershed."

MDEQ has reviewed and concurs with the Forest's evaluation that is documented in the Pipestone draft EIS (and supported by the Final EIS decision). This evaluation clearly states that bank and streambed stability is expected with increased water yields of less than 9%. Above that, it is expected that recovery of stream bank and bed stability will be delayed. Again, the point of this Plan is to provide a document, which if implemented, will result in achievement of State water quality standards.

<u>Comment 26:</u> Page 62- A sediment loading analysis that only has *quantified* current annual estimated loads from ~of eight potential sources?? How can this be a defensible sediment loading analysis??

Response: Two additional loads have been estimated and added to the Table 5-1. It is estimated that county roads deliver >2 tons of sediment per year based on the limited number of road crossings and the utilization of BMPs. It is also estimated that USFS roads deliver 50-70 tons of sediment per year. This value is determined by utilizing the 17 ton per year value on 21 crossing sites on Plum Creek Timber company land and extrapolating for the three to four times as many crossings on USFS lands.

Comment 27: Page 65- The 7-9% threshold again.....

Response: See response to comment 25.

<u>Comment 28:</u> Page 75- It would seem that the DEQ is expecting the USFS and MT DFWP to shift into the monitoring responsibility once the TMDL is approved, when the DEQ has the legal responsible for determining if the TMDL is "working". If the DEQ expects these entities to accomplish this monitoring, they will have to assist with the funding, at least for the USFS portion. The items listed in this section will be very expensive to collect and analyze, especially if the DEQ adopts the strategy of looking at reference sites for trends. This is especially critical given the adaptive management philosophy you say you will use which is heavily dependent on monitoring data.

Response: The monitoring section was originally written based on communication from the Libby District Hydrologist. It has been modified. MDEQ is not attempting to shift the responsibility for monitoring, but is encouraging other entities with management and monitoring expertise and resources to assist the MDEQ in protecting and improving a common resource.

MDEQ receives Clean Water Act Nonpoint Source (319) Funding that can be used to assist in monitoring activities. This funding does require a 40% local (non-federal) match, which can include in-kind services. In 2004, the highest funding priority for 319 watershed restoration projects was to implement approved Water Quality Restoration/TMDL Plans. It is expected that this will remain the highest priority for watershed restoration projects.

Comment 29: Plum Creek has been an active participant in water quality planning and restoration in the Bobtail Creek watershed over the past 14 years. On our ~2300 acres of land in the watershed, we have been actively implementing Montana's forestry BMPs and the SMZ law. We have monitored water quality, and conducted source assessments on our land. We have participated in stream restoration efforts. We have funded expert reviews of new procedures, such as the Severity of Ill Effects analysis. And we have been continuously engaged as the TMDL has been developed. On our greater Rocky Mountain ownership, we have developed and implemented a Native Fish Conservation Plan that was approved by the US Fish and Wildlife Service for protection of bull and cutthroat trout.

Response: Comment noted.

<u>Comment 30:</u> With regard to the public review draft *Water Quality Protection Plan and TMDLs for the Bobtail Creek Watershed*, we believe the TMDL Load Allocation and the Restoration Strategy, <u>with a few modifications</u>, presents a reasonable approach for protecting water quality. Our primary concerns with the document lies with a failure to acknowledge the primary causal situation that led to the original 303(d) listing, and the extensive list of targets that lack solid technical underpinning. These are individually discussed below.

Response: Comment noted.

Comment 31: Failure to Acknowledge the Primary Causal Situation Affecting Bobtail Creek

Bobtail Creek's problems stem from extreme erosion caused when the stream jumped out of its banks and ran down a skid road that a small-private landowner built adjacent to the stream when logging their property in the late 1980's. The diversion of the stream down this skid road first occurred during severe rain-on-snow events in the fall of 1990 and spring of 1991. DEQ analyzed this situation in a warning letter submitted to the private landowner. Additional events in February 1996, spring 1997, and more recent floods have continued to erode this unstable reach, leading to extensive channel aggradation downstream. This is what led some local landowners to petition DEQ to list the stream as impaired in order to justify extensive grants for channel restoration work (which have been obtained and projects implemented). The only mention of this issue in the draft document is in a single short paragraph at the end of Section 2.8.1 (stream flow data). We ask that this defining causal situation, and the ensuing restoration be fully discussed in the Source Assessment, TMDL, and Restoration Planning sections of the document.

Response: MDEQ agrees that Bobtail Creek's "move" into the logging skid road has created significant problems. Additional language has been added to Subsection 2.7, "Land Use", and subsection 4.3, "Field Review of Residential Reaches" of Section 4.0, Source Assessment. The TMDL load allocation of a 75% reduction from sources identified as "Eroding Banks linked to Human Activities" includes this source. Finally, subsection 6.3, "Other Private Landowner Restoration Plans and Responsibilities" includes restoration recommendations addressing this source.

MDEQ has provided a source assessment (Section 4.0), which shows that the skid road problem is not the only or necessarily the "primary causal situation". This section identifies other road sources, stream crossings, and bank erosion all contributing to the sediment impairment.

Comment 32: Historic Fisheries Data

Section 2.9.1 and Table 2-5 describe electrofishing survey data by MFWP in Bobtail Creek from 1976 and 1997, which DEQ cites as evidence that fish populations have declined. There are numerous problems with this assertion. First, the surveys were conducted in separate locations of the stream, with no habitat data provided to demonstrate that they are in fact similar. Second, the surveys were likely conducted over short reaches of stream (<500ft), so their applicability to the remainder of Bobtail Creek is questionable (i.e., less than 1% of the stream length was surveyed). Third, the reaches sampled by MFWP (Sections 17 and 20) are in a more confined section of Bobtail Creek, which we know is not representative of most of Bobtail Creek (which is a low-gradient alluvial stream). Fourth, natural trout populations are widely variable over time. Platts and Nelson (1988¹) showed that natural patterns of fluctuation could easily explain the differences in trout populations observed in Bobtail. And lastly, common sense would dictate

¹ Platts, W.S. and R.L. Nelson. 1988. Fluctuations in trout populations and their implications for land-use evaluation. N. Am. J. Fish. Mgmt (8):333-3451988

that populations in 1997 might have been impacted by the severe flooding the region experienced during spring runoff in 1997 (especially in a canyon reach). We do not believe that two survey points in different locations of the stream, which represent less than 1% sample of the overall stream, can be credibly used to justify impairment.

Response: MDEQ does not use the fisheries information discussed above as the evidence for justifying the impairment determination. Note that MDEQ has not proposed using fisheries data as either a target or as a supplemental indicator. However, MDEQ does feel that the electrofishing survey data does provide useful information in characterizing the watershed and provides additional support to the listing decision. As stated in the draft document, information from Fish Wildlife and Parks indicates that the surveys were conducted in areas of similar habitat, and densities of three fish species declined over a 21-year period. Although the older data was evaluated and considered in this document, it was generally only considered as supplemental information to assist us in the development of an overall understanding of the current water quality condition of the subject streams. Also please note that this information is included in the Watershed Characterization Chapter (Section 2.9.1), not in the Water Quality Impairment Status Chapter (Section 3.0).

Comment 33: Macroinvertebrate Data

Section 2.9.2, Par 2. This section compares 2000 and 2001 USFS macroinvertebrate data in Section 5 of Bobtail Creek with 1991 PCTC data collected upstream in Section 19. In the first sentence in this paragraph, it states that a "decrease" has been observed in some metrics. It should be noted in the text that the Plum Creek sample was taken in a fully forested reach of stream at the lower end of Plum Creek ownership where the channel bed is composed of coarse gravel (80% of bed coarser than 1 in), while the USFS samples were taken in downstream reaches of stream influenced by agriculture, grazing, and residential development where the stream gradient is much lower and the substrate is much finer. As with fish, setting matters. The difference in macroinvertebrate community composition is easily explained by the different sampling locations rather than simply infer a "decrease" over time.

Response: The text has been modified to reflect the difference in sample locations.

Comment 34: Sediment Targets

Numerous targets are proposed for Bobtail Creek, many of which are based off proposed Riparian Management Objectives in the USFS Inland Native Fish (INFISH) strategy. We object to the use of INFISH standards, since the INFISH environmental assessment never provided any technical underpinning for the proposed "Riparian Management Objectives." This is understandable since INFISH covers a 26 million acre region with diverse climate, geology, hydrology, riparian conditions, etc. There is simply no way to justify single one-size-fits-all targets over such a broad area.

Response: The pool frequency target is one target that is based solely off of Riparian Management Objectives in the USFS Inland Native Fish (INFS) strategy. This RMO,

however, is confirmed in the Forest Service's own Pipestone draft Environmental Impact Statement, as appropriate for the Bobtail watershed. MDEQ has developed targets that are based on information that has been collected in the watershed and other comparable and reference locations. The Forest Service in response to their management needs has collected a significant amount of water quality information. MDEQ is taking advantage of existing data collection efforts in developing the TMDLs. Until additional appropriate data is collected, MDEQ needs to rely on existing efforts.

MDEQ notes that the target parameters selected have been used in other Water Quality Restoration Plans produced by the Agency (Big Creek, Upper Lolo, Grave, and Bitterroot Headwaters). Our use of the weight of evidence approach as described in Section 3.3 of the document is predicated upon the fact that there is no single parameter that can be applied alone to provide a direct measure of beneficial use impairments associated with sediment. Several targets were selected to provide measures of potential sediment impairment associated with the cold-water fisheries beneficial uses. The information provided by these parameters was used in combination with each other and the supplemental indicators were necessary to reach conclusions about water quality impairment.

Comment 35: Width/Depth Ratio

The proposed target is based on KNF data at 1 standard deviation above the mean, which means that 16% of KNF reference sites would have width/depth ratios that exceed the proposed target. If DEQ intends this standard to be met at each and every point along the stream, this should be disclosed. We believe data should be averaged over a distance longer than a given cross section. Given that DEQ currently has not partitioned Bobtail into numerous reaches as far as beneficial use support is concerned, we believe the standard would logically be based over the entire stream length. Based on data provided in Table 3-10, the mean W/D ratio for B channels is 20.8 and for C it is 18.9, both of which would meet the proposed targets.

Response: MDEQ intends the W/D ratio target to be applied as an average of appropriate representative cross section ratios over the segment length. The text has been modified in Section 3.3.1 to clarify how the target is to be applied. Note however, that if a specific stream reach is not meeting the W/D ratio as a result of man-caused activities, then this would be considered demonstration that all reasonable and soil and water conservation practices have NOT been applied, and therefore water quality standards are not being met.

Comment 36: Pool Frequency

While available data provided in Table 3-5 indicate that mean pool frequency in Bobtail Creek currently meets the proposed targets, we believe there are problems with including the pool target proposed by INFISH. The pool frequency objective requires a minimum number of pools per mile based strictly on the width of the stream. This target fails to recognize that geomorphic factors play a tremendous role in determining pool frequency. The stream classification system

developed by Montgomery and Buffington (1997¹) explicitly indicates that some stream types have few or no pools. Plane-bed streams, for instance are defined by the lack of bedforms. Cascade streams do not typically have deep pools because of their steep, turbulent flow. Dune-ripple streams have a relatively low frequency of pools. Problems with standard pool frequency objectives are compounded by the tremendous observer variability when identifying the boundaries of pools, especially since these boundaries are discharge-dependent. These factors make it exceptionally difficult to reliably compare pool inventories. In short, there are strong arguments against adopting any universal requirements for the number of pools per mile of stream.

Response: MDEQ acknowledges that uncertainties exist with most, if not all, potential targets. Nevertheless targets are an EPA-required element of Water Quality Restoration Plan/TMDLs. For this reason, EPA guidance recommends and MDEQ uses a suite of targets, "to account for process complexity and the potential lack of certainty regarding the effectiveness of a single indicator" (EPA, Protocols for Developing Sediment TMDLs, October 1999). Additionally, the EPA guidance acknowledges the usefulness of streambed (including pool-type) targets. It is also noted that the Forest Service acknowledges that pool frequency is an important management objective, as evidenced by the US Forest Service's selection of pool frequency as a "Riparian Management Objectives (RMOs)".

These pool frequency values used for targets for the Bobtail Creek sediment TMDL were found to be similar to pool frequency values from reference streams as analyzed for Grave Creek Watershed TMDL development. In fact, the initial analysis for pool frequency based on local reference streams suggested that even high pool values may reflect the stream's potential, but decided here and in Grave Creek that the use of the RMOs for pool frequency reflects an appropriate "reference condition" approach consistent with MDEQ interpretation of water quality standards and subsequent development of TMDL targets. Furthermore, the application of reference stream target frequency information incorporates both Rosgen stream type and stream size, to address the types of concerns noted in the comment.

Information on this target has been collected for appropriate "reference conditions" (minimal impact from human activities, in nearby watersheds that have similar geology, hydrology, etc.). Again, due to issues regarding uncertainly, pool frequency is not the only target selected.

Comment 37: Riffle Stability Index

Kappesser (2002) only evaluated RSI as a watershed tool for B channel types in unglaciated portions of northern Idaho. As such, it is not applicable to apply the procedure to the continental and alpine-glaciated terrain of northwest Montana, which has a much higher natural sediment supply. Moreover, DEQ fails to justify how this procedure is applicable to C channel types that

January, 2005 F-14

_

¹ Montgomery, D. R. and J. M. Buffington. 1997. Channel-reach morphology in mountain drainage basins. Geological Society of America Bulletin 109(5):596-611.

were not evaluated by Kappesser (2002). Lastly, in Kappesser (2002), 25% of reference streams had RSI values over 80.5. As such, the proposed TMDL target of less than 75 would mean that up to 35% of reference streams would fail to meet the TMDL target, which seems unreasonably high. For all the reasons above, we do not believe a target based on RSI is technically justified.

Response: Because the RSI is used to indicate excess sediment loading and is based on a ratio, MDEQ believes that the RSI is a relevant parameter to indicate stream health in the Bobtail Watershed. Kappesser (2002) evaluated very different streams in both Idaho and Virginia to reach the conclusion that "the RSI provides a useful estimate of the degree of textural change of riffles in mountain streams due to increased sediment supply." We do not believe the RSI impacts would be limited by a certain type of geology, and the author does not imply this in his conclusions. Also, the 75th percentile value of 80.5 was for streams in Virginia, whereas the 75th percentile value for reference streams in Northern Idaho, which we believe provide a more appropriate value to base our target on, was 72. We agree that the author did limit his correlation to fish habitat surveys and based his conclusions on B and Fb channels. TMDL development results for the St. Regis Watershed suggest applicability of this concept for C reaches, with high values indicating an aggrading reach and very low values indicating a degrading reach, although this St. Regis data is still undergoing analysis. Nevertheless, because of the uncertainly associated with the applicability of the RSI in C-type channels, the use of this target will be applied to B-type channels in the Bobtail watershed. The text has been modified to reflect this change.

Comment 38: Woman Pebble Counts

Christina Relyea's work has shown that abundance of some macroinvertebrate species declines with increasing levels of fine sediment. However, the sediment value where this occurs is much closer to 40% than 20%. We believe the proposed target of 20% based on her work is off-base. Moreover, what is the point of having a fine sediment target if the only justification for it is a response from macroinvertebrates? That is, why have both a pebble count <u>and</u> a macroinvertebrate standard? All this aside, Figure 3-5 suggests that with the exception of a couple of reaches, Bobtail Creek currently meets the proposed target.

Response: One of the five targets proposed are Wolman pebble counts. The macroinvertebrate index is proposed as a supplemental indicator, not a target. Section 3.3 describes how each is to be used, and the differences between a target and a supplemental indicator. MDEQ agrees that for all but two reaches, the data presented in Figure 3-5 indicates that Bobtail meets the proposed target. MDEQ feels that Relyea's work clearly demonstrates a "harmful" effect level above 20% fines less than 2 mm.

Comment 39: McNeil Cores

The proposed target of 28% is based on the 75^{th} percentile of KNF reference sites, and other work looking at biological impacts of spawning gravel fines. The KNF reference sites have a mean channel gradient of 2.2% (range 1.7-3.0%). The current coring site on Bobtail Creek is located in a reach with an average gradient of 0.6%, which is substantially lower than the KNF

reference sites. As such, the coring site for Bobtail should be re-located to a reach that is similar to the reference reaches, or reference reach data for lower gradient streams should be used. That said, the 95% confidence interval on the mean level of fines in Bobtail currently encompasses the proposed target of 28%. As such, the target may currently be met, despite the low-gradient character of the Bobtail sample site.

Response: MDEQ is not opposed to sampling additional locations within Bobtail Creek and using more than one data set to evaluate impairment along different reaches where spawning habitat does or should occur. The McNeil Core sampling is typically located in pool glide locations where fish like to spawn. These glides are low gradient areas where sediment sorting occurs, thus providing "normalization" for the stream gradient variations identified in the comment. MDEQ finds that the 28% value is applicable to spawning locations within Bobtail Creek. The 28% value is similar to target values developed in other TMDL planning areas (St. Regis unpublished data; Blackfoot Headwaters – MDEQ, 2004) where relatively low gradient stream results were used to help justify target values. Nevertheless, the need to always consider potential target modification is incorporated within the overall adaptive management approach if future study indicates that the lower gradient areas on Bobtail Creek should have a different percent substrate fines target.

Comment 40: Bank Stability

The indicator of >80% bank stability has similar problems to those discussed for pool frequency. First, bank stability cannot be measured without defining the conditions that constitute instability and the parameters for measuring these conditions. Second, some streams naturally have unstable banks. Meandering, unconfined streams migrate laterally and therefore typically have eroding banks on the outside of meander bends. Conversely, measuring bank stability on bedrock streams provides little useful information on riparian conditions. Once again, uniform targets prove to be inappropriate for the varied stream systems in the region.

Response: Bank stability is proposed as a supplemental indicator, and not a target. MDEQ agrees that identification of a causal agent(s) is an important determination in order to address the underlying reason for the instability. However, bank stability can provide an indication of a TSS or sediment problem. Information on this supplemental indicator has been collected for appropriate "reference conditions" (minimal impact from human activities, in nearby watersheds that have similar geology, hydrology, etc.). Again, due to issues regarding uncertainly, bank stability is used as a supplemental indicator to provide supporting or collaborative information in determining if exceedances of targets are due to natural or anthropogenic causes.

Comment 41: TSS Reference Analysis

It is interesting to see a reference approach taken for TSS; however, likely differences in the temporal (and spatial) sampling methods between the Bobtail data and the reference data would render any comparison invalid (i.e., comparing apples and grapes). As supported by the small "n" for each reference site, the reference data were likely taken with depth-integrated samples on

a monthly basis (and possibly not even during spring flows), whereas the Bobtail data were collected by an automated sampler that were composited over the course of each day through spring runoff. As such, you would expect to have some higher-concentrations values in Bobtail than in the reference data set. One way to partly address this problem would be to randomly select one Bobtail sample from each month (or on whatever interval the reference data were taken) and compare these against the reference. But even then, samples were likely collected in different ways (depth integrated snapshots vs daily composites taken at one point in the water column). Additionally, we note that one of the selected reference sites (Stanley Creek) derives the majority of its flow from a spring that emerges from the base of the moraine impounding Spar Lake.

Response: MDEQ acknowledges the uncertainty and problems associated with the data sets (and specifically those associated with the smaller size reference data pool and differences in sample methodology). Nevertheless, MDEQ feels that this information does provide a useful tool as a supplemental indicator. Since TSS is not proposed for use as a target in this watershed, MDEQ does not feel that additional efforts in developing analyses proposed in the comment are warranted at this time. Section 3.3 discusses how supplemental indicators will be used in subsequent beneficial use evaluations if the targets are not met.

Comment 42: TSS Biological Effects Analysis

In May, 2003 we provided DEQ with a review of the SEV procedure by Dr. Tracy Hillman (attached). Dr. Hillman noted that the egg/larvae equation provided by Newcombe and Jensen was not developed for trout that burry their eggs in a gravel pocket in a stream environment. As such, it is not applicable to Bobtail Creek and should be excluded from the document.

Response: MDEQ acknowledges that there are confounding effects associated with the egg/larvae equation may not be valid for the fish species found in Bobtail Creek (due to trout burying their eggs in redds and some species being fall spawners). Section 3.4.2 and Appendix D of the document has been modified to reflect that the model for eggs and larvae may not be appropriate for the situation found in Bobtail Creek. However, the same letter states "In general, I found nothing wrong with the first model, which describes the effects of suspended sediment on juvenile and adult salmonids... I believe this model is useful in describing ill effects to salmonids in Bobtail Creek." This model indicates sublethal (and potentially paralethal) but harmful effects of TSS at concentrations and durations found in Bobtail Creek. MDEQ agrees with the analysis provided by Dr. Tracy Hillman that the model is useful in assessing the impact of total suspended sediment on trout in Bobtail Creek, and finds it appropriate information to include in the document as an additional line of evidence that the aquatic-life beneficial use is currently not fully supported.

Comment 43: Source Assessment

We are troubled to see that our analysis of road sediment delivery is the only one that estimated actual <u>loads</u> to Bobtail Creek. The USFS analysis examined indirect links to road sediment delivery (e.g., road density, stream crossings etc.), but failed to quantify actual loads, even though they have tools at their disposal to do this (e.g., R1-WATSED model). With USFS commitments to DEQ to assist in the TMDL process, I am surprised to see that they really have not provided very helpful information to DEQ for actually setting the TMDL. Additionally, other potentially important sediment sources (e.g., eroding banks, rural residential roads, etc.) were similarly unquantified. Section 4.5 of the draft report acknowledges these data gaps.

We are similarly concerned with the synoptic survey of TSS performed by the USFS. The highest site in the survey was located immediately downstream of a highly unstable reach of stream on private land that had undergone channel reconstruction immediately prior to sampling. Because of this, concentrations of TSS at this location cannot be assumed to represent conditions in the forested headwaters upstream. The document should include additional text that fully acknowledges this weakness in the TSS survey.

Response: MDEQ has modified the document and has provided an estimate of road sediment delivery for Forest Service and County roads (Table 5-11).

MDEQ has modified the document in Section 4.1 to more fully describe the situation surrounding the highest upstream sample location ("Below Harpers") during the USFS synoptic stream sampling.

Comment 44: TMDL for Suspended Sediments (5.1.1)

As was discussed above, we do not believe the data collected at reference sites is similar to data collected for Bobtail. As such, we question the attainability of a 95% reduction in TSS levels from Bobtail Creek.

Response: MDEQ acknowledges the uncertainty associated with the data collected at reference sites and the data collected for Bobtail Creek. For example, the data collected in the Bobtail includes daily measurements of flow and TSS. The reference data was usually collected monthly. The Bobtail data was collected as grab samples, while the data at reference sites collected by USGS was collected as composite samples. Nevertheless, for the purposes of developing supplemental indicators (recall that TSS is used as a supplemental indicator) and load reduction estimates, MDEQ feels that the data provides adequate confidence when incorporating a margin of safety.

MDEQ notes that the 95% reduction in TSS is for the average TSS during high flow conditions, which is when the majority of the loading occurs. These high flow conditions can be generally characterized as flows above 15 cubic feet per second at site Bobtail 1, near the mouth, based on the 3-year period of record (Appendix A). The mean TSS value collected at the Bobtail 1 site (125.3 mg/L), if decreased by 95% is close to the mean TSS value for all reference sites.

MDEQ also notes that although the TMDL is based on a percentage reduction in TSS, the proposed targets for determining compliance with standards are based on width-to-depth ratios, pool frequency, riffle stability, pebble counts and McNeil Core data.

Finally, the proposed monitoring strategy (Section 7.1 - 7.7) and adaptive management strategy (Section 7.8) will assist in determining what TSS reduction is necessary in achieving the targets.

Comment 45: Load Allocation (Table 5-1)

In acknowledgement of Montana's non-regulatory approach to BMP implementation, we suggest replacing the term "compliance" with "application." Use of the term "application" would be consistent with the DNRC audit reporting procedures. Also, we question the attainability of "100% compliance with Applicable BMP standards" with regard to future roads and harvesting and future development. Even in states with regulatory BMP programs, 100% implementation is not feasible. We suggest replacing the words "100% compliance with," with "implementation of..." Changes would also be necessitated to sections 5.2.5 and 5.2.6, and Table 5-3 as well.

Response: MDEQ agrees with the above comment and has modified the document accordingly.

Comment 46: Future Performance Based Allocations (Section 5.2.7 and Table 5-3)

While the USFS has a hard water yield standard they manage for, other landowners do not. Plum Creek addresses changes to streamflow with implementation of forestry BMPs, which suggest a landowner should "Plan timber harvest in consideration of your management objectives and ...watershed condition and cumulative effects of multiple timber management activities on water yield and sediment production (Forestry BMP IV.A.1.h.)." Under Montana law (75-5-703 [2]), DEQ must recognize established programs, such as the Montana forestry BMPs. Identifying a hard water yield threshold to manage for does not meet that requirement. Additionally, Table 5-3 suggests that all future road and harvesting impacts will be solely addressed by the USFS and Plum Creek. However, we are not the only forest landowners in the watershed. At the public meeting in Libby, a private citizen asked if the TMDL would affect his ability to log his land, and he was told by DEQ that it wouldn't. Moreover, this TMDL target could affect downstream water supplies and water rights, which is prohibited under Montana TMDL law. This entire section and standard should be removed from the document.

Response: MDEQ applauds the land managers of Montana for successfully developing and maintaining a voluntary program (Forestry BMPs) that fosters land management practices aimed at protecting soils and water quality. However, MDEQ feels that BMPs do not equate to all reasonable land, soil, and water practices until such time it is demonstrated that they can achieve water quality standards. Additionally, we do not agree that that the "BMP Audits" accurately measure the *effectiveness* of BMP mitigation application. The audits are an objective, one-shot, visual observation of management/mitigation effects on the ground. This does not imply that the audit process

is not a success, because it does present a great added value in education and provides a mechanism by which to improve, as necessary, on the application of practices across the State. It is MDEQ's position that BMPs do not equate to "all reasonable land, soil, and water practices in all cases. Therefore, it cannot automatically be assumed that BMPs equal beneficial use support.

MDEQ has identified that limiting peak monthly water yield increases of 7-9% for the entire watershed is a reasonable land, soil, and water conservation practice for the Bobtail watershed (King, 1989, USDA Forest Service Intermountain Research Station Research Paper INT-401, USFS, 2002). It may be that other reasonable land, soil, and water conservation practices may also result in the attainment of targets. The adaptive management strategy (Section 7.8) has been developed to allow flexibility in adjusting load allocations.

MDEQ also recognizes the multiple ownership/ management objective associated with many if not most of Montana's watersheds. Both Tables 5-1 (Allocations of identified sources) and 5-2 (Future performance-base allocations) include Forest, Plum Creek, and other private landowners. MDEQ's response to the private citizen, is also appropriately directed to Plum Creek and the Forest Service as well. As previously stated, MDEQ does not have the authority to require voluntary reasonable land, soil, and water conservation practices. As a result, this TMDL does not affect Plum Creek, the Forest Service, or a private landowner's ability to manage their lands as they choose. This plan only lays out a voluntary strategy, which if implemented, will meet water quality standards, including protection of beneficial uses.

MDEQ has added language in Table 5-3 to include private land owners that put in roads and engage in timber harvesting will also be encouraged to fully implement BMPs, manage water yield, engage in culvert removal when appropriate, and reclaim unnecessary roads.

Finally, it is important to note that future allocations must be applied to ensure beneficial uses are not only met but maintained through time. The intent of a future allocation is to ensure that beneficial uses are met and maintained with future anticipated land management activities. Even if future management activities include all reasonable land, soil, and water conservation practices, small increases of a pollutant can be expected. The future allocation is not likely to be met without application of all reasonable land, soil and water conservation practices.

Comment 47: Conclusions

We appreciate the Department's willingness to listen to landowner concerns as watershed protection plans are developed. While the document has improved significantly from the stakeholder draft, we believe the above changes are needed before the document is submitted to EPA for approval.

Response: Comment noted.

Comment 48: We described numerous concerns over the proposed targets. As currently proposed, each of the targets would need to be met for Bobtail Creek to ever be de-listed. As the document is currently written, we believe this to be highly unlikely. First, as a matter of simple probability, if each target is only met in 75% of reference watersheds, there is only a 75% chance that each target is attainable in Bobtail. With 5 separate targets, the statistical probability of Bobtail Creek meeting all five targets is only 24%. Moreover, the document could be interpreted to apply to each and every foot of Bobtail Creek (a definite impossibility). We think you need to scale down your list of parameters to those that directly rate to the suspended beneficial use and are most defensible (maybe McNeil Core samples and Wolman Pebble Counts), and more clearly define how they will be measured and where. While Section 3.3.3 does acknowledge uncertainty with the targets, and notes that these targets will be revisited over time, we think uncertainty needs to be discussed in more detail for each target and indicator.

Response: MDEQ appreciates the concern noted above, however, based on a need to provide an adequate margin of safety and uncertainty regarding the appropriateness of the targets, MDEQ has chosen a protective approach to target setting. If entities and individuals in the watershed are interested in implementation of the Water Quality Restoration Plan, additional data collection will help provide the ability to refine targets and revise allocations. This flexibility is written into the Plan's adaptive management approach (Section 7.8).

January, 2005 F-22

January 28, 2005

Max Dodson, Assistant Regional Administrator Office of Ecosystems Protection and Remediation U.S. EPA, Region VIII 999 18th Street, Suite 500 Denver, Colorado 80202

Dear Mr. Dodson:

In accordance with Section 303(d) of the Clean Water Act, the Montana Department of Environmental Quality (DEQ) submits for your review and approval the total maximum daily loads (TMDLs) for Bobtail Watershed in the enclosed water quality restoration plan. These TMDLs have been established at a level necessary to meet applicable water quality standards for protection of cold and warm water fisheries and aquatic life, with consideration to seasonal variation and provision for a margin of safety. The designated uses of the water will be protected through implementation of these TMDLs for sediment. Attached you will find a water quality restoration plan that discusses the EPA's eight proposed approval criteria. We believe that the federally listed endangered species Bull Trout found in the Bobtail TMDL Planning Area will be positively impacted by this plan.

We understand that your office should be able to respond to this proposal within 30 days of submittal. Please feel free to contact George Mathieus (406 444-7423) or myself, if you or your staff has any questions regarding this plan.

Sincerely,

Art Compton
Division Administrator

Attachments

Cc. Bruce Zander, EPA Ron Steg, EPA

Enclosure 1

APPROVED TMDLS

<u>2</u> TMDLs completed
<u>0</u> Determinations that no TMDLs is needed
<u>0</u> TMDLs yet to be developed

Waterbody Name*	TMDL Parameter/ Pollutant	Water Quality Goal/Endpoint	TMDL	WLA LA	Supporting Documentation (not an exhaustive list of supporting documents)
Bobtail Creek* MT76D002_080 17010101	Siltation and Turbidity [Based on 2000 & 2002 Lists]	W/D Ratio 10-28 in B reaches and 10-21 in C reaches Pool Frequency of 47 - 96 pools/mile Riffle Stability Index of 45- 75 in B reaches % fines <2 mm < 20% % fines 6.35 < 28%	95% reduction in TSS loading during high flow conditions	WLA = 0 LA = Performance-based allocations to existing USFS roads, Plum Creek roads, County Roads, eroding banks, mass wasting, culverts, future development, and future roads/timber harvest	"Water Quality Restoration Plan and Total Maximum Daily Loads for the Bobtail Creek Watershed"

^{*} An asterisk indicates the water body has been included on the State's Section 303(d) list of water bodies in need of TMDLs.

Enclosure 2

EPA REGION VIII MONTANA OFFICE TMDL REVIEW FORM

Document Name:	Water Quality Restoration Plan and Total Maximum Daily Loads for
	the Bobtail Creek Watershed (January, 2005)
Submitted by:	MTDEQ
Date Received:	January 31, 2005
Review Date:	April 4, 2005
Reviewer:	Ron Steg
Formal or Informal Review?	FORMAL

This document provides a standard format for the EPA Montana Office to provide comments to the Montana Department of Environmental Quality on TMDL documents provided to the EPA for either official formal, or informal review. All TMDL documents are measured against the following 12 review criteria:

- 1. Water Quality Impairment Status
- 2. Water Quality Standards
- 3. Water Quality Targets
- 4. Significant Sources
- 5. Total Maximum Daily Load
- 6. Allocation
- 7. Margin of Safety and Seasonality
- 8. Monitoring Strategy
- 9. Restoration Strategy
- 10. Public Participation
- 11. Endangered Species Act Compliance
- 12. Technical Analysis

Each of the 12 review criteria are described below to provide the rational for the review, followed by EPA's summary and comments/questions. <u>Comments/questions that need to be addressed are presented in bold</u>. This review is intended to ensure compliance with the Clean Water Act and also to ensure that the reviewed documents are technically sound and the conclusions are technically defensible.

1. Water Quality Impairment Status

Criterion Description - Water Quality Impairment Status

TMDL documents must include a description of the listed water quality impairments. While the 303(d) list identifies probable causes and sources of water quality impairments, the information contained in the 303(d) list is generally not sufficiently detailed to provide the reader with an adequate understanding of the impairments. TMDL documents should include a thorough description/summary of all available water quality data such that the water quality impairments are clearly defined and linked to the impaired beneficial uses and/or appropriate water quality standards.

Satisfies Criterion
Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
Satisfies Criterion. Questions or comments provided below should be considered.
Partially satisfies criterion. Questions or comments provided below need to be addressed.
Criterion not satisfied. Questions or comments provided below need to be addressed.
Not a required element in this case. Comments or questions provided for informational purposes.

Bobtail Creek was not listed as impaired on Montana's 1996 303(d) list. Aquatic life and cold-water fisheries beneficial uses were first listed as impaired on the 2000 303(d) list. Siltation and turbidity were the listed causes of impairment. The current water quality impairment status has been thoroughly evaluated and is described in Section 3.4.

2. Water Quality Standards

Criterion Description - Water Quality Standards

The TMDL document must include a description of all applicable water quality standards for all affected jurisdictions. TMDLs result in maintaining and attaining water quality standards. Water quality standards are the basis from which TMDL's are established and the TMDL targets are derived, including the numeric, narrative, use classification, and antidegradation components of the standards.

abla	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

The applicable water quality standards are adequately summarized in Section 3.2.

3. Water Quality Targets

Criterion Description – Water Quality Targets

Quantified targets or endpoints must be provided to address each listed pollutant/water body combination. Target values must represent achievement of applicable water quality standards and support of associated beneficial uses. For pollutants with numeric water quality standards, the numeric criteria are generally used as the TMDL target. For pollutants with narrative standards, the narrative standard must be translated into a measurable value. At a minimum, one target is required for each pollutant/water body combination. It is generally desirable, however, to include several targets that represent achievement of the standard and support of beneficial uses (e.g., for a sediment impairment issue it may be appropriate to include targets representing water column sediment such as TSS, embeddeness, stream morphology, up-slope conditions, and a measure of biota).

Satisfies Criterion
Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
Satisfies Criterion. Questions or comments provided below should be considered.
Partially satisfies criterion. Questions or comments provided below need to be addressed.
Criterion not satisfied. Questions or comments provided below need to be addressed.
Not a required element in this case. Comments or questions provided for informational purposes.

Targets are presented for width-to-depth ratio, pool frequency, riffle stability index, Wolman Pebble Counts, and McNeil Cores. These are summarized in the attached summary table.

These targets adequately represent both the cold-water fishery and aquatic life beneficial uses. Achievement of these targets should represent attainment of the applicable narrative water quality standards for sediment.

A suite of supplemental indicators was also applied as supporting information in Section 3.0 to verify current water quality impairment status relative to siltation and turbidity.

4. Significant Sources

Criterion Description - Significant Sources

TMDLs must consider all significant sources of the stressor of concern. All sources or causes of the stressor must be identified or accounted for in some manner. The detail provided in the source assessment step drives the rigor of the allocation step. In other words, it is only possible to specifically allocate quantifiable loads or load reductions to each significant source when the relative load contribution from each source has been estimated. Ideally, therefore, the pollutant load from each significant source should be quantified. This can be accomplished using site-specific monitoring data, modeling, or application of other assessment techniques. If insufficient time or resources are available to accomplish this step, a phased/adaptive management approach can be employed so long as the approach is clearly defined in the document.

\checkmark	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

Primary sediment sources include sediment yield from roads, an area of unstable banks, and increased water yield which contributes to unstable bank conditions. The relative importance of many of these sources was underscored by a synoptic TSS sampling event during a rain-on-snow event in 2002. Although loads were not specifically calculated for each of the sources, the source assessment adequately identified and prioritized sediment sources.

5. TMDL

Criterion Description - Total Maximum Daily Load

TMDLs include a quantified pollutant reduction target. According to EPA reg (see 40 C.F.R. 130.2(i)) TMDLs can be expressed as mass per unit of time, toxicity, % load reduction, or other measure. TMDLs must address, either singly or in combination, each listed pollutant/water body combination.

$ \overline{\checkmark} $	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational
	purposes.

The TMDL is expressed as "a 95% reduction in the average TSS concentration during high flow conditions". Insufficient information was presented in the document to specifically determine the resulting TSS concentration and the resulting TSS load during high flow conditions. The following provides an interpretation of this TMDL in terms of concentration and load.

Appendix A of the TMDL documents includes over 1000-paired discharge and TSS values collected in Bobtail Creek between 2000 and 2003. Using these data, average TSS concentrations were estimated during high flow conditions assuming: 1) high flow is represented by flows greater than or equal to the 95th percentile flow, and 2) the storm event occurring in April 2002,resulting in the maximum recorded TSS value of 14,786 mg/l, was a non-typical high flow event that does not represent normal conditions for Bobtail Creek. Excluding the April 2002 storm event, the maximum-recorded TSS value was 313.7 mg/l. The 95th percentile discharge was 31.7 cfs and the average TSS concentration during flows greater than or equal to 31.7 cfs was 61.0 mg/l.

A 95 percent reduction in TSS concentrations only applied during high flows (as defined above) would result in an average TSS concentration, during high flow, of 3.05 mg/l. When this value is averaged with existing low flow data (where there is no TMDL reduction), the resulting concentration is 4.4 mg/l, which is less than the average concentration (including all flows) in the reference streams of 5.7 mg/l.

Assuming a constant discharge of 37.6 cfs, based on the average of the 95th percentile flows for an entire day and a TSS values of 3.05 mg/l, the TMDL would be 619 pounds per day versus 12,385 pounds per day at the average high flow concentration of 61.0 mg/l. So, as proposed, the TMDL would result in an approximate 95% TSS load reduction during high flow conditions.

EPA concludes that the State's TMDL is protective of the aquatic life use of Bobtail Creek. Further, the conservative nature of the TMDL target would result in TSS levels in the creek that are less than those observed in the reference streams described in the document.

6. Allocation

Criterion Description – Allocation

TMDLs apportion responsibility for taking actions or allocate the available assimilative capacity among the various point, nonpoint, and natural pollutant sources. Allocations may be expressed in a variety of ways such as by individual discharger, by tributary watershed, by source or land use category, by land parcel, or other appropriate scale or dividing of responsibility. A performance based allocation approach, where a detailed strategy is articulated for the application of BMPs, may also be appropriate for non point sources.

In cases where there is substantial uncertainty regarding the linkage between the proposed allocations and achievement of water quality standards, it may be necessary to employ a phased or adaptive management approach (e.g., establish a monitoring plan to determine if the proposed allocations are, in fact, leading to the desired water quality improvements).

Allocating load reductions to specific sources is generally the most contentious and politically sensitive component of the TMDL process. It is also the step in the process where management direction is provided to actually achieve the desired load reductions. In many ways, it is a prioritization of restoration activities that need to occur to restore water quality. For these reasons, every effort should be made to be as detailed as possible and also, to base all conclusions on the best available scientific principles.

✓	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

Performance-based allocations are proposed for existing USFS roads, Plum Creek roads, County Roads, eroding banks, mass wasting, culverts, future development, and future roads/timber harvest. The hypothesis is that the performance-based actions will result in achievement of the targets and ultimately water quality standards compliance for siltation and turbidity. The proposed monitoring strategy in Section 7.0 includes tracking implementation of restoration actions and trend monitoring for the target variable to allow for adaptive management if the targets are not met.

7. Margin of Safety and Seasonality

Criterion Description - Margin of Safety/Seasonality

A margin of safety (MOS) is a required component of the TMDL that accounts for the uncertainty about the relationship between the pollutant loads and the quality of the receiving water body (303(d)(1)(c)). The MOS can be implicitly expressed by incorporating a margin of safety into conservative assumptions used to develop the TMDL. In other cases, the MOS can be built in as a separate component of the TMDL (in this case, quantitatively, a TMDL = WLA + LA + MOS). In all cases, specific documentation describing the rational for the MOS is required.

Seasonal considerations, such as critical flow periods (high flow, low flow), also need to be considered when establishing TMDLs, targets, and allocations.

✓	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

As described above in # 5, the TMDL is very conservative and implicitly provides a margin of safety by proposing load reductions that would achieve conditions better than those observed in reference streams described in the document.

8. Monitoring Strategy

Criterion Description – Monitoring Strategy

Many TMDL's are likely to have significant uncertainty associated with selection of appropriate numeric targets and estimates of source loadings and assimilative capacity. In these cases, a phased TMDL approach may be necessary. For Phased TMDLs, it is EPA's expectation that a monitoring plan will be included as a component of the TMDL documents to articulate the means by which the TMDL will be evaluated in the field, and to provide supplemental data in the future to address any uncertainties that may exist when the document is prepared.

At a minimum, the monitoring strategy should:

- Articulate the monitoring hypothesis and explain how the monitoring plan will test it.
- Address the relationships between the monitoring plan and the various components of the TMDL (targets, sources, allocations, etc.).
- Explain any assumptions used.
- Describe monitoring methods.
- Define monitoring locations and frequencies, and list the responsible parties.

Satisfies Criterion
Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
Satisfies Criterion. Questions or comments provided below should be considered.
Partially satisfies criterion. Questions or comments provided below need to be addressed.
Criterion not satisfied. Questions or comments provided below need to be addressed.
Not a required element in this case. Comments or questions provided for informational purposes.

A detailed monitoring strategy is proposed including trend monitoring for the target variables and supplemental indicators, monitoring to fill data gaps, and reference condition monitoring.

9. Restoration Strategy

Criterion Description – Restoration Strategy

At a minimum, sufficient information should be provided in the TMDL document to demonstrate that if the TMDL were implemented, water quality standards would be attained or maintained. Adding additional detail regarding the proposed approach for the restoration of water quality is not currently a regulatory requirement, but is considered a value added component of a TMDL document.

	Satisfies Criterion
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
$\overline{\checkmark}$	Not a required element in this case. Comments or questions provided for informational purposes.

A voluntary restoration strategy outlining a conceptual approach for the U.S. Forest Service, Plum Creek Timber Company, and private landowners in the watershed is presented in Section 6.0.

10. Public Participation

Criterion Description – Public Participation

The fundamental requirement for public participation is that all stakeholders have an opportunity to be part of the process. Public participation should fit the needs of the particular TMDL.

$ \overline{\checkmark} $	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

Public involvement is described in Section 8.0. The document was made available to the public during a formal one-month public comment period during which time a public meeting was held. This document reflects modifications made in response to public comment.

11. Technical Analysis

Criterion Description – Technical Analysis

TMDLs must be supported by an appropriate level of technical analysis. It applies to <u>all</u> of the components of a TMDL document. It is vitally important that the technical basis for <u>all</u> conclusions be articulated in a manner that is easily understandable and readily apparent to the reader. Of particular importance, the cause and effect relationship between the pollutant and impairment and between the selected targets, sources, TMDLs, and allocations needs to be supported by an appropriate level of technical analysis.

\checkmark	Satisfies Criterion
	Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
	Satisfies Criterion. Questions or comments provided below should be considered.
	Partially satisfies criterion. Questions or comments provided below need to be addressed.
	Criterion not satisfied. Questions or comments provided below need to be addressed.
	Not a required element in this case. Comments or questions provided for informational purposes.

The technical analysis linking the target, TMDL, and allocations together is adequate.

12. Endangered Species Act Compliance

Criterion Description - Endangered Species Act Compliance

EPA's approval of a TMDL may constitute an action subject to the provisions of Section 7 of the Endangered Species Act ("ESA"). EPA will consult, as appropriate, with the US Fish and Wildlife Service (USFWS) to determine if there is an effect on listed endangered and threatened species pertaining to EPA's approval of the TMDL. The responsibility to consult with the USFWS lies with EPA and is not a requirement under the Clean Water Act for approving TMDLs. States are encouraged, however, to participate with FWS and EPA in the consultation process and, most importantly, to document in its TMDLs the potential effects (adverse or beneficial) the TMDL may have on listed as well as candidate and proposed species under the ESA.

Satisfies Criterion
Satisfies Criterion with stipulations provided below that <u>must</u> be addressed.
Satisfies Criterion. Questions or comments provided below should be considered.
Partially satisfies criterion. Questions or comments provided below need to be addressed.
Criterion not satisfied. Questions or comments provided below need to be addressed.
Not a required element in this case. Comments or questions provided for informational purposes.

The EPA will consult with the US Fish and Wildlife Service under the provisions of Section 7(a)(2) of the ESA regarding its approval of these TMDLs. For now, the approval is contingent upon the outcome of such consultation.

Biological Evaluation of Proposed Total Maximum Daily Loads (TMDLs)

Montana

Summary Information

Waterbody: Bobtail Cr		reek	
Basin/HUC Upper Koo		otenai River Basin/17010101	
County(ies)	Lincoln Co	ounty	
Species of concern	White Sturgeon (Kootenai River population)(endangered; designated critical habitat) Bull Trout (threatened; designated critical habitat) Bald Eagle (threatened; proposed delisting) Grizzly Bear (threatened) Gray Wolf (endangered) Canada Lynx (threatened) Spalding's Catchfly (Campion) (threatened) Slender Moonwort (candidate)		
Pollutant/ Effect of Action	sediment	White Sturgeon	

Office of Ecosystems Protection and Remediation US Environmental Protection Agency Region VIII Denver, Colorado

April 26, 2005

Introduction

Section 7(a) of the Endangered Species Act ("ESA"), 16 U.S.C. section 1536(a), requires that each federal agency

- · in consultation with the U.S. Fish and Wildlife Service ("FWS"), 1 insure that any action it authorizes, funds, or carries out is not likely to jeopardize the continued existence of any listed species or to result in the destruction or adverse modification of any designated critical habitat of each such species ($\S7(a)(2)$); and
- \cdot confer with the FWS on any agency action that is likely to jeopardize the continued existence of any species that is <u>proposed</u> for listing or to result in the destruction or adverse modification of any critical habitat <u>proposed</u> to be designated for any such species ($\S7(a)(4)$, emphasis added).

A biological evaluation may provide an analysis of the potential effects of a proposed federal agency action on any listed, proposed, and candidate species or the designated critical habitat of any such species, based on the best scientific or commercial information available.

The federal action that is the subject of this biological evaluation is the Environmental Protection Agency's (EPA's) proposed approval of the total maximum daily load ("TMDL") described below, which the state of Montana has submitted to EPA. According to section 303(d) of the Clean Water Act ("CWA"), states are required to develop and submit to EPA TMDLs for pollutants discharged into waters for which certain technology-based controls on point source dischargers as required by the CWA are not expected to be adequate to ensure implementation of applicable water quality standards. EPA must either approve or disapprove each TMDL and, in the event of a disapproval, establish a TMDL itself.

TMDLs do not, in themselves, authorize any discharge of pollutants or create new regulatory authority to control pollutants. Rather, TMDLs rely on existing mechanisms to be implemented. These mechanisms include regulatory programs such as the CWA National Pollutant Discharge Elimination System ("NPDES") permit program and voluntary actions, including management measures or other controls by federal, state, local governments, Indian tribes, or individuals. Once EPA approves a TMDL that includes a point source wasteload allocation component, effluent limits in subsequent NPDES permits for the relevant waterbody must be consistent with the assumptions and requirements of that wasteload allocation. (See 40 C.F.R. Section 122.44(d)(1)(vii)(B).) Once EPA approves a TMDL that includes a load allocation component addressing nonpoint sources, there is wide discretion regarding how or whether that load allocation may be implemented. Past experience has been that when nonpoint source

¹ For certain actions not relevant here, federal agencies consult with the National Marine Fisheries Service instead.

components of a TMDL are implemented, it is through a voluntary, incentive-based program at the federal, state, tribal, or local level.

This biological evaluation has been prepared to assist the EPA and FWS in carrying out their activities pursuant to ESA sections 7(a)(2) and 7(a)(4) as they pertain to EPA's approval of the TMDL(s) described below.

Proposed Action

EPA proposes to approve a TMDL established by the state of Montana for the control of certain pollutants discharged into Bobtail Creek. In particular, this TMDL is designed to achieve reductions of sediment found in the stream to improve the aquatic life and the cold-water fishery. The public review draft document dated November 2004 and entitled "Water Quality Restoration Plan and Total Maximum Daily Load (TMDL) for the Bobtail Creek Watershed" discusses the watershed and has concluded that Bobtail Creek is impaired and a TMDL has been prepared.

In approving a state-submitted TMDL, EPA affirms that the TMDL (1) has been established at a level necessary to attain and maintain the applicable water quality standards and (2) has the necessary components for a TMDL. The necessary components that make up a TMDL are expressed in Region VIII's checklist for TMDL review (see attached Table). EPA's approval of the TMDL does not authorize, fund, or require any aspect of TMDL implementation as described in the TMDL submittal from the state. Likewise, EPA's approval of a nonpoint source TMDL such as this one does not create any new authorities or requirements.

The TMDL EPA proposes to approve addresses the narrative standards adopted by the state of Montana that prohibit excessive amounts of sediment which could result in impairment of designated uses. The overall sediment targets of this TMDL includes width-to-depth ratios (10 to 28 for Rosgen B channel types and 10 to 21 in C channel types), pool frequency (47 to 96 pools per mile depending upon bankfull width), riffle stability index (45 to 75 in Rosgen B channel types), Wolman pebble counts (less than 20% frequency for sizes less than 2 mm for riffle areas), and McNeil core substrate fines (less than 28% fines for particles less than 6.36 mm.) (The McNeil core substrate fines target is based on the method describe by Weaver and Fraley (1991).) Supplemental targets include a total suspended solids concentration (average of 5.7 mg/l with a maximum of 75 mg/l), a bank stability index (80% or greater), and a Montana mountain macroinvertebrate index of biological integrity (an IBI score of greater than 75%.)

Excessive sediment and scour of a channel bed can have a negative effect on aquatic life in several ways. Examples of negative effects on aquatic live include problems associated with spawning, migration, food supply, juvenile rearing, and fry emergence. Elevated levels of fine sediment can fill pools and other depositional habitats, which reduce living space for fish including hiding, security, and winter cover. They can reduce fish egg survival in gravels by smothering the eggs resulting in the lack of oxygen, or by entrapment of pre-emergent alevins (young fish with egg sacs) in the substrate. Fine sediment can also affect the composition and production of the aquatic insect community which important food sources for fish including juvenile bull trout.

There are no point sources of sediment in this watershed. Hence, this TMDL focuses on nonpoint sources. EPA's TMDL regulations define the nonpoint source and natural background component of a TMDL as the "load allocation." "Load allocation" is defined as the portion of a receiving water's loading capacity that is attributed either to one of its existing or future nonpoint sources of pollution or to natural background sources. Load allocations are best estimates of the loading, which may range from reasonably accurate estimates to gross allotments, depending on the availability of data and appropriate techniques for predicting the loading. (see 40 C.F.R. §130.2(g)).

TMDLs can be expressed in terms of either mass per time, toxicity, or other appropriate measure (see 40 C.F.R. 130.2(i)). In these cases, the TMDL is expressed in terms of a reduction in sediment load to less than 20 percent fine sediment (<2 mm) and 28 percent or less fine sediment (<6.35 mm) to result in improved levels of sediment in the stream.

The major sources of sediments (including siltation, turbidity, bank erosion, and other habitat alteration) in the Bobtail Creek watershed are from silviculture, logging road construction and maintenance, and other sources. Human land use activities in the basin include silviculture, residential development, agriculture (primarily grazing and hay harvest), and road development/maintenance (forest roads, county roads, and private residential roads).

Although these water quality controls are described in the TMDL submittal from the state, EPA does not take action on implementation components of TMDL and, as such, EPA's approval will not extend to the implementation components of the TMDL.

Geographic Scope of Action

Bobtail Creek is located in northwest Montana in Lincoln County in the upper Kootenai River Basin. Bobtail Creek is a fourth order tributary of the Kootenai River. The town of Libby is located approximately three miles southwest of the Bobtail Creek/Kootenai River confluence. Approximately 73% of the 22.2 square mile watershed is on Forest Service lands while 16% belong to the Plum Creek Timber Company, 11% are private lands, and the remainder consists of state lands (0.3%). Elevations within the basin range from approximately 4600 feet above sea level in the headwaters of Bobtail Creek, to approximately 2400 feet at the confluence of Bobtail Creek and the Kootenai River.

Species Evaluation

Any species that may be affected by the Bobtail Creek TMDL are most likely aquatic or aquatic-dependent species. EPA has, however, identified no direct effects, indirect effects, interrelated, or interdependent effects associated with approval of this TMDL. ²

² EPA's approval of a TMDL and associated wasteload allocations and load allocations does not add anything to the environmental baseline nor will it result in any physical addition or alteration

Of the ESA listed species in Lincoln County, the only aquatic or aquatic-dependent species are the **white sturgeon** (Kootenai River population) (endangered), **bull trout** (threatened), **bald eagle** (threatened), and the **grizzly bear** (threatened). Critical habitat also has been designated for the white sturgeon and the bull trout but not in Montana. The non-aquatic dependent listed species, which may occur in the area of the proposed TMDL includes the **gray wolf** (endangered), **Canada lynx** (threatened), **Spalding's catchfly** (**campion**) (threatened), and **slender moonwort** (candidate). There are no proposed species known to occur in Lincoln County.

(The ESA does not require evaluation or consultation of effects on candidate species. An evaluation is nevertheless provided below for informational purposes and to prompt evaluation of changes or alternatives to the proposed action if the proposed action is found to have an adverse effect on the candidate species.)

<u>Evaluation of Action on White Sturgeon (Kootenai River population)(Acipenser transmontanus)</u>

Status: Endangered; Designated Critical Habitat

Range: The Kootenai River population of white sturgeon is restricted to approximately 168 river miles in the Kootenai River basin in Lincoln County, Montana, northeastern Idaho, and British Columbia, Canada. Less than 30 of the 168 miles occur in Montana. This reach extends from Kootenai Falls, Montana located 31 river miles below Libby Dam, downstream through Montana and Idaho, and through Kootenay Lake to Cora Linn Dam at the outflow from Kootenai Lake, British Columbia, Canada.

<u>Habitat</u>: White sturgeon in the Kootenai River are opportunistic feeders feeding on a variety of prey items including chironomids, clams, snails, aquatic insects, and fish. There

of any kind to the environment. Thus, EPA's approval of the state's numerical calculations has no direct effect on T&E species. It is only when the numerical load calculations are implemented that additions or alterations to the environmental baseline, or effects, are expected to occur.

EPA's action in this instance is the establishment of the Bobtail Creek sediment TMDL and associated allocations. The TMDL is the expression of the amounts of sediment that can enter the waterbody without resulting in a violation of applicable water quality standards. Because there are no point sources involved in this TMDL, the "wasteload allocation" component of the TMDL attributed to point sources is zero. Regarding nonpoint sources, the TMDL establishes a load allocation that is less than what is currently entering the system. Because the sum of the loads established in the TMDL is less than the sum of the loads currently entering the Creek, EPA views its action as ultimately beneficial. Measures to implement nonpoint source load allocations, however, are beyond the scope of EPA's authority to require. Because EPA does not have authority to prescribe actions to effectuate load allocation, implementation of load allocations depends upon planning and implementation actions by state agencies, other federal agencies, local governments, and/or private landowners pursuant to state, local, and federal authorities that do not derive from the Clean Water Act.

has been almost a complete lack of recruitment of juvenile fish into the population since 1974, soon after Libby Dam in Montana began operation. The significant modifications to the natural hydrograph in the Kootenai River caused by flow regulation at Libby Dam is considered the primary reason for the Kootenai River white sturgeon's continuing lack of recruitment and declining numbers. The population and habitat also face threats from reduced biological productivity, and possibly poor water quality (e.g., lack of nutrients trapped by Libby Dam), and the effects of contaminants.

On September 6, 2001, critical habitat was designated for the Kootenai River population of the white sturgeon. It did not include any habitat in Montana.

Evaluation:

Effect of <u>sediment TMDL</u> on white sturgeon: This proposed federal action does not result in habitat loss or degradation of the white sturgeon. Also, the white sturgeon presently is known to occur in Montana in the Kootenai River below Libby Dam and not in Bobtail Creek watershed.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will have **no effect** on the white sturgeon.

Evaluation of Action on Bull Trout (Salvelinus confluentus)

Status: Threatened; Designated Critical Habitat

<u>Range</u>: The historic range of the bull trout included the Pacific northwest sector of the United States as well as the northwest territories in Canada and possibly Alaska. The current range includes ID, MT, NV, OR, and WA. They are native to streams, rivers, and lakes in northwestern Montana. Juvenile bull trout have been recorded in Bobtail Creek but have not been observed in recent years (MFWP, 1999).

Habitat: Bull trout are found primarily in upper tributary streams and several lake and reservoir systems; they have been eliminated from the main stems of most of the large rivers. Bull trout are opportunistic feeders. Juvenile bull trout feed on terrestrial and aquatic insects, macrozooplankton, amphipods, mysids, crayfish, and small fish. Adults are primarily piscivorous feeding on other fish species but will also take other prey including frogs and ducklings. Bull trout fry generally use shallow, low velocity areas with an abundance of instream overhead cover in the form of cobble, boulder, and rootwads. Juvenile bull trout use slightly deeper, faster areas of side channels that have an abundance of overhead cover in the form of boulder and woody debris. Factors contributing to their decline include habitat degradation and loss due to land and water management practices; isolation and fragmentation of populations by both structural (e.g., dams) and environmental (e.g., thermal or pollution) barriers; introduction of non-native fishes resulting in competition, predation and hybridization threats; historical eradication efforts; poisoning to remove non-game species; historical overharvest; and ongoing poaching and accidental harvest due to misidentification.

On October 6, 2004, critical habitat was designated for numerous populations of the bull trout. The U. S. Fish and Wildlife Service excluded all waterbodies in Montana from critical habitat designations because of section 4(b)(2) of ESA. Earlier (November 29, 2004), when critical habitat was proposed for the bull trout, it included some streams in the Kootenai River basin in Lincoln County. Bobtail Creek was not among these streams.

Evaluation:

Effect of <u>sediment TMDL</u> on the bull trout: Existing studies suggest that fine sediment (sediment particles smaller than 6.35 mm (0.25 inches) in diameter) smothers eggs and fry of bull trout. In particular, high levels of fine sediment can reduce embryo survival by: 1) decreasing gravel permeability; 2) slowing rate of metabolic waste flushing; and 3) interfering with emergence by filling interstitial space through which the fry emerge. Research on substrate fine sediment effects on bull trout have concluded that survival of bull trout embryos is mostly unaffected up to a composition of 30% fines in spawning substrates (Shepard *et al.* 1984). Weaver and Fraley (1991) indicated that fines above 35% resulted in decreased survival of bull trout. Rieman and McIntyre (1993) concluded:

"In the absence of detailed local information on population habitat dynamics, any increase in the proportion of fines in substrates should be considered a risk to productivity of an environment and to the persistence of associated bull trout populations."

The Bobtail Creek TMDL establishes several water quality targets associated with the reduction of sediment. These targets focus on acceptable pool frequency values, macroinvertebrate measures, measures of percent fines in riffles and spawning substrate, width to depth ratios, and total suspended solids concentrations. As mentioned earlier, this would include pool frequency values of percent surface fines <2 mm (pebble count method) in riffles to remain below <20 percent, and percent surface fines (6.35 mm) 28 percent or less based on the McNeil Core method. Target strategies would include 90% compliance with road best management practices (BMP) to minimize surface erosion from existing roads, 75% reduction in bank erosion rates in Bobtail Creek, no sediment loading from preventable mass wasting events or from culvert failures where culverts are not up to BMP standards or not maintained, and no sediment loading increases (other than potential minor, predicated, short-term increases associated with 100 compliance with applicable BMPs) related to future development and to future timber roads and timber harvest.

EPA concludes that the sediment reduction targets in the TMDL will contribute to the overall sediment health of the habitat and aquatic species. The proposed action also will not result in the loss or degradation of cold-water fishery habitat.

<u>EPA Finding</u>: EPA concludes that its approval of the Bobtail Creek sediment TMDL **will not adversely affect** the bull trout because the proposed action will be beneficial to the species.

Evaluation of Action on the Bald Eagle (*Haliaeetus leucocephalus*)

Status: Threatened; Proposed for Delisting

Range: Entire lower 48 states

Habitat: Quiet coastal areas, rivers or lakeshores with large, tall trees.

Evaluation:

Effect of <u>sediment TMDL</u> on bald eagle: Fish are the primary food source for the bald eagle, but bald eagles also take a variety of birds, mammals, and turtles when fish are not readily available. Under certain conditions, excessive sediment can have negative effects on the health of fish. The purpose of the Bobtail Creek TMDL is to establish goals for improving the level of sediment in the Creek. If implemented, the Bobtail Creek TMDL should result in improved levels of aquatic life in the Creek as a result of the improved levels of sediment.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will **not likely adversely affect** the bald eagle because the proposed action will be beneficial to the species.

Evaluation of Action on Grizzly Bear (Ursus arctos horribilis)

Status: Threatened

Range: The historic range of the grizzly bear covered much of North America from the mid-plains westward to California and from central Mexico north throughout Alaska and Canada. The current range includes CO, ID, MT, WA, and WY. Grizzly bears are found in the Northern Continental Divide ecosystem which includes Glacier National Park, parts of the Flathead and Blackfoot Indian Reservations, parts of five national forests (Flathead, Helena, Kootenai, Lewis and Clark, and Lolo), Bureau of Land Management lands, and a significant amount of state and private lands. This would include the Bobtail Creek watershed.

<u>Habitat</u>: The grizzly bears habitat includes diverse forests interspersed with moist meadows and grasslands in or near mountains. The bear is an omnivore with a diet that includes insects, wild honey, grasses, sedges, roots, mountain sorrel, buffalo berries, fish, moose, elk deer, and bighorn. Thus, aquatic species such as fish are a small but sometimes important part of the bears' food source.

Evaluation:

Effect of <u>sediment TMDL</u> on the grizzly bear: The proposed TMDL approval would not result in the loss or degradation of the grizzly bear's habitat. Any reduction in sediments

should result in the improvement of habitat for aquatic life, including species upon which the grizzly bear feeds.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will **not likely adversely affect** the grizzly bear because any effects that the proposed action will have on the species will be insignificant but beneficial.

Evaluation of Action on Gray Wolf (Canis lupus)

Status: Endangered

Range: The current range of species includes CO, ID, MI, MT, ND, SD, WI, and, WY.

Habitat: Forested areas.

Evaluation:

Effect of <u>sediment TMDL</u> on the gray wolf: The proposed federal action does not result in the loss or degradation of the gray wolf's habitat. Further, the effect of the federal action will be limited to aquatic or aquatic-dependent species.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will have **no effect** on the gray wolf.

Evaluation of Action on Canada Lynx (Lynx canadensis)

Status: Threatened

Range: The current ranges includes CO, ID, ME, MI, MN, MT, NH, NY, OR, UT, VT, WA, WI, and WY.

<u>Habitat</u>: The habitat for the lynx includes spruce/fir forests of the high mountains. They feed on snowshoe hare, which live in dense thickets of younger trees and shrubs.

Evaluation:

Effect of <u>sediment TMDL</u> on the Canada lynx: This proposed federal action does not result in the loss or degradation of Canada lynx habitat. Further, any effects of the federal action will be limited to aquatic or aquatic-dependent species.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will have **no effect** on the Canada lynx.

Evaluation of Action on the Spalding's catchfly (campion) (Silene spaldingii)

Status: Threatened

Range: The current range of the Spalding's catchfly is ID, MT, OR, and WA.

<u>Habitat</u>: This species is primarily restricted to mesic (not extremely wet or extremely dry) grasslands (prairie or steppe vegetation) that are found in southeastern Washington, northwestern Montana, and adjacent portions of Idaho and Oregon. A certain number of plants have also been located in British Columbia. This species is typically associated with grasslands dominated by native perennial grasses (<u>see</u> 64 Fed. Reg. 67814, December 3, 1999).

Evaluation:

Effect of <u>sediment TMDL</u> on the Spalding's catchfly: This proposed federal action does not result in the loss or degradation of Spalding's catchfly habitat. Further, any affects of the federal action, if any, will be limited to aquatic or aquatic-dependent species.

<u>EPA Finding</u>: EPA concludes that its approval of the sediment TMDL for Bobtail Creek will have **no effect** on the Spalding's catchfly.

Evaluation of Action on the Slender Moonwort (*Botrychium lineare*) **Status: Candidate**

<u>Range</u>: Currently known from a total of nine populations in Colorado, Montana, Oregon, and Washington. Previous populations included Lake County, Montana, which has not been seen for at least 20 years and may be extirpated (Wagner and Wagner, 1994). Three populations are known to occur in Glacier County, Montana.

<u>Habitat</u>: This small perennial fern is found in a variety of montane forest or meadow habitats.

Evaluation:

Effect of <u>sediment TMDL</u> on slender moonwort: This proposed federal action does not result in habitat loss or degradation of the slender moonwort. Also, the slender moonwort in not known to occur in Lincoln County.

<u>EPA Finding</u>: EPA concludes that there is **no effect** of its approval of the Bobtail Creek sediment TMDL on the slender moonwort.

Conclusions

EPA concludes that its approval of the sediment TMDL for the Bobtail Creek will not likely adversely affect the bald eagle, grizzly bear, or the bull trout. Further, EPA concludes that its approval will have no effect on the white sturgeon, gray wolf, Canada lynx, Spalding's catchfly, or the slender moonwort.

References

Montana Fish, Wildlife, and Parks. 1999. Decision on listing of Bobtail Creek on the 2000 303(d) List. Letter from Mike Hensler (MFWP) to Mike Suplee (MDEQ). October 29, 1999.

Rieman, B.E. and J.D. McIntyre. 1993. Demographic and habitat requirements for conservation of bull trout. U.S. Dep. Agric., For. Serv. Intermountain Res. Sta., Odgen, UT. Gen. Tech. Rep. INT-302.

Shepard, B.B., S.A. Leathe, T.M. Weaver, and M.D. Enk. 1984. Monitoring levels of fine sediment within tributaries to Flathead Lake, and impacts of fine sediment on bull trout recruitment. Pages 146-156 in F. Richardson and F.H. Hamre, editors. Wild Trout III. Trout Unlimited, Vienna, Virginia.

Wagner, W.H. and F.S. Wagner. 1994. Another widely disjunct, rare and local North American moonwort (Ophioglossaceae: *Botrychium* subg. *Botrychium*). American Fern Journal 84(1): 5-10.

Weaver, T. and J. Fraley. 1991. Fisheries Habitat and Fish Populations, Flathead Basin Forest Practices Water Quality and Fisheries Cooperative Program. Flathead Basin Commission. Kalispell, Montana.

TMDL Review Criteria US EPA; Region VIII

Review Criteria

(All criteria must be met for approval.)

- TMDLs result in maintaining and attaining water quality standards (including the numeric, narrative, use classification, and antidegradation components of the standards; the "phased" TMDL can be used where there is a level of uncertainty; in addition, TMDLs can rely on either regulatory or voluntary approaches to attain standards);
- TMDLs have a quantified target or endpoint (a numeric water quality standard often serves as the target, but any indicator or set of indicators which represent the desired condition would suffice);
- TMDLs include a quantified pollutant target, but this target can be expressed in any appropriate manner (According to EPA reg (see 40 CFR 130.2(i)) TMDLs need not be expressed in pounds per day or concentration when alternative means of expression are better suited to the waterbody problem; TMDLs can be expressed as mass per unit of time, toxicity, % reduction in sediment or nutrients, or other measure);
- TMDLs must consider all significant sources of the stressor of concern (all sources or causes of the stressor must be identified or accounted for in some manner; this accounting can lump several sources of unknown origin together;
- TMDLs are supported by an appropriate level of technical analysis (allocations for nonpoint sources are often best professional estimates whereas waste load allocations for point sources are often based on a more detailed analysis);
- TMDLs must contain a margin of safety and consider seasonality (a margin of safety can be either explicit or implicit in the analysis or assessment);
- TMDLs apportion pollutant loads among sources (allocations may be expressed in a variety of ways such as by individual discharger, by tributary watershed, by source or land use category, by land parcel, or other appropriate scale or dividing responsibility);
- TMDLs shall be subject to public review (public participation should be in accordance with the State's continuing planning process ("CPP").)

REFERENCES

- Barbour, M. T.; et al. 1999. Rapid Bioassessment Protocols for Use in Streams and Wadeable Rivers: Periphyton, Benthic Macroinvertebrates, and Fish. Second Edition. U.S. Environmental Protection Agency, Office of Water Regulations and Standards, Washington, D.C. EPA 841-B-99-002.
- Bilby, R. E. 1984. Removal of Woody Debris Effects Stream Channel Stability. Journal of Forestry. 82:609-613.
- Bjorn, T. C. and D. W. Reiser. 1991. Habitat Requirements of Salmonids in Streams. American Fisheries Society Special Publication 19:83-138.
- Clifton, C. 1989. Effects of Vegetation and Land use on Channel Morphology. In: Gresswell, R. E.; Barton, B. A.: Kershner, J. L. eds. Practical Approaches to Riparian Resources Management. Billings, MT: Bureau of Land Management: 121-129.
- Deleray, M.; L. Knotek; S. Rumsey; and T. Weaver. 1999. Flathead Lake and River System Fisheries Status Report. Montana Fish, Wildlife, and Parks, Kalispell, MT.
- Irving, J. S. and T. C Bjornn. 1984. Effects of Substrate Size Composition on Survival of Kokanee Salmon and Cutthroat Trout and Rainbow Trout Embryos. University of Idaho. Cooperative Fishery Reasearch Unity. Technical Report 84-6. Moscow, Idaho.
- Kappesser. 2002. A Riffle Stability Index to Evaluate Sediment Loading to Streams. Journal of the American Water Resources Association. Vol. 38. Number 4. pp 1069-1081.
- Kuennen, L. J.; and M. L. Nielsen-Gerhardt. 1995. Soil Survey of Kootenai National Forest area, Montana and Idaho. U.S. Department of Agriculture, Forest Service. 122 p. plus appendices.
- Merritt, R. and K. W. Cummins. 1978. An Introduction to the Aquatic Insects of North America. Kendall/Hunt Publishing Co. USA.
- Montana Department of Environmental Quality (MDEQ). 1989. Macroinvertebrate Standard Operating Procedures. Developed by Bob Bukantis. http://www.deq.state.mt.us/wqinfo/monitoring/SOP/pdf/12-1-3.pdf
- Montana Department of Environmental Quality (MDEQ). 1991. Potential Water Quality Problems on Bobtail Creek. Letter from Steve Tralles (MDEQ) to a local landowner. October 11, 1991.
- Montana Department of Environmental Quality (MDEQ). 2000. Montana 303(d) List. A Compilation of Impaired and Threatened Waterbodies in Need of Water Quality Restoration. 2000. Helena, MT.

January, 2005 87

- Montana Department of Environmental Quality (MDEQ). 2002. Montana 303(d) List. A Compilation of Impaired and Threatened Waterbodies in Need of Water Quality Restoration. 2002. Helena, MT.
- Montana Department of Environmental Quality (MDEQ). 2004. Circular WQB-7: Montana Numeric Water Quality Standards. http://www.deq.state.mt.us/wqinfo/Circulars/WQB-7.PDF.
- Montana Department of Environmental Quality (MDEQ). 2004a. Blackfoot Headwaters Planning Area Water Quality and Habitat Restoration Plan and TMDL for Sediment. http://www.deq.state.mt.us/wqinfo/TMDL/BlackfootHeadwaters/Final_BFHSed_Master.pdf.
- Montana Department of Environmental Quality (MDEQ). 2004b. Water Quality Restoration Plan and Total Maximum Daily Loads for the Ninemile Planning Area. http://www.deq.state.mt.us/wqinfo/TMDL/TMDLDrafts/Ninemile/PRDraftNinemile.pdf.
- Montana Fish, Wildlife, and Parks (MFWP). 1999. Decision on Listing of Bobtail Creek on the 2000 303(d) List. Letter from Mike Hensler (MFWP) to Mike Suplee (MDEQ). October 29, 1999.
- Newcombe, C. P. and J. O. T. Jensen. 1996. Channel Suspended Sediment and Fisheries: A Synthesis for Quantitative Assessment of Risk and Impact. North American Journal of Fisheries Management, Vol. 16, No. 4, pp 693-727.
- Plum Creek Timber Company. 2000. Native Fish Habitat Conservation Plan. http://www.plumcreek.com/environment/fish.cfm.
- Plum Creek Timber Company. 2004. Letter Re: Plum Creek comments on the public review draft *Water Quality Protection Plan and TMDLs for the Bobtail Creek Watershed* from Brian Sugden, Hydrologist.
- Riggers, Brian W.; Arne Rosquist; Richard Kramer; and Mike Bills. 1998. An Analysis of Fish Habitat and Population Conditions in Developed and Undeveloped Watersheds on the Lolo National Forest. January 1998. U.S. Forest Service, Lolo National Forest. Missoula, MT.
- Rosgen, Dave L. 1996. Applied River Morphology. Wildland Hydrology. Lakewood, CO.
- Rowe, Mike; Don Essig; and Ben Jessup. 2003. Guide to Selection of Sediment Targets for Use in Idaho TMDLs. June 2003. Idaho Department of Environmental Quality.
- Sedell, J. R., and J. L. Froggath. 1984. Importance of Streamside Forests to Large Rivers: the Isolation of the Willamette River, Oregon, USA, from its Floodplain by Snagging and Streamside Forest Removal. Verendlunger internationale Vareinigung fur Theoretische und Argewandfe Limnologie 22:1828-1834.

January, 2005

- Shepard, B. B.; M. Taper; R. G. White; and S. C. Ireland. 1998. Influence of Abiotic and Biotic Factors on Abundance of Stream-resident Westslope Cutthroat Trout *Oncorhynchus clarki lewisi* in Montana Streams.
- U.S. Census Bureau (USCB). 2004. http://www.census.gov/
- U.S. Environmental Protection Agency (USEPA). 1999. Protocol for Developing Sediment TMDLs. First Edition. Publication number: EPA 841-B-99-004. Washington DC.
- U.S. Environmental Protection Agency (USEPA). 2004. Water Quality Assessment and TMDLs for the Flathead River Headwaters Planning Area, Montana, Public Review Draft. Helena, MT.
- U.S. Forest Service (USFS). 1987. Kootenai National Forest, Forest Plan. http://www.fs.fed.us/r1/kootenai/projects/planning/documents/forest_plan/87_plan/index. shtml.
- U.S. Forest Service (USFS). 1991. R1-Watsed Model. Region 1, USDA Forest Service, Missoula, Montana.
- U.S. Forest Service (USFS). 1995. Inland Native Fish Strategy Environmental Assessment. Decision Notice and Finding of No Significant Impact. Intermountian, Northern and Pacific Regions.
- U.S. Forest Service (USFS). 2002. Pipestone Timber Sale and Restoration Project Draft Environmental Impact Statement. US Department of Agriculture, Forest Service, Kootenai National Forest. Libby, Montana.
- U.S. Forest Service (USFS). 2002a. Upper Kootenai Subbasin Review. Kootenai National Forest. April 2002.
- U.S. Forest Service (USFS). 2004. Pipestone Timber Sale and Restoration Project Final Environmental Impact Statement. Kootenai National Forest. Libby Ranger District. June 2004.
- Washington Forest Practices Board. 1997. Watershed Analysis Manual, v 4.0.
- Weaver, T.; and J. Fraley. 1991. Fisheries Habitat and Fish Populations. p. 53 68. In Flathead Basin Forest Practices Water Quality and Fisheries Cooperative Program. June 1991. Flathead Basin Commission, Kalispell, Montana.

January, 2005

January, 2005 90

January, 2005 85



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18TH STREET - SUITE 300
DENVER, CO 80202-2466
Phone 800-227-8917
http://www.epa.gov/region08

Ref: 8EPR-EP April 27, 2005

Mr. Art Compton, Director Planning, Prevention and Assistance Division Department of Environmental Quality P.O. Box 200901 Helena, MT 59620-0901

Re: TMDL Approvals

Bobtail Creek

Dear Mr. Compton:

We have completed our review of the total maximum daily loads (TMDLs) as submitted by your office for the Bobtail Creek Watershed. The TMDLs are included in the document entitled Water Quality Restoration Plan and TMDLs for the Bobtail Creek Watershed (Montana Department of Environmental Quality) transmitted to us for review and approval in correspondence dated January 28, 2005 and signed by you. In accordance with the Clean Water Act (33 U.S.C. 1251 et. seq.), we approve all aspects of the TMDLs as developed for the Bobcat Watershed TMDL Planning Area. Enclosure 1 to this letter provides a summary of the elements of the TMDLs and Enclosure 2 provides details of our review of the TMDLs.

Based on our review, we feel the separate TMDL elements listed in Enclosure 2 adequately address the pollutants of concern, taking into consideration seasonal variation and a margin of safety. In approving this TMDL, EPA affirms that the TMDLs have been established at a level necessary to attain and maintain the applicable water quality standards and has the necessary components of an approvable TMDL.

EPA has been in contact with the United States Fish and Wildlife Service (FWS) regarding whether and, if so, how the EPA's approval of the Bobtail Creek TMDL may affect the continued existence of any endangered or threatened species listed under the Endangered Species Act (ESA) or the designated critical habitat of any such species. EPA has not determined that today's approval may have such an affect. Therefore, consistent with the terms of a consent decree in the lawsuit of Friends of the Wild Swan, et al., v. U.S. Environmental Projection Agency, et al., Civil Action No. CV99-87-M-LBE, United States District Court for the District of Montana, Missoula Division, EPA has decided to approve these TMDLs contingent upon the outcome of consultation with the FWS.

Thank you for your submittal. If you have any questions concerning this approval, feel free to contact Ron Steg of my staff at (406) 457-5024.

Sincerely,

Original Signed by Max Dodson

Max H. Dodson Assistant Regional Administrator Ecosystems Protection and Remediation

Enclosures

cc:

Claudia Massman, Attorney Montana Department of Environmental Quality P.O. Box 200901 Helena, MT 59620-0901

Dean Yashan Montana Department of Environmental Quality P.O. Box 200901 Helena, MT 59620-0901

George Mathieus Montana Department of Environmental Quality P.O. Box 200901 Helena, MT 59620-0901